

23/05/2002

ASS. REC. BY:

REF: CS/TCU8003887/Kqb12 Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): CUS Hung Yin Min of FCI Date/Time: 27/02/2018 3:28pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 9706H Insured: SHC 7674Z

at Workshop m/s Trans Cab Tel: 6087 6666

of No. 2AMK 91 63

Policy No: Claim No: D180D1668MTSH

Sum Insured: Excess:

Make of Veh: D.O.A. 25/02/018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp' H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 9706H - CCB / AXA 17000737 / UZG392 DPA: 07/01/17
	SHC 7674Z - NS / TNCI 3019203 / HICB63 DPA: 13/10/13
01/31/18 @ 3:19pm	revised to Hung Yin Min by email.
	LS \$17500, 15 days (Red \$ 89613.33, 84%)

ASS. REC. BY:

REF:

1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S1HB 970014 Yr Regn: 07 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perant Caribou c.c. 1995Colour A. White 1B A/C: Insured / Std / NI / NASp. Reading 557107 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL 15 AUG 273254Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FalkenFront 7 mmR/Bal. 7 mmL/Bal. 7 mmD.O.A. 25/2/18Survey held at 28/2/18Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or2/18

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/3 File pass to Customer

RECEIVED 8 JUN 2018

Date/Time, File Pass to?

11/08/16 Final

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final ReportDays Of Repair: 15

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation: \$ + RS \$ _____

Photos: _____

Others: OSP8/6/1850Report Format: TPLump Sum / I.B.A. (\$ 17500)

97X15-1455

170+1455

50

41

1716



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003887/Kqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7674Z	Veh. Inspected	SHB 9706H
Policy No.		Coverage (\$)	0.00
Claim No.	D18001668MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	25/02/2018	Inspection Date	28/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	27-02-2018	Our Ref No. D18001668MFSH
Accident Date	25-02-2018	Claim Type. Third Party
Insured Vehicle	SHC7674Z	Third Party Vehicle. SHB9706H
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	JIONG HOW NG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235394)



PRI Documents



Close



PRI Header Details

Claim No	D18001668MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TR, PTE LTD
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : JIONG HOW NG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 6257133 EmailId: JIONGHOW.NG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7674Z	TP Vehicle No	SHB971
PRI Recieved Date	27-02-2018 03:52:49 PM	Surveyor Appointed Date	27-02-2018 03:28:16 PM	Surveyor Accept Date	28-02-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-02-2018	Upload Survey Report *:	
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 March 2018 3:19 PM
To: 'Claim Workflow System'; assignments
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001668MFSH/1
Attachments: CSFCI18003887Kqb.pdf

Dear Yin Min,

Enclosed herewith preliminary advice of SHB 9706H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 28 February 2018 11:15 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001668MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 February, 2018 3:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001668MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001668MFSH

Date: 01 March 2018

Our Ref: CS/FCI18003887/Kqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9706H.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/02/2018 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>107,113.33</u>
Revised Estimate Amount	: S\$ <u>24,934.26</u>
"Check" Items Amount	: S\$ <u>1,177.88</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear & front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB9706H
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000397
Chassis No.:	VF1ABL15AUC273254
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Jul 2013
First Registration Date:	18 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2021
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	17 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$21,955.00
Total Rebate Amount:	\$31,328.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Feb 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9706H -

AAD1802-235

Not Authorised

Proposed L/S of \$ 17,500/-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

K Auto Consultants hence notify

Repairer of the following

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

** Third party survey is on a "Without prejudice" basis*

** No illegal modification(s) is allowed*

** Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company*

SHB9706H - JHOW

VF1ABL15AUC273254

RENAULT

LATITUDE

25.02.2018

FCIL

PART

Acknowledged by Repairer

Signature:

Date:

LIST

1	1	BUMPER COVER FRT	\$	<i>RM</i>	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>RM</i>	181.75	X
3	1	BUMPER ABSORBER FRT	\$	<i>RM</i>	394.68	X
4	1	BUMPER RETAINER FRT LH	\$	<i>RM</i>	151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>RM</i>	123.88	X
6	1	BUMPER RETAINER FRT RH	\$	<i>RM</i>	150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>RM</i>	123.88	X
8	1	BUMPER UNDERTRAY FRT	\$	<i>RM</i>	472.83	X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>RM</i>	266.80	X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>RM</i>	207.21	X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>RM</i>	207.21	X
12	1	BUMPER BEAM FRT	\$	<i>RM</i>	914.08	X
13	1	TOW COVER FRT	\$	<i>RM</i>	28.61	X
14	1	RADAIOR GRILLE	\$	<i>RM</i>	1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>RM</i>	225.36	✓
16	1	RADAIOR GRILLE FRAME	\$	<i>RM</i>	1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>RM</i>	615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>RM</i>	89.79	✓
19	1	FRONT BRACE PANEL	\$	<i>RM</i>	177.22	X
20	1	HORN	\$	<i>RM</i>	314.17	X
21	1	HORN BRACKET	\$	<i>RM</i>	40.45	X
22	1	HEADLAMP LH	\$	<i>RM</i>	1,184.43	✓
23	1	HEADLAMP RH	\$	<i>RM</i>	1,184.43	✓
24	1	HEADLAMP PANEL FRT LH	\$	<i>RM</i>	152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>RM</i>	152.15	X
26	1	BONNET	\$	<i>RM</i>	1,941.63	} X
27	1	BONNET INSULATOR	\$	<i>RM</i>	405.73	
28	1	BONNET STRUT LH	\$	<i>RM</i>	88.61	
29	1	BONNET STRUT RH	\$	<i>RM</i>	88.61	
30	1	BONNET HINGE LH	\$	<i>RM</i>	348.31	
31	1	BONNET HINGE RH	\$	<i>RM</i>	348.31	
32	1	BONNET LOCK	\$	<i>RM</i>	305.48	
33	1	BONNET CABLE	\$	<i>RM</i>	119.19	
34	1	BONNET CABLE COVER	\$	<i>RM</i>	161.03	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9706H -**AAD1802-235**

35	1	BONNET SEAL OUTER	\$	92.36	}	X
36	1	BONNET SEAL INNER	\$	157.28		
37	1	FENDER PANEL FRT LH	\$	783.83		
38	1	FENDER PANEL FRT RH	\$	783.83		
39	1	WHEELARCH FRT LH	\$	278.84		
40	1	WHEELARCH FRT RH	\$	278.84		
41	1	FENDER BRACKET LOWER LH	\$	15.79		
42	1	FENDER BRACKET LOWER RH	\$	15.79		
43	1	FENDER INSULATOR LH	\$	130.84		
44	1	FENDER INSULATOR RH	\$	130.84		
45	1	WIPER RESERVOIR	\$	348.25	}	X
46	1	WIPER RESERVOIR NECK	\$	136.11		
47	1	WIPER RESERVOIR MOTOR	\$	270.06		
48	1	AIR CLEANER LOWER	\$	271.26		
49	1	AIR CLEANER HOSE	\$	76.14		
50	1	AUTO COMPUTER	\$	5,032.17		
51	1	STEERING PUMP ELECTRIC	\$	2,306.90		
52	1	A/C CONDENSER	\$	2,020.37		
53	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67		
54	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67		
55	1	A/C CONDENSER GARNISH LH	\$	58.81	}	X
56	1	A/C CONDENSER GARNISH RH	\$	59.60		
57	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39		
58	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72		
59	1	A/C PIPE COMPRESSOR	\$	334.29		
60	1	A/C PIPE	\$	658.72		
61	1	A/C COMRPRESSOR	\$	2,684.61		
62	1	AIR COOLER	\$	792.60		
63	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13		
64	1	AIR INTERCOOLER HOSE (Short)	\$	375.14		
65	1	TRANSMISSION COOLER	\$	1,219.30	}	X
66	1	TRANSMISSION COOLER PAD	\$	17.96		
67	1	RADIATOR	\$	1,202.20		
68	2	RADIATOR STUD UPPER	\$	14.41		
69	2	RADIATOR BUSH UPPER	\$	50.12		
70	2	RADIATOR MTG LOWER	\$	55.85		
71	1	RADAITOR FAN COWLING	\$	820.54		
72	1	RADIATOR FAN MOTOR LH	\$	967.36		
73	1	RADIATOR FAN MOTOR RH	\$	1,479.46		
74	1	RADIATOR TANK	\$	324.62		
75	1	RADIATOR HOSE UPPER	\$	240.56	}	X
76	1	RADIATOR HOSE LOWER	\$	491.18		

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9706H -

AAD1802-235

77	1	RADIATOR TANK HOSE	\$	Sn	61.18 X
78	1	WINDSCREEN FRT	\$	Sn	1,364.06 X
79	1	ROTARY SWITCH	\$	Sn	1,253.11 X
80	1	DASHBOARD	\$	Sn	4,900.54 X
81	1	BUMPER COVER REAR	\$	Bj	1,108.46 ✓
82	1	BUMPER LOWER REAR	\$	Dis/Re	768.84 ✓
83	1	BUMPER BRACKET CTR REAR	\$	CM	113.47 ✓
84	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn	135.97 X
85	1	BUMEPR BRACKET CTR LH REAR	\$	Sn	44.99 X
86	1	BUMEPR BRACKET SIDE RH REAR	\$	Sn	135.97 X
87	1	BUMEPR BRACKET CTR RH REAR	\$	Sn	44.99 X
88	1	BUMPER BEAM REAR	\$	Bj	777.52 ✓
89	1	BUMPER BEAM BRACKET LH REAR	\$	Bj	225.95 ✓
90	1	BUMPER BEAM BRACKET RH REAR	\$	Bj	225.95 ✓
91	1	BUMPER REFLECTOR LH	\$	Bj	43.61 ✓
92	1	BUMPER REFLECTOR RH	\$	Sn	43.61 X
93	1	BOOT REAR	\$	Bj	2,872.68 ✓
94	2	BOOT RUBBER PLUG	\$	Sn	221.81 ✓
95	1	BOOT FINISHER	\$	Sn	470.06 X
96	1	BOOT SWITCH	\$	Sn	168.13 X
97	1	BOOT TRIM BOARD	\$	Sn	914.87 X
98	1	BOOT LOCK	\$	R	202.67 X
99	1	BOOT LOCK CATCH	\$	R	74.40 X
100	1	BOOT LOCK LINKAGE	\$	Sn	34.53 X
101	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	154.52 X
102	1	BOOT LOCK CATCH TRIM BOARD	\$	Sn	249.24 X
103	1	BOOT WHEATERSTRIP	\$	Sn	323.05 X
104	1	BOOT REFLECTOR LAMP LH	\$	Re	493.35 ✓
105	1	BOOT REFLECTOR LAMP RH	\$	Re	493.35 X
106	1	BOOT BADGE 'RENAULT'	\$	Re	225.36 ✓
107	1	BOOT BADGE	\$	Re	225.36 ✓
108	1	BOOT STRUT LH	\$	Sn	276.08 X
109	1	BOOT STRUT RH	\$	Sn	276.08 X
110	1	BOOT HINGE LH	\$	R	367.84 X
111	1	BOOT HINGE RH	\$	R	367.84 X
112	2	LICENCE PLATE LAMP	\$	Sn	50.52 X
113	1	WINDSCREEN REAR	\$	Sn	1,463.28 X
114	1	WINDSCREEN GARNISH INNER LH	\$	Sn	263.74 X
115	1	WINDSCREEN GARNISH INNER RH	\$	Sn	263.74 X
116	1	TAILLAMP LH	\$	mtj/Re	552.55 ✓
117	1	TAILLAMP PANEL LH	\$	R	986.70 X
118	1	TAILLAMP RH	\$	Sn	552.55 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9706H -**AAD1802-235**

119	1	TAILLAMP PANEL RH	\$	R	986.70	X
120	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
121	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
122	1	WHEELARCH REAR LH	\$	Sm	543.47	X
123	1	WHEELARCH REAR RH	\$	Sm	543.47	X
124	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
125	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	X
126	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	BH/BH	2,189.88	✓
127	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	Sm	612.21	X
128	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73	X
129	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36	X
130	1	OUTER PANEL REAR (End Panel)	\$	BH	1,471.77	✓
131	1	OUTER PANEL REAR (End Panel)TRIM	\$	CIM	401.02	✓
132	1	EXHAUST REAR	\$	R	7,489.05	} X
133	1	EXHAUST CAP REAR	\$	R	230.49	
134	1	EXHAUST MOUNTING REAR	\$	Sm	31.97	
135	1	EXHAUST BRACKET REAR	\$	R	39.86	
136	1	EXHAUST HEAT SHIELD REAR	\$	R	99.06	
137	1	SHIELD - HEAT - TUNNEL	\$	R	225.16	
138	1	FUEL FLAP	\$	Sm	343.57	
139	1	FUEL TANK NECK	\$	Sm	684.77	
140	1	FUEL CAP	\$	Sm	233.02	
141	1	DOOR PANEL REAR LH	\$	R	2,844.66	
142	1	DOOR SEAL REAR LH	\$	Sm	187.08	
143	1	DOOR PANEL REAR RH	\$	R	2,844.66	
144	1	DOOR SEAL REAR RH	\$	Sm	162.02	

TOTAL	\$	96,567.13
10%	\$	9,656.71
	\$	86,910.41

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	R	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	R	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	Sm	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	R	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	R	12.00	X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	R	10.50	X
7	1	TOW COVER FRT	\$	Sm	14.50	X
8	1SET	RADAITOR GRILLE SCREW	\$	R	16.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9706H -**AAD1802-235**

9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	} X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	
14	1SET	WHEELARCH CLIP FRT RH	\$	nn	29.40	
15	1	CAP HUB LH FRT	\$	sn	35.00	
16	1	RIM LH FRT	\$	sn	385.00	
17	1	TYRE LH FRT	\$	sn	330.00	
18	1	CAP HUB RH FRT	\$	sn	35.00	
19	1	RIM RH FRT	\$	sn	385.00	
20	1	TYRE RH FRT	\$	sn	330.00	
21	1SET	BUMPER RR CLIP	\$	nn	66.00	✓
22	1SET	BUMPER BEAM BOLT	\$	nn	22.22	X
23	1SET	PARKING AID	\$	Short	600.00	✓
24	1	BUMPER BRACKET CLIP CTR REAR	\$	nn	15.00	} X
25	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	nn	12.00	
26	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	
27	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	
28	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	
29	1	CAP HUB LH RR	\$	sn	35.00	
30	1	RIM LH RR	\$	sn	385.00	
31	1	TYRE LH RR	\$	sn	330.00	
32	1	CAP HUB RH RR	\$	sn	35.00	
33	1	RIM RH RR	\$	sn	385.00	
34	1	TYRE RH RR	\$	sn	330.00	
35	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	
36	1	SPARE TYRE	\$	sn	330.00	
37	1SET	BOOT FINISHER CLIP	\$	nn	25.10	
38	1	Rear boots sticker "trans-cab"	\$	nn	30.00	—
39	1	Rear boots sticker "6555-3333"	\$	nn	30.00	—
40	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
41	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
42	2	Rear windscreen sealant	\$	nn	80.00	X
43	1	Windscreen moulding	\$	nn	100.00	X
44	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	X
45	1	EXHAUST MOUNTING REAR	\$	sn	65.50	X
46	1	EXHAUST BRACKET REAR	\$	R	22.22	X
47	1SET	Front licence plate with holder	\$	Bz	80.00	45sn
48	1SET	Rear licence plate with holder	\$	sn	80.00	X
49	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
50	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-235

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9706H -

TOTAL	\$	5,742.92
TOTAL PARTS	\$	92,653.33

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	1800
Towing Fees.	\$	120.00	50
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	nn X
Putty and spray painting of the affected portion.	\$	4,500.00	1760
To rust-proofing of the affected areas.	\$	170.00	90
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	120
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	40
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	250
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	nn X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	nn X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	80
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9706H -**AAD1802-235**

To transfer of tailgate fittings and conduct water seepage test.	\$	170.00 <i>601</i>
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 280.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>1001</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>501</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 <i>501</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	14,460.00
Over All Total	\$	107,113.33 <i>29</i>

< parts by parts > Repair Days

15 DAYS

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003887/Kqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7674Z	Veh. Inspected	SHB 9706H	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001668MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC273254	Colour	METALLIC WHITE / RED	
Odometer	557107	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FALKEN	7 mm	
L/H Front Tyre	215/60 R16	FALKEN	7 mm	
R/H Rear Tyre	215/60 R16	FALKEN	6 mm	
L/H Rear Tyre	215/60 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/02/2018	Inspection Date	28/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9706H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	DISTORTED	150.77	150.77
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	MTG CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET	BENT	89.79	89.79
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-

Report Ref No. CS/FC118003887/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	STEERING PUMP ELECTRIC	SERVICEABLE	2,306.90	-
1	A/C CONDENSER	PUNCTURE	2,020.37	2,020.37
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-

Report Ref No. CS/FCI18003887/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	WINDSCREEN FRT	SERVICEABLE	1,364.06	-
1	ROTARY SWITCH	SERVICEABLE	1,253.11	-
1	DASHBOARD	SERVICEABLE	4,900.54	-
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED / DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER BRACKET CTR LH REAR	SERVICEABLE	44.99	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER BRACKET CTR RH REAR	SERVICEABLE	44.99	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95

Report Ref No. CS/FCI18003887/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BEAM BRACKET RH REAR	BENT	225.95	225.95
1	BUMPER REFLECTOR LH	BROKEN	43.61	43.61
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BOOT REAR	BENT	2,872.68	2,872.68
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT TRIM BOARD	SERVICEABLE	914.87	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
1	BOOT LOCK LINKAGE	SERVICEABLE	34.53	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	154.52	-
1	BOOT LOCK CATCH TRIM BOARD	SERVICEABLE	249.24	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	DENTED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
1	WINDSCREEN REAR	SERVICEABLE	1,463.28	-
1	WINDSCREEN GARNISH INNER LH	SERVICEABLE	263.74	-
1	WINDSCREEN GARNISH INNER RH	SERVICEABLE	263.74	-
1	TAILLAMP LH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP RH	SERVICEABLE	552.55	-

Report Ref No. CS/FCI18003887/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	BENT / BUCKLED	2,189.88	2,189.88
1	SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL)	SERVICEABLE	612.21	-
1	SPARE WHEEL PANEL BRACKET LH	TO REPAIR SEE LABOUR	123.73	-
1	SPARE WHEEL PANEL BRACKET RH	TO REPAIR SEE LABOUR	121.36	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	401.02	401.02
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	EXHAUST MOUNTING REAR	SERVICEABLE	31.97	-
1	EXHAUST BRACKET REAR	TO REPAIR SEE LABOUR	39.86	-
1	EXHAUST HEAT SHIELD REAR	TO REPAIR SEE LABOUR	99.06	-
1	SHIELD-HEAT-TUNNEL	TO REPAIR SEE LABOUR	225.16	-
1	FUEL FLAP	SERVICEABLE	343.57	-
1	FUEL TANK NECK	SERVICEABLE	684.77	-
1	FUEL CAP	SERVICEABLE	233.02	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	187.08	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-

Report Ref No. CS/FCI18003887/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
	LESS 10% DISCOUNT		-9,656.71	-2,163.92
			86,910.37	19,475.26
	SPECIAL NETT ITEMS			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	29.40	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH FRT (SN)	SERVICEABLE	35.00	-
1	RIM RH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE RH FRT (SN)	SERVICEABLE	330.00	-
1	SET BUMPER RR CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BEAM BOLT (SN)	NOT NECESSARY	22.22	-
1	SET PARKING AID (SN)	SHORTED	600.00	600.00
1	BUMPER BRACKET CLIP CTR REAR (SN)	NOT NECESSARY	15.00	-
1	BUMPER BRACKET SIDE CLIP LH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP LH REAR (SN)	NOT NECESSARY	10.40	-
1	BUMPER BRACKET SIDE CLIP RH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP RH REAR (SN)	NOT NECESSARY	10.40	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-

Report Ref No. CS/FCI18003887/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN)	SERVICEABLE	330.00	-
1	SPARE TRYE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	25.10	-
1	REAR BOOTS STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOTS STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	SET WHEELARCH CLIP LH RR (SN)	NOT NECESSARY	32.34	-
1	SET WHEELARCH CLIP RH RR (SN)	NOT NECESSARY	32.34	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	65.50	-
1	EXHAUST BRACKET REAR (SN)	TO REPAIR SEE LABOUR	22.22	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	80.00	45.00
1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER "6555-3333" LH (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "6555-3333" RH (SN)	NOT NECESSARY	80.00	-
			5,742.92	889.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT.FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH. }		4,200.00	1,800.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,FENDER PANEL FRT LH,FENDER PANEL FRT RH,BOOT LOCK,BOOT LOCK CATCH,BOOT HINGE LH,BOOT HINGE RH,TAILLAMP PANEL LH,TAILLAMP PANEL RH,FENDER PANEL REAR LH,FENDER PANEL REAR RH,SPARE WHEEL PANEL BRACKET LH,SPARE WHEEL PANEL BRACKET RH,EXHAUST REAR,EXHAUST CAP REAR,EXHAUST BRACKET REAR,EXHAUST HEAT SHIELD REAR,SHIELD-HEAT-TUNNEL,DOOR PANEL REAR LH,DOOR PANEL REAR RH AND EXHAUST BRACKET REAR. }		-	-
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,760.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.		380.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.		380.00	250.00
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00

Report Ref No. CS/FC118003887/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:9 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR WINDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	280.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			14,460.00	4,570.00
	GRAND TOTAL		107,113.29	24,934.26
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,500.00

Report Ref No. CS/FCI18003887/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.