

22/03/2018

ASS. REC. BY:

REF:

CS/FCL18003893/Kgpn2

Special Instruction:

Surveyor: Kenneth.

ASSIGNMENT (Office)

From (Person): CWS May Chua

of

FCL

Date/Time: 28/02/2018 8:52am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 2372H

Insured:

SHC 3060X

at Workshop m/s

Cheng Hoe

Tel:

6755 6142

of

Blk 1019 Yishun Ind Park A #01-374

Policy No:

Claim No:

D18001673M75H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/02/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

28/02/2018

11:30am

Person Contacted:

Ebedu

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	YP 2372H - x
	SHC 3060X - CS / FCL15016663 / R/Hb2
06/3/18 @	4.12pm revised to May Chua by email.
	10/5 11pm 8/11, 6501 Cc1 firm Ebedu (Ref \$4481.00, 28%)

ASS. REC. BY:

REF: FC21

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 12 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: YP 237214Yr Regn: 05, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mit.Colour: WhiteSp. Reading: 33789

Eng/No: _____

C/No: FEB 21C A2000Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: N11 / S/Rlm / STD A/Rlm orTyre Size: F: 195/85R15R: 195/85R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/2/18D.O.I. 1/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/3File pass to Catherine

RECEIVED 15 MAY 2018

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1) 19/5/18
Date/Time, File Return to?Days Of Repair: 12Resurvey No. of Trip: 2Survey Fee: 6x152 90Transportation: 170 + 80) S + RS. \$ 50) Photos 50 + 50) Others 41) 15/5/18TOTAL 451Add Fee: ☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format: TPLump Sum / I.B.I. (\$) 11650



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003893/Kqb

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 28-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3060X	Veh. Inspected	YP 2372H
Policy No.		Coverage (\$)	0.00
Claim No.	D18001673MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	28/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/02/2018	Inspection Date	28/02/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	27-02-2018	Our Ref No. D18001673MFSH
Accident Date	27-02-2018	Claim Type. Third Party
Insured Vehicle	SHC3060X	Third Party Vehicle. YP2372H
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE:	28/02/2018 @ 11:50am
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	Elected veh in Kenneth.
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235402)



PRI Documents



Close



PRI Header Details

Claim No	D18001673MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CH
Workshop Name	CHENG HOE MOTOR PTE LTD (Contact Person : JUNE)	Survey Location & Contact Details	BLK 1019 YISHUN IND. PARK A #01-374 Mobile: 0 , Phone: 67556142 , Fax: 6755771 EmailId: CHMOTOR@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3060X	TP Vehicle No	YP2372
PRI Recieved Date	27-02-2018 06:48:11 PM	Surveyor Appointed Date	28-02-2018 08:52:04 AM	Surveyor Accept Date	28-02-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-02-2018	Upload Survey Report *:	
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 6 March 2018 4:12 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001673MFSH/1
Attachments: CSFCI18003893Kqb.pdf

Dear May,

Enclosed herewith preliminary advice of YP 2372H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Wednesday, 28 February 2018 11:31 AM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18001673MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 28 February, 2018 8:52 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001673MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001673MFSH

Date: 06 March 2018

Our Ref: CS/FCI18003893/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. YP 2372H

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/03/2018 at the premises of M/s CHENG HOE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,523.16</u>
Revised Estimate Amount	: S\$ <u>13,641.67</u>
"Check" Items Amount	: S\$ <u>861.49</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1922R
Vehicle Details	
Vehicle No.:	YP2372H
Vehicle to be Exported:	No
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	CANTER FEB21CR3SDEB
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	LTA1601708
Chassis No.:	FEB21CA20005
Maximum Power Output:	-
Open Market Value:	\$41,864.00
Original Registration Date:	03 May 2016
First Registration Date:	03 May 2016
Transfer Count:	0
Actual ARF Paid:	\$2,094.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$38,040.00
Total Rebate Amount:	\$38,040.00

The information contained herein is correct as at 27 Feb 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848 FAX: 65073849

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/FC/WL

Claim Type: Third Party

Accident Date: 27/02/2018

TP Veh Reg No: SHC3060X

Estimate No: ES1890197/YISHUN

Date: 27 Feb 2018

Policy No: D17MTPCVE000676

Veh Reg No: YP2372H

Make/Model: MITSUBISHI CANTER
 FEB21CR3SDEB

Chassis No: FEB21CA20005

Engine No: LTA1601708

Reg. Date: 03/05/2016

Estimate Repair Cost to Vehicle No :YP2372H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	1,010.33	1 PC	B ₁ 1,010.33	✓
2 FRONT BUMPER RH BRACKET	196.24	1 PC	D ₁₅ 196.24	✓
3 FRONT BUMPER RH SIDE PAD	417.72	1 PC	M ₁₇ 417.72	✓
4 RH HEADLAMP	501.41	1 PC	C ₁₂ 501.41	✓
5 HEADLAMP LOWER RUBBER	32.15	1 PC	M ₁₅ 32.15	✓
6 RH SIGNAL LAMP	266.36	1 PC	B ₂ 266.36	✓
7 FRONT GRILLE	1,105.63	1 PC	M ₁₇ 1,105.63	✓
8 FRONT RH STEP TRAY	613.20	1 PC	C ₁₂ 613.20	✓
9 FRONT RH WINDSCREEN PILLAR	1,533.24	1 PC	B ₁ 1,533.24	✓
10 FRONT WINDSCREEN GLASS RUBBER	492.50	1 PC	M ₁ 492.50	✓
11 FRONT RH DOOR	2,102.66	1 PC	B ₁ 2,102.66	✓
12 FRONT RH DOOR TOP HINGE	162.54	1 PC	B ₁ 162.54	✓
13 FRONT RH DOOR BOTTOM HINGE	162.54	1 PC	B ₁ 162.54	✓
14 FRONT RH DOOR CHECKER	83.51	1 PC	D ₁₇ 83.51	✓
15 FRONT RH DOOR INNER RUBBER	424.99	1 PC	D ₁₅ 424.99	✓
16 FRONT RH DOOR INNER LOCK	389.21	1 PC	D ₁ 389.21	✓
17 FRONT RH DOOR INNER BOARD	638.89	1 PC	B ₂ 638.89	✓
18 FRONT RH DOOR GLASS	444.49	1 PC	S ₁ 444.49	X
19 FRONT RH DOOR GLASS REGULATOR	1,684.91	1 PC	B ₁ 1,684.91	✓
20 FRONT RH DOOR GLASS CHANNEL	279.17	1 PC	S ₁ 279.17	X
21 FRONT RH DOOR FRAME CHANNEL	424.99	1 PC	D ₁₅ 424.99	✓
22 FRONT RH DOOR STICKER (DUONIC)	61.28	1 PC	M ₁ 61.28	✓
23 FRONT RH DOOR LOWER RUBBER	82.31	1 PC	M ₁ 82.31	✓
24 FRONT RH WHEEL ARP PANEL	320.00	1 PC	B ₂ 320.00	✓
25 FRONT RH WHEEL ARP TOP GARNISH	150.80	1 PC	B ₂ 150.80	✓
26 FRONT RH WHEEL REAR MUD GUARD	139.19	1 PC	C ₁₂ 139.19	✓
27 FRONT WIPER TANK	190.62	1 PC	D ₁ 190.62	✓
			13,910.88	
		Less 25%	3,477.72	10,433.16
Special Net				
28 REAR RH WHEEL FRT MUDGUARD	300.00	1 PC	B ₁ 300.00	✓
			300.00	300.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/FC/WL

Claim Type: Third Party

Accident Date: 27/02/2018

TP Veh Reg No: SHC3060X

Estimate No: ES1890197/YISHUN

Date: 27 Feb 2018

Policy No: D17MTPCVE000676

Veh Reg No: YP2372H

Make/Model: MITSUBISHI CANTER
 FEB21CR3SDEB

Chassis No: FEB21CA20005

Engine No: LTA1601708

Reg. Date: 03/05/2016

Estimate Repair Cost to Vehicle No :YP2372H

Description	U/Price	Quantity	List Price SS	Amount SS
Labour				
29 TOWING	100.00	1 LA	100.00	✓
30 PANEL BEATING	1,800.00	1 LA	1,800.00	1400
31 REMOVE & REFIX CABIN ASSY,REPAIR CABIN MOUNTING BRACKETS,STRAIGHTEN FRT CHASSIS & REALIGN CABIN POSITION	1,000.00	1 LA	1,000.00	800
32 PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR,FRT RH WHEEL ARP PANEL,FRT PANEL,FRT RH FLOOR BOARD PANEL,FRT BUMPER,CORNAL PANEL & ALL AFFECTED AREAS	1,200.00	1 LA	1,200.00	1000
33 REMOVE & REFIX DASH BOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
34 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
35 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	80
36 REMOVE & REFIX SEAT,CARPET,TOP ROOF LINING,ETC	120.00	1 LA	120.00	✓
37 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
38 RUSTPROOFING	60.00	1 LA	60.00	✓
			4,790.00	4,790.00

Total SS 15,523.16

Add GST @ 7% 1,086.62

Total Amount Payable SS 16,609.78

LKK Auto Consultants hence notify
 the Repairer as follows:

- To resurvey only - ongoing sampling
- To disassemble parts for resurvey
- Paintwork to be done on "no-deduct" basis
- To be done on "no-deduct" basis
- No deduction for paintwork
- Supply of materials to be provided and
- To be done on "no-deduct" basis

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Accepted by
 Signature
 Date

16131.04

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

YP2372H
SUPP 1

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/FC/WL

Claim Type: Third Party

Accident Date: 27/02/2018

TP Veh Reg No: SHC3060X

Estimate No: ES1890197/YISHUN

Date: 02 Mar 2018

Policy No: D17MTPCVE000676

Veh Reg No: YP2372H

Make/Model: MITSUBISHI CANTER
FEB21CR3SDEB

Chassis No: FEB21CA20005

Engine No: LTA1601708

Reg. Date: 03/05/2016

Estimate Repair Cost to Vehicle No :YP2372H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 FRONT RH DOOR INNER AIR SCROP GRILLE	49.80	1 PC	CM 49.80	✓
2 AIR VACCUM TANK	760.70	1 PC	02 760.70	✓
			810.50	
		Less 25%	202.63	607.88
Total				S\$ 607.88
GST Amount				S\$ 42.55
Total Amount Payable				S\$ 650.43

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003893/Kqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3060X	Veh. Inspected	YP 2372H	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001673MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	28/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FEB21CA20005	Colour	WHITE	
Odometer	33789	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2018	Inspection Date	01/03/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2372H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BENT	1,010.33	1,010.33
1	FRONT BUMPER RH BRACKET	DISTORTED	196.24	196.24
1	FRONT BUMPER RH SIDE PAD	MISSING	417.72	417.72
1	RH HEADLAMP	CRACKED	501.41	501.41
1	HEADLAMP LOWER RUBBER	MISSING	32.15	32.15
1	RH SIGNAL LAMP	BROKEN	266.36	266.36
1	FRONT GRILLE	MTG DISTORTED	1,105.63	1,105.63
1	FRONT RH STEP TRAY	CRACKED	613.20	613.20
1	FRONT RH WINDSCREEN PILLAR	BENT	1,533.24	1,533.24
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	492.50	492.50
1	FRONT RH DOOR	BENT	2,102.66	2,102.66
1	FRONT RH DOOR TOP HINGE	BENT	162.54	162.54
1	FRONT RH DOOR BOTTOM HINGE	BENT	162.54	162.54
1	FRONT RH DOOR CHECKER	DISTORTED	83.51	83.51
1	FRONT RH DOOR INNER RUBBER	DISTORTED / DENTED	424.99	424.99
1	FRONT RH DOOR INNER LOCK	DENTED	389.21	389.21
1	FRONT RH DOOR INNER BOARD	BUCKLED	638.89	638.89
1	FRONT RH DOOR GLASS	SERVICEABLE	444.49	-
1	FRONT RH DOOR GLASS REGULATOR	BENT	1,684.91	1,684.91
1	FRONT RH DOOR GLASS CHANNEL	SERVICEABLE	279.17	-
1	FRONT RH DOOR FRAME CHANNEL	DISTORTED / DENTED	424.99	424.99
1	FRONT RH DOOR STICKER (DUONIC)	NECESSARY	61.28	61.28
1	FRONT RH DOOR LOWER RUBBER	CUT	82.31	82.31
1	FRONT RH WHEEL ARP PANEL	BUCKLED	320.00	320.00
1	FRONT RH WHEEL ARP TOP GARNISH	BUCKLED	150.80	150.80
1	FRONT RH WHEEL REAR MUD GUARD	CRACKED	139.19	139.19
1	FRONT WIPER TANK	DENTED	190.62	190.62
1	FRONT RH DOOR INNER AIR SCROP GRILLE (ADDITIONAL)	CRACKED	49.80	49.80
1	AIR VACCUM TANK (ADDITIONAL)	DENTED	760.70	760.70

Report Ref No. CS/FCI18003893/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-3,680.34	-3,499.43
			11,041.04	10,498.29
	SPECIAL NETT ITEMS			
1	REAR RH WHEEL FRT MUDGUARD (SN)	BENT	300.00	300.00
			300.00	300.00
	LABOUR			
	TOWING.		100.00	100.00
	PANEL BEATING.		1,800.00	1,400.00
	REMOVE & REFIX CABIN ASSY,REPAIR CABIN MOUNTING BRACKETS,STRAIGHTEN FRT CHASSIS & REALIGN CABIN POSITION.		1,000.00	600.00
	PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR,FRT RH WHEEL ARP PANEL,FRT PANEL,FRT RH FLOOR BOARD PANEL,FRT BUMPER,CORNAL PANEL & ALL AFFECTED AREAS.		1,200.00	1,000.00
	REMOVE & REFIX DASH BOARD,METER ASSY & CHECK WIRING.		250.00	250.00
	REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS.		100.00	100.00
	REMOVE AND REFIX FRONT WINDSCREEN GLASS.		100.00	80.00
	REMOVE & REFIX SEAT,CARPET, TOP ROOF LINING,ETC.		120.00	120.00
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		60.00	60.00
	RUSTPROOFING.		60.00	60.00
			4,790.00	3,770.00
	GRAND TOTAL		16,131.04	14,568.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,650.00

Report Ref No. CS/FC18003893/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.