



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 833B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH WING MIRROR	CUT	2,840.70	2,079.00
1	RH WING MIRROR COVER	CRACKED	5,781.40	5,781.40
1	RH WING MIRROR SIGNAL LAMP	CUT	958.20	156.70
	LESS 5% DISCOUNT		-479.02	-400.86
			9,101.28	7,616.24
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
<u>LABOUR</u>				
	LABOUR FOR REPAIR ON AFFECTED AREA.		500.00	200.00
	SPRAY PAINT ON AFFECTED AREA.	NOT NECESSARY	300.00	-
	CHECK WIRING.		50.00	30.00
			850.00	230.00
GRAND TOTAL			10,001.28	7,866.24
RECOMMENDED COST OF REPAIRS				7,866.25

Report Ref No. CC6/EQ118003903/T1jb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.