

Repair Estimate

28 February 2018

MSIG INSURANCE PTE LTD

Attention: Motor Claims Department

Without Prejudice

Dear Sirs,

RE: VEHICLE NO.: SKN2595H
CHASSIS NO.: WVWZZZ16ZEM026514
MODEL: JETTA A6 1.4 TSI DSG 90KW TL

After inspection of the above vehicle, the front chassis member, both side pillar alignment was found damaged as such the vehicle has to be rectified on the celette bench.

Cost of repair for the vehicle is approximately above \$70K before GST.

The vehicle sustained badly damaged, side pillar alignment is out, both air bag deployed, dash board deformed, front wind screen glass and body frame badly affected.

Please conduct the survey at no:17 Tuas Ave 9, Singapore 639197

Please advise us accordingly.

NB. THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIAL AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully .

Germaine Ong
9236-1588

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin. 97495749
Rarent
Ex \$500
28/2/18 R 3pm