

ASS. REC. BY:

REF: C8/ICS18003927/Kvb02 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

Mubmin

From (Person): Janice Goh

of

ICS

Date/Time: 23022018 3.10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G8D 8838C

Insured:

SHJ 3127M

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Blk 1075 Yishun Ind Park A #01-374

Policy No:

Claim No:

DMPC1800062H

Sum Insured:

Excess:

Make of Veh:

D.O.A

73-022018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	G8D 8838C - X
	SHJ 3127M - X

ASS. REC. BY:

REF: 1051

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBD8838C Yr Regn: 10, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS NV350 c.c. 2488

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 75770 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIMC 2 E26 7000 2645

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NIT / S/Rim / STD A/Rim or

Tyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 23/2/18

Rear

R/Bal. 4 mm

L/Bal. 4 mm

D.O.I. 24/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NIS FR LUK

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/2 The pass to Customer, car not ready

12/4 11:30 896501 Car frame & side (Red 4756.20, 331)

RECEIVED 13 APR 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 13/4 ypit

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

merimen

9650p

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

350

10

360

Survey Department Check List (Case Handler)

Reference No.: CS/CS 18003927/Kvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 13/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS/ICS18003927/Kvb		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 28-02-2018		
		Code : ICS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGJ 3127M	Veh. Inspected	GBD 8388C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JANICE GOH	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/02/2018	Inspection Date	24/02/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Veron Chen (LKKAUTO)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Friday, 13 April 2018 1:44 PM
To: Veron Chen (LKKAUTO); ECICS Claims
Cc: SUR
Subject: RE: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Dear Veron

Our claim no DMPC1800062H.
Thank you!

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 13 April, 2018 12:34 PM
To: ECICS Claims; Janice Goh Siew Geok (ECICS, Claims)
Cc: SUR
Subject: RE: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Dear Janice

Please provides us claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 26 February 2018 5:17 PM
To: 'ECICS Claims' <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ECICS Claims [<mailto:claims@ecics.com.sg>]

Sent: Friday, 23 February 2018 3:10 PM

To: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>; assignments <assignments@lkkauto.com>

Cc: ECICS Claims <claims@ecics.com.sg>

Subject: RE: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Without Prejudice

Hi June

Happy New Year!!

Thank you for your email.
We will appoint LKK for the TP PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]

Sent: Friday, 23 February, 2018 2:55 PM

To: ECICS Claims

Subject: Re: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Hi Janice,

HAPPY NEW YEAR.

Our selection as below :-

1. LKK

Pls assist to arrange asap.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: ECICS Claims
Sent: Friday, February 23, 2018 2:54 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) ; ECICS Claims
Subject: RE: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Without prejudice

Dear June

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]
Sent: Friday, 23 February, 2018 2:34 PM
To: ECICS Claims
Subject: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Dear Sir,

OUR CLIENT – GBD8838C
DOA : 23/2/18 @11.45am
YR INSURED : SGJ3127M

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Friday, 23 February, 2018 3:10 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June); assignments
Cc: ECICS Claims
Subject: RE: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Without Prejudice

Hi June

Happy New Year!!

Thank you for your email.
We will appoint LKK for the TP PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Friday, 23 February, 2018 2:55 PM
To: ECICS Claims
Subject: Re: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Hi Janice,

HAPPY NEW YEAR.

Our selection as below :-

1. LKK

Pls assist to arrange asap.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: ECICS Claims

Sent: Friday, February 23, 2018 2:54 PM

To: Cheng Hoe Motor Pte Ltd (Yishun-June) ; ECICS Claims

Subject: RE: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Without prejudice

Dear June

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]

Sent: Friday, 23 February, 2018 2:34 PM

To: ECICS Claims

Subject: Repair Survey (Single Joint Expert) - GBD8838C, doa 23/2/18 (Yr insured SGJ3127M)

Dear Sir,

OUR CLIENT – GBD8838C

DOA : 23/2/18 @11.45am

YR INSURED : SGJ3127M

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

GBD 8838C
TP/ECICS

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 8533L

Vehicle Details

Vehicle No.: GBD8838C

Vehicle to be Exported: Yes

Intended De-registration
Date: 23 Feb 2018

Vehicle Make: NISSAN

Vehicle Model: NV350 PANEL VAN 2.5
5MT 5DR EURO V

Primary Colour: Black

Manufacturing Year: 2014

Engine No.: YD25352918A

Chassis No.: JN1MC2E26Z0002645

Maximum Power Output: -

Open Market Value: \$23,804.00

Original Registration Date: 27 Oct 2014

First Registration Date: 27 Oct 2014

Transfer Count: 0

Actual ARF Paid: \$1,191.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$49,889.00

COE Rebate Amount: \$33,299.00

Total Rebate Amount: \$33,299.00

The information contained herein is correct as at 23 Feb 2018

OK

TP-66157 24/2/18

~~buy~~ / ~~4~~ / ~~17~~

430 8838 C → Pg 1/2

1 pc for bumper cm \$514.70N ✓
_____ reinforcement ? \$630N ✓
_____ 4u side reliner cm \$147N ✓
_____ ~~☆☆~~ 4u fog lamp cm \$327.305N ✓
_____ 4u fog lamp garnish 2.1N \$130N ✓
6p _____ clips 2.1N \$3.5N x 6 = \$21N ✓

1 pc 4u head lamp 3.1N \$403N ✓
_____ panel ? X

1 pc for 4u cornal panel 3.1N \$525N ✓
1 pc for 4u door 3.1N \$1015N ✓
_____ top hinge 3.1N \$61.70N ✓
_____ bottom hinge 3.1N \$61.70N ✓
_____ inner lock 3.1N \$200.80N ✓
_____ inner rubber ? \$106.30N ✓
_____ glass regulator 3.1N \$147.90N ✓
_____ glass regulator motor 3.1N \$524.40N ✓
_____ glass channel ? \$84.70N ✓
_____ inner board ? \$569.70N ✓
_____ checker 3.1N \$52.30N ✓
_____ side mirror 3.1N \$520.30N ✓
_____ frame rubber ? \$127.40N ✓
_____ specker ? \$102.90N ✓

1 m for the Gap 8838 C. $\rightarrow P_g 2/2$
 1 m for the Slap Panel \rightarrow \$129.10 N ✓
 1 m for the Slap Tray garnish crs \$99.20 N ✓
 ** 1 m for upper tank ? \$222.10 SN ✓
 1 m for the upscreen pillar Br \$1033.20 N ✓
 1 m for the wheel arch panel \rightarrow X
 1 m for the upscreen pillar inner cr \$437.30 N ✓
 1 m for the upscreen moulding \rightarrow X
 ** 1 m for the wheel & mud flap. \rightarrow \$123.20 SN ✓
 1 m dash board ? \$1103.90 N ✓
 1 m for the top arm ? \$273.70 N ✓
 ** 1 m for the knuckle arm ? \$337.20 SN ✓
 ** 1 m for the wheel bearing ? \$195.60 SN ✓
 1 m dash board reinforcement \$395.30 N ✓
 1 m glove box inner housing \$209 N ✓

** 1 m for the upscreen gun \$80 SN ✓
 ** 1 m for the door by striker \$70 SN ✓

GBD 8838 C.

- ① R & R for w/ screen glass \$100 ✓
- ② R & R air-con, check, vacuum and refill gas \$100 ✓
- ③ R & R dash board, meter assy ~~ass~~, repair wiring harness and check wiring \$250 ✓
- ④ R & R for bumper assy, fog lamps, for grille, for corner panel, head lamps, for LH door and attachment, to straighten, cutting welding and renew for LH w/ screen pillar, for LH wheel arch panel, step panel, to R & R for LH door rear pillar, for LH floor board panel, and realign the same 1500
\$1800 ✓

for panel
- ⑤ Rusty & respray on LH sliding door, for LH door, door pillar, for LH w/ screen pillar, for panel, for LH corner panel, for LH wheel arch panel, step tray, for LH step panel, for bumper, reinforcement, side mirror and all affected area \$1500 ✓
1400

GRB 8838 C.

⑥ R & R for the seat, carpet, garnish,
top roof lining, etc

\$120 ✓

⑦ To R & R for the under carriage and check steering rack & Boston

⑦ To ~~check for the under carriage~~

\$200 ?

~~and~~ conduct computer wheel align

\$60 ✓

⑧ Rustproofing

\$80 ✓

~~Park \$7918.30 N~~
~~dash board~~

Park \$9626.50 N
less 10% $\frac{962.65}{\$8663.85}$

\$1265.40 N ✓

Labour \$4220 ✓

\$14,149.25

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBD8838C

TP/ECICS

M/S: ECICS LIMITED
 7 TEMASEK BOULEVARD #10-01
 SUNTEC TOWER ONE
 (S)038987
 TEL: 63374779
 ATTN: Motor Claim Department

Estimate No: ES1890177
 Date: 24 Feb 2018
 Policy No: D17MTPCVE002794
 Veh Reg No: GBD8838C
 Make/Model: NISSAN NV350 PANEL
 VAN 2.5 5MT 5DR EURO
 V

WS Ref: TP/ECICS/YS
 Claim Type: Third Party
 Accident Date: 23/02/2018
 TP Veh Reg No: SGJ3127M

Chassis No: JN1MC2E26Z0002645
 Engine No: YD25352918A
 Reg. Date: 27/10/2014

Not Authorized

Resony B4 panel

11 Sep @ 96501

12 Jan

Estimate Repair Cost to Vehicle No :GBD8838C

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT BUMPER	514.70	1 PC	514.70	✓
2 FRONT BUMPER REINFORCEMENT	630.00	1 PC	630.00	✓
3 FRONT BUMPER LH SIDE RETAINER	147.00	1 PC	147.00	✓
4 FRONT BUMPER LH FOG LAMP GARNISH	130.00	1 PCS	130.00	✓
5 FRONT BUMPER CLIPS	3.50	6 PC	21.00	✓
6 LH HEAD LAMP	403.00	1 PCS	403.00	✓
7 FRONT LH CORNAL PANEL	525.00	1 PC	525.00	✓
8 FRONT LH DOOR	1,015.00	1 PC	1,015.00	✓
9 FRONTDOOR LH TOP HINGE	61.70	1 PCS	61.70	✓
10 FRONT LH DOOR BOTTOM HINGE	61.70	1 PCS	61.70	✓
11 FRONT LH DOOR INNER LOCK	200.80	1 PCS	200.80	✓
12 FRONT LH DOOR INNER RUBBER	106.30	1 PCS	106.30	✓
13 FRONT LH DOOR GLASS REGULATOR	147.90	1 PCS	147.90	✓
14 FRONT LH DOOR GLASS REGULATOR MOTOR	524.40	1 PCS	524.40	✓
15 FRONT LH DOOR GLASS CHANNEL	84.70	1 PCS	84.70	✓
16 FRONT LH DOOR INNER BOARD	569.70	1 PCS	569.70	✓
17 FRONT LH DOOR CHECKER	52.30	1 PCS	52.30	✓
18 FRONT LH DOOR SIDE MIRROR	520.30	1 PCS	520.30	✓
19 FRONT LH DOOR FRAME RUBBER	127.40	1 PCS	127.40	✓
20 FRONT LH DOOR SPECKER	102.90	1 PCS	102.90	✓
21 FRONT STEP PANEL	129.10	1 PCS	129.10	✓
22 FRONT LH STEP TRAY GARNISH	99.20	1 PC	99.20	✓
23 FRONT LH WINDSCREEN PILLAR	1,033.20	1 PC	1,033.20	✓
24 FRONT LH WINDSCREEN PILLAR INNER	437.30	1 PC	437.30	✓
25 DASHBOARD	1,103.90	1 PC	1,103.90	✓
26 FRONT LH TOP ARM	273.70	1 PCS	273.70	✓
27 DASHBOARD REINFORCEMENT	395.30	1 PC	395.30	✓
28 GLOVE BOX INNER HOUSING	209.00	1 PCS	209.00	✓
			9,626.50	
		Less 10%	962.65	8,663.85
Special Net				
29 FRONT BUMPER LH FOG LAMP	327.30	1 PC	327.30	✓
30 FRONT WIPER TANK	222.10	1 PCS	222.10	✓
31 FRONT LH WHEEL FRONT MUD FLAP	123.20	1 PCS	123.20	✓
32 FRONT LH KNUCKLE ARM	337.20	1 PC	337.20	✓

50653.15

msm

msm

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : ECICS LIMITED
 7 TEMASEK BOULEVARD #10-01
 ES1890177/YISHUN
 SUNTEC TOWER ONE
 (S)038987
 TEL: 63374779
 ATTN: Motor Claim Department

Estimate No: ES1890177
 Date: 24 Feb 2018
 Policy No: D17MTPCVE002794
 Veh Reg No: GBD8838C
 Make/Model: NISSAN NV350 PANEL
 VAN 2.5 5MT 5DR EURO
 V
 Chassis No: JN1MC2E26Z0002645
 Engine No: YD25352918A
 Reg. Date: 27/10/2014

WS Ref: TP/ECICS/YS
 Claim Type: Third Party
 Accident Date: 23/02/2018
 TP Veh Reg No: SGJ3127M

Estimate Repair Cost to Vehicle No :GBD8838C

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
33 FRONT LH WHEEL BEARING	195.60	1 PCS	195.60	SS
34 FRONT WINDSCREEN GUM	40.00	1 PC	40.00	SS
35 FRONT LH DOOR COY STICKER	20.00	1 PCS	20.00	SS
Labour			1,265.40	1,265.40
36 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
37 REMOVE AND REFIX AIR-CON, CHECK VACUUM AND REFILL GAS	100.00	1 LA	100.00	✓
38 REMOVE AND REFIX DASH BOARD, METER ASSY, REPAIR WIRING HANES AND CHECK WIRING	250.00	1 LA	250.00	✓
39 REMOVE AND REFIX FRONT BUMPER ASSY, FOG LAMP, FRONT GRILLE, FRONT CORNAL PANEL, HEAD LAMP, FRONT LH DOOR AND ATTACHMENT, TO STRIAGHTEN, CUTTING, WELDING AND RENEW FRONT LH WINDSCREEN PILLAR, FRONT LH WHEEL ARP PANEL, STEP PANEL, TO KNOCK AND REPAIR FRONT LH DOOR REAR PILLAR, FRONT LH FLLOR BOARD PANEL, FRONT PANEL AND REALIGN THE SAME.	1,800.00	1 LA	1,800.00	1500 ✓
40 PUTTY AND RESPRAY ON LH SLIDING DOOR, FRONT LH DOOR, DOOR PILLAR, FRONT LH WINDSCREEN PILLAR, FRONT PANEL, FRONT LH CORNAL PANEL, FRONT LH WHEEL AR PANEL, STEP TRAY, FRONT LH STEP PANEL, FRONT BUMPER, REINFORCEMENT, SIDE MIRROR AND ALL AFFECTED AREA	1,500.00	1 LA	1,500.00	1400 ✓
41 REMOVE AND REFIX FRONT LH SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC	120.00	1 LA	120.00	✓
42 TO REMOVE AND REFIX FRONT LH UNDER CARRIAGE AND CHECK STEERING RACK AND PINION	200.00	1 LA	200.00	140 ✓
43 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
44 RUSTPROOFING	90.00	1 LA	90.00	✓
			Total	4,220.00
			Add GST @ 7%	SS 14,149.25
			Total Amount Payable	990.45
				SS 15,139.70

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier: any item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

14,406.20

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18003927/KVBN2

Date: 17/04/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBD8838C	Insured Vehicle No :	SGJ3127M
Date of Loss:	23/02/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD8838C	Engine No:	YD25352918A
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0002645
Reg. Date:	27/10/2014 (Man. Year: 2014)	Odometer:	75770 km
Colour:	Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,186.20	8,297.51	1,888.69	18.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	3,760.00	460.00	10.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,406.20	12,057.51	2,348.69	16.30
Approved Total (Overridden) (S\$)		9,650.00		
(S\$)	14,406.20	9,650.00	4,756.20	33.01
+ GST 7.00/7.00% (S\$)	1,008.43	675.50	332.93	33.01
Nett Amount (S\$)	15,414.63	10,325.50	5,089.13	33.01

INSPECTION

Date of Assignment: 23/02/2018

Date Inspected: 24/02/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Apr 2018)
Parts:	N/A NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8838C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	514.70 FN	*514.70 FN
2	1		*FRONT BUMPER REINFORCEMENT	Repair	630.00 FN	*- FN
3	1		*FRONT BUMPER LH SIDE RETAINER	Cracked	147.00 FN	*147.00 FN
4	1		*FRONT BUMPER LH FOG LAMP GARNISH	Missing	130.00 FN	*130.00 FN
5	6		*FRONT BUMPER CLIPS	Necessary	21.00 FN	*21.00 FN
6	1		*LH HEAD LAMP	Broken	403.00 FN	*403.00 FN
7	1		*FRONT LH CORNAL PANEL	Bent	525.00 FN	*525.00 FN
8	1		*FRONT LH DOOR	Bent	1,015.00 FN	*1,015.00 FN
9	1		*FRONT DOOR LH TOP HINGE	Bent	61.70 FN	*61.70 FN
10	1		*FRONT LH DOOR BOTTOM HINGE	Bent	61.70 FN	*61.70 FN
11	1		*FRONT LH DOOR INNER LOCK	Jammed	200.80 FN	*200.80 FN
12	1		*FRONT LH DOOR GLASS REGULATOR	Bent	147.90 FN	*147.90 FN
13	1		*FRONT LH DOOR GLASS REGULATOR MOTOR	Jammed	524.40 FN	*524.40 FN
14	1		*FRONT LH DOOR GLASS CHANNEL	Serviceable	84.70 FN	*- FN
15	1		*FRONT LH DOOR INNER BOARD	Dented	569.70 FN	*569.70 FN
16	1		*FRONT LH DOOR CHECKER	Bent	52.30 FN	*52.30 FN
17	1		*FRONT LH DOOR SIDE MIRROR	Cut	520.30 FN	*520.30 FN
18	1		*FRONT LH DOOR FRAME RUBBER	Serviceable	127.40 FN	*- FN
19	1		*FRONT LH DOOR SPEAKER	Serviceable	102.90 FN	*- FN
20	1		*FRONT STEP PANEL	Bent	129.10 FN	*129.10 FN
21	1		*FRONT LH STEP TRAY GARNISH	Cracked	99.20 FN	*99.20 FN
22	1		*FRONT LH WINDSCREEN PILLAR	Bent	1,033.20 FN	*1,033.20 FN
23	1		*FRONT LH WINDSCREEN PILLAR INNER	Repair	437.30 FN	*- FN
24	1		*DASHBOARD	Mtg Cracked	1,103.90 FN	*1,103.90 FN
25	1		*FRONT LH TOP ARM	Serviceable	273.70 FN	*- FN
26	1		*DASHBOARD REINFORCEMENT	Repair	395.30 FN	*- FN
27	1		*GLOVE BOX INNER HOUSING	Mtg Cracked	209.00 FN	*209.00 FN
28	1		*FRONT LH DOOR INNER RUBBER (50%)	Cut	95.67 FS	*53.15 FS
29	1		*FRONT BUMPER LH FOG LAMP	Cracked	327.30 FS	*327.30 FS
30	1		*FRONT WIPER TANK	Dented	222.10 FS	*222.10 FS
31	1		*FRONT LH WHEEL FRONT MUD FLAP	Cut	123.20 FS	*123.20 FS
32	1		*FRONT LH KNUCKLE ARM	Bent	337.20 FS	*337.20 FS
33	1		*FRONT LH WHEEL BEARING	Necessary	195.60 FS	*195.60 FS
34	1		*FRONT WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
35	1		*FRONT LH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
36	1		*FRONT LH WHEEL ARP TOP GARNISH	Deformed	162.60 FN	*162.60 FN
37	1		*FRONT LH FOG LAMP GARNISH	Cracked	122.90 FN	*122.90 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	11,166.77	9,072.95
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	980.57	775.44
Total Parts (\$\$)	10,186.20	8,297.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE AND REFIX AIR-CON,CHECK VACUUM AND REFILL GAS	New	100.00	100.00
3	REMOVE AND REFIX DASH BOARD,METER ASSY,REPAIR WIRING HANES AND CHECK WIRING	New	250.00	250.00
4	REMOVE AND REFIX FRONT BUMPER ASSY,FOG LAMP,FRONT GRILLE,FRONT CORNAL PANEL,HEAD LAMP,FRONT LH DOOR AND ATTACHMENT.TO STRAIGHTEN,CUTTING,WELDING AND RENEW FRONT LH WINDSCREEN PILLAR,FRONT LH WHEEL ARP PANEL,STEP PANEL.TO KNOCK AND REPAIR FRONT LH DOOR REAR PILLAR,FRONT LH FLOOR BOARD PANEL,FRONT PANEL AND REALIGN THE SAME	New	1,800.00	1,500.00
5	PUTTY AND RESPRAY ON LH SLIDING DOOR,FRONT LH DOOR,DOOR PILLAR,FRONT LH WINDSCREEN PILLAR,FRONT PANEL,FRONT LH CORNAL PANEL,FRONT LH WHEEL AR PANEL,STEP TRAY,FRONT LH STEP PANEL,FRONT BUMPER REINFORCEMENT,SIDE MIRROR AND ALL AFFECTED AREA	New	1,500.00	1,400.00
6	REMOVE AND REFIX FRONT LH SEAT,CARPET,GARNISH,TOP ROOF LINING ETC	New	120.00	120.00
7	TO REMOVE AND REFIX FRONT LH UNDER CARRIAGE AND CHECK STEERING RACK AND PINION	New	200.00	140.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
9	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (\$\$)			4,220.00	3,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >