



Your Ref: C0375644

Date: 07th March 2018

Our Ref: CS3/AXA16005512/Gqbs2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

Attn: Wancong

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YM 5966R

INSURED VEHICLE: SKA 6103L

ACCIDENT DATE: 10/03/2016

We thank you for your instruction on 26/02/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YM 5966R from M/s PAR Automotive Consultancy.
- b) Final Repair Bill of YM 5966R from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles YM 5966R.
- d) Colour damaged vehicle photographs of YM 5966R.

Pre-Repair Inspection Date : 11/04/2016 at M/s Twincar Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: YM 5966R
Make & Model	: Hino FD8JPKA
Year of Registration	: 2007
Chassis Number	: FD8JPK10015
Engine Capacity	: 7684 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.