

INS. CASE OWNER

CC 3/EQ11300

LKK:  
IDAC:

## ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

(V/L: YES / NO Insured Liability:

% Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

## FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver's Own Vehicle Number:

Insurance Company:

## STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA:

Medical Bill:

Approval Email:

Payment Breakdown Form:

Others:

17/1/14 3:19

called OI spoke to Mr Mohammad Taw. Inform about the claim. Confirm the accident. OI said he was his from behind by TP. He did not change lane. There no photo. no witness. Advise him we will proceed to settle the claim and aware of wa will be affected.

Letter out / email to w/p.

27/4/14

Richard (ECU) informed to settle 50% not pending finalisation  
PR  
Insurance agreed 50%.

24-8-15

FOR APPROVAL.

NO DEVELOPMENT FROM IT.

## FINAL SETTLEMENT

Date: 15-4-18 Confirm with

Repair Cost:

SS

17,280.00 Final Liability

100

% (Agreed / Assessed)

BOLA S/N No.:

NIV

Loss of Rental:

SS

1,829.7015 days

121.98

If NO or B 28, Ass. Lia:

Loss of Use:

SS

(S x days)

Report Format:

Disbursement:

SS

-6.XX

Total:

SS

19,116.20 Global Sum:

SS

19K

WP - 1900.XX

OI CHARGED FOR INCON-DIVING

\$19,000.XX - TRANS-CAB SERVICES PTE LTD

COPY 18/4/18

NO b/m f. FOR






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI14000597/Ksa3	
22 GEMMILL LANESINGAPORE 069257		Date : 10-01-2014	
		Code : EQI	
<b>Policy Particulars :- THIRD PARTY CLAIM</b>			
1.			
Insured Veh.	XB 3787Z	Veh. Inspected	SHB 7609T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/01/2014
<b>Vehicle Particulars &amp; Condition</b>			
2.			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>Conditions of Tyres</b>			
3.			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>Description of Damages</b>			
4.			
<b>General Information</b>			
5.			
Accident Date	06/01/2014	Inspection Date	09/01/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		
<b>Remarks</b>			
5a.			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/01/2014 15:09
Date Of Accident	06/01/2014 03:30
Exact Location Of Accident	TPE TO SLE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7609T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K

### Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 DSL TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi

### Insurance Company

Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/02
Cover Note Number	

### Driver

Name of Driver	NEO YEE HWANG (LIANG YOUHUA)
NRIC No	S7521413H
Date Of Birth	24/07/1975
Occupation	Outdoor
Date Of Driving Pass	27/10/1997
Driving Experience	16 Years And 2 Months
Gender	Male
Mobile Number	(Local) +65-96722444
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	BLK 233 BUKIT BATOK EAST AVE 5 #11-59
Postcode	650233

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	13/01/2014 10:19
Date Of Accident	06/01/2014 02:45
Exact Location Of Accident	TPE TOWARDS SLE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XB3787Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SAM LAIN EQUIPMENT SERVICES PTE LTD
Co Reg No	-
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	CKB450BTNT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Reporting Only
Vehicle Category	Commercial Vehicle
<b>Insurance Company</b>	
Name of Insurance Company	EQ Insurance Company Ltd
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	DMCPHQ14-000034
Cover Note Number	08/01/13 - 07/01/14
<b>Driver</b>	
Name of Driver	ZAIHAN BIN MOHAMED ZAIN
NRIC No	S7932839A
Date Of Birth	27/10/1979
Occupation	Outdoor
Date Of Driving Pass	03/02/2006
Driving Experience	7 Years And 11 Months
Gender	Male
Mobile Number	(Local) +65-92332325
Fax Number	
Contact Number	Office-65677601
EMail Address	NOEMAIL
Address	BLK 283 YISHUN AVE 6 #08-146
Postcode	760283
Was driver an employee of the Insured's Company	Yes

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7609T - EQ**

Andrea

*Not Notionel*  
*613mg @ 16.15ch*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHB 7609T - Andrea**  
**KL1LA69RJBB075037\***  
**CHEVROLET**  
**EPICA 2.0**  
**06.01.2014**  
**EQ**

**PART**

**LIST**

1	1	Front Bumper	\$	Tn 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	R 295.25 X
3	1	Front Bumper Lower Absorber	\$	Sn 180.00 X
4	1	Front Bumper Lower Grille	\$	Sn 78.00 X
5	1	Front Bumper Retainer RH	\$	Sn 102.00 X
6	1	Front Bumper Retainer LH	\$	cm 102.00 ✓
7	1	Front Bumper Lower Stiffener	\$	R 134.37 X
8	1	Front Headlamp RH	\$	Sn 816.00 X
9	1	Front Headlamp LH	\$	Br 816.00 ✓
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	411 32.40 ✓
11	1	Front Support Panel Assy (Panel A-Frt)	\$	Br 1,222.32 ✓
12	1	Bonnet (Panel A-Hood)	\$	Br 1,250.00 ✓
13	1	Bonnet Centre 'CHEVROLET' Logo Badge	\$	411 144.30 X
14	1	Bonnet Moulding	\$	Sn 257.00 X
15	1	Bonnet Insulator	\$	Sn 84.63 X
16	1	Bonnet hinge RH	\$	R 36.00 X
17	1	Bonnet hinge LH	\$	R 36.00 X
18	1	Bonnet cable	\$	Sn 150.00 X
19	1	Bonnet lock	\$	R 200.00 X
20	1	Bonnet insulator	\$	Sn 400.00 X
21	1	Front Shock Absorber Assy RH	\$	Br 216.17 ✓
22	1	Front Shock Absorber Top Mounting RH	\$	Br 48.32 ✓
23	1	Front Shock Absorber Assy LH	\$	Br 216.17 ✓
24	1	Front Shock Absorber Top Mounting LH	\$	Br 48.32 ✓
25	1	Front Lower Arm RH	\$	Sn 283.00 X
26	1	Front Lower Arm LH	\$	Br 283.00 ✓
27	1	Front Knuckle Arm RH	\$	Br 230.00 ✓
28	1	Front Knuckle Arm LH	\$	Br 230.00 ✓
29	1	Front Stabilizer Bar Link RH	\$	Sn 51.79 X
30	1	Front Stabilizer Bar Link LH	\$	Sn 51.79 X
31	1	Front Stabilizer Bar Bracket LH	\$	0.1 105.75 ✓
32	1	Front Stabilizer Bar Bush LH	\$	Sn 66.00 X
33	1	Front Beam A - Impact LH	\$	R 214.00 X



**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7609T - EQ**

Andrea

34	1	Front Drive Shaft RH (Shaft A-Axle,Frt,RH) ( S- \$)	R 900.00 X
35	1	Front Drive Shaft LH (Shaft A-Axle,Frt,LH) ( L- \$)	Br 900.00 ✓
36	1	Steering Rack End (Spring A-Clock)LH	Br 88.56 ✓
37	1	Steering Tie-Rod End (End -Tie Rod)	Br 67.00 ✓
38	1	W/ Harnes S-I/P FUSE BOX	Cor 1,903.05 ✓
39	1	Cross member	Br 1,030.71 ✓
40	1	Interm Axle Shaft (Centre )	R 241.14 X
41	1	Front Seat Belt RH (Belt A-Frt Seat RH)	Sen 402.50 X
42	1	Front safety belt cover garnish	Sen 125.00 ✓
43	1	Front Seat Belt LH (Belt A-Frt Seat LH)	Sen 402.50 X
44	1	Front safety belt cover garnish	Sen 125.00 X
45	1	Front Fender RH	R 837.60 ✓
46	1	Front Fender LH	R 837.60 ✓
47	1	Front Fender Liner RH	Sen 47.00 X
48	1	Front Fender Liner LH	Tn 47.00 ✓
49	1	Fender Insulation RH	Sen 39.00 X
50	1	Fender Insulation LH	Br 39.00 ✓
51	1	Front Fender RR Bracket RH	R 7.10 X
52	1	Front Fender RR Bracket LH	Br 7.10 ✓
53	1	Front Fender Inner Wheel House Panel LH	Br 1,437.00 ✓
54	1	HORN LH	Sen 159.20 X
55	1	Radiator Grille ( Grille A-Rad )	Sen 367.00 X
56	1	Radiator Assembly ( Radiator A )	Sen 618.00 X
57	1	Aircon Condenser ( Condeser A )	Sen 600.00 X
58	1	Air Intercooler ( Cooler A-Air Charge )	Sen 652.00 X
59	1	Fan Blade ( Fan A-Auxiliary (Diesel) Small )	Sen 536.00 X
60	1	Fan Blade ( Fan A-Eng Cool (Diesel) Big )	Sen 634.00 X
61	1	Fuse Box	Br 716.00 X
62	1	Air Cleaner Assembly (Cleaner A-Air)	Br 112.00 X
63	1	Air intake resonator (beside fender)	CM 20.01 ✓
64	1	Air intake resonator hose (bottom)	Sen 60.90 X
65	1	Air intake resonator tank top bracket	R 45.00 ✓
66	1	Resonator A-A/CL	Sen 37.00 X
67	1	Engine Splash Cover RH (Cover A-Engine)	Sen 168.00 X
68	1	Engine Splash Cover LH (Cover A-Engine)	Sen 168.00 X
69	1	Front Seat Belt RH (Belt A-Frt Seat RH)	Sen 402.50 X
70	1	Front safety belt cover garnish	Sen 125.00 X
71	1	Front Seat Belt LH (Belt A-Frt Seat LH)	Sen 402.50 X
72	1	Front safety belt cover garnish	Sen 125.00 X
73	1	Front Door RH (Panel A-Frt DR RH)	Br 1,133.00 ✓
74	1	Front Door Hinge Upper RH	R 35.00 X
75	1	Front Door Hinge Lower RH	R 35.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7609T - EQ**

**Andrea**

76	1	Front Door Weatherstrip RH	\$	38.79 ✓
77	1	Front Door Check / Arrestor RH	\$	19.00 X
78	1	Front Door Pillar Out Panel RH	\$	R 715.00 ✓
79	1	Front Door Pillar Inner Panel RH	\$	R 850.00 X
80	1	Front Door LH (Panel A-Frt DR LH)	\$	R 1,133.00 ✓
81	1	Front Door Outer Moulding LH	\$	Sen 220.00 X
82	1	Front Door Outer Handle LH	\$	Sen 60.00 X
83	1	Front Door Handle Support LH	\$	Sen 40.00 X
84	1	Front Door outer handle inner seal LH	\$	Sen 45.00 ✓
85	1	Front Door outer key lock LH	\$	Sen 25.00 X
86	1	Front Door Hinge Upper LH	\$	R 35.00 ✓
87	1	Front Door Hinge Lower LH	\$	R 35.00 ✓
88	1	Front Door inner lock LH	\$	R 586.00 X
89	1	Front Door Inner Lock Latch LH	\$	R 206.00 X
90	1	Front Door Check / Arrestor LH	\$	Sen 19.00 X
91	1	Front Door Weatherstrip LH	\$	Sen 38.79 X
92	1	Front Door glass channel weatherstrip LH	\$	Sen 160.00 X
93	1	Front Door inner trim board LH	\$	Sen 455.69 X
94	1	Front Door Power Window Motor (Master) Mot	\$	R 284.97 X
95	1	Front Door power window motor switch	\$	Sen 145.00 X
96	1	Front Door Window Regulator Gear LH	\$	R 84.58 ✓
97	1	Front Door Pillar Out Panel LH	\$	R 715.00 X
98	1	Front Door Pillar Inner Panel LH	\$	R 850.00 X
99	1	Front Door Pillar Center Panel LH	\$	R 635.15 X
100	1	Front Side View Mirror RH (Mirror A o/s RH)	\$	Sen 939.00 X
101	1	Front Side Rocker Panel Garnish LH	\$	Mir 236.40 ✓
102	1	Front Side Rocker Panel Outer LH	\$	R 600.00 X
103	1	Front Side Rocker Panel Garnish RH	\$	Sen 236.40 X
104	1	Front Windscreen (Glass A-W/ Shield)	\$	CR 1,304.00 ✓
105	1	Front Windscreen Moulding (Moulding A-W/ Si	\$	Sen 196.00 ✓
106	1	Rear Bumper	\$	R 1,202.00 X
107	1	Rear Fender RH	\$	R 1,145.00 X
108	1	Rear Fender Inner Cowling RH	\$	Sen 298.00 ✓
109	1	Rear Fender Inner Trim RH	\$	Sen 418.44 X
110	1	Rear Door RH	\$	R 1,133.00 ✓
111	1	Rear Door LH	\$	R 1,133.00 X
112	1	Roof top out side panel LH	\$	R 356.85 X

<b>TOTAL</b>	<b>\$</b>	<b>42,811.61</b>
<b>10%</b>	<b>\$</b>	<b>4,281.16</b>
	<b>\$</b>	<b>38,530.45</b>



**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO 201019626G  
**SHB 7609T - EQ**

Andrea

**Specical Nett**

1Set	Front Bumper Fastener Clip	\$	24.00 ✓
1Set	Front Licence Plate With Holder	\$	192.00 X
2	Front windscreen sealant	\$	80.00 40JN
1	Front windscreen inner sponge seal	\$	100.00 30JN
6	Bonnet under weatherstrip seal clips	\$	30.00 ✓
2	Front ERP Sticker	\$	40.00 20JN
1Set	Roof lining Clip	\$	45.00 X
1Set	Bonnet Insulator Clip	\$	40.00 ✓
1Set	Radiator Grille Clip	\$	18.00 X
1Set	Bootlid inner trim board Clip	\$	40.00 X
1Set	Radiator Grille Top Cover Clip	\$	10.00 X
1Set	Front Fender Liner Clip	\$	40.00 ✓
1Set	Engine Splash Cover Clip RH	\$	12.00 X
1Set	Engine Splash Cover Clip LH	\$	12.00 X
1Set	Rear Bumper Fastener Clip	\$	30.00 X
2	Door Sticker "Trans-cab"	\$	120.00 ✓
2	Door Sticker "6555-3333"	\$	120.00 ✓
1Set	Front door inner trim board LH Clip	\$	45.00 ✓
1Set	Front door inner trim board RH Clip	\$	45.00 X
1	Front Tyre RH	\$	360.00 30JN
1	Front Wheel Rim RH	\$	254.00 50JN
1	Front Tyre LH	\$	360.00 20JN
1	Front Wheel Rim LH	\$	254.00 50JN
1	Rear Tyre RH	\$	180.00 X
1	Rear Tyre Rim RH	\$	126.00 X
1	Tyre hub cap RH	\$	35.00 X
2	Hub Cup Rim	\$	70.00 X

**TOTAL \$ 2,682.00**

**TOTAL PARTS \$ 41,212.45**

Panel Beating, Knocking And Straightening  
 The Necessary Portion, Remove And  
 Renewal Of Parts, Adjust And Realign The  
 Same

\$

5,600.00 14JN

To Check Electrical Lighting Concerned.

\$

170.00 40J

To Rust-Proofing Of The Affected Areas.

\$

170.00 ✓

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7609T - EQ**

**Andrea**

Putty And Spray Painting Of The Affected Portion.	\$	5,400.00 <sup>2000</sup>
To Remove And Refit Front W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <sup>1200</sup>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 <sup>2500</sup>
To transfer of door and roof panel fittings and conduct water seepage test.	\$	340.00 <sup>1800</sup>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <sup>1000</sup>
To check steering geometry and computer wheel alignment	\$	220.00 <sup>600</sup>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <sup>400</sup>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<sup>Replaced</sup> 380.00 <sup>X</sup>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	120.00 ✓
To check ABS brake efficiency, final checking and testing.	\$	380.00 <sup>500</sup>
To remove and refit ABS pump relay to enable repair.	\$	<sup>nn</sup> 380.00 <sup>X</sup>
To remove and refit air bag system and reset.	\$	<sup>nn</sup> 480.00 <sup>X</sup>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <sup>1000</sup>

Insurance Company shall be notified  
 of the following:  
 • Unapproved before or after spray painting  
 • To display damaged part(s) during resurvey  
 • All expenses are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**TRANS-CAB AUTO SERVICES PTE LTD**  
NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346  
TEL NO.6287 6666 FAX NO.6366 8862  
CO/GST REG NO 201019626G  
**SHB 7609T - EQ**

Andrea

To replace, refix and top up coolant for  
radiator

\$

170.00 *Scd*

To vacuum, replace, refix and recharge Air  
Intercooler

\$

*Agenda* 170.00 X

Towing Fees.

\$

120.00 *Scd*

\$ 14,740.00

**TOTAL \$ 55,952.45**

**Repair Days**

**20 Days**

*10*

*52912.14*

*22421.86*

TRANS-CAB AUTO SERVICES PTE LTD  
NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346  
TEL NO.6287 6666 FAX NO.6366 8862  
CO/GST REG NO.201019626G  
SHB 7609T - EQ

Shown 50%

Andrea

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

SHB 7609T - Andrea  
KL1LA69RJBB075037\*  
CHEVROLET  
EPICA 2.0  
06.01.2014  
EQ

PART			LIST	
1	1	Gear Box Mounting RH	\$	249.00 x
2	1	Engine Mounting LH	\$	228.00 ✓
3	1	Front Engine Mounting	\$	100.14 x
4	1	Rear Engine Mounting	\$	134.00 x
5	1	W/HARNESS-GEAR BOX	\$	1,645.19 ✓
TOTAL			\$	2,356.33
10%			\$	235.63
			\$	2,120.70



Auto  
Consultants  
Pte Ltd

Company Registration No. 196607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/EQI14000597/Ksa3

Date: 10.01.2014

The Motor Claims Department  
M/s EQ INSURANCE COMPANY LTD  
Attn: Richard

Dear Richard,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHB 7609T**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on  
09.01.2014 at the premises of M/s Trans Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	55,952.45
Revised Estimate Amount	: S\$	16,591.01
"Check" Items Amount	: S\$	9,444.36
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
N/S Front Portion & O/S Body



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 10 days

Yours faithfully,

**KENNETH KONG**  
**Licensed Appraiser**

**Zayer**

**From:** Zayer  
**Sent:** Friday, 17 January, 2014 4:13 PM  
**To:** jasminetan@transcabservices.com.sg  
**Cc:** Sharon Yee  
**Subject:** ACCIDENT INVOLVING XB 3787Z & SHB 7609T ON 06/01/2014  
**Attachments:** statement of XB 3787Z.pdf

Your ref: SHB7609T  
Our ref: CC3/EQ114000597/Ksa3

**WITHOUT PREJUDICE**

Dear Sir / Madam,

**ACCIDENT INVOLVING XB 3787Z & SHB 7609T ON 06/01/2014**

We refer to the above matter.

We are of the opinion that this is a case of conflicting versions. There is no conclusive evidence to substantiate either party's version. Enclosed herewith a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident and we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, kindly forward to us with any evidence (if any) to support your claim.

Kindly take note that case handler in charge is Sharon and she can be contacted at 6749 4274.

“祝你马年鸿运当头，身体健康”

“Wishing you a Happy, Cheerful, and Successful in the Year of the Horse”

Thanks and Best regards,  
Zayer  
LKK Auto Consultants Pte Ltd  
DID: 6749 9635  
Fax: 6741 4108



## Joy Irene (LKK Auto)

---

**From:** Joy Irene (LKK Auto)  
**Sent:** Wednesday, 11 November, 2015 1:45 PM  
**To:** 'Annabel Tan'  
**Cc:** Janet Tan; Olivia Lau; Admin A; Mei Kwan (LKK Auto)  
**Subject:** RE: Accident involving XB3787Z & SHB7609T on 16 Jan 2014

Dear Ms. Annabel,

We refer to our e-mail correspondence below.

To date, we still have not receive TP's letter of demand with all its supporting claim documents.

TP also have not responded to our follow-ups made.

Since there is no development from TP with regards to their TP claim, we will temporarily close this almost one (1) year outstanding file and submit our report to your good-office.

In future, if there is any development from TP, we will update and inform you for our further handling.

Thank you.

Best Regards,

**Joy Irene** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]  
**Sent:** Thursday, 3 September, 2015 5:28 PM  
**To:** Joy Irene (LKK Auto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Mei Kwan (LKK Auto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>  
**Cc:** Precelia Ang <[precelia@lkkauto.com](mailto:precelia@lkkauto.com)>; Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>; Olivia Lau <[olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)>  
**Subject:** RE: Accident involving XB3787Z & SHB7609T on 16 Jan 2014

Hi Joy Irene,

Please proceed to attempt Direct Settlement at 100% in view of OID charged for Inconsiderate Driving.  
Update us thereafter for further instructions if TP still does not respond.

Thank you.

Regards,

## Joy Irene (LKK Auto)

---

**From:** Joy Irene (LKK Auto)  
**Sent:** Wednesday, 11 November, 2015 1:45 PM  
**To:** 'Annabel Tan'  
**Cc:** Janet Tan; Olivia Lau; Admin A; Mei Kwan (LKK Auto)  
**Subject:** RE: Accident involving XB3787Z & SHB7609T on 16 Jan 2014

Dear Ms. Annabel,

We refer to our e-mail correspondence below.

To date, we still have not receive TP's letter of demand with all its supporting claim documents.

TP also have not responded to our follow-ups made.

Since there is no development from TP with regards to their TP claim, we will temporarily close this almost one (1) year outstanding file and submit our report to your good-office.

In future, if there is any development from TP, we will update and inform you for our further handling.

Thank you.

Best Regards,

**Joy Irene** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [jovirene@lkkauto.com](mailto:jovirene@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

---

**From:** Annabel Tan [mailto:[annabel.tan@eqinsurance.com.sg](mailto:annabel.tan@eqinsurance.com.sg)]  
**Sent:** Thursday, 3 September, 2015 5:28 PM  
**To:** Joy Irene (LKK Auto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Mei Kwan (LKK Auto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>  
**Cc:** Precelia Ang <[precelia@lkkauto.com](mailto:precelia@lkkauto.com)>; Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>; Olivia Lau <[olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)>  
**Subject:** RE: Accident involving XB3787Z & SHB7609T on 16 Jan 2014

Hi Joy Irene,

Please proceed to attempt Direct Settlement at 100% in view of OID charged for Inconsiderate Driving.  
Update us thereafter for further instructions if TP still does not respond.

Thank you.

Regards,

---

**From:** Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]  
**Sent:** Tuesday, 1 September, 2015 3:00 PM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Mei Kwan (LKK Auto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>  
**Cc:** Precelia Ang <[precelia@lkkauto.com](mailto:precelia@lkkauto.com)>; Sharon Yee <[sharonyee@lkkauto.com](mailto:sharonyee@lkkauto.com)>; Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>  
**Subject:** Accident involving XB3787Z & SHB7609T on 16 Jan 2014

**OUR REF** : DM14HO00058JT (FILE REVIEW)  
**YOUR REF** : CC3/EQI1400597/KSA3

Dear Mei Kwan,

We refer to the above matter and the last correspondence from our office on 14 January 2014.

Please let us have an update on the file and if there are other correspondence after 14 January 2014, we would appreciate if you could also forward to us for our tracking and file completeness.  
Thank you.

Regards,

**Annabel Tan**  
**Assistant Manager, Claims**

**EQ Insurance Company Limited**  
5 Maxwell Road,  
#17-00 Tower Block,  
MND Complex,  
Singapore 069110

DID: 6496 9115  
Tel: 6223 9433  
Fax: 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

## Mei Kwan (LKKAUTO)

---

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Thursday, 1 March, 2018 11:06 AM  
**To:** yuqing.teo; Joy Irene (LKKAUTO)  
**Cc:** 'Jasmine Tan'; claims@transcab.com.sg; Admin A; CS A Team  
**Subject:** RE: TCS REF: AAD1401-067 - Accident involving XB 3787Z and SHB 7609T on 06.01.14 \*\*\* LKK REF: CC3/EQI14000597/Kja3s2-1  
**Attachments:** AAD 1401-067.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Yu Qing,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

By copy to Joy,

For your information and necessary action please.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** yuqing.teo [mailto:yuqing.teo@transcab.com.sg]  
**Sent:** Thursday, 1 March, 2018 9:16 AM  
**To:** Admin A <admin-a@lkkauto.com>  
**Cc:** 'Jasmine Tan' <jasminetan@transcab.com.sg>; claims@transcab.com.sg  
**Subject:** TCS REF: AAD1401-067 - Accident involving XB 3787Z and SHB 7609T on 06.01.14

Dear Sir/Madam,

We have launched a claim against the owner of XB3768Z. Attached is the LOD for your reference. Original would be sent to you by post.

Thank you.

Best Regards,  
Teo Yu Qing  
Finance Department  
TEL: 6603 1265 Ext.306

\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 19/04/2018

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	XB 3787Z	(Insd Veh)	Your Ref. No. : DM14HO00058/JT
	SHB 7609T	(TP Veh)	Our Ref. No. : CC3/EQI14000597/Kja3s2-1
Date of Accident	6/1/2014		

Liability	100%	
Final Repair Cost	: \$ 17,280.50	(W/GST)
Loss of Income	: \$	days
Rental (If any)	: \$ 1,829.70	days
Others:	: \$ 6.00	
	: \$	
	19,116.20	
Final Settlement Sum	: \$ 19,000.00	(GLOBAL SUM)
Remarks	: PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111	

**Payment Instruction: Payee's Breakdown**

1)	TRANS-CAB AUTO SERVICES PTE LTD	: \$ 19,000.00
		: \$

NUR SHAQILAH

LKK Auto Consultants Pte Ltd



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI14000597/Kja3s2-1

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 19-04-2018



Code : EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 3787Z	Veh. Inspected	SHB 7609T
Policy No.	DMCPHQ14-000034	Coverage (\$)	0.00
Claim No.	DM14HO00058/JT	Excess (\$)	0.00
Assign From		Assign Date	09/01/2014

### 2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB055298	Colour	WHITE / RED
Odometer	191470	Steering	JAMMED
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	3 mm
L/H Front Tyre	195/65R15	WEST LAKE	3 mm
R/H Rear Tyre	195/65R15	FALKEN	8 mm
L/H Rear Tyre	195/65R15	FALKEN	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. THE UNDERCARRIAGE AND BODY STRUCTURE AFFECTED DUE TO COLLISION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	06/01/2014	Inspection Date	09/01/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7609T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT BUMPER	TORN	1,202.00	1,202.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	295.25	-
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	CRACKED	102.00	102.00
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT HEADLAMP RH	SERVICEABLE	816.00	-
1	FRONT HEADLAMP LH	BROKEN	816.00	816.00
1	FRONT BUMPER FOG LAMP OUTER COVER LH	MISSING	32.40	32.40
1	FRONT SUPPORT PANEL ASSY (PANEL A-FRT)	BENT	1,222.32	1,222.32
1	BONNET (PANEL A-HOOD)	BENT	1,250.00	1,250.00
1	BONNET CENTRE 'CHEVROLET' LOGO BADGE	NOT NECESSARY	144.30	-
1	BONNET MOULDING	SERVICEABLE	257.00	-
1	BONNET INSULATOR	SERVICEABLE	84.63	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET CABLE	SERVICEABLE	150.00	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	200.00	-
1	BONNET INSULATOR	SERVICEABLE	400.00	-
1	FRONT SHOCK ABSORBER ASSY RH	BENT	216.17	216.17
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	BENT	48.32	48.32
1	FRONT SHOCK ABSORBER ASSY LH	BENT	216.17	216.17
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	BENT	48.32	48.32
1	FRONT LOWER ARM RH	SERVICEABLE	283.00	-
1	FRONT LOWER ARM LH	BENT	283.00	283.00
1	FRONT KNUCKLE ARM RH	BENT	230.00	230.00

Report Ref No. CC3/EQ14000597/Kja3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT KNUCKLE ARM LH	BENT	230.00	230.00
1	FRONT STABILIZER BAR LINK RH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR LINK LH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR BRACKET LH	DISTORTED	105.75	105.75
1	FRONT STABILIZER BAR BUSH LH	SERVICEABLE	66.00	-
1	FRONT BEAM A-IMPACT LH	TO REPAIR SEE LABOUR	214.00	-
1	FRONT DRIVE SHAFT RH (SHAFT A-AXLE, FRT, RH) (SHORT)	TO REPAIR SEE LABOUR	900.00	-
1	FRONT DRIVE SHAFT LH (SHAFT A-AXLE, FRT, LH) (LONG)	BENT	900.00	900.00
1	STEERING RACK END (SPRING A-CLOCK) LH	BENT	88.56	88.56
1	STEERING TIE-ROD END (END-TIE ROD)	BENT	67.00	67.00
1	CROSS MEMBER	BUCKLED	1,030.71	1,030.71
1	INTERN AXLE SHAFT (CENTRE)	TO REPAIR SEE LABOUR	241.14	-
1	FRONT SEAT BELT RH (BELT A-FRT SEAT RH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT SEAT BELT LH (BELT A-FRT SEAT LH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT FENDER RH	BENT	837.60	837.60
1	FRONT FENDER LH	BENT	837.60	837.60
1	FRONT FENDER LINER RH	SERVICEABLE	47.00	-
1	FRONT FENDER LINER LH	TORN	47.00	47.00
1	FENDER INSULATOR RH	SERVICEABLE	39.00	-
1	FENDER INSULATOR LH	DISTORTED	39.00	39.00
1	FRONT FENDER RR BRACKET RH	TO REPAIR SEE LABOUR	7.10	-
1	FRONT FENDER RR BRACKET LH	BENT	7.10	7.10
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	BENT	1,437.00	1,437.00
1	HORN LH	SERVICEABLE	159.20	-
1	RADIATOR GRILLE (GRILLE A-RAD	SERVICEABLE	367.00	-
1	RADIATOR ASSEMBLY (RADIATOR A)	SERVICEABLE	618.00	-
1	AIRCON CONDENSER (CONDENSER A)	SERVICEABLE	600.00	-
1	AIR INTERCOOLER (COOLER A-AIR CHARGE)	SERVICEABLE	652.00	-

Report Ref No. CC3/EQI14000597/Kja3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FAN BLADE (FAN A-AUXILIARY (DIESEL) SMALL)	SERVICEABLE	536.00	-
1	FAN BLADE (FAN A-ENG COOL (DIESEL) BIG)	SERVICEABLE	634.00	-
1	FUSE BOX	SERVICEABLE	716.00	-
1	AIR CLEANER ASSEMBLY (CLEANER A-AIR)	SERVICEABLE	112.00	-
1	AIR INTAKE RESONATOR (BESIDE FENDER)	CRACKED	20.01	20.01
1	AIR INTAKE RESONATOR HOSE (BOTTOM)	SERVICEABLE	60.90	-
1	AIR INTAKE RESONATOR TANK TOP BRACKET	TO REPAIR SEE LABOUR	45.00	-
1	RESONATOR A-A/CL	SERVICEABLE	37.00	-
1	ENGINE SPLASH COVER RH (COVER A-ENGINE)	SERVICEABLE	168.00	-
1	ENGINE SPLASH COVER LH (COVER A-ENGINE)	SERVICEABLE	168.00	-
1	FRONT SEAT BELT RH (BELT A-FRT SEAT RH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT SEAT BELT LH (BELT A-FRT SEAT LH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT DOOR RH (PANEL A-FRT DR RH)	BENT	1,133.00	1,133.00
1	FRONT DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	35.00	-
1	FRONT DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	35.00	-
1	FRONT DOOR WEATHERSTRIP RH	SERVICEABLE	38.79	-
1	FRONT DOOR CHECK / ABSORBER RH	SERVICEABLE	19.00	-
1	FRONT DOOR PILLAR OUT PANEL RH	TO REPAIR SEE LABOUR	715.00	-
1	FRONT DOOR PILLAR INNER PANEL RH	TO REPAIR SEE LABOUR	850.00	-
1	FRONT DOOR LH (PANEL A-FRT DR LH)	BENT	1,133.00	1,133.00
1	FRONT DOOR OUTER MOULDING LH	SERVICEABLE	220.00	-
1	FRONT DOOR OUTER HANDLE LH	SERVICEABLE	60.00	-
1	FRONT DOOR HANDLE SUPPORT LH	SERVICEABLE	40.00	-
1	FRONT DOOR OUTER HANDLE INNER SEAL LH	SERVICEABLE	45.00	-
1	FRONT DOOR OUTER KEY LOCK LH	SERVICEABLE	25.00	-
1	FRONT DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	35.00	-
1	FRONT DOOR HINGE LOWER LH	BENT	35.00	35.00

Report Ref No. CC3/EQ114000597/Kja3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR INNER LOCK LH	TO REPAIR SEE LABOUR	586.00	-
1	FRONT DOOR INNER LOCK LATCH LH	TO REPAIR SEE LABOUR	206.00	-
1	FRONT DOOR CHECK / ARRESTOR LH	SERVICEABLE	19.00	-
1	FRONT DOOR WEATHERSTRIP LH	SERVICEABLE	38.79	-
1	FRONT DOOR GLASS CHANNEL WEATHERSTRIP LH	SERVICEABLE	160.00	-
1	FRONT DOOR INNER TRIM BOARD LH	SERVICEABLE	455.69	-
1	FRONT DOOR POWER WINDOW MOTOR (MASTER) MOTOR	TO REPAIR SEE LABOUR	284.97	-
1	FRONT DOOR POWER WINDOW MOTOR SWITCH	SERVICEABLE	145.00	-
1	FRONT DOOR WINDOW REGULATOR GEAR LH	TO REPAIR SEE LABOUR	84.58	-
1	FRONT DOOR PILLAR OUTER PANEL LH	TO REPAIR SEE LABOUR	715.00	-
1	FRONT DOOR PILLAR INNER PANEL LH	TO REPAIR SEE LABOUR	850.00	-
1	FRONT DOOR PILLAR CENTER PANEL LH	TO REPAIR SEE LABOUR	635.15	-
1	FRONT SIDE VIEW MIRROR RH (MIRROR A O/S RH)	SERVICEABLE	939.00	-
1	FRONT SIDE ROCKER PANEL GARNISH LH	MISSING	236.40	236.40
1	FRONT SIDE ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	600.00	-
1	FRONT SIDE ROCKER PANEL GARNISH RH	SERVICEABLE	236.40	-
1	FRONT WINDSCREEN (GLASS A-W/SHIELD)	CRACKED	1,304.00	1,304.00
1	FRONT WINDSCREEN MOULDING (MOULDING A-W/SHIELD)	NECESSARY	196.00	196.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,202.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER COWLING RH	SERVICEABLE	298.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR DOOR RH	BENT	1,133.00	1,133.00
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,133.00	-
1	ROOF TOP OUT SIDE PANEL LH	TO REPAIR SEE LABOUR	356.85	-

Report Ref No. CC3/EQ114000597/Kja3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GEAR BOX MOUNTING RH (ADDITIONAL)	SERVICEABLE	249.00	-
1	ENGINE MOUNTING LH (ADDITIONAL)	TORN	228.00	228.00
1	FRONT ENGINE MOUNTING (ADDITIONAL)	SERVICEABLE	100.14	-
1	REAR ENGINE MOUNTING (ADDITIONAL)	SERVICEABLE	134.00	-
1	W/HARNESS-GEAR BOX (ADDITIONAL)	TORN	1,645.19	1,645.19
	LESS 10% DISCOUNT		-4,326.49	-1,835.76
			38,938.40	16,521.86
1	W/HARNESS S-I/P FUSE BOX (LOCAL REPAIR) (SN)	CUT	1,903.05	300.00
	LESS 10% DISCOUNT		-190.31	-
			1,712.74	300.00
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	24.00	24.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	192.00	-
2	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
6	BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NECESSARY	30.00	30.00
2	FRONT ERP STICKER (SN)	NECESSARY	40.00	26.00
1	SET PROOF LINING CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BONNET INSULATOR CLIP (SN)	NECESSARY	40.00	40.00
1	SET RADIATOR GRILLE CLIP (SN)	NOT NECESSARY	18.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET RADIATOR GRILLE TOP COVER CLIP (SN)	NOT NECESSARY	10.00	-
1	SET FRONT FENDER LINER CLIP (SN)	NECESSARY	40.00	40.00
1	SET ENGINE SPLASH COVER CLIP RH (SN)	NOT NECESSARY	12.00	-
1	SET ENGINE SPLASH COVER CLIP LH (SN)	NOT NECESSARY	12.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NOT NECESSARY	30.00	-
2	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	120.00	120.00
2	DOOR STICKER "6555-3333" (SN)	O/S NECESSARY	120.00	60.00
1	SET FRONT DOOR INNER TRIM BOARD LH CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FRONT DOOR INNER TRIM BOARD RH CLIP (SN)	NOT NECESSARY	45.00	-
1	FRONT TYRE RH (30%) (SN)	PUNCTURE	360.00	180.00

Report Ref No. CC3/EQI14000597/Kja3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL RIM RH (LOCAL PURCHASE) (SN)	BENT	254.00	50.00
1	FRONT TYRE LH (20%) (SN)	PUNCTURE	360.00	180.00
1	FRONT WHEEL RIM LH (LOCAL PURCHASE) (SN)	BENT	254.00	50.00
1	REAR TYRE RH (SN)	SERVICEABLE	180.00	-
1	REAR TYRE RIM RH (SN)	SERVICEABLE	126.00	-
1	TYRE HUB CAP RH (SN)	SERVICEABLE	35.00	-
2	HUB CUP RIM (SN)	NOT NECESSARY	70.00	-
			2,682.00	870.00
	<b>LABOUR</b>			
	PANEL BEATING, KNOCKING AND STRIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BUMPER LOWER STIFFENER, BONNET HINGE RH, BONNET HINGE LH, BONNET LOCK, FRONT BEAM A-IMPACT LH, FRONT DRIVE SHAFT RH (SHAFT A-AXLE, FRT, RH) (SHORT), INTERN AXLE SHAFT (CENTRE), FRONT FENDER RR BRACKET RH, AIR INTAKE RESONATOR TANK TOP BRACKET, FRONT DOOR HINGE UPPER RH, FRONT DOOR HINGE LOWER RH, }		5,600.00	1,400.00
	FRONT DOOR PILLAR OUT PANEL RH, FRONT DOOR PILLAR INNER PANEL RH, FRONT DOOR HINGE UPPER LH, FRONT DOOR INNER LOCK LH, FRONT DOOR INNER LOCK LATCH LH, FRONT DOOR POWER WINDOW MOTOR (MASTER) MOTOR, FRONT DOOR WINDOW REGULATOR GEAR LH, FRONT DOOR PILLAR OUT PANEL LH, FRONT DOOR PILLAR INNER PANEL LH, FRONT DOOR PILLAR CENTER PANEL LH, FRONT SIDE ROCKER PANEL OUTER LH, REAR BUMPER, REAR FENDER RH, REAR DOOR LH AND ROOF TOP OUT SIDE PANEL LH. }		-	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED		170.00	40.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	170.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,400.00	2,000.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.		380.00	250.00

Report Ref No. CC3/EQ114000597/Kja3s2-1





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF DOOR AND ROOF PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.		340.00	180.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	40.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	REPEATED	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		120.00	120.00
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.		380.00	50.00
	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	REPEATED	170.00	-
	TOWING FEES.		120.00	50.00
			15,580.00	4,730.00
<b>GRAND TOTAL</b>			<b>58,913.14</b>	<b>22,421.86</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>16,150.00</b>

Report Ref No. CC3/EQ114000597/Kja3s2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.