

8/10/2013

INS. CASE OWNER:

CC 3 /EQ11300

0597

1K82302

LKK:

IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured :

Insured Tel No. :

Excess Sec II :SS

Is driver the owner? (YES / NO)

If NO, Driver Name / Age :

Driver Tel No. :

HP:

D.O.A :

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

(V/L: YES / NO Insured Liability :

% Final ? Yes / No



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date / Time

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age :

Driver's Own Vehicle Number:

Insurance Company:

STAGE

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

DATE / PIC

Documentation Check List: Handler Typist

OI Apt Ltr:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
Approval Email:	☐	☐
Payment Breakdown Form:	☐	☐
Others:	☐	☐

14/1/14

called OI. spoke to Mr Mohammad Zain.
Inform about the claim. Confirm the
accident. OI said he was not from
behind by TP. He did not change name.
No photo. no witnesses.
Advise him we will proceed to settle
the claim and aware of wa. w. u
be affected.

Letter out / email to w/p.

22/4/14

Richard (EQI) informed to settle 50% if not Pending Finalisation
PR.
Jasmine agreed 50%.

24-8-15

FOR APPROVAL.

NO DEVELOPMENT FROM TP.

FINAL SETTLEMENT

Date :

Confirm with

NO SETTLEMENT

Repair Cost:

SS

Final Liability

50

% (Agreed / Assessed)

BOLA S/N No. :

NIL

Loss of Rental:

SS

(days)

If NO or B 28, Ass. Lia :

Loss of Use:

SS

(\$ x days)

Report Format :

Disbursement:

SS

Global Sum: SS

WP - \$400.00

Total:

SS

ASS. REC. BY:

REF:

EQ /

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 7609T

Yr Regn:

03, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

c.c

1991

Colour

White / Red

A/C: Insured / Std / NI / NA

Sp. Reading

191470

T/Radio: Insured / Std / NI / NA

Eng/No:

KL11A 89RTAB 055298

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Wytake 195/65R15

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

3

mm

Rear

R/Bal.

8

mm

L/Bal.

2

mm

L/Bal.

8

mm

D.O.A.

6/1/14

D.O.I.

9/1/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & L/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/4/14

Call Sup \$16,150.6 Confirmed Jasmine (10+5 x 121.98)

RED (\$42,763.14 / 73%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQ114000597/Ksa3	
22 GEMMILL LANESINGAPORE 069257		Date : 10-01-2014	
		Code : EQ1	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XB 3787Z	Veh. Inspected	SHB 7609T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/01/2014
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/01/2014	Inspection Date	09/01/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7609T - EQ

Not Authorized
61 Sep @ 16, 150k

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 7609T - Andrea
 KL1LA69RJBB075037*
 CHEVROLET
 EPICA 2.0
 06.01.2014
EQ

PART			LIST	
		\$	Tn	1,202.00 ✓
1	1	\$	R	295.25 X
2	1	\$	Sm	180.00 X
3	1	\$	Sm	78.00 X
4	1	\$	Sm	102.00 X
5	1	\$	cm	102.00 ✓
6	1	\$	R	134.37 X
7	1	\$	Sm	816.00 X
8	1	\$	Br	816.00 ✓
9	1	\$	n1	32.40 —
10	1	\$	Br	1,222.32 ✓
11	1	\$	Br	1,250.00 —
12	1	\$	nn	144.30 X
13	1	\$	Sm	257.00 X
14	1	\$	Sm	84.63 X
15	1	\$	R	36.00 X
16	1	\$	R	36.00 X
17	1	\$	Sm	150.00 X
18	1	\$	R	200.00 X
19	1	\$	Sm	400.00 X
20	1	\$	Br	216.17 ✓
21	1	\$	Br	48.32 ✓
22	1	\$	Br	216.17 ✓
23	1	\$	Br	48.32 —
24	1	\$	Sm	283.00 X
25	1	\$	Br	283.00 —
26	1	\$	Br	230.00 —
27	1	\$	Br	230.00 —
28	1	\$	Sm	51.79 X
29	1	\$	Sm	51.79 X
30	1	\$	0.1	105.75 ✓
31	1	\$	Sm	66.00 X
32	1	\$	R	214.00 X
33	1	\$		

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7609T - EQ

34	1	Front Drive Shaft RH (Shaft A-Axle, Frt, RH) (S	\$	R	900.00 X
35	1	Front Drive Shaft LH (Shaft A-Axle, Frt, LH) (L	\$	Bt	900.00 ✓
36	1	Steering Rack End (Spring A-Clock) LH	\$	Bt	88.56 —
37	1	Steering Tie-Rod End (End -Tie Rod)	\$	Bt	67.00 —
38	1	W/Harnes S-I/P FUSE BOX	\$	Cut	1,903.05 3000
39	1	Cross member	\$	Bt	1,030.71 ?
40	1	Interm Axle Shaft (Centre)	\$	R	241.14 X
41	1	Front Seat Belt RH (Belt A-Frt Seat RH)	\$	Sm	402.50 X
42	1	Front safety belt cover garnish	\$	Sm	125.00 X
43	1	Front Seat Belt LH (Belt A-Frt Seat LH)	\$	Sm	402.50 X
44	1	Front safety belt cover garnish	\$	Sm	125.00 X
45	1	Front Fender RH	\$	Bt	837.60 ✓
46	1	Front Fender LH	\$	Bt	837.60 ✓
47	1	Front Fender Liner RH	\$	Sm	47.00 X
48	1	Front Fender Liner LH	\$	Tr	47.00 ✓
49	1	Fender Insulation RH	\$	Sm	39.00 X
50	1	Fender Insulation LH	\$	Dt	39.00 —
51	1	Front Fender RR Bracket RH	\$	R	7.10 X
52	1	Front Fender RR Bracket LH	\$	Bt	7.10 ✓
53	1	Front Fender Inner Wheel House Panel LH	\$	Bt	1,437.00 ?
54	1	HORN LH	\$	Sm	159.20 X
55	1	Radiator Grille (Grille A-Rad)	\$	Sm	367.00 X
56	1	Radiator Assembly (Radiator A)	\$	Sm	618.00 X
57	1	Aircon Condenser (Conderser A)	\$	Sm	600.00 X
58	1	Air Intercooler (Cooler A-Air Charge)	\$	Sm	652.00 X
59	1	Fan Blade (Fan A-Auxiliary (Diesel) Small)	\$	Sm	536.00 X
60	1	Fan Blade (Fan A-Eng Cool (Diesel) Big)	\$	Sm	634.00 X
61	1	Fuse Box	\$	Bt	716.00 X
62	1	Air Cleaner Assembly (Cleaner A-Air)	\$	Bt	112.00 X
63	1	Air intake resonator (beside fender)	\$	cm	20.01 ✓
64	1	Air intake resonator hose (bottom)	\$	Sm	60.90 X
65	1	Air intake resonator tank top bracket	\$	R	45.00 X
66	1	Resonator A-A/CL	\$	Sm	37.00 X
67	1	Engine Splash Cover RH (Cover A-Engine)	\$	Sm	168.00 X
68	1	Engine Splash Cover LH (Cover A-Engine)	\$	Sm	168.00 X
69	1	Front Seat Belt RH (Belt A-Frt Seat RH)	\$	Sm	402.50 X
70	1	Front safety belt cover garnish	\$	Sm	125.00 X
71	1	Front Seat Belt LH (Belt A-Frt Seat LH)	\$	Sm	402.50 X
72	1	Front safety belt cover garnish	\$	Sm	125.00 X
73	1	Front Door RH (Panel A-Frt DR RH)	\$	Bt	1,133.00 ✓
74	1	Front Door Hinge Upper RH	\$	R	35.00 X
75	1	Front Door Hinge Lower RH	\$	R	35.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7609T - EQ

76	1	Front Door Weatherstrip RH	\$	38.79 ✓
77	1	Front Door Check / Arrestor RH	\$	19.00 X
78	1	Front Door Pillar Out Panel RH	\$	R 715.00 ✓
79	1	Front Door Pillar Inner Panel RH	\$	R 850.00 X
80	1	Front Door LH (Panel A-Frt DR LH)	\$	R 1,133.00 ✓
81	1	Front Door Outer Moulding LH	\$	220.00 X
82	1	Front Door Outer Handle LH	\$	R 60.00 X
83	1	Front Door Handle Support LH	\$	40.00 X
84	1	Front Door outer handle inner seal LH	\$	45.00 X
85	1	Front Door outer key lock LH	\$	25.00 X
86	1	Front Door Hinge Upper LH	\$	R 35.00 ✓
87	1	Front Door Hinge Lower LH	\$	R 35.00 ✓
88	1	Front Door inner lock LH	\$	R 586.00 X
89	1	Front Door Inner Lock Latch LH	\$	R 206.00 X
90	1	Front Door Check / Arrestor LH	\$	19.00 X
91	1	Front Door Weatherstrip LH	\$	38.79 X
92	1	Front Door glass channel weatherstrip LH	\$	160.00 X
93	1	Front Door inner trim board LH	\$	455.69 X
94	1	Front Door Power Window Motor (Master) Mot	\$	R 284.97 X
95	1	Front Door power window motor switch	\$	145.00 X
96	1	Front Door Window Regulator Gear LH	\$	R 84.58 X
97	1	Front Door Pillar Out Panel LH	\$	R 715.00 X
98	1	Front Door Pillar Inner Panel LH	\$	R 850.00 X
99	1	Front Door Pillar Center Panel LH	\$	R 635.15 X
100	1	Front Side View Mirror RH (Mirror A o/s RH)	\$	939.00 X
101	1	Front Side Rocker Panel Garnish LH	\$	236.40 ✓
102	1	Front Side Rocker Panel Outer LH	\$	R 600.00 X
103	1	Front Side Rocker Panel Garnish RH	\$	236.40 X
104	1	Front Windscreen (Glass A-W/ Shield)	\$	CR 1,304.00 ✓
105	1	Front Windscreen Moulding (Moulding A-W/ Si	\$	196.00 X
106	1	Rear Bumper	\$	R 1,202.00 X
107	1	Rear Fender RH	\$	R 1,145.00 X
108	1	Rear Fender Inner Cowling RH	\$	298.00 X
109	1	Rear Fender Inner Trim RH	\$	418.44 X
110	1	Rear Door RH	\$	R 1,133.00 ✓
111	1	Rear Door LH	\$	R 1,133.00 X
112	1	Roof top out side panel LH	\$	R 356.85 X

TOTAL	\$	42,811.61
10%	\$	4,281.16
	\$	38,530.45

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7609T - EQ

Specical Nett

1Set	Front Bumper Fastener Clip	\$	24.00 ✓
1Set	Front Licence Plate With Holder	\$	192.00 X
2	Front windscreen sealant	\$	80.00 40sn
1	Front windscreen inner sponge seal	\$	100.00 30sn
6	Bonnet under weatherstrip seal clips	\$	30.00 ✓
2	Front ERP Sticker	\$	40.00 26sn
1Set	Roof lining Clip	\$	45.00 X
1Set	Bonnet Insulator Clip	\$	40.00 ✓
1Set	Radiator Grille Clip	\$	18.00 X
1Set	Bootlid inner trim board Clip	\$	40.00 X
1Set	Radiator Grille Top Cover Clip	\$	10.00 X
1Set	Front Fender Liner Clip	\$	40.00 ✓
1Set	Engine Splash Cover Clip RH	\$	12.00 X
1Set	Engine Splash Cover Clip LH	\$	12.00 X
1Set	Rear Bumper Fastener Clip	\$	30.00 X
2	Door Sticker "Trans-cab"	\$	120.00 ✓
2	Door Sticker "6555-3333"	\$	120.00 ✓
1Set	Front door inner trim board LH Clip	\$	45.00 ✓
1Set	Front door inner trim board RH Clip	\$	45.00 X
1	Front Tyre RH	\$	360.00 30lin
1	Front Wheel Rim RH	\$	254.00 50sn
1	Front Tyre LH	\$	360.00 29lin
1	Front Wheel Rim LH	\$	254.00 50sn
1	Rear Tyre RH	\$	180.00 X
1	Rear Tyre Rim RH	\$	126.00 X
1	Tyre hub cap RH	\$	35.00 X
2	Hub Cup Rim	\$	70.00 X

TOTAL \$ 2,682.00

TOTAL PARTS \$ 41,212.45

Panel Beating, Knocking And Straightening
 The Necessary Portion, Remove And
 Renewal Of Parts, Adjust And Realign The
 Same

\$ 5,600.00 1400

To Check Electrical Lighting Concerned.

\$ 170.00 40

To Rust-Proofing Of The Affected Areas.

\$ 170.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7609T - EQ

Putty And Spray Painting Of The Affected Portion.	\$	5,400.00 ²⁰⁰⁰
To Remove And Refit Front W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00 ¹²⁰
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 ²⁵⁰
To transfer of door and roof panel fittings and conduct water seepage test.	\$	340.00 ¹⁸⁰
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 ¹⁰⁰
To check steering geometry and computer wheel alignment	\$	220.00 ⁶⁰
To transfer of tire, rim and on wheel balancing.	\$	170.00 ⁴⁰
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	^{Hydraulic} 380.00 ^X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	120.00 ✓
To check ABS brake efficiency, final checking and testing.	\$	380.00 ⁵⁰
To remove and refit ABS pump relay to enable repair.	\$	ⁿⁿ 380.00 ^X
To remove and refit air bag system and reset.	\$	ⁿⁿ 480.00 ^X
To vacuum, replace, refix and recharge air condenser	\$	380.00 ¹⁰⁰

Andrea

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHB 7609T - EQ

To replace, refix and top up coolant for
radiator

\$

170.00 *50/*

To vacuum, replace, refix and recharge Air
Intercooler

\$

Repair 170.00 X

Towing Fees.

\$

120.00 *50/*

\$ 14,740.00

TOTAL \$ 55,952.45

Repair Days

20 Days

10

52913.14

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHB 7609T - EQ

Sharon 50%

Andrea

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 7609T - Andrea
KL1LA69RJBB075037*
CHEVROLET
EPICA 2.0
06.01.2014
EQ

PART		
1	1	Gear Box Mounting RH
2	1	Engine Mounting LH
3	1	Front Engine Mounting
4	1	Rear Engine Mounting
5	1	W/HARNESS-GEAR BOX

LIST	
\$	Sm 249.00 X
\$	Tn 228.00 ✓
\$	Sm 100.14 X
\$	Sm 134.00 X
\$	Tn 1,645.19 ✓
TOTAL	\$ 2,356.33
10%	\$ 235.63
	\$ 2,120.70

1,202.00	1,400.00	816.00
102.00	40.00	216.17
816.00	170.00	48.32
32.40	2,000.00	283.00
1,222.32	250.00	51.79
1,250.00	180.00	51.79
216.17	100.00	66.00
48.32	60.00	214.00
283.00	40.00	1,903.05
230.00	120.00	1,030.71
230.00	50.00	241.14
105.75	100.00	1,437.00
900.00	50.00	716.00
88.56	50.00	45.00
67.00	4,610.00	37.00
837.60		168.00
837.60	11,027.01	220.00
47.00	954.00	38.79
39.00	4,610.00	284.97
7.10	16,591.01	145.00
20.01		1,304.00
1,133.00		196.00
1,133.00		9,513.73
35.00		
236.40		9,513.73
1,133.00		90.00
12,252.23		8,562.36
12,252.23		80.00
90.00		100.00
11,027.01		40.00
		12.00
24.00		232.00
30.00		
40.00		170.00
40.00		480.00
120.00		650.00
60.00		
252.00		8,562.36
50.00		232.00
288.00		650.00
50.00		9,444.36
954.00		



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI14000597/Ksa3

Date: 10.01.2014

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD
Attn: Richard

Dear Richard,

PRELIMINARY ADVICE OF VEHICLE NO.


SHB 7609T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.01.2014 at the premises of M/s Trans Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	55,952.45
Revised Estimate Amount	: S\$	16,591.01
"Check" Items Amount	: S\$	9,444.36
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
N/S Front Portion & O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Zayyer

From: Zayyer
Sent: Friday, 17 January, 2014 4:13 PM
To: jasminetan@transcabservices.com.sg
Cc: Sharon Yee
Subject: ACCIDENT INVOLVING XB 3787Z & SHB 7609T ON 06/01/2014
Attachments: statement of XB 3787Z.pdf

Your ref: SHB7609T
Our ref: CC3/EQ114000597/Ksa3

WITHOUT PREJUDICE

Dear Sir / Madam,

ACCIDENT INVOLVING XB 3787Z & SHB 7609T ON 06/01/2014

We refer to the above matter.

We are of the opinion that this is a case of conflicting versions. There is no conclusive evidence to substantiate either party's version. Enclosed herewith a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident and we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, kindly forward to us with any evidence (if any) to support your claim.

Kindly take note that case handler in charge is Sharon and she can be contacted at 6749 4274.

“祝你马年鸿运当头，身体健康”

“Wishing you a Happy, Cheerful, and Successful in the Year of the Horse”

Thanks and Best regards,
Zayer
LKK Auto Consultants Pte Ltd
DID: 6749 9635
Fax: 6741 4108



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/EQ114000597/Ksa3

20 January 2014

SAM LIAN EQUIPMENT SERVICES PTE LTD
13 Jurong East Street 13
#04-263
Singapore 600131

Dear Sir/Madam,

ACCIDENT INVOLVING XB 3787Z & SHB 7609T ON 06/01/2014

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 30/1/2014, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Zayer
Case Handler
DID: 6749 9635
FAX: 6741 4108
Email: zayyer@lkkauto.com

Case Handler

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI14000597/Kja3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-11-2015



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 3787Z	Veh. Inspected	SHB 7609T
Policy No.	DMCPHQ14-000034	Coverage (\$)	0.00
Claim No.	DM14HO00058/JT	Excess (\$)	0.00
Assign From		Assign Date	09/01/2014

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB055298	Colour	WHITE / RED
Odometer	191470	Steering	JAMMED
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	3 mm
L/H Front Tyre	195/65R15	WEST LAKE	3 mm
R/H Rear Tyre	195/65R15	FALKEN	8 mm
L/H Rear Tyre	195/65R15	FALKEN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/01/2014	Inspection Date	09/01/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7609T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TORN	1,202.00	1,202.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	295.25	-
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	CRACKED	102.00	102.00
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT HEADLAMP RH	SERVICEABLE	816.00	-
1	FRONT HEADLAMP LH	BROKEN	816.00	816.00
1	FRONT BUMPER FOG LAMP OUTER COVER LH	MISSING	32.40	32.40
1	FRONT SUPPORT PANEL ASSY (PANEL A-FRT)	BENT	1,222.32	1,222.32
1	BONNET (PANEL A-HOOD)	BENT	1,250.00	1,250.00
1	BONNET CENTRE 'CHEVROLET' LOGO BADGE	NOT NECESSARY	144.30	-
1	BONNET MOULDING	SERVICEABLE	257.00	-
1	BONNET INSULATOR	SERVICEABLE	84.63	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET CABLE	SERVICEABLE	150.00	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	200.00	-
1	BONNET INSULATOR	SERVICEABLE	400.00	-
1	FRONT SHOCK ABSORBER ASSY RH	BENT	216.17	216.17
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	BENT	48.32	48.32
1	FRONT SHOCK ABSORBER ASSY LH	BENT	216.17	216.17
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	BENT	48.32	48.32
1	FRONT LOWER ARM RH	SERVICEABLE	283.00	-
1	FRONT LOWER ARM LH	BENT	283.00	283.00
1	FRONT KNUCKLE ARM RH	BENT	230.00	230.00

Report Ref No. CC3/EQI14000597/Kja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT KNUCKLE ARM LH	BENT	230.00	230.00
1	FRONT STABILIZER BAR LINK RH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR LINK LH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR BRACKET LH	DISTORTED	105.75	105.75
1	FRONT STABILIZER BAR BUSH LH	SERVICEABLE	66.00	-
1	FRONT BEAM A-IMPACT LH	TO REPAIR SEE LABOUR	214.00	-
1	FRONT DRIVE SHAFT RH (SHAFT A-AXLE, FRT, RH) (SHORT)	TO REPAIR SEE LABOUR	900.00	-
1	FRONT DRIVE SHAFT LH (SHAFT A-AXLE, FRT, LH) (LONG)	BENT	900.00	900.00
1	STEERING RACK END (SPRING A-CLOCK) LH	BENT	88.56	88.56
1	STEERING TIE-ROD END (END-TIE ROD)	BENT	67.00	67.00
1	CROSS MEMBER	BUCKLED	1,030.71	1,030.71
1	INTERN AXLE SHAFT (CENTRE)	TO REPAIR SEE LABOUR	241.14	-
1	FRONT SEAT BELT RH (BELT A-FRT SEAT RH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT SEAT BELT LH (BELT A-FRT SEAT LH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT FENDER RH	BENT	837.60	837.60
1	FRONT FENDER LH	BENT	837.60	837.60
1	FRONT FENDER LINER RH	SERVICEABLE	47.00	-
1	FRONT FENDER LINER LH	TORN	47.00	47.00
1	FENDER INSULATOR RH	SERVICEABLE	39.00	-
1	FENDER INSULATOR LH	DISTORTED	39.00	39.00
1	FRONT FENDER RR BRACKET RH	TO REPAIR SEE LABOUR	7.10	-
1	FRONT FENDER RR BRACKET LH	BENT	7.10	7.10
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	BENT	1,437.00	1,437.00
1	HORN LH	SERVICEABLE	159.20	-
1	RADIATOR GRILLE (GRILLE A-RAD)	SERVICEABLE	367.00	-
1	RADIATOR ASSEMBLY (RADIATOR A)	SERVICEABLE	618.00	-
1	AIRCON CONDENSER (CONDENSER A)	SERVICEABLE	600.00	-
1	AIR INTERCOOLER (COOLER A-AIR CHARGE)	SERVICEABLE	652.00	-

Report Ref No. CC3/EQ14000597/Kja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FAN BLADE (FAN A-AUXILIARY (DIESEL) SMALL)	SERVICEABLE	536.00	-
1	FAN BLADE (FAN A-ENG COOL (DIESEL) BIG)	SERVICEABLE	634.00	-
1	FUSE BOX	SERVICEABLE	716.00	-
1	AIR CLEANER ASSEMBLY (CLEANER A-AIR)	SERVICEABLE	112.00	-
1	AIR INTAKE RESONATOR (BESIDE FENDER)	CRACKED	20.01	20.01
1	AIR INTAKE RESONATOR HOSE (BOTTOM)	SERVICEABLE	60.90	-
1	AIR INTAKE RESONATOR TANK TOP BRACKET	TO REPAIR SEE LABOUR	45.00	-
1	RESONATOR A-A/CL	SERVICEABLE	37.00	-
1	ENGINE SPLASH COVER RH (COVER A-ENGINE)	SERVICEABLE	168.00	-
1	ENGINE SPLASH COVER LH (COVER A-ENGINE)	SERVICEABLE	168.00	-
1	FRONT SEAT BELT RH (BELT A-FRT SEAT RH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT SEAT BELT LH (BELT A-FRT SEAT LH)	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	FRONT DOOR RH (PANEL A-FRT DR RH)	BENT	1,133.00	1,133.00
1	FRONT DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	35.00	-
1	FRONT DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	35.00	-
1	FRONT DOOR WEATHERSTRIP RH	SERVICEABLE	38.79	-
1	FRONT DOOR CHECK / ABSORBER RH	SERVICEABLE	19.00	-
1	FRONT DOOR PILLAR OUT PANEL RH	TO REPAIR SEE LABOUR	715.00	-
1	FRONT DOOR PILLAR INNER PANEL RH	TO REPAIR SEE LABOUR	850.00	-
1	FRONT DOOR LH (PANEL A-FRT DR LH)	BENT	1,133.00	1,133.00
1	FRONT DOOR OUTER MOULDING LH	SERVICEABLE	220.00	-
1	FRONT DOOR OUTER HANDLE LH	SERVICEABLE	60.00	-
1	FRONT DOOR HANDLE SUPPORT LH	SERVICEABLE	40.00	-
1	FRONT DOOR OUTER HANDLE INNER SEAL LH	SERVICEABLE	45.00	-
1	FRONT DOOR OUTER KEY LOCK LH	SERVICEABLE	25.00	-
1	FRONT DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	35.00	-
1	FRONT DOOR HINGE LOWER LH	BENT	35.00	35.00

Report Ref No. CC3/EQI14000597/Kja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR INNER LOCK LH	TO REPAIR SEE LABOUR	586.00	-
1	FRONT DOOR INNER LOCK LATCH LH	TO REPAIR SEE LABOUR	206.00	-
1	FRONT DOOR CHECK / ARREDTOR LH	SERVICEABLE	19.00	-
1	FRONT DOOR WEATHERSTRIP LH	SERVICEABLE	38.79	-
1	FRONT DOOR GLASS CHANNEL WEATHERSTRIP LH	SERVICEABLE	160.00	-
1	FRONT DOOR INNER TRIM BOARD LH	SERVICEABLE	455.69	-
1	FRONT DOOR POWER WINDOW MOTOR (MASTER) MOTOR	TO REPAIR SEE LABOUR	284.97	-
1	FRONT DOOR POWER WINDOW MOTOR SWITCH	SERVICEABLE	145.00	-
1	FRONT DOOR WINDOW REGULATOR GEAR LH	TO REPAIR SEE LABOUR	84.58	-
1	FRONT DOOR PILLAR OUTER PANEL LH	TO REPAIR SEE LABOUR	715.00	-
1	FRONT DOOR PILLAR INNER PANEL LH	TO REPAIR SEE LABOUR	850.00	-
1	FRONT DOOR PILLAR CENTER PANEL LH	TO REPAIR SEE LABOUR	635.15	-
1	FRONT SIDE VIEW MIRROR RH (MIRROR A O/S RH)	SERVICEABLE	939.00	-
1	FRONT SIDE ROCKER PANEL GARNISH LH	MISSING	236.40	236.40
1	FRONT SIDE ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	600.00	-
1	FRONT SIDE ROCKER PANEL GARNISH RH	SERVICEABLE	236.40	-
1	FRONT WINDSCREEN (GLASS A-W/SHIELD)	CRACKED	1,304.00	1,304.00
1	FRONT WINDSCREEN MOULDING (MOULDING A-W/SHIELD)	NECESSARY	196.00	196.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,202.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER COWLING RH	SERVICEABLE	298.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR DOOR RH	BENT	1,133.00	1,133.00
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,133.00	-
1	ROOF TOP OUT SIDE PANEL LH	TO REPAIR SEE LABOUR	356.85	-

Report Ref No. CC3/EQI14000597/Kja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GEAR BOX MOUNTING RH (ADDITIONAL)	SERVICEABLE	249.00	-
1	ENGINE MOUNTING LH (ADDITIONAL)	TORN	228.00	228.00
1	FRONT ENGINE MOUNTING (ADDITIONAL)	SERVICEABLE	100.14	-
1	REAR ENGINE MOUNTING (ADDITIONAL)	SERVICEABLE	134.00	-
1	W/HARNESS-GEAR BOX (ADDITIONAL)	TORN	1,645.19	1,645.19
	LESS 10% DISCOUNT		-4,326.49	-1,835.76
			38,938.40	16,521.86
1	W/HARNESS S-I/P FUSE BOX (LOCAL REPAIR) (SN)	CUT	1,903.05	300.00
	LESS 10% DISCOUNT		-190.31	-
			1,712.74	300.00
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	24.00	24.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	192.00	-
2	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
6	BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NECESSARY	30.00	30.00
2	FRONT ERP STICKER (SN)	NECESSARY	40.00	26.00
1	SET PROOF LINING CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BONNET INSULATOR CLIP (SN)	NECESSARY	40.00	40.00
1	SET RADIATOR GRILLE CLIP (SN)	NOT NECESSARY	18.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET RADIATOR GRILLE TOP COVER CLIP (SN)	NOT NECESSARY	10.00	-
1	SET FRONT FENDER LINER CLIP (SN)	NECESSARY	40.00	40.00
1	SET ENGINE SPLASH COVER CLIP RH (SN)	NOT NECESSARY	12.00	-
1	SET ENGINE SPLASH COVER CLIP LH (SN)	NOT NECESSARY	12.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NOT NECESSARY	30.00	-
2	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	120.00	120.00
2	DOOR STICKER "6555-3333" (SN)	O/S NECESSARY	120.00	60.00
1	SET FRONT DOOR INNER TRIM BOARD LH CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FRONT DOOR INNER TRIM BOARD RH CLIP (SN)	NOT NECESSARY	45.00	-
1	FRONT TYRE RH (30%) (SN)	PUNCTURE	360.00	180.00

Report Ref No. CC3/EQI14000597/Kja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL RIM RH (LOCAL PURCHASE) (SN)	BENT	254.00	50.00
1	FRONT TYRE LH (20%) (SN)	PUNCTURE	360.00	180.00
1	FRONT WHEEL RIM LH (LOCAL PURCHASE) (SN)	BENT	254.00	50.00
1	REAR TYRE RH (SN)	SERVICEABLE	180.00	-
1	REAR TYRE RIM RH (SN)	SERVICEABLE	126.00	-
1	TYRE HUB CAP RH (SN)	SERVICEABLE	35.00	-
2	HUB CUP RIM (SN)	NOT NECESSARY	70.00	-
			2,682.00	870.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BUMPER LOWER STIFFENER, BONNET HINGE RH, BONNET HINGE LH, BONNET LOCK, FRONT BEAM A-IMPACT LH, FRONT DRIVE SHAFT RH (SHAFT A-AXLE, FRT, RH) (SHORT), INTERN AXLE SHAFT (CENTRE), FRONT FENDER RR BRACKET RH, AIR INTAKE RESONATOR TANK TOP BRACKET, FRONT DOOR HINGE UPPER RH, FRONT DOOR HINGE LOWER RH, FRONT DOOR PILLAR O		5,600.00	1,400.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	170.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,400.00	2,000.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.		380.00	250.00
	TO TRANSFER OF DOOR AND ROOF PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.		340.00	180.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	40.00

Report Ref No. CC3/EQI14000597/Kja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	REPEATED	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		120.00	120.00
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.		380.00	50.00
	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	REPEATED	170.00	-
	TOWING FEES.		120.00	50.00
			15,580.00	4,730.00
	GRAND TOTAL		58,913.14	22,421.86
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			16,150.00

Report Ref No. CC3/EQI14000597/Kja3s2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.