

REPAIR ESTIMATE*

VEHICLE NO : SHB 4002M

DATE 19/2/2018 23:45

MAKE :

MODEL : HYUNDAI i40

NGT CLK

JM

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Bracket (LH)			\$ 24.60
	Frt Wheel Hub Cap		<i>0</i>	\$ 150.70
	SUB TOTAL			\$ 737.60
	LESS 20%			\$ 147.52
	DISCOUNTED TOTAL			\$ 590.08
	Labour Charge			
	Panel Beating- Repair Frt LH Fender		<i>620</i>	\$ 500.00 <i>200</i>
	Spray Painting Charge			\$ 400.00 <i>360</i>
	Frt Wheel Alignment			\$ 80.00 <i>60</i>
	TOTAL LABOUR			\$ 980.00
	ESTIMATE TOTAL			\$ 1,570.08

*Repair
x300
x100
old an
damage*

*200
360
60*

*Panel
19/2/18 @ 1420
3 days
P/P
Resy after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.