

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18003974/BTD3E2

Date: 13/12/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant Vehicle No : GBE9091C	Insured Vehicle No :	SH8031R
Date of Loss: 24/02/2018	Nature of Claim:	TP Claim No: MCT18020845

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE9091C	Engine No:	1KD2570011
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	KDH2015020070
Reg. Date:	20/04/2016 (Man. Year: 2015)	Odometer:	32674 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,206.40	5,207.22	5,999.18	53.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	1,750.00	2,480.00	58.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,436.40	6,957.22	8,479.18	54.93
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	15,436.40	5,500.00	9,936.40	64.37

INSPECTION

Date of Assignment:	28/02/2018		
Date Inspected:	01/03/2018	Inspected At:	Heng Yap Seng Auto Services 160 Sin Ming Auto City, #08-13 Singapore 575722
Estimated Period of Repair:	6.0 days		

Adjuster: MA CHIN FOOK

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Dec 2018)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE9091C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	599.10 F	*599.10 FL
2	2		*REAR BUMPER RETAINERS	Necessary	124.10 F	*124.10 FL
3	1		*REAR BUMPER BRACKETS (2PCS)	Broken	110.35 F	*110.35 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
5	1		*REAR TAILGATE	Dented	1,755.95 F	*1,755.95 FL
6	1		*REAR TAILGATE LOCK	Dented	359.40 F	*359.40 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Cut	399.10 F	*399.10 FL
8	2		*REAR TAILGATE HINGES	Not Necessary	136.10 F	*- FL
9	2		*REAR TAILGATE DAMPERS	Not Necessary	211.60 F	*- FL
10	1		*REAR TAILGATE OUTER HANDLE	Dislodged	214.10 F	*155.00 FL
11	1		*REAR TAILGATE EMBLEM	Necessary	65.10 F	*65.10 FL
12	1		*REAR TAILGATE BRAKE LIGHT	Not Necessary	298.10 F	*- FL
13	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	210.10 F	*210.10 FL
14	2		*REAR TAILGATE ABSORBER	Not Necessary	299.20 F	*- FL
15	1		*REAR TAILGATE INNER TRIM BOARD	Distorted	680.10 F	*680.10 FL
16	1		*TAIL LAMP	Broken-1pc only	786.10 F	*393.00 FL
17	1		*TAIL LAMP PANEL	Dented-1pc only	808.10 F	*404.00 FL
18	1		*REAR END PANEL (INNER)	Dented	654.40 F	*654.40 FL
19	1		*REAR END PANEL (OUTER)	Dented	453.30 F	*453.30 FL
20	1		*REAR FLOOR PANEL	Repair	1,567.60 F	*- FL
21	1		*REAR EXHAUST SILENCER	Not Necessary	606.10 F	*- FL
22	1		*REAR EXHAUST SILENCER MOUNTING	Not Necessary	95.10 F	*- FL
23	1		*REAR SPARE TYRE BRACKET	Bent	273.30 F	*273.30 FL
24	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
25	2		*REVERSE SENSOR	Cut	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,206.40	6,876.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,669.08
Total Parts (\$\$)	11,206.40	5,207.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	2,200.00	1,000.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
3	TO REMOVE, REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR	New	350.00	60.00
4	TO REMOVE, REPLACE REVERSE SENSOR	New	250.00	60.00
5	TO REMOVE, REPLACE REAR EXHAUST SILENCER	New	150.00	0.00
6	TO CHECK WIRING AND LIGHTINGS	New	80.00	30.00
Gross Labour Cost (S\$)			4,230.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >