

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| GRE | AT AMERICAN IN | SURANCE COMPANY | Ref: | CS3/GAI18003998/Gd3e2 | | |
|--|---|--------------------|---------|-----------------------|-------------------------|--|
| 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190 | | | | 20-07-2018 | | |
| | | | Code: | GAI | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | | |
| | Insured Veh. | YP 872U | Veh. lı | nspected | YN 6208J | |
| | Policy No. | | Cover | age (\$) | 0.00 | |
| | Claim No. | | Exces | s (\$) | 0.00 | |
| | Assign From | RACHEL TAN | Assig | n Date | 28/02/2018 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | MITSUBISHI CANTER | c.c | | 2998 | |
| | Engine No. | HIDDEN | Year c | of Reg. | 2014 | |
| | Chassis No. | FEB21EA00500 | Colou | r | WHITE | |
| | Odometer | 195900 KM | Steeri | ng | IN ORDER | |
| | Brakes | IN ORDER | Modifi | ication | NIL | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 195/80 R15 | YOKO | HAMA | 5 mm | |
| | L/H Front Tyre | 195/80 R15 | YOKO | HAMA | 5 mm | |
| | R/H Rear Tyre | 195/80 R15 | YOKOH | HAMA | 5 mm | |
| | L/H Rear Tyre | 195/80 R15 | YOKO | HAMA | 5 mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 24/02/2018 | Insped | ct Date / Time | 05/03/2018 (06:22 PM) | |
| | Survey held at | N-51 AUTOMOTIVE PL | | | | |
| | 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | | | | |
| 5a. | Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800-\$3,500 | | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | |

Report Ref No. CS3/GAI18003998/Gd3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.