

INS CASE OWNER

CC6 /AIG1800 4053, Amb3

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

1/2/18

Date / Time:

1/2/18

Registered in Merimen:

20/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLC 2384X

Name of Insured:

OH YONG MENG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

26/2/18

Is driver the owner?

( YES / ☒ NO )

Nature of Accident:

FLEW

If NO, Driver Name / Age:

OH HUI SHUN (Hui Hui SHUN)

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

804344710556

Policy No.:

200464832-01001

Make / Model:

MSSAN

Place of Accident:

PUNHAGOL EAST RD B4 PUNHAGOL

OI GIA REPORT: YES / NO:

☒ YES

/ NO:

TP GIA REPORT: YES / NO

☒ YES

/ NO

Insured Liability: %

Final ? Yes / No

STH 54482



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hua Meng



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

2/2/18

Bevan

24/3/18

Called OIP confirm accident details,  
OIP rtr ended to inform him to  
claim OIP amount NCB issues  
Letter sent to OIP.

pending ATA

RECEIVED 14 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

7 BEVAN

After call ltr to OI:

Documentation Check List: Handler: Typist:

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days)

Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

31/5/18 Confirm with JUNE

Email ☐Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

22

If NO or B 28, Ass. Lia:

Repair Cost:

SS

5300

Loss of Rental (LOR):

SS

500

(5 days)

100

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

745

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent )

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

320 + 20

Total:

SS

5 607.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

SS

Name 1:

HUA MENG SPRAY PAINTING WORKSHOP.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

24/3/18

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJH5448Z Yr Regn: 13/08/08 2008 AugustType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit. cc 1339Colour: Red A/C: Insured / Std / NI / NASp. Reading: 296000 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GE 61107056Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/50R15R: 195/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FalkenFront R/Bal. 06 mmL/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 01/03/18Survey held at Hua MengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG.

MV: 11.5K  
PV: 6.3K  
Nett: 5.2K.

\$5300

(ren 8041.52 / 60.23%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 88026

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) ☐ : S + RS (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_) ☐ : Photos☐ : Tech. Invs (\$ \_\_\_\_\_) ☐ : Others☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18004053/Amb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 02-03-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 2384X	Veh. Inspected	SJH 5448Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	28/02/2018	Inspection Date	01/03/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

TAN SEOK JOO

BLK 196A PUNGGOL FIELD

#04-517

S 021196

TP A16

327-90

Date

:13.03.2018

Vehicle no

:SJH 5448 Z

Make/Model

:HONDA FIT

Accident date

:28.02.2018

No	Description	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 80 ✓
2	Rear tailgate <i>Distorted</i>	1	\$ 736 ✓
3	Rear tailgate hinges @ \$120.00 <i>Not New</i>	2	\$ 240 X
4	Rear tailgate upper lock <i>Damaged</i>	1	\$ 220 ✓
5	Rear tailgate lower lock <i>Not New</i>	1	\$ 38 X
6	Rear tailgate shock absorber @ \$125.00 <i>Not New</i>	2	\$ 250 X
7	Rear tailgate inner board <i>Cracked</i>	1	\$ 195 ✓
8	Rear tailgate FIT emblem <i>new</i>	1	\$ 28.8 ✓
9	Rear tailgate H emblem? <i>Not New</i>	1	\$ 36 ✓
10	Rear tailgate handle	1	\$ 95 X
11	Rear number plate lamp @ \$45.00 <i>Not New</i>	2	\$ 90 X
12	Rear tailgate weather strip <i>lit</i>	1	\$ 92.3 ✓
13	Rear lamp @ \$276.00 <i>Cracked</i>	2	\$ 552 ✓
14	Rear lamp housing @ \$98.00 <i>Reqs</i>	2	\$ 196 X
15	Rear end panel <i>Distorted</i>	1	\$ 295.5 ✓
16	Rear end panel inner top garnish <i>Deformed</i>	1	\$ 107 ✓
17	Rear bumper <i>Deformed</i>	1	\$ 440.3 ✓
18	Rear bumper side holder @ \$18.00 <i>new</i>	2	\$ 36 ✓
19	Rear bumper towing hook cover <i>Not New</i>	1	\$ 65 X
20	Rear bumper PG TRACKIES sticker <i>new</i>	1	\$ -55 <i>20(In)</i>
21	Rear bumper clips (1set) <i>new</i>	1	\$ -70 <i>30</i>
22	Rear fender @ \$626.70 <i>Reqs</i>	2	\$ 1253.4 X
23	Rear fender inner garnish @ \$175.00 <i>Cracked</i>	2	\$ 350 ✓
24	Rear fender inner shield @ \$166.80 <i>Not New</i>	2	\$ 333.6 X
25	Rear spare tyre top board <i>Deformed</i>	1	\$ 185 ✓
26	Rear spare tyre tool sponge <i>Deformed</i>	1	\$ 180 ✓
27	Rear spare tyre well <i>Reqs</i>	1	\$ 737 X
28	Rear exhaust pipe <i>Not</i>	1	\$ 430 ✓
29	Rear bumper bracket @ \$65.00 <i>Not New</i>	2	\$ 130 X
30	Rear spare tyre insulation @ \$95.00 <i>Not New</i>	3	\$ 285 X
31	Rear fender quarter glass rubber @ \$75.00	2	\$ 150 X
			\$ 7951.9
Less 20% Disc			\$ 1590.38
Total			\$ 6361.52

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

TAN SEOK JOO

BLK 196A PUNGGOL FIELD

#04-517

S 021196

Date :13.03.2018

Vehicle no :SJH 5448 Z

Make/Model :HONDA FIT

Accident date :28.02.2018

No	Description	Qty	Amount (\$\$)
<b>Special Nett Items</b>			
1	Rear bumper reverse sensor <i>Damaged</i>	1	\$ 380-200
2	Rear number plate <i>New</i>	1	\$ 50 x
3	Rear number plate holder <i>New</i>	1	\$ 50 x
4	Rear bumper lower lip <i>Behind</i>		\$ 800-350
5	Rear Exhaust Pipe <i>Best</i>		\$ 1280
		<b>Total</b>	

### Labour Cost

1	Towing fee	\$ 100 x
2	To supply rear windscreen sealant	\$ 50 ✓
3	To supply rear end panel inner sealant	\$ 200-60
4	Remove & reinstall rear windscreen	\$ 200-120
5	Remove & reinstall petrol tank	\$ 100 x
6	Remove & reinstall roof lining & cushion	\$ 150-60
7	Remove & reinstall reverse sensor	\$ 150-50
8	Remove & reinstall exhaust pipe	\$ 200-80
9	Remove ,replace & repair consistent to the accident	\$ 2600-1800
10	Respray painting	\$ 1800-1000
11	Tuff kote	\$ 150-40
	<b>Total</b>	\$ 5700
	<b>Grand Total</b>	\$ 13341.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 6662.32  
H/S: 15.3K.  
06/03/18



華 明 噴 漆 廠  
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref :

Our Ref :

Date: 25.05.2018

Attn: Motor Claims Dept

**ACCIDENT ON 28.02.2018 INVOLVING VEHICLE SJH 5448 Z & SLC 2384 X ALONG  
PUNGGOL EAST**

With regards to the above, we are writing on behalf of the registered owner of vehicle SJH 5448 Z which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SLC 2384 X. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair Cost	\$	5,300.00
2) Loss of rental-\$120 X 05days	\$	600.00
3) LTA serach	\$	7.45
<b>Total</b>	<b>\$</b>	<b>5,907.45</b>

We hereby enclosed herewith the following documents for your consideration of the above claim.

a) Final Repair Bill Of SJH 5448 Z

c) LTA SEARCH

b) GIA report

d) Owner / Driver NRIC & Driving License

華 明 噴 漆 廠  
HUA MENG SPRAY PAINTING WORKSHOP  
AUTOBAY@KAKI BUKIT  
1, KAKI BUKIT AVE 6 #01-34 SINGAPORE 417883  
TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,

HUA MENG SPRAY PAINTING WORKSHOP



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC6/AIG18004053/Amb3**

04 APRIL 2018

**OH YONG HENG**  
BLK 253 HOUGANG AVENUE 3  
#03-324  
SINGAPORE 530253

Dear Sir/Madam,

**ACCIDENT INVOLVING SLC 2384X AND SJH 5448Z ON 28/02/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim  
Case Handler  
DID: 6749 4274  
FAX: 6741 4108  
Email: [bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)




## AUTHORISATION TO ACT

I/We, Tan Suk Joo ("the third party claimant") of  
81K196A Punggol Road #04-517. S10211967 (address),  
owner of SJH54482 (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**  
**WORKSHOP** ("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SJH54482 that was damaged pursuant  
to the accident which occurred on 28-02-2018 (date) along Punggol East  
(location) involving vehicle no/s SLC2384X ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem  
fit and the workshop is further authorized to receive payment further to settlement of my claim  
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 28 (day) of Feb (month) 2018 (year)

  
Signed by "the third party claimant"  
(with chop if applicable)

華明噴漆廠  
HUA MENG SPRAY PAINTING WORKSHOP  
AUTOMATE KAKI BUKIT  
SUNT WE 5 #01/84 SINGAPORE 41786.  
TEL: 786 6746 5519 / FAX 6743 4891

Signed by "the workshop"  
(with company stamp)



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, HUA MENG SPRAY PAINTING ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5,300.00 (Repair Cost), S\$500.00 (Loss of Use/Rental), S\$ 7.45 (Disbursement) for vehicle no. SJH 5448Z that was damaged pursuant to the accident which occurred on 28/02/2018 (date) along PUNGGOL EAST (location) involving vehicle no/s SLC 2384X. This is pursuant to the inspection conducted on 01/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN SEOK JOO ("the third party claimant") of vehicle no. SJH 5448Z make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJH 5448Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 4 (day) of June (month) 2018 (year)



Signed by appointed surveyor

明噴漆廠  
HUA MENG SPRAY PAINTING WORKSHOP  
AUTOBAY@KAKI BUKIT  
1001 JALAN SINGAPORE 417883  
TEL: 6743 4896 FAX: 6743 4896

Signed by "the workshop" (with chop)

WITHOUT PREJUDICE  
TO OUR CLIENT'S PERSONAL INJURY  
CLAIM (PRESENT OR FUTURE) WHICH IS  
EXPRESSLY RESERVED



華 明 噴 漆 廠  
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref : SLC 23844

Our Ref : SJH 5448 Z

18/5/2018

Date:.....

VEHICLE NO :SJH 5448 Z  
MAKE / MODEL :HONDA FIT  
NAME :TAN SEOK JOO  
ADDRESS :BLK 196A PUNGGOL ROAD  
#04-517  
S 021196

FINAL REPAIR BILL FOR VEHICLE NO: SJH 5448 Z

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR  
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING  
(LUMP SUM REPAIR)

\$ 5,300.00

SINGAPORE DOLLARS:FIVE THOUSAND THREE HUNDRED ONLY



# INVOICE

KS LEASING  
BLK 606 WOODLANDS RING ROAD  
#11-267 S'PORE 730606  
ROB: 53367173J  
Singapore  
9387 4964

BILL TO  
TAN TECK WEE

Invoice Number: 97820202  
Invoice Date: March 9, 2018  
Payment Due: March 9, 2018  
Amount Due (SGD): \$0.00

Rental	Days	Rate	Amount
CAR DAILY RENTAL	5	\$120.00	\$600.00

Total: \$600.00

Payment on March 9, 2018 using cash: \$600.00

Amount Due (SGD) : \$0.00



Company No: 1060857-K  
Email: ksl@ksleasing.com

S/NO: \_\_\_\_\_

DATE: \_\_\_\_\_

## RENTAL AGREEMENT

### HIRER'S PARTICULARS

Name: TAN TECK WEE

Address: 811C 196A PULGUA FIELD

#04-517 2 (82196)

NRIC/Passport No: S8224776I Country: SINGAPORE

Occupation: OUTDOOR TECH

Date of Birth: 02 Age: \_\_\_\_\_

Driving Licence No: \_\_\_\_\_ Date Passed: \_\_\_\_\_

Tel (Mobile): \_\_\_\_\_ (Residence): \_\_\_\_\_

### DRIVER'S PARTICULARS

Name: \_\_\_\_\_

Address: \_\_\_\_\_

NRIC/Passport No: \_\_\_\_\_ Country: \_\_\_\_\_

Occupation: \_\_\_\_\_

Date of Birth: \_\_\_\_\_ Age: \_\_\_\_\_

Driving Licence No: \_\_\_\_\_ Date Passed: \_\_\_\_\_

Tel (Mobile): \_\_\_\_\_ (Residence): \_\_\_\_\_

Make/Model: <u>MIT Lancer</u>	Vehicle No: <u>SJK 9782R</u>
Date & Time Out: <u>28/2/18 1300 hrs</u>	Date & Time In: <u>7/3/18 (97730 hrs)</u>
<div><div></div><div>0</div><div>1/4</div><div>Full</div></div> Mileage Out: _____	<div><div></div><div>0</div><div>1/4</div><div>Full</div></div> Mileage In: _____
DAILY RENTAL CHARGES: \$ _____	DEPOSIT: \$ _____
TOTAL DAYS USAGES: _____	TOTAL RENTAL: \$ _____

Remarks: petrol full - out.

### Terms & Conditions:

- 1 No Insurance Coverage if the driver is below 24 years old or less than 2 years driving licence.
- 2 This vehicle is licenced to carry \_\_\_\_\_ passengers only.
- 3 Hirer is liable to pay first \$ \_\_\_\_\_ as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
- 4 For usage to Malaysia subject to higher excess all claim of S\$5000/- and different rental rate.
- 5 Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
- 6 No refund will be given for vehicle which returns early.
- 7 No refund will be given for petrol left in the vehicle.
- 8 Hirer is liable to pay all parking fines and traffic summonses should there be any during renting period.
- 9 Vehicle to be return during office hour only.

  
Hirer's Signature

\_\_\_\_\_  
Driver Signature



\* I/We have read and understood the Terms & Conditions above and hereby agreed to abide.

Copyright © 2017 KS LEASING

2/28/2018

Vehicle Hub

**Enquire Vehicle & Owner Information ( Vehicle No. SLC2384X As At 28 Feb 2018 / 06:50:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: H47 (SJH5448Z) - YL

**Current Owner Details**

Owner ID Type: Singapore NRIC  
Owner ID: S0196323F  
Owner Name: OH YONG HENG  
Registered Address Type: HDB / HUDC  
Registered Block/House No.: 253  
Registered Street Name: HOUGANG AVENUE 3  
Registered Unit No.: # 03 - 324  
Registered Building Name: -  
Registered Postal Code: 530253

**Current Vehicle Details**

Vehicle No.: SLC2384X  
Make Description/Model: NISSAN / SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR  
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Feb 2018 <a href="#">Edit Reg</a>		01 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$55,300.00</b> <a href="#">Edit Estimates</a>	<b>\$55,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>OH YONG HENG</b> , ID: 50196323F								
Main Claimant:	<b>TAN SEOK JOO</b> , ID: S8008802G								
Vehicle Reg. No.:	<b>SJH5448Z</b>	Date of Loss:	28/02/2018 06:00 - :59 [114 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 8243447105SG</b>	Policy/Cover Note No.:	2100464832 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLC2384X</b>	Policy No. (Claimant):	DMPPHQ17-004143						
		Excess:							
Repairer:	<b>Hua Meng Spray Painting Workshop (HQ)</b> No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com								
Claimant's Insurer:	<b>EQ Insurance Company Ltd (HQ)</b> - Tel: 6223 9433								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 29/03/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



























## Claim Documents

\*SJH5448Z (8243447105SG)  
[SLC2384X]  
TP  
TAN SEOK JOO  
Feb 28 2018 6:00AM  
[OH YONG HENG]  
Hua Meng Spray Painting Workshop








Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Letters/Correspondences														1 per page		<div></div>	<div></div>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown												<div>1</div>	Edit			
Assessment Reports														1 per page		<div></div>	<div></div>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	21/03/18 11:53	Accident Statement From: SC - Reg. No: SLC2384X, Claimant: OH YONG HENG												<div>1</div>	Load HTM			
Photos/Images														3 per page		<div></div>	<div></div>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
2	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
3	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
4	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
5	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
6	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
7	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
8	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
9	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
10	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
11	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
12	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
13	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
14	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
15	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
16	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
17	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
18	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
19	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
20	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
21	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
22	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
23	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
24	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
25	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
26	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
27	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
28	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
29	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		
30	10/05/18 18:34	General View												<div>1</div>	Load JPG	<div></div>		



Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)		
31	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/05/18 18:34	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	10/05/18 18:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/18 14:37	TP GIA REPORT	 Load PDF	
2	04/04/18 08:58	LETTER TO OI	 Load PDF	
3	18/06/18 16:01	WORKSHOP INVOICE	 Load PDF	
4	18/06/18 16:01	AUTHORISATION TO ACT FORM	 Load PDF	
5	18/06/18 16:01	Release Voucher	 Load PDF	
6	18/06/18 16:01	RENTAL RECEIPT	 Load PDF	
7	18/06/18 16:01	LTA SEARCH	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLC2384X (Insd veh)	Model:	HONDA FIT 1.3 G
	SJH5448Z (TP veh)		F-PACKAGE SKYROOF (A)
Date of Accident:	28/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	14,197.52
Final Repair Cost	:	\$	5,300.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,807.45

**Is Third Party Workshop GIA Registered?** ☐ YES ☒ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ 100 (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Hua Meng Spray Painting Workshop	:	\$ 5,807.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

18 Jun  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18004053/AMB3Q2

Date: 18/06/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100464832  
**Claimant Vehicle** SJH5448Z **Insured Vehicle No :** SLC2384X  
**No :**  
 Date of Loss: 28/02/2018 Nature of Claim: TP Claim No: 8243447105SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJH5448Z**  
 Make & Model: HONDA FIT, 1.3 G F-Package Skyroof (A) Engine No: L13A4118949  
 Reg. Date: 13/08/2008 (Man. Year: 2008) Chassis No: GE61107056  
 Colour: Red Odometer: 296000 km  
 Engine Capacity: 1339 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,497.52	4,202.32	4,295.20	50.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	2,460.00	3,240.00	56.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,197.52</b>	<b>6,662.32</b>	<b>7,535.20</b>	<b>53.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,197.52</b>	<b>5,300.00</b>	<b>8,897.52</b>	<b>62.67</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,807.45</b>		

## INSPECTION

Date of Assignment: 01/03/2018  
 Date Inspected: 01/03/2018 Inspected At: Hua Meng Spray Painting Workshop (HQ)  
 No 1 Kaki Bukit Avenue 6, #01-61  
 Autobay@Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Lim Chin Siong Bevan

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	80.00 FL	*80.00 FL
2	1		*REAR TAILGATE	Distorted	736.00 FL	*736.00 FL
3	2		*REAR TAILGATE HINGES	Not Necessary	240.00 FL	*- FL
4	1		*REAR TAILGATE UPPER LOCK	Damaged	220.00 FL	*220.00 FL
5	1		*REAR TAILGATE LOWER LOCK	Not Necessary	38.00 FL	*- FL
6	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	250.00 FL	*- FL
7	1		*REAR TAILGATE INNER BOARD	Cracked	195.00 FL	*195.00 FL
8	1		*REAR TAILGATE FIT EMBLEM	Necessary	28.80 FL	*28.80 FL
9	1		*REAR TAILGATE H EMBLEM	Not Necessary	36.00 FL	*- FL
10	1		*REAR TAILGATE HANDLE	Not Necessary	95.00 FL	*- FL
11	2		*REAR NUMBER PLATE LAMP	Not Necessary	90.00 FL	*- FL
12	1		*REAR TAILGATE WEATHER STRIP	Cut	92.30 FL	*92.30 FL
13	2		*REAR LAMP	Cracked	552.00 FL	*552.00 FL
14	2		*REAR LAMP HOUSING	Repair	196.00 FL	*- FL
15	1		*REAR END PANEL	Dented	295.50 FL	*295.50 FL
16	1		*REAR END PANEL INNER TOP GARNISH	Deformed	107.00 FL	*107.00 FL
17	1		*REAR BUMPER	Deformed	440.30 FL	*440.30 FL
18	2		*REAR BUMPER SIDE HOLDER	Necessary	36.00 FL	*36.00 FL
19	1		*REAR BUMPER TOWING HOOK COVER	Not Necessary	65.00 FL	*- FL
20	1		*REAR BUMPER PG TRACKIES STICKER	Necessary	44.00 FS	*30.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
22	2		*REAR FENDER	Repair	1,253.40 FL	*- FL
23	2		*REAR FENDER INNER GARNISH	Cracked	350.00 FL	*350.00 FL
24	2		*REAR FENDER INNER SHIELD	Not Necessary	333.60 FL	*- FL
25	1		*REAR SPARE TYRE TOP BOARD	Deformed	185.00 FL	*185.00 FL
26	1		*REAR SPARE TYRE TOOL SPONGE	Deformed	180.00 FL	*180.00 FL
27	1		*REAR SPARE TYRE WELL	Repair	737.00 FL	*- FL
28	2		*REAR BUMPER BRACKET	Not Necessary	130.00 FL	*- FL
29	3		*REAR SPARE TYRE INSULATION	Not Necessary	285.00 FL	*- FL
30	2		*REAR FENDER QUARTER GLASS RUBBER	Not Necessary	150.00 FL	*- FL
31	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
32	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
33	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
34	1		*REAR BUMPER LOWER LIP	Deformed	800.00 FS	*350.00 FS
35	1		*REAR EXHAUST PIPE	Bent	1,200.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

<b>Sub Total (\$\$)</b>	<b>9,990.90</b>	<b>4,907.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,493.38</b>	<b>705.58</b>
<b>Total Parts (\$\$)</b>	<b>8,497.52</b>	<b>4,202.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	100.00	0.00
2	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
3	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
4	REMOVE & REINSTALL REAR WINDSCREEN	New	200.00	120.00
5	REMOVE & REINSTALL PETROL TANK	New	100.00	0.00
6	REMOVE & REINSTALL ROOF LINING & CUSHION	New	150.00	60.00
7	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
8	REMOVE & REINSTALL EXHAUST PIPE	New	200.00	80.00
9	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	2,600.00	1,000.00
10	RESPRAY PAINTING	New	1,800.00	1,000.00
11	TUFF KOTE	New	150.00	40.00
Gross Labour Cost (S\$)			<b>5,700.00</b>	<b>2,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >