

SJW 5423R.

Date

No.

Kia Cerato Forte

KNAFW411MAS186101

Rees Bumper Deformed	586.50	✓
Rees Bumper Clips New	30	✓
Rees Bumper Side Holder x02 New	32.6x2=65.20	✓
Rees Bumper Lower Spoiler Deformed	980(SN) 780(SN)	
Rees Bumper Sponge Deformed	174	✓
Rees Bumper Reinforcement crumpled	279	✓
Rees Bumper Reinforcement Stay x02 Bent	135x2=270	✓
Rees Bumper Reinforcement Bracket x05. Dmgd	24x5=120	✓
Reverse Sensor x04 Dmgd.	220x4=880 250(SN)	
Rees End Panel Deformed	385	✓
Rees End Panel Top Garnish Deformed	89.50	✓
Rees End Panel Sealant New	60(SN)	✓
Tailfin x02 Crumpled.	246x2=492	✓
Tailfin Sponge Gasket x02 New	20x2=40	✓
Bootlid Buckled.	685	✓
Bootlid Lock Damaged.	104.70	✓
Bootlid Lock Sensor Crumpled	81.90	✓
Bootlid Weatherstripe Lit	89.90	✓
Bootlid Zones Trim 2 New	168	✓
Bootlid Zones Trim Clips.	30	X
Bootlid Reflector x02 New	130.9x2=261.80	+
Bootlid Reflector Sponge Gasket x02 New	20x2=40	+
Kia Logo	46	✓
Cerato Wordmark	38	✓
Forte Wordmark	37	✓
Cycle and carriage Logo.	32	✓
Rees Fender Zones Trim x02 2 New	268.5x2=537	+
Rees Fender Zones Trim Clips.	60	+
Rees Exhaust Pipe Repairs	686	+
Rees Exhaust Mounting New	44	+



STW5423R

Spare Tyre Panel Top Cover: Delivered

Date

No.

179

Panel Bending

Spray Painting

Welding

To undersell

To remove reverse sensor

To remove upholstery

To remove exhaust pipe

To transfer bootlid fittings

~~1200~~ 1000

~~1400~~ 1200

~~50~~ 30

~~150~~ 50

~~100~~ 50

~~150~~ 60

~~150~~ 80

~~150~~ 60

List: 382510

inc 10%: 344259

S.N: 1090

Labour: 2330

total: 706259

1/sr 56K 06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10921.90

