

REF: CS/GAL18004109/Kvb22

Special Instruction:

From (Person): Rachel Tan of GAL Date/Time: 23 02 2018
Estimated Cost: _____ Bill to: _____

45. \$ 14600.00

Third Parties:

Claimant:

Surveyor: Chartered Auto

Workshop: Wien Her

OD/TP Re-inspection) / Evaluation

To Inspect Vehicle No: SLB 218Y Insured: _____
at Workshop m/s Lian Hermitus Tel: 8399 0599 (James)
of Blk 5038 AMK Ind Park 2 #01-405
Policy No: _____ Claim No: CLMOMVP00000402
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. _____

05.03.2018 (monday) @ 11am

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 11/12 Confirmed with Final Fig , days (Red S / %; Original 114 days)

Date/Time: 12/4/18 Submit Final Fig LS 5900, 07 days (Red S 8700 / 60 %; Original days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 12 APR 2015

Para(3) : Nett Value

Market Value :

Salvage Value : _____

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add	
Transport	
Photos	
Others	
Total	

390

1) Date/Time 12/14 - typist File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days:

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLP 2984

Yr Regn:

17

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toy CHR

CC

1797

Colour:

M. Silver

A/O

Insured / Std / NI / NA

Sp Reading:

41525

T Radio Insured / Std / NI / NA

Eng No:

C No:

84X10

2063785

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

215/50R17

R:

BS ☒ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal:

3

mm

R/Bal:

4

mm

L/Bal:

3

mm

L/Bal:

4

mm

D.O.A.

D.O.A.

5/3/17

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Data/Time: File Pass 10/

☐

Preli. Report

☐

Final Report

Data/Time: File Return 10/

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

W 3480 130

Pilot

Chief

Technician

Report Format:

Lump Sum / I.B. / B

Add Fee:

☐

Site Insp

\$

☐

Interview

\$

☐

Technician

\$

☐

Witness

\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18004109/Kvb

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 03-03-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	Veh. Inspected	SLS 2918Y
Policy No.	Coverage (\$)	0.00
Claim No. CLMOMVP000000402	Excess (\$)	0.00
Assign From RACHEL TAN	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	Inspection Date	05/03/2018
Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Friday, 23 February, 2018 10:21 PM
To: Prestina Moh
Cc: LKK Assignments
Subject: RE: **RE-INSPECTION** Y/ref: CLMOMVP000000402 O/ref: AM1.ylv.INS.L141.104701.17.pmv

Without Prejudice

Dear Prestina

Thank you for making arrangement. We will be appointing LKK to conduct the re-inspection.

Dear LKK

Please accept appointment to conduct re-inspection.

Thank you.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Prestina Moh [mailto:prestinaamoh@visionlawllc.com]
Sent: Thursday, February 22, 2018 3:47 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: **RE-INSPECTION** Y/ref: CLMOMVP000000402 O/ref: AM1.ylv.INS.L141.104701.17.pmv

WITHOUT PREJUDICE

Our ref: AM1.ylv.INS.L141.104701.17.pmv

We refer to your request for a re-inspection on our client's vehicle, **SLS 2918 Y**.

Please be informed that the re-inspection as per your request has been arranged as follows:-

Date : 05 MARCH 2018 (MONDAY)
Time : AT 11:00 A.M.
Venue : LIAN HER MOTORS
BLOCK 5038 ANG MO KIO AVENUE 3
#01-405 ANG MO KIO INDUSTRIAL PARK 2
Singapore 569541
Contact: MR. JAMES (TEL: 8299 0599)

Accordingly, kindly ensure the attendance of your appointed surveyor at the above arranged re-inspection without fail.

Please let us have your written confirmation and the name and contact number of your appointed surveyor.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

LIAN HER MOTORS

Bik 5038 Ang Mo Kio Industrial Park 2 #01-405 Singapore 569541
TEL : 64812027 / FAX : 64816131 / EMAIL : lhcar@hotmail.sg

LH CAR RENTAL PTE LTD

BLK 5038 ANG MO KIO INDUSTRIAL PARK 2

#01-405 Singapore 569541

INVOICE : 2918/A/2017

Vehicle No. :	SLS 2918 Y	Date	08/11/2017
Make :	TOYOTA C-HR		

DESCRIPTION		AMOUNT
	REPAIR COST	\$14,600.00
		\$14,600.00

All cheques should be crossed and made payable to LIAN HER MOTORS

LIAN HER MOTORS

7/11

CHARTERED AUTO ASSESSORS

17 Joo Seng Road #08-129 Joo Seng Heights Singapore 360017 Reg No. 26910200X
Tel: +65 9631 7008 Fax: +65 6281 9989 Email: charteredauto@gmail.com

L H Car Rental Private Limited
Block 5038 Ang Mo Kio Industrial Park 2, #01-405
Singapore, 569541


Invoice No : 1710144

Date : 11 November, 2017

DESCRIPTION		AMOUNT
Your Ref	: SLS 2918 Y	
Our Ref	: 201710254/CA	
Vehicle No	: SLS 2918 Y	
Workshop	: Lian Her Motors	
Survey Fee		1,003.00
Out of Pocket Expenses:		
Photographs		
Transport		
Total		: \$ 1,003.00

Please make cheque payment to: CHARTERED AUTO ASSESSORS

CHARTERED AUTO ASSESSORS



Authorised Signature

CHARTERED AUTO ASSESSORS

17 Joo Seng Road #08-129 Joo Seng Heights Singapore 360017 Reg No. 26910200X
Tel: +65 9631 7008 Fax: +65 6281 9989 Email: charteredauto@gmail.com

L H Car Rental Private Limited
Block 5038 Ang Mo Kio Industrial Park 2, #01-405
Singapore, 569541

Your Ref : SLS 2918 Y
Our Ref : 201710254/CA
Date : 11 November, 2017
Survey : Third Party

SURVEY REPORT

PARTICULARS OF VEHICLE

Vehicle No.	: SLS 2918 Y	Propellant	: Petrol - Electric, Auto
Make	: Toyota	Capacity	: 1800 cc
Type of Body	: 5 Doors SUV	Mileage	: 7536
Year & Model	: 2017, C-HR, Hybrid	Engine No	: 2ZR8166525
Colour	: Silver	Chassis No	: ZYX102063785
Passenger-cap	: 4	Road Tax	: March, 2018

TYRES CONDITIONS

Front Left	: Dunlop	Worn	: New	Size	: 215/60 R17
Front Right	: Dunlop	Worn	: New	Size	: 215/60 R17
Rear Left	: Dunlop	Worn	: New	Size	: 215/60 R17
Rear Right	: Dunlop	Worn	: New	Size	: 215/60 R17

PRE-ACCIDENT CONDITION (Static Test Only)

Handbrake	: Serviceable	Steering	: Serviceable
Footbrake	: Serviceable	Paintwork	: Good

QUANTUM

Repair Estimate : \$ 20,010.93
Revised Amount : \$ 14,600.00 (Lump-sum Without Prejudice)

Under normal circumstances, the repair period would be: fourteen (14) days.
We have not authorised repairs.

Survey Done At : Lian Her Motors
Block 5038 Ang Mo Kio Industrial Park 2, #01-405
Singapore, 569541

Assignment Date : 25 October, 2017
Survey Date : 25 October, 2017
Accident Date : 17 October, 2017
Assignment Given By : L H Car Rental Private Limited

Our Ref: 201710254/CA

Vehicle No. SLS 2918 Y

Description	Qty	Repair Estimate	Revised Amount	Remarks
Rear fender assy o/s	1	1,204.20	1,204.20	Bent 2 crs
Rear fender wheelarch garnish o/s	1	148.08	148.08	Torn/Deformed
Rear fender wheelarch garnish inner sticker o/s	1	28.70	28.70	To replace
Rear fender wheelarch garnish clip o/s	7	90.30	90.30	To replace
Rear fender lower shield o/s	1	165.30	165.30	Bent/Deformed
Rear fender lower shield clip o/s	6	77.40	77.40	To replace
Rear door assy o/s 1245.01	1	1,204.20	1,204.20	Badly Bent
Rear door inner rubber stopper o/s	2	57.20	57.20	To replace
Rear door outer protector o/s	1	203.70	203.70	Torn/Deformed
Rear door outer protector clip o/s	8	103.20	103.20	To replace
Rear door inner lock assy o/s	1	544.70	544.70	Bent X
Rear door outer handle o/s	1	339.50	339.50	Holder Broken
Rear door outer handle holder plate rivert o/s	2	25.80	25.80	To replace
Rear door weatherstrip o/s	1	174.01	174.01	To replace
Rear door glass regulator o/s	1	201.70	201.70	Bent
Rear door glass regulator motor o/s	1	779.10	779.10	Damaged
Rear door glass channel o/s	1	103.80	103.80	To replace
Rear door glass channel bracket o/s	1	123.20	123.20	Bent
Rear door window vertical black sticker o/s	1	38.90	38.90	To replace
Rear door window top black moulding o/s	1	134.20	134.20	To replace
Rear door window top black moulding rivert o/s	7	90.30	90.30	To replace
Rear door glass outer scrap moulding o/s	1	175.30	175.30	To replace
Rear door hinge o/s	2	168.20	168.20	Bent X
Rear door checker n/s	1	128.60	128.60	Bent X
Rear door inner board o/s	1	752.50	752.50	Torn X
Rear door inner board clip o/s	8	103.20	103.20	To replace X
Front door assy o/s	1	1,295.01	1,295.01	Bent 2 crs
Front door window vertical black sticker o/s	1	38.90	38.90	To replace
Front door window top black moulding o/s	1	178.60	178.60	To replace
Front door window top black moulding rivert o/s	8	103.20	103.20	To replace
Front door inner rubber stopper o/s	2	57.20	57.20	To replace
Front door weatherstrip o/s	1	174.40	174.40	To replace X
Front door outer protector o/s	1	335.70	335.70	Grazed/Deformed
Front door outer protector clip o/s	8	103.20	103.20	To replace
Rocker panel side skirting o/s	1	546.71	546.71	Torn/Deformed X
Rocker panel side skirting clip o/s	8	103.20	103.20	To replace X
Rear lower arm o/s	1	497.50	497.50	Bent X
Rear upper control arm o/s	1	200.80	200.80	Bent X
Rear trailing arm o/s	1	185.70	185.70	Bent X
Rear trailing arm bracket o/s	1	82.10	82.10	Bent X
Rear knuckle arm o/s	1	847.12	847.12	Bent X
Rear knuckle bearing hub assy o/s	1	672.90	672.90	Bent X
Rear shock absorber o/s	1	407.60	407.60	Bent X
Rear stabiliser bar stay o/s	1	205.80	205.80	Bent X

13,200.93

13,200.93

3,300.23 Less 25%

Page Total :

13,200.93

9,900.70

Our Ref: 201710254/CA

Vehicle No. SLS 2918 Y

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		13,200.93	9,900.70	
Rear alloy sport rim o/s	S.Nett 1	950.00	950.00	Grazed/Bent
Rear 17" tyre o/s	S.Nett 1	380.00	<i>nil</i> 380.00	Damaged <i>X</i>
Total Materials Cost :		14,530.93	11,230.70	

(To remove all damaged parts with all necessary components/attachments. To apply hot-works where necessary, straighten chassis members, repair/reshape dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.

2,000.00 1,750.00 *750*

To remove/refit roof lining. To remove/refit seats, carpets and interior garnishes to enable repairs.

280.00 250.00 *100*

To remove/refit boot garnishes, speakers, interior garnishes, carpets where necessary.

200.00 150.00

To conduct wheel alignment (Before & After).

240.00 240.00 *120*

To remove/refit rear undercarriage/suspension assembly with all attachments/components.

350.00 *~* 320.00 *X*

(To renew wheel rim/tyre and conduct wheel balancing.

120.00 120.00 *20*

Page Total: 17,720.93 14,060.70

Our Ref: 201710254/CA

Vehicle No. SLS 2918 Y

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		17,720.93	14,060.70	
To transfer o/s rear door window mechanisms with motor assembly, door glass and all attachments.		180.00	150.00	
To transfer o/s front door window mechanisms with motor assembly, door glass and all attachments.		180.00	150.00	
To remove/refit wire harness, all related connectors. Check proper function.		150.00	120.00	
To spray paint o/s rear fender, o/s rear wheelarch garnish, o/s rear door, o/s rear door protector, o/s centre pillar, o/s front door, o/s front door protector, o/s running board, o/s running board side skirting and etc., inclusive of preparatory works and painting materials.		1,600.00	1,400.00	
To apply underseal and rust-proofing on the affected areas.		180.00	150.00	
Grand Total:		20,010.93	16,030.70	

Summary

Total Material	14,530.93	11,230.70
Total Labour/Painting	5,480.00	4,800.00
Grand Total	20,010.93	16,030.70
Lump-sum Amount		<u>14,600.00</u>

Our Ref: 201710254/CA

Vehicle No. SLS 2918 Y

CAUSE OF DAMAGE

The vehicle sustained impact along the offside, more to the rear.

REMARKS

Having checked the scope of repair works we were satisfied that it was in accordance with the damage sustained. We also checked each item and have indicated its nature of damage. It was our opinion that these items were found damaged beyond repair and require replacement.

A reinspection was carried out after completion of the repairs.


Photographs showing the damaged vehicle and reinspection pictures were enclosed.

We checked the damage carefully and were of the opinion that the vehicle could be repaired.

We would therefore recommend repairs to be carried out at: \$ 14,600.00 on a lump-sum basis.

The survey was conducted on a without prejudice basis and we submit this report for your consideration.

CHARTERED AUTO ASSESSORS



Tan Chin Suan (Licensed Appraiser)
AMLMU, T Eng (CEB) AMLM, (U.K)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18004109/Kvbe2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 12-04-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SKC 4320D	Veh. Inspected	SLS 2918Y
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000000402	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CHR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102063785	Colour	METALLIC GREY
Odometer	41525	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R16	DUNLOP	3 mm
L/H Front Tyre	215/50 R16	DUNLOP	3 mm
R/H Rear Tyre	215/50 R16	DUNLOP	4 mm
L/H Rear Tyre	215/50 R16	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	17/10/2017	Inspection Date	05/03/2018
Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2918Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER WHEELARCH GARNISH O/S	NOT CHANGED	148.08	-
1	REAR FENDER WHEELARCH GARNISH INNER STICKER O/S	REPLACED	28.70	28.70
7	REAR FENDER WHEELARCH GARNISH CLIP O/S	REPLACED	90.30	90.30
1	REAR FENDER LOWER SHIELD O/S	NOT CHANGED	165.30	-
6	REAR FENDER LOWER SHIELD CLIP O/S	NOT NECESSARY	77.40	-
1	REAR DOOR ASSY O/S	REPLACED	1,204.20	1,204.20
2	REAR DOOR INNER RUBBER STOPPER O/S	REPLACED	57.20	57.20
1	REAR DOOR OUTER PROTECTOR O/S	REPLACED	203.70	203.70
8	REAR DOOR OUTER PROTECTOR CLIP O/S	REPLACED	103.20	103.20
1	REAR DOOR INNER LOCK ASSY O/S	REPAIRED SEE LABOUR	544.70	-
1	REAR DOOR OUTER HANDLE O/S	NOT CHANGED	339.50	-
2	REAR DOOR OUTER HANDLE HOLDER PLATE RIVERT O/S	NOT NECESSARY	25.80	-
1	REAR DOOR WEATHERSTRIP O/S	NOT CHANGED	174.01	-
1	REAR DOOR GLASS REGULATOR O/S	REPLACED	201.70	201.70
1	REAR DOOR GLASS REGULATOR MOTOR O/S	REPLACED	779.10	779.10
1	REAR DOOR GLASS CHANNEL O/S	NOT CHANGED	103.80	-
1	REAR DOOR GLASS CHANNEL BRACKET O/S	NOT CHANGED	123.20	-
1	REAR DOOR WINDOW VERTICAL BLACK STICKER O/S	REPLACED	38.90	38.90
1	REAR DOOR WINDOW TOP BLACK MOULDING O/S	REPLACED	134.20	134.20
7	REAR DOOR WINDOW TOP BLACK MOULDING RIVERT O/S	REPLACED	90.30	90.30
1	REAR DOOR GLASS OUTER SCRAP MOULDING O/S	REPLACED	175.30	175.30
2	REAR DOOR HINGE O/S	REPAIRED SEE LABOUR	168.20	-
1	REAR DOOR CHECKER O/S	SERVICEABLE	128.60	-
1	REAR DOOR INNER BOARD O/S	NOT CHANGED	752.50	-
8	REAR DOOR INNER BOARD CLIP O/S	NOT NECESSARY	103.20	-
1	FRONT DOOR WINDOW VERTICAL BLACK STICKER O/S	REPLACED	38.90	38.90
1	FRONT DOOR WINDOW TOP BLACK MOULDING O/S	REPLACED	178.60	178.60

Report Ref No. CS/GAI18004109/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	FRONT DOOR WINDOW TOP BLACK MOULDING RIVERT O/S	REPLACED	103.20	103.20
2	FRONT DOOR INNER RUBBER STOPPER O/S	REPLACED	57.20	57.20
1	FRONT DOOR WEATHERSTRIP O/S	NOT CHANGED	174.40	-
1	FRONT DOOR OUTER PROTECTOR O/S	REPLACED	335.70	335.70
8	FRONT DOOR OUTER PROTECTOR CLIP O/S	REPLACED	103.20	103.20
1	ROCKER PANEL SIDE SKIRTING O/S	NOT CHANGED	546.71	-
8	ROCKER PANEL SIDE SKIRTING CLIP O/S	NOT NECESSARY	103.20	-
1	REAR LOWER ARM O/S	NOT CHANGED	497.50	-
1	REAR UPPER CONTROL ARM O/S	NOT CHANGED	200.80	-
1	REAR TRAILING ARM O/S	NOT CHANGED	185.70	-
1	REAR TRAILING ARM BRACKET O/S	NOT CHANGED	82.10	-
1	REAR KNUCKLE ARM O/S	NOT CHANGED	847.12	-
1	REAR KNUCKLE BEARING HUB ASSY O/S	NOT CHANGED	672.90	-
1	REAR SHOCK ABSORBER O/S	NOT CHANGED	407.60	-
1	REAR STABILISER BAR STAY O/S	NOT CHANGED	205.80	-
	LESS 25% DISCOUNT		-	-980.90
			10,701.72	2,942.70
	SPECIAL NETT ITEMS			
1	REAR FENDER ASSY O/S (LOCAL REPAIR) (SN)	REPAIRED SEE LABOUR	1,204.20	200.00
1	FRONT DOOR ASSY O/S (LOCAL REPAIR) (SN)	REPAIRED SEE LABOUR	1,295.01	200.00
1	REAR ALLOY SPORT RIM O/S (SN)	REPLACED	950.00	950.00
1	REAR 17" TYRE O/S (SN)	NOT CHANGED	380.00	-
			3,829.21	1,350.00

Report Ref No. CS/GAI18004109/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ ATTACHMENTS. TO APPLY HOT-WORKS WHERE NECESSARY, STRAIGHTEN CHASSIS MEMBERS, REPAIR/RESHAPE DENTED BODY PANELS, IN ACCORDANCE WITH FACTORY SPECIFICATIONS. REPLACE DAMAGED PARTS, REFIT AND ALIGN INTO POSITION. REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. INCLUSIVE OF THE REPAIR OF REAR DOOR INNER LOCK ASSY O/S, REAR DOOR HINGE O/S, FRONT DOOR ASSY O/S AND REAR ALLOY SPORT RIM O/S.		2,000.00	750.00
	TO REMOVE / REFIT ROOF LINING. TO REMOVE / REFIT SEATS, CARPET AND INTERIOR GARNISHES TO ENABLE REPAIRS.		280.00	100.00
	TO REMOVE/ REFIT BOOT GARNISHES, SPEAKERS, INTERIOR GARNISHES, CARPETS WHERE NECESSARY.		200.00	150.00
	TO CONDUCT WHEEL ALIGNMENT (BEFORE & AFTER)		240.00	120.00
	TO REMOVE/ REFIT REAR UNDERCARRIAGE / SUSPENSION ASSEMBLY WITH ALL ATTACHMENTS / COMPONENTS.	NOT NECESSARY	350.00	-
	TO RENEW WHEEL RIM/ TYRE AND CONDUCT WHEEL BALANCING.		120.00	20.00
	TO TRANSFER O/S REAR DOOR WINDOW MECHANISMS WITH MOTOR ASSEMBLY, DOOR GLASS AND ALL ATTACHMENTS.		180.00	150.00
	TO TRANSFER O/S FRONT DOOR WINDOW MECHANISMS WITH MOTOR ASSEMBLY, DOOR GLASS AND ALL ATTACHMENTS.		180.00	150.00
	TO REMOVE/ REFIT WIRE HARNESS, ALL RELATED CONNECTORS. CHECK PROPER FUNCTION.		150.00	120.00
	TO SPRAY PAINT O/S REAR FENDER, O/S REAR WHEELARCH GARNISH, O/S REAR DOOR, O/S REAR DOOR PROTECTOR, O/S CENTRE PILLAR, O/S FRONT DOOR, O/S FRONT DOOR PROTETOR, O/S RUNNING BOARD. O/S RUNNING BOARD SIDE SKIRTING AND ETC. INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		1,600.00	1,400.00
	TO APPLY UNDERSEAL AND RUST-PROOFING ON THE AFFECTED AREAS.		180.00	150.00
			5,480.00	3,110.00
	GRAND TOTAL		20,010.93	7,402.70

Report Ref No. CS/GAI18004109/Kvbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,900.00
---	--	--	----------

Report Ref No. CS/GAI18004109/Kvbe2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.