





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED LEGAL ALLIANCE LLC			Ref : CS1/LAW18004112/R1qb	
20 MAXWELL ROAD #13-00 MAXWELL HOUSESINGAPORE 069113			Date : 03-03-2018	
			Code : L040	
<b>1. Policy Particulars :- PAPER SURVEY</b>				
Insured Veh.	SJF 6114R	Veh. Inspected	SCV 82L	
Policy No.		Coverage (\$)	0.00	
Claim No.	ASA/JAG/NTUC0587/ns	Excess (\$)	0.00	
Assign From	ABDUL SALIM	Assign Date	27/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	02/06/2016	Inspection Date	03/03/2018	
Survey held at	KENT SENG VEHICLE REPAIRER BLOCK 1016, YISHUN IND. PARK A #01-238 SINGAPORE 768758			
<b>5a. Remarks</b>				

## Catherine Chong (LKK Auto)

---

**From:** Deborah <deborah@ulallc.com>  
**Sent:** Tuesday, 27 February, 2018 11:58 AM  
**To:** admin-d@lkkauto.com  
**Cc:** Salim; Judy  
**Subject:** [LKK Ref: To be advised] [Our Ref: ASA/NTUC/0587/deb]

Dear Catherine,

**MC/MC 21725/2016**  
**ACCIDENT INVOLVING SCV 82L AND SJF 6114R**  
**ALONG JURONG EAST AVENUE 1 ON 2 JUNE 2016**

We refer to our email and letter dated 7 February 2018.

Please note that Ms Janessa Goh has since left the firm. Our Mr Abdul Salim would be taking over conduct of this matter and the undersigned would be assisting him.

If your Mr Mohammed Rasul Bin Mohd Yunus is unable to act as the SJE for the above matter, please let us know.

Otherwise, please acknowledge receipt of this assignment. We look forward to receiving your SJE report as soon as possible.

Best regards,  
Deborah Lee  
Trainee to Mr Abdul Salim, Director  
United Legal Alliance LLC



**United Legal Alliance LLC**  
20 Maxwell Road #13-00 Maxwell House Singapore 069113  
Tel: 6338 2477 Fax: 6338 4497 / 6338 3135 / 6396 4897  
Website : [www.ulallc.com](http://www.ulallc.com)

**Catherine Chong (LKK Auto)**

---

**From:** Syafiqah <syafiqah@ulallc.com>  
**Sent:** Monday, 15 January, 2018 11:41 AM  
**To:** sur@lkkauto.com  
**Cc:** assignments  
**Subject:** Request for CV and SJE report fees: Accident involving SCV 82L and SJF 6114R on 02.06.2016 (Our Ref: ASA/JAG/NTUC0587/ns) (Your Ref: Please advise)

Dear Sirs,

**MC/MC 21725/2016**  
**ACCIDENT INVOLVING SCV 82L AND SJF 6114R ALONG JURONG EAST AVENUE 1 ON 2 JUNE 2016**

We refer to the above-captioned matter.

We act for NTUC Income Insurance Co-operative Limited, the motor insurers of SCV 82L at the material time. M/s Bonnie Kwok LLC act for Yong Wei Hsiung, the owner of SJF 6114R, who commenced the above-captioned suit against our Clients' insured owner and driver for property damage and consequential loss and expenses.

Our Clients wish to propose your representative as the Single Joint Expert under Order 108 rule 5 of the Rules of Court.

In the circumstances, please let us know the fees for the following:-

- (a) Physical re-inspection of a vehicle (after repairs) and accompanying report;
- (b) Paper survey based on damage photos and accompanying report; and
- (c) A half-day court attendance.

We would also be grateful if you could let us have a copy of your representative's Curriculum Vitae and the estimated duration for the SJE report to be completed.

Please let us hear from you.

Best regards,  
Nur Syafiqah (ns)  
Secretary to Ms Janessa Goh, Senior Legal Associate  
United Legal Alliance LLC



**United Legal Alliance LLC**  
20 Maxwell Road #13-00 Maxwell House Singapore 069113  
Tel: 6338 2477 Fax: 6338 4497 / 6338 3135 / 6396 4897  
Website : [www.ulallc.com](http://www.ulallc.com)

Important: This message is intended for the recipient(s) addressed above. It contains privileged and confidential information. If you are not the intended recipient, kindly notify the sender or United Legal Alliance LLC generally at [contactus@ulallc.com](mailto:contactus@ulallc.com) immediately by replying to this message and then delete it from your system. You must not read, copy, use or disseminate this communication in any form. Thank you.

Disclaimer: Email communications are not secure. While we have taken every reasonable effort to ensure that this communication has not been tampered with, United Legal Alliance LLC is not responsible for any changes made to the contents of or any attachments to this message without its consent. If you wish to receive a hard copy of this message to verify the accuracy of the contents thereof, please contact the sender. Note that only views, opinions or such other information contained in this message that relate to the official business of the Firm is to be taken to have been sent by and on behalf of United Legal Alliance LLC.



United Legal Alliance LLC  
20 Maxwell Road  
#13-00 Maxwell House  
Singapore 069113  
(Reception at Level 12)

Tel 65.6338.2477  
Fax 65.6338.4497  
65.6338.3135  
65.6396.4897

Website [www.ulallc.com](http://www.ulallc.com)

**Directors:**

Michael Eu  
[michael@ulallc.com](mailto:michael@ulallc.com)

Abdul Salim  
[salim@ulallc.com](mailto:salim@ulallc.com)

Edwina Fan  
[edwina@ulallc.com](mailto:edwina@ulallc.com)

Anthony Wee  
[anthony@ulallc.com](mailto:anthony@ulallc.com)

**Associate Directors:**

Faizal Ashraf  
[faizal@ulallc.com](mailto:faizal@ulallc.com)

Pak Waltan  
[waltan@ulallc.com](mailto:waltan@ulallc.com)

Leong Lu Yuan  
[luyuan@ulallc.com](mailto:luyuan@ulallc.com)

**Consultant:**  
V Subramaniam  
[subra@ulallc.com](mailto:subra@ulallc.com)

**Snr. Associates:**

Cynthia Lee  
[cynthia@ulallc.com](mailto:cynthia@ulallc.com)

Gloria Lee  
[gloria@ulallc.com](mailto:gloria@ulallc.com)

Noraisah Hussin  
[noraisah@ulallc.com](mailto:noraisah@ulallc.com)

Janessa Goh  
[janessa@ulallc.com](mailto:janessa@ulallc.com)

**Associates:**

Lydia Lee  
[lydia@ulallc.com](mailto:lydia@ulallc.com)

Vanesse Koh  
[vanesse@ulallc.com](mailto:vanesse@ulallc.com)

Iris Pek  
[iris@ulallc.com](mailto:iris@ulallc.com)

Manoj Belani  
[manoj@ulallc.com](mailto:manoj@ulallc.com)

Nicole Toh  
[nicole@ulallc.com](mailto:nicole@ulallc.com)

Our Ref:  
Your Ref:

ASA/JAG/NTUC0587/ns  
Please advise

(Celine)

7 February 2018

**LKK Auto Consultants Pte Ltd**  
Block 51 Paya Ubi Industrial Park  
Ubi Avenue 1  
#02-25  
Singapore 408933

**BY POST, E-MAIL AND  
BY FAX (6256 4315)**

Dear Sirs,

**MC/MC 21725/2016**

**ACCIDENT INVOLVING SCV 82L AND SJF 6114R ALONG JURONG EAST AVENUE  
1 ON 2 JUNE 2016**

We act for Peh Book Chuan, the owner and driver of SCV 82L at the material time and the Defendant in the above-captioned suit and M/s Bonnie Kwok LLC act for Yong Wei Hsiung, the driver of SJF 6114R at the material time and the Plaintiff in the said suit.

Please be informed that the Court has appointed your Mr Mohammed Rasul Bin Mohd Yunus as the Single Joint Expert (SJE) for the above matter. As such, his primary duty is to the court and is independent of both parties.

Your fees are agreed as follows:-

- |  |              |
|--|--------------|
| (a) Paper Survey                         | - \$ 700.00  |
| (b) Physical Re-inspection               | - \$1,000.00 |
| (c) Court Attendance Expert Witness Fee: |              |
| State Courts Half Day                    | - \$ 400.00  |
| State Courts Full Day                    | - \$ 800.00  |

We attach herewith the following for your attention:-

- (a) A copy of our clients' survey report by AJAX Inspection Services Pte Ltd; and
- (b) A copy of the Plaintiff's survey report by Priority Services.

Kindly acknowledge receipt of this assignment and let us have the SJE report as soon as possible.

Yours faithfully



**Janessa Goh / Abdul Salim A Ibrahim**  
United Legal Alliance LLC  
Enc.

cc. **M/s Bonnie Kwok LLC**  
(Your ref: *BK.17084.16.st*)

**BY FAX (6536 2279) ONLY**



Inspection Services Pte Ltd

### RE-INSPECTION REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Rajeswary D/o Doraisamy

Assign Date:	04/10/2016	Inspection Date:	06/10/2016	OI Report Date:	15/06/2016
Accident Date:	02/06/2016	TP Policy No:	TBA	Our Ref:	AVS2016-07747/BL
Repairer	Kent Seng Vehicle repairer			Your Ref:	MT/0903318-002
	1016 Yishun Industrial Park A			Claim Type:	Third Party
	Singapore 768758			Claimant:	Eddy Yong Heng Kit

#### Description of Vehicle:

Veh. No:	SJF6114R	Make/Model:	Toyota Picnic Auto W/O Roof Rack	Sum Insured (S\$):	NA
Colour:	Metallic black	Engine No:	1AZ5766654	Mkt Value (S\$):	\$33,000.00
Engine Capacity:	1,998 CC	Chassis No:	JTEGH23B000025637	Excess (S\$):	NA
Odometer:	145663	Reg. Date:	04/06/2008		

#### Condition of Vehicle:

General:	Good	Modification:	No	Steering:	Serviceable
Air-Conditioner:	Good	Radio/Cassette/CD:	Good	Wing Mirror:	Serviceable
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Good
Tyre Make:	Michelin				
Front Tyre Size:	205 / 60 R16	Front Left Side:	7mm	Front Right Side:	7mm
Rear Tyre Size:	205 / 60 R16	Rear Left Side:	7mm	Rear Right Side:	7mm

#### Description of Damage:

Physical re-inspection of the vehicle was arranged and conducted on 6 October 2016, which was about 4 months after the repairs. This time frame would still be appropriate for assessment of whether the parts have been repaired or replaced.


#### Remarks:

We have inspected thoroughly each and every item on the Third Party surveyor's estimate against the vehicle's damage photographs provided and we have listed the breakdown of our findings and our recommendation as per schedule attached.

Our recommended amount for the cost of contract lumpsum repair is S\$8,400.00 with approximately eight (8) working days to complete.

However, no finalisation was agreed with the repairer.

Adjuster:

  
Billy Loh  
Motor Appraiser

Date

COMPLETED 21 OCT 2016

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R





Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle: <u>SJF6114R</u>				Our Ref: AVS2016-07747/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
<b>List Items</b>					
1	1	Tailgate	Bent	1,330.13	1,330.13
2	1	Tailgate windscreen glass rubber moulding	Necessary	159.60	159.60
3	1	Tailgate centre emblem	Necessary	79.24	79.24
4	1	Tailgate "Toyota" emblem	Necessary	46.34	46.34
5	1	Tailgate "Picnic" emblem	Necessary	54.18	54.18
6	1	Tailgate RH lamp	Buckled	248.30	248.30
7	1	Tailgate RH lamp inner seal	Necessary	22.70	22.70
8	1	Tailgate LH lamp	Not necessary	248.30	--
9	1	Tailgate LH lamp inner seal	Not necessary	22.70	--
10	1	Tailgate lock	Bent	235.43	160.00
11	1	Tailgate lock catch	Bent	55.10	55.10
12	1	Tailgate RH hinge	Not necessary	--	--
13	1	Tailgate LH hinge	Not necessary	--	--
14	1	Tailgate RH absorber stay	Not necessary	--	--
15	1	Tailgate LH absorber stay	Not necessary	--	--
16	1	Tailgate inner trim board	Not necessary	515.90	515.90
17	1	Tailgate inner RH side garnish	Not necessary	135.20	--
18	1	Tailgate inner LH side garnish	Not necessary	135.20	--
19	1	Tailgate inner centre garnish	Not necessary	--	--
20	1	Tailgate weatherstrip	Deformed	379.05	170.00
21	1	Rear bumper	Bent	522.21	522.21
22	1	Rear bumper RH side retainer	Necessary	43.75	43.75
23	1	Rear bumper LH side retainer	Necessary	43.75	43.75
24	1	Rear bumper RH side support	Necessary	22.12	22.12
25	1	Rear bumper LH side support	Necessary	22.12	22.12
26	1	Rear bumper RH side reflector	Necessary	49.70	49.70
27	1	Rear bumper LH side reflector	Not necessary	--	--
28	1	RH tail- lamp	Buckled	317.40	317.40
29	1	RH tail- lamp inner seal	Necessary	25.60	25.60
30	1	LH tail- lamp	Not necessary	317.40	--
31	1	LH tail- lamp inner seal	Not necessary	25.60	--
32	1	Rear fender LH inner trim	Cracked	627.60	560.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

# AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				SIF6114R	Our Ref: AVS2016-07747/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$	
33	1	Rear fender LH air vent		--	--	
34	1	Rear fender RH	Repair	1,081.60	--	
35	1	Rear fender RH glass with rubber moulding	Not necessary	155.80	--	
36	1	Rear fender RH inner trim	Cracked	627.60	560.00	
37	1	Rear fender RH air vent	Cracked	98.31	98.31	
38	1	Rear RH air-con blower	Cracked	1,665.55	1,665.55	
39	1	End panel	Bent	601.71	601.71	
40	1	End panel inner garnish	Not necessary	406.60	406.60	
41	1	Rear compartment panel	Bent	983.10	983.10	
42	1	Rear compartment panel lower enforcement	Not necessary	81.06	--	
43	1	Rear compartment panel insulator	Necessary	180.00	80.00	
44	1	Rear compartment panel mat	Not necessary	350.96	--	
45	1	Rear compartment panel top cover	Not necessary	687.10	--	
46	1	Rear compartment RH rubber cover	Not necessary	18.70	--	
47	1	Exhaust silencer	Damaged	991.50	991.50	
48	1	Exhaust silencer rubber mountings	Necessary	111.80	111.80	
Sub Total:				13,726.01	9,946.71	
Discount (less 25% ):				3,431.50	2,486.68	
				10,294.51	7,460.03	

## Special Nett Items

1	1	Tailgate windscreen glass sealant	Necessary	40.00	40.00
2	1	Tailgate windscreen glass inner seal	Necessary	25.00	25.00
3	1	Rear number plate		--	--
4	1	Tailgate inner trim board clips	Not necessary	35.00	--
5	1	Tailgate inner RH side garnish clips	Necessary	18.00	15.00
6	1	Tailgate inner LH side garnish clips	Necessary	18.00	15.00
7	1	Rear bumper reverse sensor	Damaged	300.00	200.00
8	1	Rear bumper clips	Necessary	40.00	30.00
9	1	Rear bumper RH inner trim board clips	Necessary	32.00	15.00
10	1	Rear bumper LH inner trim board clips	Necessary	32.00	15.00
11	1	Rear fender RH glass rubber sealant	Necessary	25.00	25.00
12	1	Rear fender RH glass rubber inner seal	Necessary	10.00	10.00
Sub Total:				575.00	390.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



## Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				Our Ref: AVS2016-07747/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
Total Parts Price:				10,869.51	7,850.03

### Labour Cost

1	To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re-position & re-align, replacement of parts to the original position including adjustment	1,800.00	1,200.00
2	Apply rust coating on the replaced & repaired panels	120.00	60.00
3	Remove & re-install tailgate windscreen glass to assist repairs	120.00	120.00
4	Transfer & replace tailgate mechanism to new tailgate	80.00	60.00
5	Remove, replace & re-install rear inner trims, garnishes, boards, seats & mat to assist repairs	320.00	80.00
6	Remove & replace exhaust silencer & rubber hangers to assist repairs	100.00	80.00
7	Remove, re-adjust & replace rear bumper reverse sensor	40.00	30.00
8	Remove & re-install RH rear fender glass to assist repairs	80.00	--
9	Remove, re-install & replace A/C blower & pipe to assist repairs, to vacuum & refill A/C gas	100.00	100.00
10	To putty & spray repaired & replaced body panels	1,500.00	900.00
Sub Total:		4,260.00	2,630.00
Grand Total:		15,129.51	10,480.03

*Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.*

### AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155  
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



## PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers  
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779  
Tel : 62934822 Fax : 62963283

### VEHICLE INSPECTION REPORT

Report No. TP/0054/16	Date of Report	: 15 June 16
To : Yong Wei Hsiung	Date of Request	: 9 June 16
1003, Bukit Timah Road #10-04	Report requested by	: Yong Wei Hsiung
Singapore 596289	Date of Accident	: 2 June 16
	Date of Inspection	: 9 June 16
	Claim No.	: Third Party Claim

### PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SJF 6114 R	Odometer Reading	: 145663km
Make	: Toyota	Carrying Capacity	: 6
Model	: Picnic (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2008	Air-Conditioner	: Yes
Colour	: Metallic Black	Wing Mirror	: Yes
Engine Capacity	: 1998cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: JTEGH23B000025637	Others	: Nil

### TYRE CONDITION

Front Left	: 7mm	Front Right	: 7mm
Make	: Michelin	Make	: Michelin
Rear Left	: 7mm	Rear Right	: 7mm
Make	: Michelin	Make	: Michelin
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: Intact
--------------	----------	------------	----------

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

*This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.*

## ASSESSMENT

	<u>Repairer's Estimate (S S)</u>	<u>Our Recommendation (S S)</u>
Spare Parts :	15,688.06	10,869.51
Labour Charges :	3,710.00	2,760.00
Paint Work :	1,800.00	1,500.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	21,198.06	15,129.51

Reduction (S S) : 9,198.06

Recommended Reserve (S S) : 12,000.00 (Lump Sum)

Estimated Normal Period of Repairs : 16 working days

## CONTRIBUTIONS BY INSURED

Excess (S S) : N/A

Others : --

## GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

### The Assignment

The survey was conducted at Kent Seng Vehicle Repairer, Block 1016, Yishun Industrial Park A, #01-238, Singapore 768758.

Follow-up inspection has been conducted.

### Point of Impact

At the rear portion.

### Damages

The tailgate, tailgate lamps, rear bumper, end panel, rear compartment panel, RH rear fender, tail-lamps assembly, exhaust silencer, etc.

Other parts were also found damaged. (see schedule for details)

### Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$15,129.51

### Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$12,000.00

We now revert to you for your decision on repairs.

Very truly yours

**PRIORITY SERVICES**

  
**JIMMY S. T. LEE** AMSOE, AMIRTE, AMSAE-AUS, MSAAA  
Motor Appraiser

  
**LAWRENCE NG**  
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SJF 6114 R Toyota Picnic (A)  
Workshop : Kent Seng Vehicle Repairer

TP/0054/16

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist. %	Our Recommendation (S S)	Dist. %
To Supply :					
1pc. Tailgate	Dented	1,330.13		1,330.13	25
1pc. Tailgate windscreen glass rubber moulding	Necessary	159.60		159.60	25
1pc. Tailgate centre emblem	Necessary	79.24		79.24	25
1pc. Tailgate 'Toyota' emblem	Necessary	46.34		46.34	25
1pc. Tailgate 'Picnic' emblem	Necessary	54.18		54.18	25
1pc. Tailgate RH lamp	Cracked / Defaced	248.30		248.30	25
1pc. Tailgate RH lamp inner seal	Necessary	22.70		22.70	25
1pc. Tailgate LH lamp	Cracked / Defaced	248.30		SVC 248.30	25 X
1pc. Tailgate LH lamp inner seal	Necessary	22.70		SVC 22.70	25 X
1pc. Tailgate lock	Bent	235.43		235.43	25
1pc. Tailgate lock catch	Bent	55.10		55.10	25
1pc. Tailgate RH hinge	Serviceable	109.00		--	25
1pc. Tailgate LH hinge	Serviceable	109.00		--	25
1pc. Tailgate RH absorber stay	Refit	219.60		--	25
1pc. Tailgate LH absorber stay	Refit	219.60		--	25
1pc. Tailgate inner trim board	Cracked	515.90		515.90	25
1pc. Tailgate inner RH side garnish	Deformed	135.20		SVC 135.20	25 X
1pc. Tailgate inner LH side garnish	Deformed	135.20		SVC 135.20	25 X
1pc. Tailgate inner centre garnish	Refit	115.75		--	25
1pc. Tailgate weatherstrip	Bent	379.05		379.05	25
1pc. Rear bumper	Dented	522.21		522.21	25
1pc. Rear bumper RH side retainer	Necessary	43.75		43.75	25
1pc. Rear bumper LH side retainer	Necessary	43.75		43.75	25
1pc. Rear bumper RH side support	Necessary	22.12		22.12	25
1pc. Rear bumper LH side support	Necessary	22.12		22.12	25
1pc. Rear bumper RH side reflector	Broken	49.70		49.70	25
1pc. Rear bumper LH side reflector	Refit	49.70		--	25
1pc. RH tail-lamp	Cracked	317.40		317.40	25
1pc. RH tail-lamp inner seal	Necessary	25.60		25.60	25
1pc. LH tail-lamp	Cracked	317.40		SVC 317.40	25 X
1pc. LH tail-lamp inner seal	Necessary	25.60		SVC 25.60	25 X
1pc. Rear fender LH inner trim	Deformed	627.60		627.60	25
1pc. Rear fender LH air vent	Refit	68.40		--	25
1pc. Rear fender RH	Dented / Distorted	1,081.60		1,081.60	25 R
1pc. Rear fender RH glass with rubber moulding	Necessary	155.80		SVC 155.80	25 X
1pc. Rear fender RH inner trim	Broken	627.60		627.60	25
1pc. Rear fender RH air vent	Cracked	98.31		98.31	25
1pc. Rear RH air-con blower	Cracked	1,665.55		1,665.55	25
1pc. End panel	Dented	601.71		601.71	25
1pc. End panel inner garnish	Deformed	406.60		406.60	25
1pc. Rear compartment panel	Dented	983.10		983.10	25
1pc. Rear compartment panel lower enforcement	Necessary	81.06		81.06	25

9264.18



Vehicle No : SJF 6114 R Toyota Picnic (A)  
Workshop : Kent Seng Vehicle Repairer

TP/0054/16

1283-30

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist.%	Our Recommendation (S \$)	Dist.%
1pc. Rear compartment panel insulator	Necessary	180.00		180.00	25
1pc. Rear compartment panel mat	Crumpled	350.96		350.96	25
1pc. Rear compartment panel top cover	Dented / Cracked	687.10		687.10	25
1pc. Rear compartment RH rubber cover	Broken / Dislodged / Missing	18.70		18.70	25
1pc. Exhaust silencer	Bent	991.50		991.50	25
3pcs. Exhaust silencer rubber mountings	Necessary	111.80		111.80	25
Sub-Total :-	10547.45	14,617.06		13,726.01	
Total Discount :-	2596	--		3,431.50	
	7910.58	14,617.06		10,294.51	
Special Nett Items :-					
1tube. Tailgate windscreen glass sealant	Necessary	100.00		40.00	
1pc. Tailgate windscreen glass inner seal	Necessary	70.00		25.00	
1pc. Rear number plate	Refit	70.00		--	
1set. Tailgate inner trim board clips	Necessary	35.00		35.00	
1set. Tailgate inner RH side garnish clips	Necessary	18.00		18.00	
1set. Tailgate inner LH side garnish clips	Necessary	18.00		18.00	
1set. Rear bumper reverse sensor	Broken	450.00		300.00	
1set. Rear bumper clips	Necessary	70.00		40.00	
1set. Rear bumper RH inner trim board clips	Necessary	70.00		32.00	
1set. Rear bumper LH inner trim board clips	Necessary	70.00		32.00	
1tube. Rear fender RH glass rubber sealant	Necessary	60.00		25.00	
1pc. Rear fender RH glass rubber inner seal	Necessary	40.00		10.00	
Total For Parts :-		15,688.06		10,869.51	
Labour Charges :					

440



Vehicle No : SJF 6114 R Toyota Picnic (A)  
Workshop : Kent Seng Vehicle Repairer

TP/0054/16

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist. %	Our Recommendation (S S)	Dist. %
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re-position & re-align, replacement of parts to the original position including adjustment.		2,100.00		<del>1,800.00</del> 1200	
Apply rust coating on the replaced & repaired panels.		180.00		60 <del>120.00</del>	
Remove & re-install tailgate windscreen glass to assist repairs.		250.00		120.00	
Transfer & replace tailgate mechanism to new tailgate.		120.00		60 <del>80.00</del>	
Remove, replace & re-install rear inner trims, garnishes, boards, seats & mat to assist repairs.		450.00		80 <del>320.00</del>	
Remove & replace exhaust silencer & rubber hangers to assist repairs.		180.00		80 <del>100.00</del>	
Remove, re-adjust & replace rear bumper reverse sensor.		100.00		40.00	
Remove & re-install RH rear fender glass to assist repairs.		150.00		X 80.00	
Remove, re-install & replace A/C blower & pipes to assist repairs. To vacuum & re-fill A/C gas.		180.00		100.00	
Spray Painting :					
To putty & spray repaired & replaced body panels.		1,800.00		1000 <del>1,500.00</del>	
Grand Total :-		21,198.06		15,129.51	

Surveyed By : Lawrence Ng

7910.58

440.00

2740.00

11090.58

20%

8872.46

4/5 - 8850.00 12 days

2740



Your Ref: ASA/JAG/NTUC0587/ns

Date: 27<sup>th</sup> April 2018

Our Ref: CS1/LAW18004112/R1rbs2

**M/s United Legal Alliance LLC**

20 Maxwell Road

#13-00 Maxwell House

Singapore 069113

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SJF 6114R INSURED VEHICLE: SCV 82L ACCIDENT DATE: 02/06/2016**

We thank you for your instruction on 27/02/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJF 6114R from M/s Priority Services.
- b) Survey report by AJAX Inspection Services Pte Ltd.
- c) Colour damaged vehicle photographs of SJF 6114R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJF 6114R
Make & Model	: Toyota Picnic Auto
Year of Registration	: 2008
Chassis Number	: JTEGH238000025637
Engine Capacity	: 1998cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 6114R**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILGATE	DENTED	1,330.13	1,330.13
1	TAILGATE WINDSCREEN GLASS RUBBER MOULDING	NECESSARY	159.60	159.60
1	TAILGATE CENTRE EMBLEM	NECESSARY	79.24	79.24
1	TAILGATE 'TOYOTA' EMBLEM	NECESSARY	46.34	46.34
1	TAILGATE 'PICNIC' EMBLEM	NECESSARY	54.18	54.18
1	TAILGATE RH LAMP	CRACKED / DEFACED	248.30	248.30
1	TAILGATE RH LAMP INNER SEAL	NECESSARY	22.70	22.70
1	TAILGATE LH LAMP	SERVICEABLE	248.30	-
1	TAILGATE LH LAMP INNER SEAL	SERVICEABLE	22.70	-
1	TAILGATE LOCK	BENT	235.43	235.43
1	TAILGATE LOCK CATCH	BENT	55.10	55.10
1	TAILGATE RH HINGE	SERVICEABLE	109.00	-
1	TAILGATE LH HINGE	SERVICEABLE	109.00	-
1	TAILGATE RH ABSORBER STAY	REFIT	219.60	-
1	TAILGATE LH ABSORBER STAY	REFIT	219.60	-
1	TAILGATE INNER TRIM BOARD	CRACKED	515.90	515.90
1	TAILGATE INNER RH SIDE GARNISH	SERVICEABLE	135.20	-
1	TAILGATE INNER LH SIDE GARNISH	SERVICEABLE	135.20	-
1	TAILGATE INNER CENTRE GARNISH	REFIT	115.75	-
1	TAILGATE WEATHERSTRIP	BENT	379.05	379.05
1	REAR BUMPER	DENTED	522.21	522.21
1	REAR BUMPER RH SIDE RETAINER	NECESSARY	43.75	43.75
1	REAR BUMPER LH SIDE RETAINER	NECESSARY	43.75	43.75
1	REAR BUMPER RH SIDE SUPPORT	NECESSARY	22.12	22.12
1	REAR BUMPER LH SIDE SUPPORT	NECESSARY	22.12	22.12
1	REAR BUMPER RH SIDE REFLECTOR	BROKEN	49.70	49.70
1	REAR BUMPER LH SIDE REFLECTOR	REFIT	49.70	-
1	RH TAIL-LAMP	CRACKED	317.40	317.40
1	RH TAIL-LAMP INNER SEAL	NECESSARY	25.60	25.60
1	LH TAIL-LAMP	SERVICEABLE	317.40	-

Report Ref No. CS1/LAW18004112/R1rbs2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH TAIL-LAMP INNER SEAL	SERVICEABLE	25.60	-
1	REAR FENDER LH INNER TRIM	DEFORMED	627.60	627.60
1	REAR FENDER LH AIR VENT	REFIT	68.40	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,081.60	-
1	REAR FENDER RH GLASS WITH RUBBER MOULDING	SERVICEABLE	155.80	-
1	REAR FENDER RH INNER TRIM	BROKEN	627.60	627.60
1	REAR FENDER RH AIR VENT	CRACKED	98.31	98.31
1	REAR RH AIR-CON BLOWER	CRACKED	1,665.55	1,665.55
1	END PANEL	DENTED	601.71	601.71
1	END PANEL INNER GARNISH	DEFORMED	406.60	406.60
1	REAR COMPARTMENT PANEL	DENTED	983.10	983.10
1	REAR COMPARTMENT PANEL LOWER ENFORCEMENT	NECESSARY	81.06	81.06
1	REAR COMPARTMENT PANEL INSULATOR	NECESSARY	180.00	180.00
1	REAR COMPARTMENT PANEL MAT	SERVICEABLE	350.96	-
1	REAR COMPARTMENT PANEL TOP COVER	SERVICEABLE	687.10	-
1	REAR COMPARTMENT RH RUBBER COVER	SERVICEABLE	18.70	-
1	EXHAUST SILENCER	BENT	991.50	991.50
3	EXHAUST SILENCER RUBBER MOUNTINGS	NECESSARY	111.80	111.80
	LESS 25% DISCOUNT		-	-2,636.86
			14,617.06	7,910.59
	<b>SPECIAL NETT ITEMS</b>			
1	TUBE TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	100.00	40.00
1	TAILGATE WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	70.00	25.00
1	REAR NUMBER PLATE (SN)	REFIT	70.00	-
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	35.00	35.00
1	SET TAILGATE INNER RH SIDE GARNISH CLIPS (SN)	NECESSARY	18.00	18.00
1	SET TAILGATE INNER LH SIDE GARNISH CLIPS (SN)	NECESSARY	18.00	18.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	BROKEN	450.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	70.00	40.00
1	SET REAR BUMPER RH INNER TRIM BOARD CLIPS (SN)	NECESSARY	70.00	32.00
1	SET REAR BUMPER LH INNER TRIM BOARD CLIPS (SN)	NECESSARY	70.00	32.00
1	TUBE REAR FENDER RH GLASS RUBBER SEALANT (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS1/LAW18004112/R1rbs2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER RH GLASS RUBBER INNER SEAL (SN)	NOT NECESSARY	40.00	-
			1,071.00	440.00
	<b>LABOUR</b>			
	TO REMOVE & REPLACE THE ABOVE LISTED PARTS, KNOCK, STRAIGHTEN & RESHAPE, CUT & WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION & RE-ALIGN, REPLACEMENT OF PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		2,100.00	1,200.00
	APPLY RUST COATING ON THE REPLACED & REPAIRED PANELS.		180.00	60.00
	REMOVE & RE-INSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIRS.		250.00	120.00
	TRANSFER & REPLACE TAILGATE MECHANISM TO NEW TAILGATE.		120.00	60.00
	REMOVE, REPLACE & RE-INSTALL REAR INNER TRIMS, GARNISHES, BOARDS, SEATS & MAT TO ASSIST REPAIRS.		450.00	80.00
	REMOVE & REPLACE EXHAUST SILENCER & RUBBER HANGERS TO ASSIST REPAIRS.		180.00	80.00
	REMOVE, RE-ADJUST & REPLACE REAR BUMPER REVERSE SENSOR.		100.00	40.00
	REMOVE & RE-INSTALL RH REAR FENDER GLASS TO ASSIST REPAIRS.	NOT NECESSARY	150.00	-
	REMOVE, RE-INSTALL & REPLACE A/C BLOWER & PIPES TO ASSIST REPAIRS. TO VACUUM & RE-FILL A/C GAS.		180.00	100.00
	TO PUTTY & SPRAY REPAIRED & REPLACED BODY PANELS.		1,800.00	1,000.00
			5,510.00	2,740.00
<b>GRAND TOTAL</b>			<b>21,198.06</b>	<b>11,090.59</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,850.00</b>

Report Ref No. CS1/LAW18004112/R1rbs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.