

22/03/2002

SS. REC. BY:

REF:

C3/SPF18004140/Stber

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Lim Wei Yea

of

SPF

Date/Time:

02032018 356pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

QX 1021E

Insured:

at Workshop m/s

SMRT

Tel:

of

60 Woodlands Ind Park E4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	QX 1021E - CT/TP018003844/Dn DUP: 10012018
7/3/18	Revert via email to Wei Yea.
9/3/18	sent amended report to wei Yea

REF:

Simulator

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAG Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time | Action / Instruction

Man Hour - 66
Parts - \$1890

RECEIVED 12 APR 2018

RECEIVED 20 APR 2018

Date/Time, File Pass to?

1) D/H Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐ : Proli. Report☒ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Phone

Others

TOTAL

280

280

Veh No: QX 1021E

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: N/A / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

6/3/18

28 Sg Kadut An

N/S Body



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18004140/Stb		
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 05-03-2018		
		Code : SPF		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 1021E	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	LIM WEI YEA	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	Inspection Date		05/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR:	SMRT	VEH TYPE:	FRC	UNIT:	SPF
VEH NO:	QX1021E		REPAIR TYPE:	DAMAGE	
VEH MAKE/MODEL:	HYUNDAI ELANTRA		ODOMETER:	142664	

Reference No.
1021/SPF/4W/18/03/02

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Windscreen moulding ✓ NCC		1		0.00	0.00
1.2	Windscreen sealant ✓ NCC		1		0.00	0.00
1.3	Windscreen premier ✓ NCC		2		0.00	0.00
1.4	Windscreen & door pillar ✓ DT		1		0.00	0.00
1.5	L/H rear view mirror		1		0.00	0.00
1.6	L/H rear view mirror end cap ✓ cut		1		0.00	0.00
1.7	L/H door shell ✓ Defam		1		0.00	0.00
1.8	L/H door lower hinge ✓ BT		1		0.00	0.00
1.9	L/H door upper hinge ✓ BT		1		0.00	0.00
1.10	L/H door wire hardness ✓ DMG		1		0.00	0.00
1.11	L/H door locking mechanism ✓ JM		1		0.00	0.00
1.12	L/H door pillar ?		1		0.00	0.00
1.13	L/H fender ✓ DT		1		0.00	0.00
1.14	L/H fender inner panel garnish ?		1		0.00	0.00
1.15	L/H mud flap ?		1		0.00	0.00
1.16	Front shock absorber ?		1		0.00	0.00
1.17	Front lower arm ?		1		0.00	0.00
1.18	Front knuckle arm ?		1		0.00	0.00
1.19	Front knuckle arm bearing ?		1		0.00	0.00
1.20	Front stabilizer bar ?		1		0.00	0.00
1.21	Front stabilizer link ?		1		0.00	0.00
1.22	Front Door Sensor Switch ?		1		0.00	0.00
1.23	o supply Labour & Material to replace Bar Light (SOR 3, Item	\$1,890.00	1 ✓	0%	1890.00	1890.00
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:	This estimate is based on visual inspection only. Additional parts maybe required upon commencing of repair.				Parts Total:	\$ 1,890.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.01	Bar Light:		7	0.00
	Remove & Re-fix Bar Light			
	Reconnect all Wiring			
1.02	Roof top panel	10	12	0.00
	Remove & re-install ceiling upholstery			
	Panel beat roof top panel			
	Putty & spray paint roof top panel			
	Water seepage for roof top			
1.03	Windscreen pillar & door pillar		16	0.00
	Remove & re-install windscreen			
	Replace windscreen moulding			
	Cut, weld & replace windscreen pillar & door pillar			
	Water seepage for windscreen			
	Putty & spray paint windscreen pillar & door pillar			
1.04	L/H rear view mirror		1	0.00
	Remove & replace L/H rear view mirror			
	Replace L/H rear view mirror end cap			
1.05	Front bonnet	4	6	0.00
	Remove & replace front bonnet hinge			
	Panel beat & align front bonnet			
	To replace "POLICE" Wording Sticker (To be provided by AEMD)			
	Putty & spray paint front bonnet (2 colour)			
1.06	Front L/H door	12	16	0.00
	Remove & replace front L/H door shell			
	Remove & transfer L/H door part to new door shell			
	Replace front L/H door upper & lower hinge			
	Cut, weld & replace front L/H door pillar			
	Replace front L/H door wire hardness			
	Wiring for front L/H door			
	Replace front L/H door locking mechanism			

Registration No. QX1021E

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Windscreen moulding	1	Necessary			
1.2	Windscreen sealant	1	Necessary			
1.3	Windscreen premier	2	Necessary			
1.4	Windscreen & door pillar	1	Dent			
1.5	L/H rear view mirror	1	unconfirm			
1.6	L/H rear view mirror end cap	1	Cut			
1.7	L/H door shell	1	Deform			
1.8	L/H dooe lower hinge	1	Bent			
1.9	L/H door upper hinge	1	Bent			
1.10	L/H door wire hardness	1	Damage			
1.11	L/H door locking mechansim	1	Jammed			
1.12	L/H door pillar	1	unconfirm			
1.13	L/H fender	1	Dent			
1.14	L/H fender inner panel garnish	1	unconfirm			
1.15	L/H mud flap	1	unconfirm			
1.16	Front shock absorber	1	unconfirm			
1.17	Front lower arm	1	unconfirm			
1.18	Front knuckle arm	1	unconfirm			
1.19	Front knuckle arm bearing	1	unconfirm			
1.20	Front stabilizer bar	1	unconfirm			
1.21	Front stabilizer link	1	unconfirm			
1.22	Front Door Sensor Switch	1	unconfirm			
1.23	To supply Labour & Material to replace Bar Light	1			\$1,890.00	
	COSTING		TOTAL PARTS COST		\$1,890.00	
2	SCOPE OF REPAIRS					
2.1	Bar Light:					7
	Remove & Re-fix Bar light					

[illegible]

	Remove & replace front shock absorber					
	Remove & replace front lower arm					
	Remove & replace front knuckle arm					
	Remove & replace front knuckle arm bearing					
	Remove & replace stabilizer bar					2
3.01	Remove & replace front stabilizer link					
	4 Wheel alignment					
COSTING				TOTAL MAN-HOUR		66.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18004140/Stbe2		
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 18-04-2018		
		Code : SPF3		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 1021E	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	LIM WEI YEA	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHDH41CMEU085258	Colour	WHITE	
Odometer	142664	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FALKEN	6 mm	
L/H Front Tyre	205/55 R16	FALKEN	6 mm	
R/H Rear Tyre	205/55 R16	FALKEN	6 mm	
L/H Rear Tyre	205/55 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	Inspection Date		06/03/2018	
Survey held at	2B SUNGEI KADUT DR			
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				



Registration No. QX1021E

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Windscreen moulding	1	Necessary			
1.2	Windscreen sealant	1	Necessary			
1.3	Windscreen premier	2	Necessary			
1.4	Windscreen & door pillar	1	Dent			
1.5	L/H rear view mirror	1	unconfirm			
1.6	L/H rear view mirror end cap	1	Cut			
1.7	L/H door shell	1	Deform			
1.8	L/H dooe lower hinge	1	Bent			
1.9	L/H door upper hinge	1	Bent			
1.10	L/H door wire hardness	1	Damage			
1.11	L/H door locking mechansim	1	Jammed			
1.12	L/H door pillar	1	unconfirm			
1.13	L/H fender	1	Dent			
1.14	L/H fender inner panel garnish	1	unconfirm			
1.15	L/H mud flap	1	unconfirm			
1.16	Front shock absorber	1	unconfirm			
1.17	Front lower arm	1	unconfirm			
1.18	Front knuckle arm	1	unconfirm			
1.19	Front knuckle arm bearing	1	unconfirm			
1.20	Front stabilizer bar	1	unconfirm			
1.21	Front stabilizer link	1	unconfirm			
1.22	Front Door Sensor Switch	1	unconfirm			
1.23	To supply Labour & Material to replace Bar Light	1			\$1,890.00	
	COSTING	TOTAL PARTS COST			\$1,890.00	
2	SCOPE OF REPAIRS					
2.1	Bar Light:					7
	Remove & Re-fix Bar light					

	Reconnect all Wiring					
2.2	Roof top panel					10
	Remove & Re-install ceiling upholstery					
	Panel beat roof top panel					
	Putty & spray paint roof top panel					
	Water seepage for roof top					
2.3	Window Pillar & door pillar					16.00
	Remove & re-install windscreen					
	Replace windscreen moulding					
	Cut, weld & replace windscreen pillar & door pillar					
	Water seepage for windscreen					
	Putty & spray paint windoscreen pillar & door pillar					
2.4	L/H rear view mirror					1
	Remove & replace L/H rear view mirror					
	Replace L/H rear view mirror end cap					
2.5	Front bonnet					4
	Remove & replace front bonnet hinge					
	Panel beat & align front bonnet					
	to replace "POLICE" wording sticker(To be provided by AEMD)					
	Putty & Spray paint front bonner (2 color)					
2.6	Front L/H door					12
	Remove & replace front L/H door shell					
	Remove front L/H door part to new door shell					
	Replace front L/H door upper & lower hinge					
	Cut, weld & repalce front L/H door pillar					
	Replace front L/H door wire hardness					
	Wiring for front L/H door					
	Replace front L/H door locking mechanism					
	Remove & Replace Front LH Door Sensor Switch					
	To Replace "POLICE" Wording Sticker (To be provided by AEMD)					
	Putty & spray paint front L/H door					
2.7	Rear L/H door					4
	Panel beat & align L/H centre door pillar					
	Align rear L/H door					

	To replace " POLICE CREST" Sticker (To provide by AEMD)					
	Putty & Spray paint rear L/H door (3 colour)					
2.8	L/H Fender					6
	Remove & replace L/H fender					
	Remove & replace L/H fender inner panel garnish					
	Remove & replace L/H mud flap					
	Putty & spray paint L/H fender					
2.9	Front bumper					4
	Repair & align front bumper					
	Putty & spray paint front bumper (2 colour)					
3.0	Front L/H tyre		Unconfirm			
	Remove & replace front shock absorber					
	Remove & replace front lower arm					
	Remove & replace front knuckle arm					
	Remove & replace front knuckle arm bearing					
	Remove & replace stabilizer bar					
3.01	Remove & replace front stabilizer link					2
	4 Wheel alignment					
COSTING		TOTAL MAN-HOUR				66.00

Registration No. QX1021E

Vehicle Inspected By

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.