



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 HONDA JAZZ 1.3L A HONXXX (SKD1781X)

Date of Loss

28 February 2018

Time of Loss

10.30

Loss Description

SKD1781X (INSD) C/W SKC8649E (TP)

Comment

Workshop Details

Total Rebate Amount

31161

Nett Loss Amount

\$11,839.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/05/2018



Days of work completion *

73



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKD1781X

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

02/11/2011



Mileage

97869

Age of Vehicle

6

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA JAZZ 1.3L A

ASSESSMENT INFO...

CATEGORY Model

POLICY INFORMAT... HONXXX

ASSESSMENT INFO...

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JHMGE68509S238936

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF...



CATEGORY Age

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driver License #

ASSESSMENT INFO... JHMGE68509S238936

CATEGORY Engine No

POLICY INFORMAT... L13Z1138960

ASSESSMENT INFO... L13Z11038960

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1339

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 43000

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

05/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

185/55R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

185/55R16

Front left side

BRIDGESTONE3mm

Front right side

BRIDGESTONE3mm

Rear left side

BRIDGESTONE3mm

Rear right side

BRIDGESTONE3mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRT BONNET			Buckled	240				240	Review
		2	2			FRT BONNET HINGE			Bent	22				44	Review
		3	1			FRT BONNET LOCK			Bent	75				75	Review
		4	1			FRT BONNET LOCK CABLE			Serviceable	0	0	0	0	0	Deny
		5	1			FRT GRILLE			Bent	75				75	Review
		6	1			FRT GRILLE LOGO			Damaged	18				18	Review
		7	1			FRT BUMPER			Damaged	170				170	Review
		8	2			FRT BUMPER RETAINER			Bent	12				24	Review
		9	10			FRT BUMPER CLIP			Necessary	2				20	Review
		10	2			FRT BUMPER BEAM (BELOW HEADLAMP)			Bent	15				30	Review
		11	1			FRT BUMPER TOWING COVER			Damaged	10				10	Review
		12	1			FRT BUMPER LOWER GRILLE			Twisted	45				45	Review
		13	1			FRT BUMPER REINFORCEMENT			Damaged	95				95	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		14	2			HEADLAMP			Cracked	330				660	Review
		15	1			HEADLAMP SUPPORT PANEL			Twisted	180				180	Review
		16	1			AIRCON CONDENSER			Bent	140				140	Review
		17	1			RADIATOR			Bent	200				200	Review
		18	2			AIRCON CONDENSER BRACKET			Serviceable	0	0	0	0	0	Deny
		19	2			RADIATOR BRACKET			Serviceable	0	0	0	0	0	Deny
		20	1			RADIATOR MOTOR COWLING			Cracked	60				60	Review
		21	1			RADIATOR MOTOR			Serviceable	0	0	0	0	0	Deny
		22	1			RADIATOR FAN BLADE			Serviceable	0	0	0	0	0	Deny
		23	1			AIRCON MOTOR COWLING			Cracked	70				70	Review
		24	1			AIRCON MOTOR			Serviceable	0	0	0	0	0	Deny
		25	1			AIRCON FAN BLADE			Serviceable	0	0	0	0	0	Deny
		26	1			RADIATOR TOP HOSE			Twisted	15				15	Review
		27	1			AIRCON COOLING PIPE			Serviceable	0	0	0	0	0	Deny
		28	1			AIRCON DISCHARGE PIPE			Bent	110				110	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		29	1			AIRCON SUCTION PIPE			Serviceable	0	0	0	0	0	Deny
		30	1			RADIATOR SPARE TANK			Damaged	35				35	Review
		31	1			WASHER TANK			Deformed	45				45	Review
		32	1			AIR CLEANER BOX (TOP)			Serviceable	0	0	0	0	0	Deny
		33	1			AIR CLEANER BOX (LOWER)			Serviceable	0	0	0	0	0	Deny
		34	2			HORN			Bent	45				90	Review
		35	1			ENGINE MOUNTING RH			Damaged	105				105	Review
		36	1			TIMMING HOUSING COVER			Serviceable	0	0	0	0	0	Deny
		37	1			WIPER GARNISH			Cut	150				150	Review
		38	1			ENGINE OIL DIP STICK			Serviceable	0	0	0	0	0	Deny

Labour

Add		Approve		Deny						
EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
		1		WIRE CHECKING	20	0	0	Reviewing		1
		2		REMOVE & REFIX AIRCON AND GAS	100	0	0	Reviewing		1
		3		REMOVE & REFIX ENGINE MOUNTING & TIMING HOUSING COVER	50	0	0	Reviewing		1
		4		LABOUR CHARGE	700	0	0	Reviewing		1

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
		5		SPRAY PAINTING	700	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 7 DAYS	Reviewing			
		2	FUSE RELAY BOX	Reviewing	110	CRACKED (SUPPLEMENTARY)	
		3	FRT NUMBER PLATE	Reviewing	35	BENT	
		4	AIRCON COOLANT	Reviewing	50	NECESSARY	
		5	RADIATOR COOLANT	Reviewing	25	NECESSARY	
		6	HEADLAMP BULB	Deny	0	NOT NECESSARY	
		7	SMALL LAMP BULB	Deny	0	NOT NECESSARY	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		8	SIGNAL LAMP BULB	Deny	0	NOT NECESSARY	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$2,496.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,570.00	\$1,570.00
Spare Parts	\$2,706.00	\$2,706.00
Miscellaneous	\$220.00	\$220.00
Excess	-\$2,000.00	-\$2,000.00

Submit for Review