



⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2016 HINO XZU710R-HKFMS3 (YP6072Y)

Date of Loss 23 February 2018

Time of Loss 16.30

Loss Description YP6072Y (INSD) C/W COLLIDED INTO PROPERTY

Comment

Workshop Details

Total Rebate Amount 35228

Nett Loss Amount \$49,772.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 372

Maximum value is 365



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# YP6072Y

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

18/04/2017



Mileage

25234

Age of Vehicle

0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
----------	--------------------	------------------------

Manufacturing Year

2016

2016

Make

HINO

HINO

Model

XZU710R-HKFMS3

HINO XZU710R-I

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
----------	------------------	-------------------------

Driver Name

LAM HON HOU

Date of Birth

27 May 1985

dd/mm/yy

Age

33

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	JHHUCS3H20K019494	<input type="text" value="JHHUCS3H20K01"/>
Engine No	N04CUS30526	<input type="text" value="N04CUS30526"/>
Engine Capacity		<input type="text" value="4009"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="85000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	1	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date	1 January 2018	<input type="text" value="dd/mm/yy"/> 
License Expiration Date		<input type="text" value="dd/mm/yy"/> 
Address	18 WHOLESALE CENTRE, #01-123, 110018, Singapore	<input type="text" value=""/>
Address type	Personal Correspondence	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text" value=""/>
Marital status	Unknown	<input type="text" value=""/>
Identification #	G8353712X	<input type="text" value=""/>



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

05/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2800

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



● Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

Please enter the required fields in General & Workshop Details

<< **Assessment Details**

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Parts

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT WINDSCREEN RUBBER			Necessary	442.4		15		376.04	Reviewing	
		2	1			FRONT WIPER PANEL			Serviceable	0	0	0	0	0	Deny	
		3	1			FRONT CORNER PANEL O/S			Cracked	483.22		15		410.74	Reviewing	
		4	1			FRONT CORNER PANEL N/S			Repair	0	0	0	0	0	Deny	
		5	1			FRONT SIDE MIRROR N/S			Cracked	183.4		15		155.89	Reviewing	
		6	1			FRONT SIDE MIRROR O/S			Serviceable	0	0	0	0	0	Deny	
		7	2			FRONT SIDE ROUND MIRROR			Serviceable	0	0	0	0	0	Deny	
		8	1			FRONT SIDE ROUND MIRROR ARM			Serviceable	0	0	0	0	0	Deny	
		9	1			FRONT PANEL			Dented	898		15		763.3	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		10	1			FRONT REFLECTOR LAMP O/S			Cracked	282.75		15		240.34	Reviewing	
		11	1			FRONT REFLECTOR LAMP N/S			Serviceable	0	0	0	0	0	Deny	
		12	2			HEADLAMP			Cut	1016		15		1727.2	Reviewing	
		13	2			FRONT SIDE LAMP			Serviceable	0	0	0	0	0	Deny	
		14	1			FRONT GRILLE			Cracked	739.4		15		628.49	Reviewing	
		15	1			FRONT GRILLE EMBLEM			Necessary	85.3		15		72.51	Reviewing	
		16	1			FRONT BUMPER			Damaged	967		15		821.95	Reviewing	
		17	2			FRONT BUMPER BRACKET			Bent	132.15		15		224.66	Reviewing	
		18	1			FRONT FLOOR PANEL			Repair	0	0	0	0	0	Deny	
		19	2			FRONT DOOR PILLAR OUTER			Repair	0	0	0	0	0	Deny	
		20	2			FRONT DOOR PILLAR INNER			Repair	0	0	0	0	0	Deny	
		21	1			FRONT DOOR PANEL O/S			Dented	1980		15		1683	Reviewing	
		22	1			FRONT DOOR PANEL N/S			Serviceable	0	0	0	0	0	Deny	
		23	2			FRONT DOOR PANEL GARNISH			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		24	4			FRONT DOOR HINGE			Serviceable	0	0	0	0	0	Deny	
		25	2			FRONT DOOR ARRESTER			Serviceable	0	0	0	0	0	Deny	
		26	2			FRONT DOOR GLASS			Serviceable	0	0	0	0	0	Deny	
		27	2			FRONT DOOR GLASS RUN CHANNEL			Serviceable	0	0	0	0	0	Deny	
		28	2			FRONT DOOR GLASS OUTER MOULDING			Serviceable	0	0	0	0	0	Deny	
		29	2			FRONT DOOR GLASS INTER MOULDING			Serviceable	0	0	0	0	0	Deny	
		30	2			FRONT DOOR INNER TOP HANDLE			Serviceable	0	0	0	0	0	Deny	
		31	2			FRONT DOOR INNER TRIM TOP			Serviceable	0	0	0	0	0	Deny	
		32	2			FRONT RH DOOR INNER TRIM			Serviceable	0	0	0	0	0	Deny	
		33	2			FRONT DOOR GLASS REGULATOR			Serviceable	0	0	0	0	0	Deny	
		34	2			FRONT RH GLASS REGULATOR MOTOR			Serviceable	0	0	0	0	0	Deny	
		35	2			FRONT DOOR STRIKER			Serviceable	0	0	0	0	0	Deny	
		36	2			FRONT DOOR WEATHERSTRIP			Serviceable	0	0	0	0	0	Deny	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./BTRR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	37	2			FRONT DOOR FRAME WEATHERSTRIP			Serviceable	0	0	0	0	0	Deny	
	38	2			FRONT DOOR ARCH SEAL			Serviceable	0	0	0	0	0	Deny	
	39	2			FRONT STEP PANEL			Serviceable	0	0	0	0	0	Deny	
	40	2			FRONT STEP GARNISH			Cracked	279.1		15		474.47	Reviewing	
	41	2			FRONT WHEEL ARCH PANEL			Serviceable	0	0	0	0	0	Deny	
	42	2			FRONT WHEEL ARCH GARNISH			Serviceable	0	0	0	0	0	Deny	
	43	1			AIR PRESSURE TANK			Serviceable	0	0	0	0	0	Deny	
	44	1			AIRCON CONDENSER			Dented	1679		15		1427.15	Reviewing	
	45	1			AIR CON DISCHARGER TUBE			Bent	455		15		386.75	Reviewing	
	46	1			AIRCON DISCHARGE HOSE			Bent	572		15		486.2	Reviewing	
	47	1			AIRCON LIQUID TUBE			Bent	330.9		15		281.27	Reviewing	
	48	1			AIRCON CONDENSER FAN ASSY			Cracked	536.9		15		456.37	Reviewing	
	49	1			AIRCON CONDENSER BRACKET			Bent	317.34		15		269.74	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		50	1			DASHBOARD TOP			Serviceable	0	0	0	0	0	Deny	
		51	1			DASHBOARD BOTTOM			Serviceable	0	0	0	0	0	Deny	
		52	1			DASHBOARD SIDE COVER			Serviceable	0	0	0	0	0	Deny	
		53	1			DASHBOARD REINFORCEMENT			Serviceable	0	0	0	0	0	Deny	
		54	1			SPEEDOMETER ASSY			Serviceable	0	0	0	0	0	Deny	
		55	1			SPEEDOMETER GARNISH			Serviceable	0	0	0	0	0	Deny	
		56	1			STEERING COLUMN ASSY			Serviceable	0	0	0	0	0	Deny	
		57	2			STEERING SHAFT JOINT ASSY			Serviceable	0	0	0	0	0	Deny	
		58	1			P/STEERING			Serviceable	0	0	0	0	0	Deny	
		59	2			P/STEERING TIE ROD END			Serviceable	0	0	0	0	0	Deny	
		60	2			FRONT SHOCK ABSORBER			Bent	482.6		15		820.42	Reviewing	
		61	2			FRONT UPPER ARM			Serviceable	0	0	0	0	0	Deny	
		62	2			FRONT WHEEL HUB ASSY			Damaged	325		15		552.5	Reviewing	
		63	2			FRONT KNUCKLE ARM			Bent	550		15		935	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		64	2			FRONT LOWER ARM			Bent	425		15		722.5	Reviewing	
		65	2			SIDE REINFORCEMENT BAR			Bent	400.15		15		680.26	Reviewing	
		66	1			REAR EXHAUST BRACKET			Serviceable	0	0	0	0	0	Deny	
		67	1			REAR EXHAUST GASKET			Serviceable	0	0	0	0	0	Deny	
		68	2			REAR EXHAUST RUBBER MOUNTING			Serviceable	0	0	0	0	0	Deny	
		69	1			REAR EXHAUST SILENCER BOX			Bent	856.32		15		727.87	Reviewing	
		70	2			REAR SIDE GATE FLIP LOCK HANDLE			Bent	149.3		15		253.81	Reviewing	
		71	1			REA SIDE GATE HINGE-12PCS			Bent	75		15		63.75	Reviewing	
		72	2			REAR TAILLAMP			Cracked	258.95		15		440.22	Reviewing	
		73	2			REAR TAILLAMP BRACKET			Bent	98.22		15		166.97	Reviewing	
		74	6			REAR TAILGATE HINGE			Serviceable	0	0	0	0	0	Deny	
		75	1			REAR TAILLAMP LOWER PANEL			Bent	747.35		15		635.25	Reviewing	
		76	1			REAR TAILGATE LOWER PANEL NUMBER PLATE BRACKET			Bent	39.4		15		33.49	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	77	1			REAR TAILGATE LOWER PANEL STEP BRACKET			Cracked	479.4		15		407.49	Reviewing	
	78	1			REAR TAILGATE OUTER LOCK HANDLE			Bent	221.52		15		188.29	Reviewing	
	79	2			REAR TAILGATE LOWER PANEL NUMBER PLATE LAMP			Cracked	81.35		15		138.3	Reviewing	
	80	1			REAR DIFFERENTIAL ASSY			Serviceable	0	0	0	0	0	Deny	
	81	1			REAR FUEL TANK			Dented	1204		15		1023.4	Reviewing	
	82	1			RER FUEL TANK BRACKET			Bent	301		15		255.85	Reviewing	
	83	4			REAR LEAF SPRING			Serviceable	0	0	0	0	0	Deny	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		CHECK WIRING AND LIGHTNING SYSTEM	60	0	0	Reviewing		
	2		REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	60	0	0	Reviewing		
	3		REMOVE AND RENEW FRONT WINDSCREEN	120	0	0	Reviewing		
	4		REMOVE AND RENEW FRONT DASHBOARD	220	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		5		REMOVE AND RENEW FUEL TANK	100	0	0	Reviewing		
		6		CHECK FRONT AND REAR WHEEL ALIGNMENT	120	0	0	Reviewing		
		7		REMOVE AND REPLACE FRONT AND REAR UNDERCARRIAGE	400	0	0	Reviewing		
		8		REMOVE AND REPLACE AIRCON CONDENSER AND TOP UP GAS	100	0	0	Reviewing		
		9		REMOVE AND REPLACE RADIATOR AND TOP UP COOLANT	100	0	0	Reviewing		
		10		TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	0	0	0	Deny		
		11		MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	300	0	0	Reviewing		
		12		PANEL BEATING ON AFFECTED AREAS	1400	0	0	Reviewing		
		13		SPRAY PAINTING ON AFFECTED AREAS	1400	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add Approve Deny Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 24 DAYS	Reviewing			
		2	REAR LH CHASSIS SIDE FRAME	Reviewing	1200	CRACKED	
		3	REAR SIDE WODDEN GATE-2PCS	Reviewing	1300	CRACKED	
		4	REAR SIDE GATE BRACKET - 2PCS	Reviewing	60	BENT	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		5	REAR WOODEN TAILGATE	Reviewing	800	DAMAGED	
<input type="checkbox"/>		6	FRONT NUMBER PLATE	Reviewing	80	BENT	
<input type="checkbox"/>		7	REAR NUMBER PLATE	Reviewing	80	MISSING	
<input type="checkbox"/>		8	JOINT SEALANT	Deny	0	NOT NECESSARY	
<input type="checkbox"/>		9	WINDSCREEN SEALANT	Reviewing	120	NECESSARY	
<input type="checkbox"/>		10	RIM - 4PCS	Reviewing	1200	BENT	
<input type="checkbox"/>		11	TYRE - 4PCS	Reviewing	200	DEFORMED-1PC ONLY	
<input type="checkbox"/>		12	BRAKE FLUID	Reviewing	40	NECESSARY	
<input type="checkbox"/>		13	P/STEERING FLUID	Reviewing	40	NECESSARY	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		14	24 PAX STICKER	Reviewing	15	NECESSARY	
		15	6/KM STICKER	Reviewing	15	NECESSARY	
		16	REAR CANOPY ASSY	Reviewing	5800	DISTORTED	



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$31,461.44

Claim Amount

\$31,461.44

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$18,931.44

\$18,931.44

Labour

\$4,380.00

\$4,380.00

Miscellaneous

\$10,950.00

\$10,950.00

Excess

-\$2,800.00

-\$2,800.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	FINAL LUMP SUM	Reviewing	25000		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$22,200.00

Claim Amount

\$22,200.00

CATEGORY

ESTIMATE

REVISED AMOUNT

Miscellaneous

\$25,000.00

\$25,000.00

Excess

-\$2,800.00

-\$2,800.00

[Submit for Review](#)