

ASS. REC. BY:

REF: CS/FCI18004174/Kvd3/n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Serene Ler

of

FCI

Date/Time: 2/3/18 @ 6:48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5538Y

Insured:

SHC 3219G

at Workshop m/s

Trans Cab

Tel:

62876666

of

No. 2 Amksf. 63

Policy No:

Claim No:

D18001779MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

1/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS / wp

H.O.D. Endorsement:

Date/Time:

9:04am @ 5/3/18

Person Contacted:

Jiong how

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 5538Y - cc3/ALG12000371/Ka2b/q2

D.O.A: 04/01/2012

SHC 3219G - cc3/FCI15017666/Wqbc2

D.O.A: 28/8/15

6/3/18

Email preli revised to FCI

FCI

URGENT

SHL 5538Y at 14

Date 5/3/18

Estimated Cost
 05 ☒ WS / TP RES / OD RES / EVA / INV / MV
 To inspect vehicle No SHL 5538Y
 at Worksite No Trans-Cab
 on No. 2 AMK street 63
 Insured
 Policy No
 Claims No
 Sum Insured Excess
 Clients Record
 Make of van



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value
 DAD Accident Report Consistent? : Yes or No
 G/A / FR / Seen Consistent? : Yes or No
 Est. Repairs days Res: Yes or No
 LHM Sum 20 % 3 Val: Yes or No
 CA / REV / REP / 24 HRS 1wp
 Date Person Contacted
 Vehicle IN / OUT

Type M Car M Cycle B Scooter 4072 C
 Truck Trailer
 Make Renault Latitude 1995
 Colour M. White / Red
 No. 380534
 Engine
 VIN VI1ABL15AUC 278883
 Gen Cond ☒ Good Fair Poor Burnt
 Steering In ☒ Jammed / Leaked Burnt or
 Brakes In ☒ Jammed / Leaked Burnt or
 Mod ☒ S R R STD A R R
 Tyre Size Ling Long 215/60R16
 = Falken
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUM
 TOYO / YOKO
 Front R/R 7
 L/R 7
 D/O 11/3/18 3/3/18
 Survey notes
 Des. of Damages Fr. ☒ Res: OS NS UC Roofed or
 The UIC / Chassis/frame / Body Structure affected due to collision

RECEIVED 06 MAR 2018

Date Time Action / Instruction
 6/3 File pass to Catherine
 L1 Rep @ 2450 (Rel 34, 248.72, 939)

Date Time File Resur ☐ Preli. Report
☐ Final Report
 Date Time File Resur
 6/3 - typst
 Resur Format
 LHM Sum
 WS
 LS \$ 2450p

Days Of Repair 2
 Resurvey No. of Trip -
 Add Fee: ☐ Grease ☐
☐ Wash ☐
☐ Test ☐
☐ Rep ☐
 Sum Fee
 26X15 = 390
 170 + 390
 50
 : 12
 58A
 037
 6/3/18 622

Survey Department Check List (Case Handler)

Reference No.: CS/FCI/800474/Kvc3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA/REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 6/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004174/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3219G	Veh. Inspected	SHC 5538Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001779MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	05/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/03/2018	Inspection Date	05/03/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	02-03-2018	Our Ref No. D18001779MFSH
Accident Date	01-03-2018	Claim Type. Third Party
Insured Vehicle	SHC3219G	Third Party Vehicle. SHC5538Y
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	JIONG HOW NG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: EST. COR - \$36,698.72	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235537)



PRI Documents



Close



PRI Header Details

Claim No	D18001779MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS C / LEE KIM CHI
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : JIONG HOW NG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: JIONGHOW.NG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: EST. COR - \$36,698.72		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3219G	TP Vehicle No	SHC5538Y
PRI Recieved Date	02-03-2018 04:57:27 PM	Surveyor Appointed Date	02-03-2018 06:47:40 PM	Surveyor Accept Date	05-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 6 March 2018 12:37 PM
To: 'Claim Workflow System'
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001779MFSH/1, SHC 5538Y
Attachments: SHC 5538Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 5538Y
Date of survey: 5/3/2018
Number of days:2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 5 March 2018 10:21 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001779MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 2 March 2018 6:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001779MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001779MFSH

Our ref: CS/FCI18004174/Kvd3

Date : 6/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5538Y


We thank for your instruction on 2/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/3/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$36,698.72
Revised Estimate Amount	: S\$2,450.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5538Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	02 Mar 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001697
Chassis No.:	VF1ABL15AUC278883
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	15 Aug 2014
First Registration Date:	15 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	14 Aug 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,088.00
COE Rebate Amount:	\$27,854.00
Total Rebate Amount:	\$37,227.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Mar 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5538Y -**AAD1803-009***Not Authored*
11 Sep \$2450.

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5538Y - JHOW

VF1ABL15AUC278883

RENAULT

LATITUDE

01.03.2018

FCIL

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 —
2	1	BUMPER LOWER REAR	\$	<i>not in</i> 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sh</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sh</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sh</i> 44.99 <
6	1	BUMPER REFLECTOR RH	\$	<i>Sh</i> 43.61 <
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sh</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sh</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sh</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 —
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1	BOOT REAR	\$	<i>R</i> 2,872.68
14	1	BOOT FINISHER	\$	<i>Sh</i> 470.06
15	1	BOOT WHEATERSTRIP	\$	<i>Sh</i> 323.05
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sh</i> 493.35
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sh</i> 493.35
18	1	BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
19	1	BOOT BADGE	\$	<i>na</i> 225.36
20	1	BOOT SWITCH	\$	<i>Sh</i> 168.13
21	1	BOOT LOCK	\$	<i>R</i> 202.67
22	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
23	2	LICENCE PLATE LAMP	\$	<i>Sh</i> 50.52
24	2	BOOT RUBBER PLUG	\$	<i>Sh</i> 221.81
25	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
26	1	WHEELARCH REAR LH	\$	<i>Sh</i> 543.47
27	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
28	1	WHEELARCH REAR RH	\$	<i>Sh</i> 543.47
29	1	TAILLAMP RH	\$	<i>Sh</i> 552.55
30	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
31	1	TAILLAMP LH	\$	<i>Sh</i> 552.55
32	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70
33	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77
34	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sh</i> 404.56

X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-009

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5538Y -

35	1	EXHAUST REAR	\$	7,489.05	X
36	1	EXHAUST CAP REAR	\$	230.49	✓

TOTAL	\$	29,849.67	⁴
10%	\$	2,984.97	
	\$	26,864.70	

Specical Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEP R RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	30.00	
13	1	BOOT STICKER "6555-3333"	\$	30.00	
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	
16	1	TAILLAMP CLIP RH	\$	5.00	
17	1	TAILLAMP CLIP LH	\$	5.00	
18	2	REAR WINDSCREEN SELANT	\$	80.00	
19	1	WINDSCREEN MOULDING	\$	100.00	
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	} X
22	1	SPARE TYRE	\$	330.00	

TOTAL	\$	2,124.02
TOTAL PARTS	\$	28,988.72

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 ²²⁰¹

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 2,800.00 ²⁰⁰¹

To Rust-Proofing Of The Affected Areas. \$ 170.00 X ²⁰⁰¹

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-009**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5538Y -

To reinstall rear bumper parking sensor.	\$	170.00	602
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
Towing Fees	\$	~ 120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X

TOTAL \$ 7,710.00**Over All Total \$ 36,698.72****(PARTS BY PARTS)****Repair Days****10 Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004174/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3219G	Veh. Inspected	SHC 5538Y	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001779MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC278883	Colour	METALLIC WHITE / RED	
Odometer	380534	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	LING LONG	8 mm	
L/H Front Tyre	215/60 R16	LING LONG	8 mm	
R/H Rear Tyre	215/60 R16	FALKEN	7 mm	
L/H Rear Tyre	215/60 R16	FALKEN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2018	Inspection Date	05/03/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5538Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-

Report Ref No. CS/FCI18004174/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-2,984.96	-265.48
			26,864.68	2,389.34
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-

Report Ref No. CS/FCI18004174/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,124.02	165.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	220.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		2,800.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME. TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,710.00	480.00

Report Ref No. CS/FCI18004174/Kvd3n2



GRAND TOTAL		36,698.70	3,034.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00

Report Ref No. CS/FCI18004174/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.