

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18004184/KPS3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : SLS4207C

Insured Vehicle No :

SHD401K

Date of Loss: 13/02/2018

Nature of Claim:

TP

Claim No: C0471170

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLS4207C

Make & Model:

RENAULT LATITUDE, 2.0 CVT ABS (A)

Engine No:

2ZR8171920

Reg. Date:

22/09/2017 (Man. Year: 2017)

Chassis No:

ZYX102066428

Colour:

Metallic Black

Odometer:

34863 km

Engine Capacity:

1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side:

Michelin 8 mm

Rear Left Side:

Michelin 7 mm

Front Right Side:

Michelin 8 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,481.22	1,773.23	707.99	28.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	575.00	905.00	61.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,961.22	2,348.23	1,612.99	40.72
+ Car Rental (2.0 x S\$80.00/day) (S\$)		160.00		
Nett Liability (S\$)		2,508.23		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment: 02/03/2018

Date Inspected: 05/03/2018 Inspected At:

Lian Her Motors (HQ)

Block 5038 Ang Mo Kio Avenue 3,

#01-405 Ang Mo Kio Industrial Park 2

Singapore 569541

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2020)
Parts:	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS4207C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER N/S (CONSISTENT)	Bent	819.30 FL	*780.31 FL
2	1		*FRONT FENDER EMBLEM N/S (CONSISTENT)	Necessary	57.80 FL	*57.80 FL
3	1		*FRONT FENDER LOWER SHIELD N/S (CONSISTENT)	Serviceable	272.60 FL	*- FL
4	6		*FRONT FENDER LOWER SHIELD CLIP N/S (CONSISTENT)	Not Necessary	77.40 FL	*- FL
5	3		*FRONT FENDER REAR PROTECTOR CLIP N/S (CONSISTENT)	Not Necessary	38.70 FL	*- FL
6	1		*FRONT WHEELARCH GARNISH N/S (CONSISTENT)	Dented	173.00 FL	*173.00 FL
7	8		*FRONT WHEELARCH GARNISH CLIP N/S (CONSISTENT)	Necessary	103.20 FL	*103.20 FL
8	1		*FRONT BUMPER RETAINER N/S (CONSISTENT)	Serviceable	116.30 FL	*- FL
9	1		*LH FRONT DOOR SIDE MIRROR	Punctured	1,650.00 FL	*1,250.00 FL
					Sub Total (\$\$)	3,308.30 2,364.31
					- List Item Discount on L Items 25.00/25.00% (\$\$)	827.08 591.08
					Total Parts (\$\$)	2,481.22 1,773.23

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW & ALIGN ABOVE MENTIONED DAMAGED PARTS	New	450.00	250.00
2	TO PUTTY AND SPRAY PAINT	New	450.00	220.00
3	TO CHECK WIRINGS AND FOCUS HEADLAMP	New	150.00	15.00
4	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS	New	100.00	30.00
5	TO APPLY UNDERSEAL ON THE AFFECTED AREAS	New	80.00	0.00
6	TO PUTTY AND SPRAY PAINT	New	150.00	60.00
7	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,480.00	575.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >