



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 4008L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COMPLETE FRONT BUMPER MGT (CONSISTENT)	DEFORMED	6,500.00	6,500.00
13	SCREW (CONSISTENT)	NECESSARY	214.50	214.50
4	RIVET (CONSISTENT)	NECESSARY	19.40	19.40
4	SCREW FOR FRT GRILLE (CONSISTENT)	NECESSARY	24.80	24.80
4	SCREW (CONSISTENT)	NECESSARY	16.00	16.00
4	WASHER FOR BRACKET ON HEAT (CONSISTENT)	NECESSARY	8.00	8.00
1	BUMPER UPPER SUPPORT PADDING (CONSISTENT)	* CHECK	539.20	-
1	BUMPER LOWER SUPPORT PADDING (CONSISTENT)	* CHECK	539.20	-
1	AIR CONVEYOR (CONSISTENT)	* CHECK	1,085.00	-
1	SIDE GRILL KIT (CONSISTENT)	BENT	502.70	502.70
1	FRONT LH SUSP ARM KIT (CONSISTENT)	* CHECK	2,820.00	-
1	LH FRONT HEADLIGHTS (CONSISTENT)	* CHECK	6,800.00	-
1	LH FOG LIGHT (CONSISTENT)	NOT NECESSARY	250.00	-
1	COMPLETE STEERING RACK (CONSISTENT)	* CHECK	7,268.00	-
2	STEERING RACK PIPE COPPER WASHER (CONSISTENT)	* CHECK	3.00	-
2	STEERING PIPE COPPER WASHER (CONSISTENT)	* CHECK	2.40	-
1	LH FRONT WHEELHOUSE (CONSISTENT)	NOT NECESSARY	150.00	-
1	LH FRONT DEFLECTOR (CONSISTENT)	TORN	120.00	120.00
11	SCREW (CONSISTENT)	NECESSARY	60.50	60.50
11	WASHER (CONSISTENT)	NECESSARY	28.05	28.05
1	FRONT BUMPER PARKING SENSOR (CONSISTENT)	* CHECK	480.00	-
2	PARKING SENSOR GASKET (CONSISTENT)	NECESSARY	70.00	70.00
2	BUMPER SIDE PARK SENSOR MOUNT (CONSISTENT)	NECESSARY	36.00	36.00
1	FRONT WHEEL RIM SILVER "19 (CONSISTENT)	CUT	2,600.00	2,600.00
1	245/40 ZR19 94Y PZERO (@ \$780.00 DISC 80%) (CONSISTENT)	* CHECK	780.00	-
5	WHEEL STUDS (CONSISTENT)	NECESSARY	125.00	125.00
1	TYRE VALVE (CONSISTENT)	NECESSARY	17.60	17.60
1	LH FENDER MGT (CONSISTENT)	BENT	6,000.00	6,000.00
3	LH AIR INTAKE (CONSISTENT)	NECESSARY	169.20	169.20
1	PININFARINA INSCRIPTION (CONSISTENT)	NECESSARY	28.00	28.00

Report Ref No. CC4/ASM18004189/T1pb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH KICK PLATE (CONSISTENT)	NECESSARY	169.00	169.00
1	REG PLATE (CONSISTENT)	NECESSARY	60.00	60.00
1	SYNTHETIC ATF 111G (2.5) (CONSISTENT)	* CHECK	55.00	-
1	LH HEADLIGHT SUPPORT BRACKET (CONSISTENT)	* CHECK	620.00	-
1	OVAL EMBLEM, MGS (FRT BUMPER) (CONSISTENT)	NECESSARY	62.00	62.00
1	LH SIDE LIGHT (CONSISTENT)	NECESSARY	30.55	30.55
1	FRONT BUMPER CROSS MEMBER (CONSISTENT)	TO REPAIR SEE LABOUR	5,250.00	-
1	LH SKIRT HOLDER BRACKET - MTG (CONSISTENT)	NECESSARY	192.75	192.75
8	NUT (CONSISTENT)	NECESSARY	8.80	8.80
11	SIDE SKIRT SCREW (CONSISTENT)	NECESSARY	181.50	181.50
1	LH BALL TIE ROD (CONSISTENT)	* CHECK	350.00	-
1	FRONT SUSPENSION SCREW (CONSISTENT)	* CHECK	121.50	-
2	NUT (CONSISTENT)	NECESSARY	24.00	24.00
2	WASHER (CONSISTENT)	NECESSARY	17.00	17.00
1	FRONT SUSPENSION BOLT (CONSISTENT)	* CHECK	218.00	-
1	LH BRACKET HEADLAMP WASHER GUN HOLDER (CONSISTENT)	NECESSARY	56.00	56.00
1	RH BRACKET HEADLAMP WASHER GUN HOLDER (CONSISTENT)	NECESSARY	56.00	56.00
1	WHEEL CAP BLACK (CONSISTENT)	NECESSARY	36.00	36.00
			44,764.65	17,433.35
LABOUR				
REMOVE, INSTALL & RENEW: FRONT BUMPER, FRONT GRILL, BOTH HEADLAMP WASHER SYSTEM PIPING, FRONT BUMPER AIR CONVEYOR, BOTH HEADLAMP, FENDER GRILLS, INDICATOR LAMP & ENGINE COPARTMENT COVER TO FACILITATE REPAIRS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER CROSS MEMBER.			5,800.00	4,200.00
RENEW LEFT HEADLAMP SUPPORT BRACKET INCLUDE CUT & WELD.			950.00	800.00
REMOVE & RENEW LEFT FRONT FENDER INCLUDE CUT & WELD INCLUDE REMOVE & REINSTALL LEFT SIDE SKIRT TO FACILITATE REPAIR.			3,000.00	2,800.00
RENEW FRONT LEFT RIM & TYRE INCLUDE BALANCE.			180.00	140.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & RENEW LEFT RIGHT SUSPENSION ARMS, WHEEL BEARING.		1,600.00	1,400.00
	REMOVE & RENEW POWER STEERING RACK & BLEED SYSTEM.		1,600.00	1,400.00
	RESET ALL SYSTEM WITH COMPUTER TESTER AND RESET HEADLIGHT AIMING.		950.00	950.00
	RESET ALL WHEEL ALIGNMENT.		750.00	750.00
	RESPRAY PREMIER & PAINT: FRONT BUMPER, LEFT FRONT FENDER. PARKING SENSOR.		3,500.00	3,000.00
			18,330.00	15,440.00
	GRAND TOTAL		63,094.65	32,873.35
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$21,525.30 NETT)			32,873.35

Report Ref No. CC4/ASM18004189/T1pb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.