

ASS. REC. BY:

REF: CS / ICS18004211 / G903ⁿ² Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

janice goh

of

ECICS

Date/Time:

5/3/18 @ 10:06am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 5256 H

Insured:

SFS 5252K

at Workshop m/s

Gforce Autotech

Tel:

6205 8108

of

10 Kaki Bkt Rd 2 #01-34

Policy No:

MPC12A00340101

Claim No:

bMPC1800082H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

11:42am 5/3/18

Person Contacted:

Elle

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKK 5256 H -x
	SFS 5252K -x

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s **Gforce Auto**

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$62k.**

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: **SKK5256H** Yr Regn: **27 Jul 2013**

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Subaru Impreza** c.c. **1600**

Colour: **white** A/C: Insured / Std / Nil / NA

Sp. Reading: **51836** T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: **JF16P3KC5DG025076**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **195/65 R15** R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. _____ D.O.I. **05-03-18**

Survey held at **w/s** **5pm**

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Finalized \$3350 with file (red to 6976, 67%)

RECEIVED 20 DEC 2018

28/12/2018

Date/Time, File Pass to? ☐ : Preli. Report

1) **28/12/2018** ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: **WIKI-TP**

Lump Sum / I.B.I. (\$) **3350**

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp. (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee: _____ Transportation: _____ Photos: _____ Covers: _____

TOTAL

350
10
360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18004211/Gqd3

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 05-03-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFS 5252H	Veh. Inspected	SKK 5256H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	05/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date		Inspection Date	05/03/2018
Survey held at	GFORCE AUTOTECH PRIVATE LIMITED 10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE SINGAPORE 417868		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 5 March 2018 10:06 AM
To: Gforce Autotechnik; assignments
Cc: gforce.elle@gmail.com; ECICS Claims
Subject: RE: NEW ACCIDENT CLAIM INVOLVING SKK 5256H & SFS 5252K
Attachments: CCI01018_0004.jpg; CCI01018_0005.jpg; OWNER DRIVING LICENSE.JPG; OWNER IC NUMBER.JPG; SKK5256H - GIA REPORT.PDF; File-20180301-112713.pdf

Without Prejudice

Dear Elle

Thank you for your email with the attachment.
We will appoint LKK for the PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Gforce Autotechnik [mailto:gforce.workforce@gmail.com]
Sent: Friday, 2 March, 2018 11:55 AM
To: ECICS Claims
Cc: gforce.elle@gmail.com
Subject: NEW ACCIDENT CLAIM INVOLVING SKK 5256H & SFS 5252K

Dear Sirs,

Notice to insurer to conduct Pre Repair inspection accident involving SKK 5256H & SFS 5252K on 1st March 2018, 07.30am along Tanah Merah Coast Road.

We would like to inform you to conduct Pre-Repair Inspection and arrange your surveyor to come and take picture. Here I attached GIA report, NRIC and driving license our client's for your reference. Our client car at workshop already.

As per result of the accident, our client's vehicle has been damaged. Before our client's proceed to repair damaged of the vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle.

Location	10 KaKi Bukit Road 2, First East Centre #01-34 Gforce Autotech Singapore 417868
Contact Number	+65 6205 8108 (Office) +65 9139 1448 (Adrian)
Operation Hour	9.00am to 6pm (Weekdays) 9.00am to 3pm (Saturday) PH (Closed)

Regards,

Elle (Ms)

Gforce Autotechnik

Tel: +65 6205 8108

Sent from Mail for Windows 10

follow us on  follow us on  visit our website 
facebook  twitter  ecics.com.sg 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7555C
Vehicle Details	
Vehicle No.:	SKK5256H
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	SUBARU
Vehicle Model:	IMPREZA 1.6I-S AWD CVT
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	FB16R588006
Chassis No.:	JF1GP3KC5DG025076
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$12,925.00
Original Registration Date:	27 Jul 2013
First Registration Date:	27 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,925.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2023
PARF Rebate Amount:	\$9,693.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$73,989.00
COE Rebate Amount:	\$37,573.00
Total Rebate Amount:	\$47,266.00

The information contained herein is correct as at 27 Jun 2018

OK

GFORCE AUTOTECH PRIVATE LIMITED

10 KAKI BUKIT ROAD 2 #01-34
SINGAPORE 417868
MOBILE: +65-9139 1448
CO REGISTRATION NO: 201631929K



Vehicle Registration No: SKK 5256 H

Qty	Description	Amount
<u>SPARE PART - LIST ITEMS</u>		
1	Rear bumper / <i>el</i>	\$ <i>720</i> 953.00 /
1	Rear bumper beam / <i>BT</i>	\$ <i>227.2</i> 300.00 /
1	Rear bumper tow cover X <i>NN</i>	\$ X 26.00
2	Tail lamp lower brackets X <i>NN</i>	\$ X 92.00
2	Rear bumper side retainer / <i>el</i>	\$ / 78.00 /
2	Tail lamps X <i>NN</i>	\$ X 1210.00
2	Rear bumper reflector X <i>NN</i>	\$ X 74.00
1	End panel garnish / <i>el</i>	\$ <i>180</i> 258.00 /
1	Tail gate lock / <i>BT</i>	\$ <i>172</i> 282.00 /
1	Tail gate clutch X <i>NN</i>	\$ X 170.00
1	Rear windscreen sealant / <i>el</i>	\$ <i>40(SN)</i> 80.00 /
1	Rear end panel X <i>repair</i>	\$ X 50.00
2	Boot absorber X <i>NN</i>	\$ X 352.00
1	Exhaust muffler / <i>BT</i>	\$ <i>676</i> 930.00 /
1	Antenna - Exterior X <i>NN</i>	\$ X 208.00
1	Bumper clip / <i>el</i>	\$ <i>40(SN)</i> 80.00 /
1	Rear reverse sensor / <i>DM</i>	\$ <i>200(SN)</i> 369.00 /
1	Rear boot bonnet / <i>BT</i>	\$ / 800.00 /
Total Cost - List Items		\$ 6312.00

2853.2

20%: 2282.56

List Items Total c/f

\$ 6312.00

SN: 280

GFORCE AUTOTECH PRIVATE LIMITED

10 KAKI BUKIT ROAD 2 #01-34
SINGAPORE 417868
MOBILE: +65-9139 1448
CO REGISTRATION NO: 201631929K



Vehicle Registration No: SKK 5256 H

QTY	Description	Amount
<u>SPECIAL NETT ITEMS</u>		
1	Tail gate "Impreza" Emblem	\$ 48.00 /
1	Tail gate "Subaru" Emblem	\$ 48.00 /
2	Tail gate AWD Emblem	\$ 38.00 /
1	Car number plate	\$ 50.00 X
4	Tail light rear bulb	\$ 100 (4pcs) X
Total Cost – Special Nett		\$ 284.00
Items		134
Total cost of parts		\$ 6596.00

GFORCE AUTOTECH PRIVATE LIMITED

10 KAKI BUKIT ROAD 2 #01-34
SINGAPORE 417868
MOBILE: +65-9139 1448
CO REGISTRATION NO: 201631929K



Vehicle Registration No: SKK 5256 H

S/No Description**Amount****LABOUR**

1.	To check wiring and refit headlamp	\$	80.00	30
2.	To remove and refit inner garnishes	\$	120.00	60
3.	To remove and refit rear windscreen	\$	180.00	100
4.	To remove and refit reverse sensor	\$	150.00	40
5.	Transfer and replace tail gate mechanism	\$	150.00	60
6.	To remove, refit and replace exhaust mufflers and mountings	\$	150.00	60
7.	To apply undercoating on repaired and replaced panel	\$	250.00	60
8.	To provide labour charges, workmanship to dismantle above damage parts, repair including cut and welding, re-align body structure and damage consistent to the accident	\$	1400.00	500
9.	To respray painting including polish and waxing on affected areas,	\$	1200.00	60.

Total Amount \$ 3680.00 1560

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GRAND TOTAL \$ 10,276.00

4206.56

2%: 3350

5 Days.

GFORCE AUTOTECH PRIVATE LIMITED

10 KAKI BUKIT ROAD 2 #01-34

SINGAPORE 417868

MOBILE: +65-8555 8300

CO REGISTRATION NO: 201631929K

**INVOICE**

Bill To : ONG KOK TONG
C/O: 10 KAKI BUKIT ROAD 2
#01-34 SINGAPORE 417868

MODEL : SUBARU IMPREZA

Car Plate: SKK 5256 H

Tel:

DATE: 25-06-18

PAGE: 1 / 1

ITEM NO	DESCRIPTION	QUANTITY ORDERED	U.PRICE SGD	AMOUNT SGD
1	REAR PORTION DAMAGED PARTS REPLACEMENT, REPAIR, ALIGNMENT, RESET, CHECK AND LABOUR , SPRAY-PAINTING ETC LUMP SUM REPAIR COST AS PER RECOMMENDATION		SGD 10,276.00	SGD 10,276.00
Grand Total Amount:				SGD 10,276.00

MODE OF PAYMENT: CHEQUE SHOULD BE CROSSED AND PAYABLE TO
GFORCE AUTOTECH PRIVATE LIMITED
OCBC BANK: 519-431951-001

THIS IS AN AUTO-GENERATED INVOICE. THEREFORE SIGNATURE IS NOT REQUIRED. THANK YOU.

(ALL TRADEMARKS AND TRADE NAMES ARE REGISTERED PROPERTIES OF THEIR RESPECTIVE COMPANIES)

CONFIDENTIALITY NOTE: The information contained in this document is legally privileged and confidential. It is use for GFORCE AUTOTECH PRIVATE LIMITED.
If you are not an intended recipient, you are hereby notified that any dissemination, distribution, or copying of this document is prohibited

PAGE 1 / 1

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18004211/GQD3N2

Date: 31/12/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC17A00340101
Claimant Vehicle No :	SKK5256H	Insured Vehicle No :	SFS5252K
Date of Loss:	01/03/2018	Nature of Claim:	TP
		Claim No:	DMPC1800082H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK5256H	Engine No:	FB16R588006
Make & Model:	SUBARU IMPREZA, 1.6I SEDAN	Chassis No:	JF1GP3KC5DG025076
Reg. Date:	27/07/2013 (Man. Year: 2012)	Odometer:	51836 km
Colour:	White		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,596.00	2,696.56	3,899.44	59.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,510.00	2,170.00	58.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,276.00	4,206.56	6,069.44	59.06
Approved Total (Overridden) (S\$)		3,350.00		
Nett Amount (S\$)	10,276.00	3,350.00	6,926.00	67.40

INSPECTION

Date of Assignment:	05/03/2018	
Date Inspected:	05/03/2018	Inspected At:
		Gforce Autotech (HQ) BLK 10 KAKI BUKIT ROAD 2, #01-34 Singapore 417868
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 Dec 2018)
Parts: 143	SUBARU IMPREZA 1.6I SEDAN (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKK5256H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	953.00 F	*720.00 FL
2	1		*REAR BUMPER BEAM	Bent	300.00 F	*227.20 FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	26.00 F	*- FL
4	2		*TAIL LAMP LOWER BRACKETS	Not Necessary	92.00 F	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Deformed	78.00 F	*78.00 FL
6	2		*TAIL LAMPS	Not Necessary	1,210.00 F	*- FL
7	2		*REAR BUMPER REFLECTOR	Not Necessary	74.00 F	*- FL
8	1		*END PANEL GARNISH	Deformed	258.00 F	*180.00 FL
9	1		*TAIL GATE LOCK	Bent	282.00 F	*172.00 FL
10	1		*TAIL GATE CLUTCH	Not Necessary	170.00 F	*- FL
11	1		*REAR END PANEL	Repair	50.00 F	*- FL
12	2		*BOOT ABSORBER	Not Necessary	352.00 F	*- FL
13	1		*EXHAUST MUFFLER	Dented	930.00 F	*676.00 FL
14	1		*ANTENNA-EXTERIOR	Not Necessary	208.00 F	*- FL
15	1		*REAR BOOT BONNET	Bent	800.00 F	*800.00 FL
16	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
17	1		*BUMPER CLIP	Necessary	80.00 FS	*40.00 FS
18	1		*REAR REVERSE SENSOR	Damaged	369.00 FS	*200.00 FS
19	1		*TAIL GATE IMPREZA EMBLEM	Necessary	48.00 FS	*48.00 FS
20	1		*TAIL GATE SUBARU EMBLEM	Necessary	48.00 FS	*48.00 FS
21	2		*TAIL GATE AWD EMBLEM	Necessary	38.00 FS	*38.00 FS
22	1		*CAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
23	4		*TAIL LIGHT REAR BULB	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,596.00	3,267.20
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	570.64
Total Parts (\$\$)	6,596.00	2,696.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REFIT HEADLAMP	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	120.00	60.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	180.00	100.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	40.00
5	TRANSFER AND REPLACE TAIL GATE MECHANISM	New	150.00	60.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST MUFFLERS AND MOUNTINGS	New	150.00	60.00
7	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	250.00	60.00
8	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGE PARTS,REPAIR INCLUDING CUT AND WELDING,RE-ALIGN BODY STRUCTURE AND DAMAGE CONSISTENT TO THE ACCIDENT	New	1,400.00	500.00
9	TO RESPRAY PAINTING INCLUDING POLISH AND WAXING ON AFFECTED AREAS	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,680.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >