

ASS. REC. BY:

REF: CS/FCI/18004261/Kgd3n2 Special Instruction:

Surveyor: May Chua

ASSIGNMENT (Office)

From (Person): May Chua of FCI Date/Time: 5/3/18 @ 5:03pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 9932G Insured: SH 7290Rat Workshop m/s C.S. Ong Auto Tel: 64841933of 10 AMK Ind. Prk 2A #02-16Policy No: _____ Claim No: D18001809 MFSTI

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/2/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement: _____

Date/Time: 1037am 6/3/18 Person Contacted: Mrs. Ong Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJX 9932G - x</u>
<u>02/3/18 @ 3:38pm</u>	<u>SH 7290R - CC3/TM/ISO 20328/H/H/bd</u> <u>revised to May Chua by email.</u>
	<u>CI by @ 5000 email & confirm (red 68503.70, 63%)</u>

ASS. REC. BY:

REF: 1702/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

3x15: 45

130+45

50

50

21

336

RECEIVED 21 JAN 2010



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004261/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7290R	Veh. Inspected	SJX 9932G
Policy No.		Coverage (\$)	0.00
Claim No.	D18001809MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	06/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/02/2018	Inspection Date	06/03/2018
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001809MFSH

Date: 07 March 2018

Our Ref: CS/FCI18004261/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJX 9932G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/03/2018 at the premises of M/s C.S.ONG AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,503.70</u> .
Revised Estimate Amount	: S\$ <u>7,040.40</u> .
"Check" Items Amount	: S\$ <u>2,068.90</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	02-03-2018	Our Ref No. D18001809MFSH
Accident Date	28-02-2018	Claim Type. Third Party
Insured Vehicle	SH7290R	Third Party Vehicle. SJX9932G
Survey Location	10 ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT	
Contact Person.	NA	
Contact No.	64841933/ 0	Fax No. 64841922
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	C.S. ONG AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235572)



PRI Documents



Close



PRI Header Details

Claim No	D18001809MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & C. S. ONG
Workshop Name	C.S. ONG AUTO PTE LTD (Contact Person : NA)	Survey Location & Contact Details	10 ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT Mobile: 0 , Phone: 64841933 , Fax: 64841922 EmailId: CSONGAUTO@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7290R	TP Vehicle No	SJX9932G
PRI Recieved Date	02-03-2018 09:22:14 PM	Surveyor Appointed Date	05-03-2018 05:02:00 PM	Surveyor Accept Date	05-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 7 March 2018 3:38 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001809MFSH/1
Attachments: CSFCI18004261Kqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SJX 9932G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 6 March 2018 10:39 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001809MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 5 March 2018 5:02 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001809MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

*Not Authorized
L1 Rep \$5000
Preserving After Paint
6 days*

C. S. ONG AUTO PTE. LTD.

Business Reg No.: 201408916W

GST Reg No.: 201408916W

10, Ang Mo Kio Ind. Park 2A, #02-16, AMK Autopoint, Singapore (568047).

Tel: 6484 1933 Fax: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
FIRST CAPITAL INS LTD

Date: 02/03/2018

Accident Involving Vehicles SJX9932G & SH7290R [Your Insured] on 28/02/2018 @
1640hrs along SLIP ROAD SCOTTS ROAD TO ORCHARD ROAD

Estimated Repair Costs For SJX9932G [KIA CERATO FORTE 1.6]

Qty	Parts	Amount
2Pcs	Rear Boot Hinges @ \$69.00 Each	\$ R 138.00 X
1Pc	Rear Boot Inner Trim Cover	Sn \$ 191.00 X
1Set	Rear Boot Inner Trim Cover Clips	nn \$ 35.00 X
1Pc	Rear Boot No. Plate Lamp Set	nn \$ 38.00 X
1Pc	Rear Boot Weatherstrip Rubber	Di/LM \$ 109.00 506nn
1Pc	Rear Windscreen Moulding	Sn Di/LM \$ 143.00 506nn X
2Pcs	Rear Tail Lamp Panel RH & LH @ \$119.00 Each	Di/LM \$ 238.00 4
1Pc	Rear Bumper	Rn \$ 609.00 ✓
1Set	Rear Bumper Clips	nn \$ 35.00 ✓
2Pcs	Rear Bumper Side Retainers RH & LH @ \$28.00 Each	Di \$ 56.00 ✓
2 4Pcs	Rear Reverse Sensor @ \$277.00 Each	Short \$ 1,108.00 44
1Pc	Rear Spare Tyre Panel	\$ R 696.00 7
1Pc	Rear Boot	Rn \$ 874.00 ✓
1Pc	Rear Boot Hinge Lock	\$ R 79.00 X
1Pc	Rear Boot Inner Lock	\$ R 107.00 ✓
1Pc	Rear Boot "KIA" Logo	nn \$ 34.00 X
1Pc	Rear Boot "Cerato" Emblem	nn \$ 28.00 X
1Pc	Rear Boot "Forte" Emblem	nn \$ 25.00 X
1Pc	Rear Boot "C&C" Emblem	nn \$ 35.00 X
2Pcs	Rear Fender Tail Lamp @ \$287.00 Each	n/s Bux Di/LM \$ 574.00 4
2Pcs	Rear Boot Tail Lamp @ \$147.00 Each	Sn \$ 294.00 X
1Pc	Rear Boot Top Chrome Moulding	Sn \$ 87.00 X
1Pc	Rear End Panel	Rn \$ 492.00 ✓
1Pc	Rear End Panel Top Garnish	Di \$ 139.00 ✓
1Set	Rear End Panel Top Garnish Clips	nn \$ 35.00 ✓
1Pc	Rear Bumper Lower Lip	CM \$ 677.00 ✓
1Pc	Rear Bumper Lower Lip Top Rubber Seal	nn \$ 45.00 ✓

1Pc	Rear Reinforcement Bar	CM	\$	404.00	✓
1Pc	Rear Reinforcement Exhaust Chrome Tip	NC	\$	68.00	✓
1Pc	Rear Boot Inner Spare Tyre Panel Top Trim Cover	SN	\$	359.00	X
1Pc	Rear Bumper Sponge	IN	\$	141.00	X
Parts Sum:			\$	7,893.00	
Parts Less 10%:			\$	789.30	
Parts Total:			\$	7,103.70	

Special Nett. Items

1Pc	Rear Camera	IN	\$	300.00	X
1set	Rear Number Plate with Holder	SIX	\$	100.00	455
1Set	Rear End Panel Sealants	nn	\$	150.00	305
2Set	Rear RH & LH Tail Lamp Panel Sealants	nn	\$	300.00	X
1Set	Rear Spare Tyre Panel Sealants	nn	\$	100.00	X
Special Nett. Items Total:			\$	950.00	

Labour & MISC Charges

<u>Description</u>	<u>Amount</u>	
* To remove all rear affected areas interior upholstery items to facilitate repair and to refit all back once repair is done.	\$ 1,000.00	Pol
* To remove and replace rear windscreen glass to facilitate repair and to refit back once repair is done.	\$ 200.00	X
* To cut & remove all rear damaged panels, replace new parts, refit and to realign all of the replaced and transferred parts.	\$ 1,500.00	Pol
* To putty & re-spray new paintwork on all rear affected areas.	\$ 1,800.00	100d
* To conduct a check on all wiring systems.	\$ 150.00	2d
* To refit new rear reverse sensors on new rear bumper.	\$ 150.00	Pol
* To refit rear boot spoiler on new rear boot.	\$ 150.00	100d
* To anti rust all affected areas.	\$ 500.00	60d

Labour & Charges Total: \$ 5,450.00
Parts Total: \$ 7,103.70
Special Nett. Items Total: \$ 950.00
Labour & Charges Total: \$ 5,450.00
Total Cost of Repair: \$ 13,503.70
(Non inclusive of 7% GST)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004261/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7290R	Veh. Inspected	SJX 9932G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001809MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	05/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KNAFW411MA5255182	Colour	METALLIC BLACK	
Odometer	197667	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	ACHILLES	4 mm	
L/H Front Tyre	215/45 ZR17	ACHILLES	4 mm	
R/H Rear Tyre	215/45 ZR17	ACHILLES	6 mm	
L/H Rear Tyre	215/45 ZR17	ACHILLES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2018	Inspection Date	06/03/2018	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 9932G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	REAR BOOT HINGES @\$69.00	TO REPAIR SEE LABOUR	138.00	-
1	REAR BOOT INNER TRIM COVER	SERVICEABLE	191.00	-
1	SET REAR BOOT INNER TRIM COVER CLIPS	NOT NECESSARY	35.00	-
1	REAR BOOT NO PLATE LAMP SET	SERVICEABLE	38.00	-
1	REAR WINDSCREEN MOULDING	SERVICEABLE	143.00	-
2	REAR TAIL LAMP PANEL RH & LH @\$119.00	O/S BENT	238.00	119.00
1	REAR BUMPER	BUCKLED	609.00	609.00
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
2	REAR BUMPER SIDE RETAINERS RH & LH @\$28.00	DISTORTED	56.00	56.00
4	REAR REVERSE SENSOR @\$277.00	SHORTED (2 PCS ONLY)	1,108.00	554.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	696.00	-
1	REAR BOOT	BENT	874.00	874.00
1	REAR BOOT HINGE LOCK	TO REPAIR SEE LABOUR	79.00	-
1	REAR BOOT INNER LOCK	DENTED	107.00	107.00
1	REAR BOOT "KIA" LOGO	NOT NECESSARY	34.00	-
1	REAR BOOT "CERATO" EMBLEM	NOT NECESSARY	28.00	-
1	REAR BOOT "FORTE" EMBLEM	NOT NECESSARY	25.00	-
1	REAR BOOT "C&C" EMBLEM	NOT NECESSARY	35.00	-
2	REAR FENDER TAIL LAMP @\$287.00	O/S MTG CRACKED / N/S SERVICEABLE	574.00	287.00
2	REAR BOOT TAIL LAMP @\$147.00	SERVICEABLE	294.00	-
1	REAR BOOT TOP CHROME MOULDING	SERVICEABLE	87.00	-
1	REAR END PANEL	BENT	492.00	492.00
1	REAR END PANEL TOP GARNISH	DISTORTED	139.00	139.00
1	SET REAR END PANEL TOP GARNISH CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER LOWER LIP	CRACKED	677.00	677.00
1	REAR BUMPER LOWER LIP TOP RUBBER SEAL	NECESSARY	45.00	45.00
1	REAR REINFORCEMENT BAR	CRACKED	404.00	404.00

Report Ref No. CS/FCI18004261/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR REINFORCEMENT EXHAUST CHROME TIP	DENTED	68.00	68.00
1	REAR BOOT INNER SPARE TYRE PANEL TOP TRIM COVER	SERVICEABLE	359.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	141.00	-
	LESS 10% DISCOUNT		-778.40	-450.10
			7,005.60	4,050.90
1	REAR BOOT WEATHERSTRIP RUBBER (50%)(SN)	DISTORTED / CUT	109.00	54.50
	LESS 10% DISCOUNT		-10.90	-
			98.10	54.50
	SPECIAL NETT ITEMS			
1	REAR CAMERA (SN)	SERVICEABLE	300.00	-
1	SET REAR NUMBER PLATE WITH HOLDER (SN)	SCRATCHED	100.00	45.00
1	SET REAR END PANEL SEALANTS (SN)	NECESSARY	150.00	30.00
2	SET REAR RH & LH TAIL LAMP PANEL SEALANTS (SN)	NOT NECESSARY	300.00	-
1	SET REAR SPARE TYRE PANEL SEALANTS (SN)	NOT NECESSARY	100.00	-
			950.00	75.00
	LABOUR			
	TO REMOVE ALL REAR AFFECTED AREAS INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIR AND TO REFIT ALL BACK ONCE REPAIR IS DONE.		1,000.00	80.00
	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS TO FACILITATE REPAIR AND TO REFIT BACK ONCE REPAIR IS DONE.	NOT NECESSARY	200.00	-
	TO CUT & REMOVE ALL REAR DAMAGED PANELS, REPLACE NEW PARTS, REFIT AND TO REALIGN ALL OF THE REPLACED AND TRANSFERRED PARTS, INCLUSIVE OF THE REPAIR OF REAR BOOT HINGES, REAR SPARE TYRE PANEL AND REAR BOOT HINGE LOCK.		1,500.00	800.00
	TO PUTTY & RE-SPRAY NEW PAINTWORK ON ALL REAR AFFECTED AREAS.		1,800.00	1,000.00
	TO CONDUCT A CHECK ON ALL WIRING SYSTEMS.		150.00	20.00
	TO REFIT NEW REAR REVERSE SENSORS ON NEW REAR BUMPER.		150.00	80.00
	TO REFIT REAR BOOT SPOILER ON NEW REAR BOOT.		150.00	100.00

Report Ref No. CS/FCI18004261/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO ANTI RUST ALL AFFECTED AREAS.		500.00	60.00
			5,450.00	2,140.00
GRAND TOTAL			13,503.70	6,320.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/FCI18004261/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.