

A.S.S. REC. BY:

REF: CS/EGN18004282/U1b72

Special Instruction:

Surveyor: Maros

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EAT

Date/Time: 09032018 11:04am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 1341D

Insured:

Ym 387U

at Workshop m/s

Fasterh

Tel:

6746 5405

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

Ym387U/SE/p1

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 1341D - X

Ym 387U - CS/EGN18004282/Tgh302

DCA: 081217

(08/11/13) waf

ASS. REC. BY: Marcus

REF:

ER1/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RE. / EVA / INV / MV
 To Inspect Vehicle No: 5BF1341D
 at Workshop m/s LL
 of _____
 Insured: 1/M 3874
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: 1 Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 6BF1341D Yr Regn: 6, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or LMMake: Toyota C.C. 2982Colour: white A/C: Insured / Std / NI / NASp. Reading: 68472 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KapsenFront 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 6/3/18D.O.L. 6/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

None

2/3/18 confirmed 2/5 \$5500 with Alan (Ref. 10,646.28, 657)
 just follow Assignment date 7/3/2018

RECEIVED 7 MAR 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 5

1)

☐

Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: TPLump Sum / I.B.I: (\$ 5500)

TOTAL

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18004282/Utb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 06-03-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 387U	Veh. Inspected	GBF 1341D
Policy No.		Coverage (\$)	0.00
Claim No.	YM387U/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/03/2018	Inspection Date	06/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No. : CEA118004382/14th
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Marcus): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Celine

Case Handler

Date

27/3/18

*C: Critical *N: Non-Critical

21/05/2014

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 7 March, 2018 11:04 AM
To: 'admin-d@lkkauto.com'
Subject: OI : YM387U / TP : GBF1341D/LKK / DOA : 06/03/2018
Attachments: YM387U - SAS.pdf; GBF1341D - SAS.pdf; GBF1341D - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 07.03.2018
Our Reference: YM 387U/SE/pl
Your Reference: GBF 1341D

To: FASTECH AUTO PTE LTD

Sent via Fax ☐
or
Email ☐ nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBF 1341D
Insured's Vehicle: YM 387U
Date Of Accident: 06.03.2018

We acknowledge receipt of your request for PRS on: 06.03.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

☒	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us todate.
☒	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:	<u>[Signature]</u>		<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 7400E

Vehicle Details

Vehicle No.: GBF1341D

Vehicle to be Exported: No

Intended De-registration
Date: 06 Mar 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO
5 DR MANUAL

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1KD2624955

Chassis No.: JTFHT02P500199316

Maximum Power Output: -

Open Market Value: \$27,741.00

Original Registration Date: 27 Jun 2016

First Registration Date: 27 Jun 2016

Transfer Count: 0

Actual ARF Paid: \$1,388.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Jun 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$39,529.00

COE Rebate Amount: \$32,831.00

Total Rebate Amount: \$32,831.00

The information contained herein is correct as at 06 Mar 2018

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20176

Date : 06.03.2018

Vehicle Num : GBF 1341D

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 06.03.2018

Claim No : 0318-20176

Reference :

Policy No :

Not Allowed
date
2/5 @ 5500
5 day.
6/3/18

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc	Rear boot	2149.20	30/Bent	\$	2,265.00	✓
1 pc	Rear boot rubber		twl	\$	328.50	✓
1 pc	Rear boot lock		twl/Jm	\$	265.10	✓
2 pc	Rear boot hinga @ 85.20		11	\$	170.40	X
2 pc	Rear boot absorber @ 285.00		11	\$	570.00	X
1 pc	Rear boot centre garnish		11	\$	176.50	X
1 pc	Rear boot inner board		11	\$	315.20	X
1 pc	Rear boot glass		11	\$	1,243.60	X
1 pc	Rear boot lock actuator		11	\$	410.60	X
1 pc	Rear boot mirror with braket		11	\$	356.50	X
1 pc	Rear boot wiper motor		11	\$	498.50	X
1 pc	Rear boot wiper arm		11	\$	145.40	X
1 pc	Rear boot wiper blade		11	\$	89.50	X
1 pc	Rear boot emblem logo		nu	\$	65.20	✓
1 pc	Rear boot sticker toyota		nu	\$	38.50	✓
1 pc	Rear boot sticker hiace		nu	\$	38.50	✓
1 pc	Rear end panel inner		sedg, D	\$	850.00	✓
1 pc	Rear end panel outer		2y, D	\$	486.50	✓
1 pc	Rear third brake light		11	\$	410.40	X
1 pc	Rear floor board panel		n	\$	2,381.40	X
1 pc	Rear bumper	465.10	DD	\$	498.00	✓
2 pc	Rear bumper side retainer @ 60.80		3ul	\$	121.60	✓
4 pc	Rear bumper lower support bracket @ 56.20		3ul	\$	224.80	✓
2 pc	Rear number plate lamp @ 65.60		11	\$	131.20	X
2 pc	Rear taillamp @ 352.30		1ne	\$	704.60	✓
2 pc	Rear taillamp garnish @ 109.50		n	\$	219.00	X
1 pc	Rear exhaust silencer		11	\$	825.00	X
2 pc	Rear exhaust rubber @ 58.70		11	\$	117.40	X
1 pc	Rear spare tyre carrier	345.20	twl	\$	412.10	✓
1 pc	Rear boot rubber top garnish		11	\$	82.70	X
List Item Total :				\$	14,441.70	
Discount 25 %				\$	3,610.43	
				\$	10,831.28	

60828
48621

FASTECH AUTO PTE LTD

page 2/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20176

Date : 06.03.2018

Vehicle Num : GBF 1341D

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 06.03.2018

Claim No : 0318-20176

Reference :

Policy No :

Qty	Particular	Amount S\$
		B/F \$ 10,831.28
<u>Special Nett Item :</u>		
1 pc	Rear Cruden floor board panel	\$ 550.00 ✓
1 set	Rear bumper clip	\$ 50.00 ✓
1 set	Rear windscreen glass sealant	\$ 120.00 40
1 pc	Rear 70 KM/h sticker	\$ 25.00 10
1 set	Reversing sensor	\$ 350.00 200
Special Nett Total :		\$ 1,095.00
<u>Labour Charge :</u>		
	To check wiring	\$ 100.00 30
	Apply anti rust <i>proofing</i>	\$ 150.00 60
	Remove & refix rear windscreen glass	\$ 150.00 120
	Remove, refix & renew rear exhaust pipe	\$ 150.00 X
	Remove & refix rear floor mat etc	\$ 120.00 X
	Remove & renew reversing sensor	\$ 150.00 50
	Labour charge knock dents on rear damage portion cut, welding & renew parts	\$ 1,800.00 980
	To spray paint affected portion	\$ 1,600.00 800
Labour Charge Total :		\$ 4,220.00

69021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O. E.
Acknowledged by Repairer
Signature:
Date:

Total Amount : \$ 16,146.28

FASTECH AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18004282/Utbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 28-03-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 387U	Veh. Inspected	GBF 1341D	
Policy No.		Coverage (\$)	0.00	
Claim No.	YM387U/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	07/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFHT02P500199316	Colour	WHITE	
Odometer	68472	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	KAPSEN	6 mm	
L/H Front Tyre	195 R15	KAPSEN	6 mm	
R/H Rear Tyre	195 R15	KAPSEN	6 mm	
L/H Rear Tyre	195 R15	KAPSEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/03/2018	Inspection Date	06/03/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 1341D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	DENTED / BENT	2,265.00	2,149.20
1	REAR BOOT RUBBER	TWISTED	328.50	328.50
1	REAR BOOT LOCK	TWISTED / JAMMED	265.10	265.10
2	REAR BOOT HINGA @\$85.20	NOT NECESSARY	170.40	-
2	REAR BOOT ABSORBER @\$285.00	NOT NECESSARY	570.00	-
1	REAR BOOT CENTRE GARNISH	NOT NECESSARY	176.50	-
1	REAR BOOT INNER BOARD	NOT NECESSARY	315.20	-
1	REAR BOOT GLASS	NOT NECESSARY	1,243.60	-
1	REAR BOOT LOCK ACTUATOR	NOT NECESSARY	410.60	-
1	REAR BOOT MIRROR WITH BRACKET	NOT NECESSARY	356.50	-
1	REAR BOOT WIPER MOTOR	NOT NECESSARY	498.50	-
1	REAR BOOT WIPER ARM	NOT NECESSARY	145.40	-
1	REAR BOOT WIPER BLADE	NOT NECESSARY	89.50	-
1	REAR BOOT EMBLEM LOGO	NECESSARY	65.20	65.20
1	REAR BOOT STICKER TOYOTA	NECESSARY	38.50	38.50
1	REAR BOOT STICKER HIACE	NECESSARY	38.50	38.50
1	REAR END PANEL INNER	BADLY DENTED	850.00	850.00
1	REAR END PANEL OUTER	BADLY DENTED	486.50	486.50
1	REAR THIRD BRAKE LIGHT	NOT NECESSARY	410.40	-
1	REAR FLOOR BOARD PANEL	TO REPAIR SEE LABOUR	2,381.40	-
1	REAR BUMPER	DENTED	498.00	465.10
2	REAR BUMPER SIDE RETAINER @\$60.80	BENT	121.60	121.60
4	REAR BUMPER LOWER SUPPORT BRACKET @\$56.20	BENT	224.80	224.80
2	REAR NUMBER PLATE LAMP @\$65.60	NOT NECESSARY	131.20	-
2	REAR TAILLAMP @\$352.30	CRACKED	704.60	704.60
2	REAR TAILLAMP GARNISH @\$109.50	TO REPAIR SEE LABOUR	219.00	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	825.00	-
2	REAR EXHAUST RUBBER @\$58.70	NOT NECESSARY	117.40	-
1	REAR SPARE TYRE CARRIER	TWISTED	412.10	412.10

Report Ref No. CS/EGI18004282/Utbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT RUBBER TOP GARNISH	NOT NECESSARY	82.70	-
	LESS 25% DISCOUNT		-3,610.42	-1,537.43
			10,831.28	4,612.27
	SPECIAL NETT ITEMS			
1	REAR CRUDEN FLOOR BOARD PANEL (SN)	NOT NECESSARY	550.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	SET REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR 70KM/H STICKER (SN)	NECESSARY	25.00	10.00
1	SET REVERSING SENSOR (SN)	SHORTED	350.00	200.00
			1,095.00	300.00
	LABOUR			
	TO CHECK WIRING.		100.00	30.00
	APPLY ANTI RUST PROOFING.		150.00	60.00
	REMOVE & REFIX REAR WINDSCREEN GLASS.		150.00	120.00
	REMOVE,REFIX & RENEW REAR EXHAUST PIPE.	NOT NECESSARY	150.00	-
	REMOVE & REFIX REAR FLOOR MAT ETC.	NOT NECESSARY	120.00	-
	REMOVE & RENEW REVERSING SENSOR.		150.00	50.00
	LABOUR CHARGE KNOCK DENTS ON REAR DAMAGE PORTION CUT,WELDING & RENEW PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR BOARD PANEL AND REAR TAILLAMP GARNISH.		1,800.00	980.00
	TO SPRAY PAINT AFFECTED PORTION.		1,600.00	800.00
			4,220.00	2,040.00
	GRAND TOTAL		16,146.28	6,952.27
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00

Report Ref No. CS/EGI18004282/Utnb2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.