



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2017 MITSUBISHI LANCER 1.6 (SLP5169M)

Date of Loss

5 February 2018

Time of Loss

20.05

Loss Description

SLP5169M (INSD) C/W SKS7507D (TP)

Comment

Workshop Details

Total Rebate Amount

57689

Nett Loss Amount

\$15,311.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

26/06/2018



Days of work completion *

112



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SLP5169M

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

08/06/2017



Mileage

23566

Age of Vehicle

0

Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2017

ASSESSMENT INFO...

2017

CATEGORY

Driver Name

FNOL INFORMATI...

TAN YI XIAO

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MITSUBISHI

ASSESSMENT INFO... MITSUBISHI

CATEGORY Model

POLICY INFORMAT... LANCER 1.6

ASSESSMENT INFO... LANCER EX 1.6 AT LED TAIL LAMP

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JMYSRCY1AGU006836

CATEGORY Date of Birth

FNOL INFORMATI... 12 January 1986

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 32

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JMYSRCY1AGU006836

CATEGORY Engine No

POLICY INFORMAT... 4A92CP4909

ASSESSMENT INFO... 4A92CP4909

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1590

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 73000

FNOL INFORMATI... 10

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF... ▼

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Address

FNOL INFORMATI... BLK 89OB TAMPINES AVE 1, #16-317,
522890, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Female

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Single

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S8638498A

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

08/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/60R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

205/60R16

Front left side

YOKOHAMA8mm

Front right side

YOKOHAMA8mm

Rear left side

YOKOHAMA8mm

Rear right side

YOKOHAMA8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts															
Add Approve Deny															
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			Rear door LH			Repair	0	0	0	0	0	Deny
☐		2	1			Rear door weatherstrip LH			Serviceable	0	0	0	0	0	Deny
☐		3	1			Rear door window glass outer moulding LH			Serviceable	0	0	0	0	0	Deny
☐		4	1			Rear door lock assy LH			Serviceable	0	0	0	0	0	Deny
☐		5	1			Rear door hinge upper LH			Serviceable	0	0	0	0	0	Deny
☐		6	1			Rear door hinge lower LH			Serviceable	0	0	0	0	0	Deny
☐		7	1			Rear fender LH			Repair	0	0	0	0	0	Deny
☐		8	1			Rear fender shield LH			Serviceable	0	0	0	0	0	Deny
☐		9	1			Rear windscreen moulding set			Serviceable	0	0	0	0	0	Deny
☐		10	1			Rear bumper			Repair	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		11	12			Rear bumper clips			Serviceable	0	0	0	0	0	Deny
		12	1			Rear bumper side retainer LH			Serviceable	0	0	0	0	0	Deny
		13	1			Rear bumper side retainer RH			Serviceable	0	0	0	0	0	Deny
		14	1			Rear wheel rim LH			Serviceable	0	0	0	0	0	Deny
		15	1			Rear axle assembly			Serviceable	0	0	0	0	0	Deny
		16	1			Rear wheel bearing LH			Serviceable	0	0	0	0	0	Deny
		17	1			Rear absorber LH			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts	300	0	0	Reviewing		
		2		Provide skill labour & material to putty all damaged parts & panel to respray with 2K paint with oven spray booth facilities	450	0	0	Reviewing		
		3		Provide skill labour to disconnect and check electrical wiring	30	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	4		Provide skill labour to remove and re-install cushion, seats, backrest, inner trim, garnish, roof lining and / or upholstery to facilitate repairs	0	0	0	Deny		
 	5		Provide skill labour to check and re-adjust wheel alignment	0	0	0	Deny		
 	6		Provide skill labour to remove and replace rear windscreen	0	0	0	Deny		
 	7		Provide skill labour to remove and replace / refit whole rear with axle	0	0	0	Deny		
 	8		Provide skill labour to dismantle and transfer door fittings and mechanism to new door / facilitate repair	0	0	0	Deny		
 	9		Provide skill labour to remove and replace bumper sensor	0	0	0	Deny		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	Windscreen sealant	Deny	0	
☐		2	DAYS OF REPAIR : 3 DAYS	Reviewing		
☐		3	(REPAIR COST NOT CONCLUDE)	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$280.00

Claim Amount \$280.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$780.00	\$780.00
Excess	-\$500.00	-\$500.00

Submit for Review