



Your Ref : S8M00A1A

Date: 20th March 2018

Our Ref : CS/ASM18004324/Ktd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Yvonne Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKZ 1451H
ACCIDENT ON 03/03/2018**

Instruction was received to inspect the vehicle Reg. No. SKZ 1451H. The inspection was conducted on 07/03/2018 at the premises of M/s Ah Lim Motor Company, No 10 Ang Mo Kio Industrial Park 2A #01-09 AMK Autopoint Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SKZ 1451H
Make/Model	: B.M.W 525I XL (A)
Year of Registration	: 2009
Body Colour	: Metallic Black
Chassis Number	: WBANU52060C228472
Engine Capacity	: 2497 cc
Speedometer Reading	: 160558 km

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 41,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 30,856.00)
Nett Liability	<u>S\$ 10,144.00</u>

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.