

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHD 4115K

DATE 5/3/2018 13:45

Jumani

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Repair			\$ 578.40
	Rear Bumper Protector (RH) X			\$ 38.00
	Rear Fender (RH) X Repair			\$ 1,935.90
	Rear Fender Inner Lining (RH) X			\$ 74.10
	Rear Windscreen Moulding X			\$ 60.00
	Rear Door (RH)			\$ 1,294.70
	Rear Door Protector(RH) X Repair			\$ 54.50
	Rocker Panel Outer Garnish (RH) X Repair			\$ 463.40
	Rear Wheel Hup-Cap (RH)			\$ 145.00
	SUB TOTAL			\$ 4,644.00
	LESS 20%			\$ 928.80
	DISCOUNTED TOTAL			\$ 3,715.20
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Windscreen Sealant X			\$ 46.00
	Rear Door Advertisement Logo (RH)			\$ 100.00
				\$ 196.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door			\$ 120.00
	Rear Wheel Alignment			\$ 120.00
	TOWING			\$ 50.00
	TOTAL LABOUR			\$ 2,530.00
	ESTIMATE TOTAL			\$ 6,441.20
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: _____ Signature: _____ Date: _____			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company			

K9621 (100K)

6/3/18 1030h

3 hrs

45

After Repair photo

400

720

X

20

50

X

X

50

X

X

6,491.2