

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 12549 Yr Regn: 25/2/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet Epica C.C. 1991Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 577091 T/Radio: Insured / Std / NI / NAEng/No: 539091C/No: KL114 69KJBB 136359

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 18 205/55R15R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 4/5/18 D.O.I. 5/3/18Survey held at SMARTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

12/4/18 : Confirm LLS \$4050.00 with 5 working days

TAX/03/18/2015

LKE

Chino Topping

G13.88415

(Red) \$4546.98

53.1)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Copies☐ : Weekend (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18004344/Sws3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 06-03-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 8814G	Veh. Inspected	SHB 1254Y	
Policy No.	DMCVSN3011951800	Coverage (\$)	0.00	
Claim No.	SNM18D01254C02	Excess (\$)	0.00	
Assign From		Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/03/2018	Inspection Date	05/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI18004344/Sws3

Date: 06/03/2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 1254Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.03.2018 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

Workshop Estimate Amount	: S\$	8,596.98
Revised Estimate Amount	: S\$	2,448.60
"Check" Items Amount	: S\$	4,805.51
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Remarks :

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1254Y
Vehicle to be Exported:	No
Intended De-registration Date:	06 Mar 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS/AB 2WD 4DR TURBO
Primary Colour:	Maroon
Manufacturing Year:	2012
Engine No.:	Z20S1463184K
Chassis No.:	KL1LA69RJBB136359
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,189.00
Original Registration Date:	25 Feb 2013
First Registration Date:	25 Feb 2013
Transfer Count:	0
Actual ARF Paid:	\$14,189.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2021

PARF Rebate Amount:	\$9,932.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$66,403.00
COE Rebate Amount:	\$24,654.00
Total Rebate Amount:	\$34,586.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Mar 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1254Y
 Ref. No : TAX/03/18/2015
 Reg. Date : 25/02/2013
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : MOHD NOR BIN TALEB
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 02/03/2018 07:43:00 PM
 Accident Reported Date / Time : 03/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094863
 Special Instruction to ARC, if any :
 DROVE IN /GBB8814G
 Prepared Date : 03/03/2018 12:04:03 PM



Sebastian
 5/3/18
 - Lump Sum Repair
 - Question Mark Item Photo
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB136359

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 5,726.98	5,843.86
Other Charges	: 740.00	0.00
TOTAL	: 8,596.98	0.00
Lum Sum Total	: 8,600.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	3 days.
Arc / Surveyor Sign Off Date	: 05/03/2018 12:56:33 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/03/2018 12:56:07 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 500
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR BOOT LID	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00 ?	0.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00 ?	0.00
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 x
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 <
Total Other Costs	740.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ✓	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ✓	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace ✓	No
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace ✓	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ✓	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace ✓	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace ✓	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace ✓	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace ✓	No
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace ✓	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓	No
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ✓	No
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace ✓	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace ✓	No
96647117	COMMO N		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Replace ✓	No
TOTAL MATERIALS								7,100.21	7,100.21	
TOTAL MATERIALS(Discounted)								5,726.98	5,843.86	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



Tow

5-3.18/12.43

+2 DAYS

5-3.18/16.43

clo.

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

5-3.18/16.43

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1254Y
 Ref. No : TAX/03/18/2015
 Reg. Date : 25/02/2013
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : MOHD NOR BIN TALEB
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 02/03/2018 07:43:00 PM
 Accident Reported Date / Time : 03/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094863
 Special Instruction to ARC, if any :
 DROVE IN / GBB8814G China 4s
 AFTER PAINT PHOTO, LUMP SUM REPAIR, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP:90036121
 Prepared Date : 03/03/2018 12:04:03 PM



QC 9/3/18 16.03 P935

Vehicle to Waga Date In: 6/3/18 Towing: Peng
 Time In: 1630 Driver:
 Waga Job No: 03 0175
 Vehicle sent to SMRT Date In: 9/3/18 Towing:
 Time In: 1425 Driver: N
 Received by (SMRT):

Recording Camera ☒ CSC ☐

Radio Antenna ☒ X ☐

1st witness 9 Date 5-3.18

2nd witness Date

E 120 F
539091

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB136359

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	850.00
Total Spray Painting Charges	: 1,296.00	650.00
Total Material Charges	: 4,579.29	2,286.48
Other Charges	: 740.00	270.00
TOTAL	: 7,629.29	4,056.48
Lum Sum Total	: 7,650.00	4,050.00
No. of Repair Days	: 6.00	5.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 05/03/2018 12:56:33 PM	05/03/2018 02:40:19 PM

[Signature]

[Signature: LKK]

Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/03/2018 12:56:07 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0196

Invoice No :

Quotation Date : 10/3

Invoice Date :

Invoice Amount :

Prepared Date :

2858.10 /
 - 202
 2286.48 /
 + 850.00 /
 + 920.00 /

 4056.48 /
 US \$4050/-

Sebastian
 13/3/18

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	850.00 /
Total Labour	1,014.00	850.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY REAR BOOT LID	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00 /
TO RESPRAY TAIL LAMP PANEL LH	180.00	50.00 /
Total Spray Painting & Panel Beating	1,296.00	650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	140.00 / nec CSN
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	740.00	270.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No ✓
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace S	No ✓
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace S	No ✓
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace S	No ✓
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Check	No X
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace S	No ✓
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Check	No X
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Check	No X
96636630	REAR	6504631	REAR BOOT LID	1	974.00	100.00	0.00	Replace	Repair	No ✓
96636677	REAR	6504634	REAR BOOT LOCK	0	77.00	10.00	0.00	Replace	Not given	No X
96636426	REAR	6504633	REAR BOOT STRIKER	0	15.00	10.00	0.00	Replace	Not given	No X
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace	No ✓
96976171	REAR	6504635	REAR BOOT REFLECTOR	0	165.00	10.00	0.00	Replace	Not given	No X
96636502	REAR		REAR BOOT HINGE	0	92.00	10.00	0.00	Replace	Not given	No X
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No ✓
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No ✓
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No ✓
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Check	No X
96637759	REAR	6504579	TRIM REAR END PANEL	0	114.00	10.00	0.00	Replace	Not given	No X
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Check	No X
96647117	COMMO N		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Check	No X
TOTAL MATERIALS							5,724.11	2,858.10		
TOTAL MATERIALS(Discounted)							4,579.29	2,286.48		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

10819.74.

Shirley Hiew (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 9 March 2018 1:46 PM
To: Shirley Hiew (LKK Auto); Vivian Lau (LKKAuto)
Cc: Claims Dept of CTI
Subject: RE: Direct Settlement - Accident Involving GBB8814G (OI : CTI - SNM18D01254C02) AND SHB1254Y (TP : LKK REF - CC3/CTI18004344/Sws3) on 02/03/2018
Attachments: INSD REPORT.PDF

Dear both,

Pls find Insured report as requested.

Look forward to your further update.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Lucas Lee
Sent: Friday, 9 March, 2018 1:21 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: Direct Settlement - Accident Involving GBB8814G (OI : CTI - SNM18D01254) AND SHB1254Y (TP : LKK REF - CC3/CTI18004344/Sws3) on 02/03/2018

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.

Shirley Hiew (LKK Auto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 9 March 2018 1:21 PM
To: Shirley Hiew (LKK Auto)
Cc: Chong Boon Sen
Subject: RE: Direct Settlement - Accident Involving GBB8814G (OI : CTI - SNM18D01254) AND SHB1254Y (TP : LKK REF - CC3/CTI18004344/Sws3) on 02/03/2018
Attachments: leeSZ_SNM18D01254C02-GBB8814G-LKKDirectSettlementAccidentLtr_CLCR95.406.pdf; MSAT18032604-GBB8814G.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 7 March, 2018 8:58 AM
To: Claims Dept of CTI; Vivian Lau (LKKAuto)
Cc: Chong Boon Sen; CS A Team; Admin A
Subject: Direct Settlement - Accident Involving GBB8814G (OI : CTI - TBA) AND SHB1254Y (TP : LKK REF - CC3/CTI18004344/Sws3) on 02/03/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 1254Y at M/s SMRT Automotive Services Pte Ltd - Woodlands.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18004344/Swa3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 01-10-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 8814G	Veh. Inspected	SHB 1254Y	
Policy No.	DMCVSN3011951800	Coverage (\$)	0.00	
Claim No.	SNM18D01254C02/4	Excess (\$)	0.00	
Assign From		Assign Date	05/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KL1LA69RJBB136359	Colour	MAROON	
Odometer	539091	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R15	FALKEN	6 mm	
L/H Front Tyre	205/55 R15	FALKEN	6 mm	
R/H Rear Tyre	205/55 R15	FALKEN	6 mm	
L/H Rear Tyre	205/55 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/03/2018	Inspection Date	05/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1254Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER RR (DISC 10%)	DENTED	1,238.00	1,114.20
1	ABSORBER ENGY RR BUMPER (DISC 10%)	CRACKED	70.00	63.00
1	BEAM RR BUMPER IMPACT (DISC 10%)	BENT	1,221.00	1,098.90
1	REFLECTOR REFLEX RR LH (DISC 10%)	CRACKED	264.00	237.60
1	REAR BOOT WEATHERSTRIP (DISC 10%)	DEFORMED	49.00	44.10
1	LETTERING "CHEVROLET" (DISC 10%)	NECESSARY	29.00	26.10
1	LETTERING "EPICA LT" (DISC 10%)	NECESSARY	28.00	25.20
1	EMBLEM REAR (DISC 10%)	NECESSARY	44.00	39.60
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	SHIELD REAR BUMPER (SN)	NECESSARY	140.00	140.00
1	REFLECTOR REFLEX RR RH	NOT NECESSARY	264.00	-
1	BRACKET RR BUMPER SIDE LH	NOT NECESSARY	49.00	-
1	BRACKET RR BUMPER SIDE RH	NOT NECESSARY	49.00	-
1	REAR BOOT LOCK	NOT NECESSARY	77.00	-
1	REAR BOOT STRIKER	NOT NECESSARY	15.00	-
1	REAR BOOT REFLECTOR	NOT NECESSARY	165.00	-
1	REAR BOOT HINGE	NOT NECESSARY	92.00	-
1	PANEL END REAR	NOT NECESSARY	255.00	-
1	TRIM REAR END PANEL	NOT NECESSARY	114.00	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	PANEL SPARE TYRE	NOT NECESSARY	2,299.00	-
1	W/HARNESS RR BPR	NOT NECESSARY	227.34	-
1	REAR BOOT LID	TO REPAIR SEE LABOUR	974.00	-
			7,909.74	2,998.10
LABOUR				
PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF REAR BOOT LID.			1,014.00	850.00
SPRAY PAINT.			1,296.00	650.00

Report Ref No. CC3/CTI18004344/Swa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	50.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,910.00	1,630.00
GRAND TOTAL			10,819.74	4,628.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00

Report Ref No. CC3/CTI18004344/Swa3n2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.