

22/03/2002

ASS. REC. BY:

REF:

CS3 / MSC718004375 / Wbet

Special Instruction:

make & model

Surveyor: Wilson

Marmen

From (Person):

Chhia Nyuk Pui

ASSIGNMENT (Office)

of

MSU

Estimated Cost:

Date/Time: 07032018 835am

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PJB 7547

at Workshop m/s

C & L Automotiv

Insured:

XE 2655L

of

Blk 1 Kaki Bukit Ave 6 # 02-49

Tel:

9232 7457

Policy No:

A28909851MCC

Claim No:

549843

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10-02-2018

CA / REV / REP. / REV 24 HRS wpi

Date/Time: 07032018 10am

Person Contacted:

Ah Xuan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (x) Estimate
	PJB 7547 - x
	XE 2655L - x
	Disassemble Part: 09032018
	After repair: 16-03-2018

30/01/18 W-10m

MSU

PRS

ASSIGNMENT

From _____ Date _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No PIB 7547

at Workshop No Cand L

1. Make Subst Acc. # 0249

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Ver _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value _____

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs. days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No PIB 7547 Regn 2009 Feb 10

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Yamaha 135 LC cc 135

Colour Red Insured / Std / NI / NA

Sp Reading 25417 T Read: Insured / Std / NI / NA

Eng No _____

CNo PMXUG 024990029111

Gen Cond Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 70/90-17

R: 90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal 2 mm R/Bal 2 mm

L/Bal _____ mm L/Bal _____ mm

D.O.A. _____ DO: 7/3/2008

Survey held at: Ac Alara

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Range \$2800 - \$3500

3 Days Repair

4/4/2018

RECEIVED 20/03/2018

Date Time File Passed:

06042018

Date Time File Returned:

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. \$

☐ Inter. Ev. \$

☐ Tech. Insp. \$

☐ Web-end \$

Survey Fee

Transportation

Sub-Fee \$

Sub-Fee

Sub-Fee

Sub-Fee

Sub-Fee

120

50

10

180

Report Format:

PRS

Lump Sum / I.B.I. \$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018		07 Mar 2018 08:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	HCG ENVIRONMENT PTE LTD, Co. Reg. No.: 201218872G	[Created by insurer]
Main Claimant:	CHANTHIRAN PALAGIVEER, ID: G2574134Q	
Vehicle Reg. No.:	PJB7547	
Claim Type:	TP / 549843	Date of Loss: 10/02/2018 07:00 - :59
Vehicle Reg. No. (Insured):	XE2655L	Policy/Cover Note No.: A28909851MKC (Comprehensive) Coverage: 03/03/2017 - 02/03/2018
		Policy No. (Claimant):
		Excess: S\$1,500.00
Repairer:	C & L Automotive Llp (HQ) 1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 92327457	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhla Nyuk Pui - 6594 2521]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/03/2018]	
Driver/Custodian (Insured):	RAMESH S/O SONAN (51 / Male), NRIC: S1760487B, Tel: +6590293065	
Adj Asg. Remarks:	Please contact AH XIAN @ 9232 7457 to arrange for survey	

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete Done?
No results.									

07/03/2018 @ 11am

Ah xian veh in

#02-49 Autobay

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN

No. Siri A 7206196



NO. PENDAFTARAN PJB7547

Nama Pemunya
Bendaftar

SITI FAIRUZ BINTI ABDUL HAKIM

880625025428
[MAL]

Alamat

F24 KAMPUNG GUAR LOBAK
09400 PADANG SERAI KEDAH D.A.

No. Enjin

G367EE029111

B.D.M/B.G.K

No. Casis

PMYKG024090029111

B.T.T.

Buatan

YAMAHA

Berat Kerb

Nama Model

YAMAHA 135LC ES

B.T.M.

Keupayaan Enjin

135 S.P

B.G.1

Bahan Bakar

PETROL

B.G.2

Warna

HITAM

B.G.3

Kelas Kegunaan

MOTOSIKAL

B.G.4

Jenis Badan

MOTOSIKAL

B.G.5

Tahun Dibuat

2009

B.G.6

Tarikh Pendaftaran

10/02/2009

B.G.7

Status Pemunya

PERSENDIRIAN

B.G.8

Muatan Tempet

B.G.9

Duduk

2

B.G.10

Kadar Lesen

B.G.11

Kenderaan Motor

6 bulan

12 bulan

B.G.12

RM2.00

RM2.00

Perakuan Pendaftaran ini dikeluarkan

Tandatangan Pemunya Bendaftar

oleh Pengarah JPJ Negeri JPJ PULAU PINANG 1

UNTUK KEGUNAAN PEJABAT

PENASANGAN TERPATAN

HAKMILIK DITUNTUT OLEH : LEAN HUAT MOTOR SDN BHD

NO SIRI SURAT : A006094

NOTA PENTING

Perakuan ini di tempat yang selamat. Jika perakuan ini hilang,
ia dikehendaki diserahkan kepada pihak polis dengan segera dan

5. Jika anda menjual kenderaan, serahkan perakuan penda
pembeli. Anda dan pembeli dikehendaki mengisi dan

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		07 Mar 2018 08:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HCG ENVIRONMENT PTE LTD , Co. Reg. No.: 201218872G								
Main Claimant:	CHANTHIRAN PALAGIVEER , ID: G2574134Q								
Vehicle Reg. No.:	PJB7547	Date of Loss:	10/02/2018 07:00 - :59 [108 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 549843	Policy/Cover Note No.:	A28909851MKC (Comprehensive) Coverage: 03/03/2017 - 02/03/2018						
Vehicle Reg. No. (Insured):	XE2655L	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	C & L Automotive Llp (HQ) 1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 92327457								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 08/03/2018]								
Driver/Custodian (Insured):	RAMESH S/O SONAN (51 / Male), NRIC: S1760487B, Tel: +6590293065								
Adj Asg. Remarks:	Please contact AH XIAN @ 9232 7457 to arrange for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PJB7547 (549843)
[XE2655L]
TP
CHANTHIRAN PALAGIVEER
Feb 10 2018 7:00AM
[HCG ENVIRONMENT PTE LTD]
C & L Automotive Llp

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/03/18 16:50	Accident Statement From: SC - Reg. No: XE2655L, Claimant: HCG ENVIRONMENT PTE LTD		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/04/18 11:20	General View		Load JPG	☒
2	06/04/18 11:20	General View		Load JPG	☒
3	06/04/18 11:20	General View		Load JPG	☒
4	06/04/18 11:20	General View		Load JPG	☒
5	06/04/18 11:20	General View		Load JPG	☒
6	06/04/18 11:20	General View		Load JPG	☒
7	06/04/18 11:20	General View		Load JPG	☒
8	06/04/18 11:20	General View		Load JPG	☒
9	06/04/18 11:20	General View		Load JPG	☒
10	06/04/18 11:20	General View		Load JPG	☒
11	06/04/18 11:20	General View		Load JPG	☒
12	06/04/18 11:20	General View		Load JPG	☒
13	06/04/18 11:20	General View		Load JPG	☒
14	06/04/18 11:20	General View		Load JPG	☒
15	06/04/18 11:20	General View		Load JPG	☒
16	06/04/18 11:20	General View		Load JPG	☒
17	06/04/18 11:20	General View		Load JPG	☒
18	06/04/18 11:20	General View		Load JPG	☒
19	06/04/18 11:20	General View		Load JPG	☒
20	06/04/18 11:20	General View		Load JPG	☒
21	06/04/18 11:20	General View		Load JPG	☒
22	06/04/18 11:20	General View		Load JPG	☒
23	06/04/18 11:20	General View		Load JPG	☒
24	06/04/18 11:20	General View		Load JPG	☒
25	06/04/18 11:20	General View		Load JPG	☒
26	06/04/18 11:20	General View		Load JPG	☒
27	06/04/18 11:20	General View		Load JPG	☒
28	06/04/18 11:20	General View		Load JPG	☒
29	06/04/18 16:33	Photographs of Damaged Parts		Load JPG	☒
30	06/04/18 16:33	Photographs of Damaged Parts		Load JPG	☒
31	06/04/18 16:33	Photographs of Damaged Parts		Load JPG	☒
32	06/04/18 16:33	Photographs of Damaged Parts		Load JPG	☒
33	06/04/18 16:33	Photographs of Damaged Parts		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
35	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
36	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
37	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
38	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
39	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
40	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
41	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
42	06/04/18 16:33	Photographs of Damaged Parts	 Load JPG	☒
43	06/04/18 16:34	Photo After Spray	 Load JPG	☒
44	06/04/18 16:34	Photo After Spray	 Load JPG	☒
45	06/04/18 16:34	Photo After Spray	 Load JPG	☒
46	06/04/18 16:34	Photo After Spray	 Load JPG	☒
47	06/04/18 16:34	Photo After Spray	 Load JPG	☒
48	06/04/18 16:34	Photo After Spray	 Load JPG	☒
49	06/04/18 16:34	Photo After Spray	 Load JPG	☒
50	06/04/18 16:34	Photo After Spray	 Load JPG	☒
51	06/04/18 16:34	Photo After Spray	 Load JPG	☒
52	06/04/18 16:34	Photo After Spray	 Load JPG	☒
53	06/04/18 16:34	Photo After Spray	 Load JPG	☒
54	06/04/18 16:34	Photo After Spray	 Load JPG	☒
55	06/04/18 16:34	Photo After Spray	 Load JPG	☒
56	06/04/18 16:34	Photo After Spray	 Load JPG	☒
57	06/04/18 16:34	Photo After Spray	 Load JPG	☒
58	06/04/18 16:34	Photo After Spray	 Load JPG	☒
59	06/04/18 16:34	Photo After Spray	 Load JPG	☒
60	06/04/18 16:34	Photo After Spray	 Load JPG	☒
61	06/04/18 16:34	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/18 16:49	Email to TP Lawyer KANNAN SG with 10 survey name - PJB7547	 Load PDF	
2	06/03/18 16:50	Pre-Repair Survey	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004375/WBE2

Date: 11/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28909851MKC

Claimant Vehicle
No : PJB7547

Insured Vehicle No : XE2655L

Date of Loss: 10/02/2018

Nature of Claim: TP

Claim No: 549843

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PJB7547

Make & Model: YAMAHA 135LC, 135cc ES

Engine No: G367EE029111

Reg. Date: 10/02/2009 (Man. Year: 2009)

Chassis No: PMYKG024090029111

Colour: Red

Odometer: 25417 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size: 90/80-17

Front Left Side: VOLANS 2 mm

Rear Left Side: Timsun 2 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/03/2018

Date Inspected: 07/03/2018 Inspected At:

Blk 1 Kaki Bukit Ave 6 #02-49

Repairer : C & L Automotive Llp (HQ)

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 -\$3,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Apr 2018)

Parts: N/A YAMAHA 135LC 135cc ES (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PJB7547)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >