

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3735P

DATE 6/3/2018 14:24

MAKE :

Chiang

AVC

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,480.00
	Radiator Grille H Emblem ✕			\$ 290.80
	Radiator Grille Chrome Moulding ✕			\$ 395.50
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 619.00
	SUB TOTAL			\$ 5,940.80
	LESS 20%			\$ 1,188.16
	DISCOUNTED TOTAL			\$ 4,752.64
	Labour Charge			
	Panel Beating			\$ 560.00 ³⁰⁰
	Spray Painting Charge			\$ 400.00 ³⁶⁰
	Wiring Charge			\$ 50.00 ²⁰
	TOTAL LABOUR			\$ 1,010.00
	ESTIMATE TOTAL			\$ 5,762.64

Ka Lin 16/6/18
✓ 6/3/18 15 to 4 hrs
2 hrs
PP
Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.