



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

136 2017 BMW 530I SE AUTO BMWXXX (SDJ62X)

Date of Loss

26 February 2018

Time of Loss

19.30

Loss Description

SDJ62X (INSD) C/W SHC5081Y

Comment

Workshop Details

Total Rebate Amount

91144

Nett Loss Amount

\$116,856.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

24/04/2018

**Days of work completion ***

48



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SDJ62X

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

29/12/2017



Mileage

2505

Age of Vehicle

0

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2017

ASSESSMENT INFO...

2017

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LAM HANG NGO CATHERINE

CATEGORY Make

POLICY INFORMAT... BMW 530I SE AUTO

ASSESSMENT INFO... B.M.W.

CATEGORY Model

POLICY INFORMAT... BMWXXX

ASSESSMENT INFO... 530I SE AUTO

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WBAJA52080WC07339

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 4 March 1964

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Age

FNOL INFORMATI... 54

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 16799985B48B20B

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 2

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2016

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... 63 MOUNT SINAI DRIVE 19-05, 277116,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... G6184637P

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/03/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

800

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

245/45R18

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

245/45R18

Front left side

GOODYEAR8mm

Front right side

GOODYEAR8mm

Rear left side

GOODYEAR8mm

Rear right side

GOODYEAR8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

 Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		1	1			FRONT BUMPER FASCIA			Damaged	1390.35		5		1320.83	Revie
		2	1			SET FRONT BUMPER CLIPS			Necessary	50		5		47.5	Revie
		3	1			FRONT BUMPER SIDE RETAINER LH			Cracked	35.55		5		33.77	Revie
		4	1			FRONT BUMPER SIDE RETAINER RH			Serviceable	0	0	0	0	0	Deny
		5	1			FRONT BUMPER PARKING SENSOR (2PCS)			Damaged	248.7		5		236.27	Revie
		6	1			FRONT BUMPER REINFORCEMENT BEAM			Serviceable	0	0	0	0	0	Deny
		7	1			FRONT BUMPER SPONGE			Serviceable	0	0	0	0	0	Deny
		8	1			FRONT BUMPER LOWER GRILLE LH			Damaged	94.55		5		89.82	Revie
		9	1			FRONT BUMPER LOWER GRILLE (CENTRE)			Serviceable	0	0	0	0	0	Deny
		10	1			FRONT BUMPER LOWER GRILLE CHROME			Cut	40.85		5		38.81	Revie

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
<input type="checkbox"/>		11			FRONT BUMPER LOWER REINFORCEMENT BEAM			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		12			FRONT GRILLE			Damaged	232.5		5		220.88	Revie
<input type="checkbox"/>		13			FRONT GRILLE BASE			Cracked	368.35		5		349.93	Revie
<input type="checkbox"/>		14			BONNET			Bent	2369.2		5		2250.74	Revie
<input type="checkbox"/>		15			HEADLAMP LH			Damaged	4071.25		5		3867.69	Revie
<input type="checkbox"/>		16			HEADLAMP BALLAST LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		17			HEADLAMP PANEL LH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		18			HEADLAMP BRACKET LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		19			FRONT FENDER LH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		20			FRONT FENDER COWLING LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		21			FRONT FENDER COWLING CLIPS			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		22			LED DAYTIME DRIVING LIGHT MODULE (ADDITIONAL)			Damaged	260.55		5		247.52	Revie

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	I
------	-------	-------------------------	-----------	------------	---------------	-------	-----------------	---------	---

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	
 	1		CUT OUT, RENEW, KNOCKING & WELDING FRONT BONNET, FRONT BUMPER FASCIA, HEADLAMP LH, REINFORCEMENT BEAM, FRONT FENDER LH, BULKHEAD SUPPORT PANEL, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY	1000	0	0	Reviewing		
 	2		REMOVE & INSTALL FRONT BUMPER SENSOR	50	0	0	Reviewing		
 	3		SPRAY PAINTING ON DAMAGE PARTS	1000	0	0	Reviewing		
 	4		TUFF-KOTE ON DAMAGE PARTS	0	0	0	Deny		
 	5		DIAGNOSTIC & RESET, PROGRAMING OF HEADLAMP CONTROL UNIT	200	0	0	Reviewing		
 	6		REMOVE & INSTALL AIR CON SYSTEM, VACUUM & TOP UP GAS	0	0	0	Deny		
 	7		CHECK ALL LIGHTING AFTER REPAIRS	30	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$10,183.76

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,280.00	\$2,280.00
Spare Parts	\$8,703.76	\$8,703.76
Excess	-\$800.00	-\$800.00

Submit for Review