

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		06 Mar 2018 14:39 Edit Adj Rpt	S\$22,630.17 Edit Estimates	S\$22,630.17 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K	
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G	
Vehicle Reg. No.:	SLK2566X	Date of Loss: 02/03/2018 19:00 - :59 [13 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0471938	Policy/Cover Note No.: P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB7583H	Policy No. (Claimant): A29069766MKF
		Excess: S\$5,000.00
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:	
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Kitty Teo - 6880 4602]	
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/03/2018]	
Driver/Custodian (Insured):	TAN THYE SIONG (63 / Male) , NRIC: S0101237A, Tel: +6590073407 Email:	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AXA_SG (17/04/2020): Alert - Adj Mandate Approved (S\$25660.83) - SLK2566X - Claim Handler: Kitty Teo AXA_SG (27/09/2019): Alert - Adj Mandate Maintained - SLK2566X - Claim Handler: Kitty Teo AXA_SG (25/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SLK2566X - Claim Handler: SASHE Go Mui S... AXA_SG (06/06/2019): Re: C0471938 AXA_SG (29/11/2018): C0471938 AXA_SG (22/03/2018): Re: C0471938/P1680520 AXA_SG (06/03/2018): C0471938/P1680520 AXA_SG (06/03/2018): New TP Assignment - C0471938/P1680520 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLK2566X (C0471938)**
[SHB7583H]
TP
GRAB RENTALS PTE LTD
Mar 2 2018 7:00PM
[TRANS-CAB SERVICES PTE LTD]
Esteem Performance Pte Ltd - Sin Ming

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/18 14:17	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/18 17:14	LKK INSPECTION PHOTOS	Load PDF	
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/03/18 08:54	EMAIL_ABS	Load PDF	
2	06/03/18 08:54	ESTIMATE & SLK2566X TP GIA_ABS	Load PDF	
3	06/03/18 08:54	SHB7583H INS GIA_ABS	Load PDF	
4	06/03/18 08:54	SLJ3600D GIA_ABS	Load PDF	
5	06/03/18 08:54	SLV8552M GIA_ABS	Load PDF	
6	06/03/18 14:28	EMAIL_ABS	Load PDF	
7	06/03/18 14:37	E-filed GIA report - TP SLK2566X	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/18 15:27	TP ESTIMATE- MARKED	Load PDF	
2	21/03/18 17:12	EMAIL TO OI	Load PDF	
3	10/07/19 14:28	LKK SURVEY PHOTO	Load PDF	
4	10/07/19 14:28	LKK RESURVEY PHOTO 1	Load PDF	
5	10/07/19 14:28	LKK RESURVEY PHOTO 2	Load PDF	
6	10/07/19 14:28	LKK RESURVEY PHOTO 3	Load PDF	
7	10/07/19 14:38	TP Estimate- revise + Supplementary	Load PDF	
8	10/07/19 14:39	Rental Agreement and rental rate	Load PDF	
9	10/07/19 14:39	LTA search fee	Load PDF	
10	10/07/19 14:39	Immediate Advice (with mandate) dated 10.07.2019	Load PDF	
11	30/09/19 10:00	PARF_COE REBATE	Load PDF	
12	06/05/20 16:43	Authorisation to Act	Load PDF	
13	06/05/20 16:43	PAYMENT BREAKDOWN - EXPRESS SETTLEMENT FORM	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18004416/KPS3S2
Date: 06/05/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520
Claimant Vehicle No : SLK2566X **Insured Vehicle No :** SHB7583H
Date of Loss: 02/03/2018 Nature of Claim: TP Claim No: C0471938

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK2566X**
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR975969
Reg. Date: 11/01/2017 (Man. Year: 2016) Chassis No: JTDKB3FU903539892
Colour: Metallic Silver Odometer: 0 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 9 mm Rear Left Side: Nexen 6 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,455.61	18,300.17	11,155.44	37.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,790.00	4,330.00	1,460.00	25.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,245.61	22,630.17	12,615.44	35.79
+ GST 7.00/7.00% (S\$)	2,467.19	1,584.11	883.08	35.79
Nett Amount (S\$)	37,712.80	24,214.28	13,498.52	35.79
+ Car Rental (18.0 x S\$79.95/day) (S\$)		1,439.10		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		25,660.83		
Global Sum Settlement (S\$)		25,600.00		

INSPECTION

Date of Assignment: 06/03/2018
Date Inspected: 07/03/2018 Inspected At: Esteem Performance Pte Ltd - Sin Ming (HQ)
385 Sin Ming Drive
Singapore 575718
Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$22,630.18

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 06 May 2020)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLK2566X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE GARNISH (CONSISTENT)	Cracked	45.00 FL	*45.00 FL
2	1		*BONNET (CONSISTENT)	Buckled	812.40 FL	*812.40 FL
3	1		*BONNET LOCK (CONSISTENT)	Bent	130.00 FL	*130.00 FL
4	1		*BONNET HINGE LH (CONSISTENT)	Distorted	57.80 FL	*57.80 FL
5	1		*BONNET HINGE RH (CONSISTENT)	Distorted	57.80 FL	*57.80 FL
6	1		*BONNET HEAT INSULATOR (CONSISTENT)	Serviceable	440.12 FL	*- FL
7	10		*BONNET HEAT INSULATOR CLIP (CONSISTENT)	Necessary	35.00 FL	*35.00 FL
8	1		*FRONT SUPPORT PANEL CENTRE (CONSISTENT)	Bent	338.50 FL	*338.50 FL
9	1		*FRONT SUPPORT PANEL LH (CONSISTENT)	Bent	213.50 FL	*213.50 FL
10	1		*FRONT SUPPORT PANEL RH (CONSISTENT)	Bent	213.50 FL	*213.50 FL
11	1		*HEADLAMP PANEL LH (CONSISTENT)	Bent	89.20 FL	*89.20 FL
12	1		*HEADLAMP PANEL RH (CONSISTENT)	Bent	89.20 FL	*89.20 FL
13	1		*SUPPORT PANEL LOWER (CONSISTENT)	Bent	387.95 FL	*387.95 FL
14	1		*FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	Cracked	285.40 FL	*285.40 FL
15	10		*FRONT SUPPORT PANEL TOP GARNISH CLIP (CONSISTENT)	Necessary	35.00 FL	*35.00 FL
16	1		*AIR DUCT (CONSISTENT)	Cracked	195.40 FL	*195.40 FL
17	1		*AIR DUCT - INLET (CONSISTENT)	Dented	109.75 FL	*109.75 FL
18	1		*BRACE PANEL (CONSISTENT)	Bent	105.20 FL	*75.20 FL
19	1		*CONDENSER (CONSISTENT)	Bent	1,544.70 FL	*1,336.60 FL
20	1		*RADIATOR (CONSISTENT)	Bent	1,841.80 FL	*1,841.80 FL
21	1		*RADIATOR FAN MOTOR RH (CONSISTENT)	Serviceable	455.70 FL	*- FL
22	1		*RADIATOR FAN MOTOR LH (CONSISTENT)	Serviceable	491.79 FL	*- FL
23	1		*RADIATOR FAN BLADE LH (CONSISTENT)	Serviceable	197.80 FL	*- FL
24	1		*RADIATOR FAN BLADE RH (CONSISTENT)	Distorted	219.80 FL	*219.80 FL
25	1		*RADIATOR FAN COWLING (CONSISTENT)	Cracked	287.67 FL	*287.67 FL
26	1		*RADIATOR TOP HOSE (CONSISTENT)	Punctured	49.80 FL	*49.80 FL
27	1		*RADIATOR BOTTOM HOSE (CONSISTENT)	Serviceable	46.95 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*RADIATOR SPARE TANK (CONSISTENT)	Dented	186.70 FL	*186.70 FL
29	1		*RADIATOR TOP GARNISH (CONSISTENT)	Cracked	54.24 FL	*54.24 FL
30	1		*INTAKE MANIFOLD (CONSISTENT)	Dented / Cut	892.74 FL	*892.74 FL
31	1		*HEADLAMP LH (CONSISTENT)	Mtg Cracked	2,531.60 FL	*2,531.60 FL
32	1		*HEADLAMP RH (CONSISTENT)	Cracked	2,531.60 FL	*2,531.60 FL
33	1		*FRONT BUMPER (CONSISTENT)	Bent / Cracked	450.80 FL	*450.80 FL
34	10		*FRONT BUMPER CLIP (CONSISTENT)	Necessary	40.00 FL	*40.00 FL
35	1		*FRONT BUMPER REINFORCEMENT - UPPER (CONSISTENT)	Bent	711.50 FL	*696.40 FL
36	1		*FRONT BUMPER REINFORCEMENT - LOWER (CONSISTENT)	Repair	245.30 FL	*- FL
37	1		*FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	Distorted	107.20 FL	*107.20 FL
38	1		*FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	Distorted	107.20 FL	*107.20 FL
39	1		*FRONT BUMPER UPPER GRILLE (CONSISTENT)	Cracked	321.90 FL	*301.90 FL
40	1		*FRONT BUMPER LOWER GRILLE (CONSISTENT)	Cracked	148.60 FL	*148.60 FL
41	1		*FRONT BUMPER EMBLEM (CONSISTENT)	Necessary	87.10 FL	*87.10 FL
42	1		*FRONT BUMPER TOW COVER RH (CONSISTENT)	Dented	25.70 FL	*25.70 FL
43	1		*FRONT BUMPER TOW COVER LH (CONSISTENT)	Serviceable	25.70 FL	*- FL
44	1		*FRONT BUMPER SPONGE - UPPER (CONSISTENT)	Cracked	89.81 FL	*89.81 FL
45	1		*FRONT BUMPER SPONGE - LOWER (CONSISTENT)	Serviceable	135.70 FL	*- FL
46	1		*FOG LAMP LH (CONSISTENT)	Serviceable	910.70 FL	*- FL
47	1		*FOG LAMP RH (CONSISTENT)	Serviceable	910.70 FL	*- FL
48	1		*ENGINE UNDER COVER (CONSISTENT)	Serviceable	198.30 FL	*- FL
49	10		*ENGINE UNDER COVER CLIP (CONSISTENT)	Not Necessary	35.00 FL	*- FL
50	1		*WASHER TANK (CONSISTENT)	Serviceable	195.60 FL	*- FL
51	1		*WASHER TANK MOTOR (CONSISTENT)	Serviceable	196.74 FL	*- FL
52	1		*RH FRONT FENDER (CONSISTENT)	Buckled	868.70 FL	*868.70 FL
53	1		*RH FRONT FENDER UNDERSHIELD (CONSISTENT)	Serviceable	185.64 FL	*- FL
54	10		*RH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	Not Necessary	25.00 FL	*- FL
55	1		*RHF FENDER WORDING HYBRID (CONSISTENT)	Necessary	44.17 FL	*44.17 FL
56	1		*LH FRONT FENDER (CONSISTENT)	Repair	868.70 FL	*- FL
57	1		*LH FRONT FENDER UNDERSHIELD (CONSISTENT)	Serviceable	195.60 FL	*- FL
58	10		*LH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	Not Necessary	25.00 FL	*- FL
59	1		*LHF FENDER WORDING HYBRID (CONSISTENT)	Not Necessary	44.17 FL	*- FL
60	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Necessary	97.70 FL	*97.70 FL
61	1		*REAR BUMPER (CONSISTENT)	Bent	497.50 FL	*497.50 FL
62	10		*REAR BUMPER CLIP (CONSISTENT)	Necessary	40.00 FL	*40.00 FL
63	1		*REAR BUMPER SIDE RETAINER LH (CONSISTENT)	Distorted	112.70 FL	*112.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*REAR BUMPER SIDE RETAINER RH (CONSISTENT)	Serviceable	112.70 FL	*- FL
65	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	398.90 FL	*398.90 FL
66	1		*REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT)	Bent	582.60 FL	*582.60 FL
67	1		*REAR BUMPER LOWER GARNISH LH (CONSISTENT)	Missing	149.70 FL	*149.70 FL
68	1		*REAR BUMPER LOWER GARNISH RH (CONSISTENT)	Cracked	149.70 FL	*149.70 FL
69	1		*REAR BUMPER TOW COVER (CONSISTENT)	Missing	31.70 FL	*31.70 FL
70	1		*REAR BUMPER UNDER COVER (CONSISTENT)	Missing	355.20 FL	*355.20 FL
71	1		*REAR BUMPER UNDER COVER LH (CONSISTENT)	Serviceable	187.60 FL	*- FL
72	1		*REAR BUMPER UNDER COVER RH (CONSISTENT)	Serviceable	187.60 FL	*- FL
73	4		*REAR BUMPER UNDER COVER CLIP (CONSISTENT)	Not Necessary	14.00 FL	*- FL
74	1		*TAIL DOOR (CONSISTENT)	Buckled	1,122.50 FL	*1,122.50 FL
75	1		*TAIL DOOR LOCK (CONSISTENT)	Repair	487.70 FL	*- FL
76	1		*TAIL DOOR EMBLEM (CONSISTENT)	Necessary	61.70 FL	*61.70 FL
77	1		*WORDING PRIUS (CONSISTENT)	Necessary	51.90 FL	*51.90 FL
78	1		*WORDING HYBRID (CONSISTENT)	Necessary	55.47 FL	*55.47 FL
79	1		*TAIL DOOR HINGE LH (CONSISTENT)	Repair	87.60 FL	*- FL
80	1		*TAIL DOOR HINGE RH (CONSISTENT)	Repair	87.60 FL	*- FL
81	1		*TAIL DOOR PLATE GARNISH (CONSISTENT)	Repair	782.50 FL	*- FL
82	1		*TAIL DOOR INNER TRIM (CONSISTENT)	Serviceable	278.90 FL	*- FL
83	10		*TAIL DOOR INNER TRIM CLIP (CONSISTENT)	Not Necessary	28.00 FL	*- FL
84	1		*TAILDOOR SPOILER (CONSISTENT)	Serviceable	1,567.83 FL	*- FL
85	1		*TAIL END PANEL (CONSISTENT)	Bent	596.60 FL	*596.60 FL
86	1		*TAIL END PANEL GARNISH (CONSISTENT)	Distorted	151.60 FL	*151.60 FL
87	10		*TAIL END PANEL GARNISH CLIP (CONSISTENT)	Necessary	35.00 FL	*35.00 FL
88	1		*BOOT WEATHERSTRIP (CONSISTENT)	Distorted / Dented	353.10 FL	*353.10 FL
89	1		*SPARE TYRE WELL PANEL (CONSISTENT)	Repair	793.15 FL	*- FL
90	1		*SPARE TYRE BOARD (CONSISTENT)	Serviceable	566.79 FL	*- FL
91	1		*TAIL LAMP LH - UPPER (CONSISTENT)	Serviceable	498.75 FL	*- FL
92	1		*TAIL LAMP RH - UPPER (CONSISTENT)	Serviceable	498.75 FL	*- FL
93	1		*TAIL LAMP LH - LOWER (CONSISTENT)	Serviceable	511.60 FL	*- FL
94	1		*TAIL LAMP RH - LOWER (CONSISTENT)	Serviceable	511.60 FL	*- FL
95	1		*TAIL DOOR SPOILER (CONSISTENT)	Serviceable	1,567.83 FL	*- FL
96	1		*REAR WINDSCREEN SEALANT (CONSISTENT)	Necessary	40.00 FS	*40.00 FS
97	1		*TAILDOOR GLASS SEALANT (CONSISTENT)	Necessary	40.00 FS	*40.00 FS
98	1		*FRONT NUMBER PLATE (CONSISTENT)	Dented	45.00 FS	*45.00 FS
99	1		*REAR NUMBER PLATE (CONSISTENT)	Dented	45.00 FS	*45.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
100	1		*REVERSE SENSOR (CONSISTENT)	Torn	200.00 FS	*200.00 FS
101	1		*HEADLAMP BALLAST RH (CONSISTENT)	Cracked	725.60 FL	*725.60 FL
102	1		*WASHER TANK NECK (CONSISTENT)	Dented	72.80 FL	*72.80 FL
103	1		*FRONT BUMPER TOP RUBBER (CONSISTENT)	Torn	42.70 FL	*42.70 FL
104	1		*AIRCON PIPE (CONDENSER TO COOLING COIL) (CONSISTENT)	Dented	597.80 FL	*597.80 FL
105	1		*WATER PUMP (CONSISTENT)	Torn	678.40 FL	*678.40 FL
106	1		*AIR CLEANER AIR DUCT (CONSISTENT)	Dented	178.40 FL	*178.40 FL
107	1		*VACUUM SENSOR (CONSISTENT)	Cracked	297.40 FL	*297.40 FL
108	1		*AIR RESONATOR (CONSISTENT)	Cracked	45.70 FL	*45.70 FL
109	1		*AIR RESONATOR HOSE (CONSISTENT)	Dented	81.40 FL	*81.40 FL
110	1		*SPARE TANK WATER HOSE ADAPTER (CONSISTENT)	Dented	17.20 FL	*17.20 FL
111	1		*INTAKE MANIFOLD HOSE (CONSISTENT)	Punctured	121.70 FL	*121.70 FL
112	1		*RADIATOR AIR GUIDE RH (CONSISTENT)	Cracked	78.70 FL	*78.70 FL
113	1		*BONNET CABLE (CONSISTENT)	Torn	54.80 FL	*54.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	39,150.81	24,276.90
- List Item Discount on L Items 25.00/25.00% (S\$)	9,695.20	5,976.73
Total Parts (S\$)	29,455.61	18,300.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RH UPPER PILLAR).	New	2,400.00	1,600.00
2	TO PUTTY RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RH UPPER PILLAR).	New	2,200.00	2,000.00
3	TO CHECK WIRING & FOCUS HEADLAMP.	New	50.00	40.00
4	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS.	New	150.00	100.00
5	TO REMOVE & REFIT REAR WINDSCREEN.	New	120.00	120.00
6	TO TUFF COAT.	New	300.00	150.00
7	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	New	150.00	100.00
8	TO TRANSFER BOOT MECHANISM TO NEW BOOT.	New	120.00	60.00
9	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	New	120.00	30.00
10	TO REMOVE & REFIT TAILDOOR GLASS TO ASSIST WORK LOAD.	New	120.00	80.00
11	TOWING.	New	60.00	50.00
			Gross Labour Cost (\$\$)	5,790.00
				4,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >