



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5150E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COOLER DOOR ASSEMBLY (CONSISTENT)	DEFORMED	2,872.05	2,872.05
	LESS 10% DISCOUNT		-287.21	-287.20
			2,584.84	2,584.85
1	FLYSCREEN ASSEMBLY (CONSISTENT)	DEFORMED	900.80	900.80
	LESS 10% DISCOUNT		-	-90.08
			900.80	810.72
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS .		1,325.00	1,090.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		432.00	300.00
			1,757.00	1,390.00
GRAND TOTAL			5,242.64	4,785.57
RECOMMENDED COST OF REPAIRS				4,785.57

Report Ref No. CC4/ASM18004442/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.