



SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5150E
 Ref. No : BUS/02/18/7047
 Reg. Date : 01/03/2018
 Vehicle Type : DOUBLE DECK
 Make : VOLVO
 Model : Volvo B9TL DD
 Name of Driver : Liu Rui Gang
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 14/02/2018 06:40:00 PM
 Accident Reported Date / Time : 27/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AXA
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SG5150E - REAR RIGHT CRACKED
 YP6653X (TP) - INSURED WITH AXA
 Prepared Date : 01/03/2018 09:38:07 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.

7/3/18.

- Part by part repair.

- Place Before Paint.

90036121

Sebastianyeang@lkkauto.com.

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,325.00	0.00
Total Spray Painting Charges	: 432.00	0.00
Total Material Charges	: 4,386.44	4,386.44
Other Charges	: 0.00	0.00
TOTAL	: 6,143.44	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 06/03/2018 11:10:31 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :
Remarks :

Prepared Date : 06/03/2018 11:10:31 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	0.00 1090
Total Labour	1,325.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	432.00	0.00 300
Total Spray Painting & Panel Beating	432.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
A12-03438			COOLER DOOR ASSEMBLY	1	2,872.05	10.00	2,584.84	Replace	Replace	No <i>✓ Deform</i>
A12-03302			FLYSCREEN ASSEMBLY	1	900.80	0.00	900.80	Replace	Replace	No <i>✓ Deform</i>

TOTAL MATERIALS

3,485.65 3,485.64

TOTAL MATERIALS(Discounted)

4,386.44 4,386.44

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									