

ASS. REC. BY:

REF: CS/CT118004467/M/rd3n2 Special Instruction:

Surveyor:  
Menmen

MA

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT1

Date/Time:

7/3/18 3:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 3614T

Insured:

SGJ 9566P

at Workshop m/s

Chunni Motor

Tel:

65425119

of

10 AMK Ind park 2A # 03-19

Policy No:

DMPCSN7042621710

Claim No:

SNM18D01178C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/3/18

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

9:29am 8/3/18

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHD 3614T-x

SGJ 9566P-x

Confirmed

L/s

8/5K

@ 12 days

Red: \$ 10,719.38, 42%.

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD364T.

Yr Regn:

SEP 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS.

c.c 1798

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

NO READING

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU703536407

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Watake

Front

8

Rear

8

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

05/03/2018

D.O.I.

8/3/2018

Survey held at

Des. of Damages (Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 05 JUN 2018

Date/Time, File Pass to?



Preli. Report

1) typist



Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / L+ (\$) 15K

Days Of Repair: 12

Resurvey No. of Trip: -

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		07 Mar 2018 15:17 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ANG BIN KEONG, LAWRENCE, ID: S1401021A		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD3614T	Date of Loss:	05/03/2018 07:00 - :59
Claim Type:	TP / SNM18D01178C02	Policy/Cover Note No.:	DMPCSN7042621710 (Comprehensive)
Vehicle Reg. No. (Insured):	SGJ9566P	Policy No. (Claimant):	MCOM0015
		Excess:	S\$0.00
Repairer:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/03/2018]		
Driver/Custodian (Insured):	ANG BIN KEONG, LAWRENCE (57 / Male), NRIC: S1401021A		
Adj Asg. Remarks:	EST - \$25,719.38, ASSIGN KENNETH KONG AS SJE		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004467/M1rd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 08-03-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 9566P	Veh. Inspected	SHD 3614T
Policy No.	DMPCSN7042621710	Coverage (\$)	0.00
Claim No.	SNM18D01178C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	08/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	05/03/2018	Inspection Date	08/03/2018
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

MCD618030768 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 05/03/2018 14:51  
 SUBMITTED BY: Catherine Per May Juan

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/03/2018 14:51
Date Of Accident	05/03/2018 07:20
Exact Location Of Accident	BUKIT PANJANG RING RD TWDS PETIR RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3614T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	BENJAMIN EUGENE CHUA CHIN CHEONG
NRIC No	S7815004A
Date Of Birth	29/05/1978
Occupation	OUTDOOR
Date Of Driving Pass	12/12/1998
Driving Experience	19 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 437 04-364 FAJAR ROAD  
 Postcode 670437  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : -  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 POLICE STATION NAME [OTHER] TAMPINES NPC  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

SEE POLICE REPORT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SGJ9566P  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver ANG BIN KEONG LAWRENCE  
 NRIC/Passport Number S1401021A  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SLN7472J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAN KHAY SOON

NRIC/Passport Number

S1647211E

Contact Number

90661118

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

BENJAMIN EUGENE CHUA CHIN CHEONG

Approximate Age

40

Injuries Sustain

NECK,BACK

Injured person in which vehicle?

SHD3614T

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

Address

Postcode



**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R


Policyholder's Signature  
Date & Time:

Driver's Signature   
(If driver is not the policyholder)  
Date & Time: 05/03/2018 @ 14:00hrs

ALICE

Reporting Centre Personnel's Signature  
Name: Alice Tee  
NRIC/FIN No.: -



**SKETCH PLAN**

A-SHD 3614T

B-SGJ 9566P (Private Car)

C-SLN 7472J (Private Car)

Along B.Panjang Ring Rd Twds Petir Rd In Frt Of Greenridge Sec School

**Describe Circumstances of the Accident**

Refer to Police Report no: T/20180305/2045

After the accident, I felt pain on my back and neck. I was given 5 days MC.

A - SHD 3614T

B - SGJ 9566P, Mr. Ang Bin Keong Lawrence, NRIC : S 1401021A.

C - SLN 7472J, Mr. Tan Khay Soon, NRIC : S 1647211E, H/P : 9066 1118.

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821Rpolicyholder's Signature  
Date & TimeDriver's Signature (If driver is not the policyholder)  
Date & Time 05/03/2018 @ 14:00hrs

ALICE

Reporting Centre Personnel's Signature  
Name: Alice Tee  
NRIC/FIN No: -



**SINGAPORE  
POLICE FORCE**



T/20180305/2045

1 of 4

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20180305/2045

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/03/2018 12:27	Vide Report No.:	Station Diary No.: 59
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: BENJAMIN EUGENE CHUA CHIN CHEONG			Address: APT BLK 437 FAJAR ROAD #04-364 SINGAPORE 670437	
ID Type / ID No.: NRIC NO / S7815004A			Contact No.: Home/Office: Mobile: 88184908	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 39	Date of Birth: 29/05/1978	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/03/2018 07:20	Type of Location: Straight Road
Location: Along Road 1 BUKIT PANJANG RING ROAD				
Along Bukit Panjang Ring Road in front of Greenridge secondary along the bus stop towards petir road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGJ9566P	Car					0
SHD3614T	Car				Seriously Damaged	1
SLN7472J	Car					0



**SINGAPORE  
POLICE FORCE**



T/20180305/2045

2 of 4

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

Report No. T/20180305/2045

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	ANG BIN KEONG LAWRENCE	ID No.	S1401021A
Related Vehicle	SGJ9566P (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	BENJAMIN EUGENE CHUA CHIN CHEONG	ID No.	S7815004A
Related Vehicle	SHD3614T (Car)	Contact No.	88184908
Hospital/Clinic	A LIFE CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/03/2018	Date Discharge	05/03/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL
<b>Driver</b>			
Name	Tan Khay Soon	ID No.	S1647211E
Related Vehicle	SLN7472J (Car)	Contact No.	90661118
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 05/03/2018 at about 0720hrs, I was driving my Taxi, SHD3614T along Bukit Panjang Ring Road towards Petir road in front of Greenridge secondary school. I stopped my Taxi behind SLN7472J and waited for the traffic light to turn green at the junction. After I stopped my vehicle for about 1-2 seconds, I felt an impact from the rear. And my vehicle moved forward and hit SLN7472J. I went out and made a check, SGJ9566P had hit the rear of my Taxi.

We all exchanged particulars and left the place. No police attended to us.

The back of my neck and back was in pain at the point of accident.



**SINGAPORE  
POLICE FORCE**



T/20180305/2045

3 of 4

Report No, T/20180305/2045

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

**CONTINUATION OF REPORT**

I had advised my passenger if there's any claim she wants to make can contact my company straight as she informed she was rushing to the airport.

My Taxi's rear bumper is dislodged and the boot cannot be closed.

I was given 5 days MC.

No ambulance attended to us. I have a in car camera in my Taxi point to the front.

**SINGAPORE  
POLICE FORCE**

T/20180305/2045

4 of 4

Report No. T/20180305/2045

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 ANABELLE TEY SOO LIN

Sgt Ann Xue Ni

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI DZUL HAIRIE BIN RAMLI

Contact No.: 65476220

SINGAPORE  
POLICE  
AUTHENTICATED  
NP168

Signature Of Informant:

Date/Time:

05/03/2018 12:27

Classification Of Case:

to survey by LKK

ChinaTaiping

DATE : 5.03.2018

**TEL NO : 6542 5119**

**FAX NO : 6542 6039**

Page 1 of 4



SHD 3614T

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
<b>LABOUR CHARGE</b>			
Panel Beating		400	\$ 1,000.00
Spray Painting Charge			\$ 200.00
Wiring Charge			\$ 50.00
Towing Charge			\$ 50.00
Remove/Refix Aircon & Refill Gas			\$ 150.00
<b>TOTAL LABOUR</b>			<b>\$ 1,450.00</b>
REAR TRUNK LID COVER		62	\$ 922.50
REAR TRUNK LID LOCK		2	\$ 447.70
REAR TRUNK LID COVER TRIM BOARD		cur	\$ 216.50
REAR TRUNK LID RUBBER		2	\$ 357.00
REAR TRUNK LID GLASS (BLACK COLOR)		2	\$ 721.30
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$ 889.70
REAR TRUNK LID LOGO (PRIUS)		1	\$ 60.80
REAR TRUNK LID LOGO (HYBRID)		1	\$ 52.40
REAR TRUNK LID LOGO (TOYOTA STAR)		1	\$ 52.90
REAR BUMPER		del	\$ 458.60
REAR BUMPER RE-INFORCEMENT			\$ 318.80
REAR BUMPER UNDER COVER		del	\$ 552.60
REAR BUMPER SIDE RETAINER		2	\$ 112.70
REAR BUMPER SPONGE			\$ 143.40
REAR BUMPER UNDER SIDE COVER (RH)		1	\$ 167.60
REAR BUMPER UNDER SIDE CENTRE COVER		Rep	\$ 552.60
REAR BUMPER CLIPS		12	\$ 22.00
ARM SUB-ASSY, REAR BUMPER, RH			\$ 139.60
ARM SUB-ASSY, REAR BUMPER, LH			\$ 139.60
RETAINER, REAR BUMPER, SIDE, RH		2	\$ 94.80
SEAL, REAR BUMPER SIDE, RH			\$ 148.40
TAIL LAMP ASSY (UPPER) (LH/RH)	NS ave	557.90	\$ 1,115.80
TAIL LAMP ASSY (LOWER) (LH/RH)	ave	548.40	\$ 1,096.80
REAR END PANEL	62		\$ 602.10
REAR END PANEL GARNISH	2		\$ 121.60
REAR SPARE TYRE CHUSHION (FLR BOARD CENTRE)	2		\$ 101.40
REAR EXHAUST PIPE			\$ 1,163.40
REAR EXHAUST PIPE HANGER			\$ 40.70
REAR EXHAUST PIPE INSULATOR			\$ 314.60
REAR WINDSCREEN GLASS			\$ 1,555.80
REAR WINDSCREEN GLASS MOULDING			\$ 208.60
<b>SUB TOTAL</b>			<b>\$ 12,892.30</b>
<b>LESS 20%</b>			<b>\$ 2,578.46</b>
<b>DISCOUNTED TOTAL</b>			<b>\$ 10,313.84</b>



SHD 3614T

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR TRUNK LID APPS STICKER	111		\$ 40.00	NETT
REAR TRUNK LID COMFORT & TEL NO. STICKER	112		\$ 60.00	NETT
REAR BUMPER REVERSE SENSOR	8111		\$ 135.70	NETT
REAR BUMPER RUBBER MAT	112		\$ 50.00	NETT
REAR WINDSCREEN SEALANT	112		\$ 46.00	NETT
			\$ 331.70	
<b>LABOUR CHARGE</b>				
Panel Beating			\$ 1,200.00	800
Spray Painting Charge			\$ 600.00	
Wiring Charge			\$ 50.00	30
Tuff Kote			\$ 50.00	—
Remove/Refix Rear Windscreen Glass			\$ 120.00	100
Remove/Refix Reverse Sensor			\$ 120.00	60
Remove/Refix Exhaust Pipe			\$ 150.00	80
<b>TOTAL LABOUR</b>			\$ 2,290.00	
<b>ESTIMATE TOTAL</b>			\$ 25,719.38	

40 570

10,190.00

2 days

15000

12 days  
con

No Duller

TP Repair

Before put A 100%

100% Auto

8 days

20/3/18

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118004467/M1RD3N2

Date: 06/06/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN7042621710
Claimant Vehicle No :	SHD3614T	Insured Vehicle No :	SGJ9566P
Date of Loss:	05/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01178C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD3614T	Engine No:	2ZRR923660
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU703530401
Reg. Date:	14/09/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	21,979.38	13,402.70	8,576.68	39.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	2,400.00	1,340.00	35.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>25,719.38</b>	<b>15,802.70</b>	<b>9,916.68</b>	<b>38.56</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>15,000.00</b>		
<b>(\$\$)</b>	<b>25,719.38</b>	<b>15,000.00</b>	<b>10,719.38</b>	<b>41.68</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,800.36</b>	<b>1,050.00</b>	<b>750.36</b>	<b>41.68</b>
<b>Nett Amount (\$\$)</b>	<b>27,519.74</b>	<b>16,050.00</b>	<b>11,469.74</b>	<b>41.68</b>

## INSPECTION

Date of Assignment:	07/03/2018	
Date Inspected:	08/03/2018	Inspected At:
		Chunni Motor Pte Ltd (HQ)
		10 Ang Mo Kio Industrial Park 2A, #03-
		19 AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	12.0 days	

Adjuster: MA CHIN FOOK

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2018)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD3614T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Distorted	438.00 FL	*438.00 FL
2	1		*RADIATOR GRILLE EMBLEM	Distorted	86.50 FL	*86.50 FL
3	1		*FRONT BUMPER COVER	Deformed	490.50 FL	*490.50 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	691.50 FL	*691.50 FL
5	2		*FRONT BUMPER REINFORCEMENT ABSORBER	Torn	231.40 FL	*231.40 FL
6	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
7	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	301.90 FL	*- FL
8	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
9	1		*FRONT BUMPER TOP GARNISH	Serviceable	225.40 FL	*- FL
10	1		*BRACKET,FRONT BUMPER SIDE,RH	Serviceable	77.00 FL	*- FL
11	1		*BRACKET,FRONT BUMPER SIDE,LH	Serviceable	77.00 FL	*- FL
12	1		*UNIT ASSY,HEADLAMP RH (LED)	Cracked	3,380.30 FL	*3,380.30 FL
13	1		*UNIT ASSY,HEADLAMP LH (LED)	Cracked	3,380.30 FL	*3,380.30 FL
14	1		*HEAD LAMP PANEL (RH)	Repair	213.50 FL	*- FL
15	1		*HEAD LAMP PANEL (LH)	Repair	213.50 FL	*- FL
16	1		*TOP PANEL CENTRE	Serviceable	364.90 FL	*- FL
17	1		*TOP PANEL SIDE,LH	Serviceable	69.20 FL	*- FL
18	1		*TOP PANEL SIDE,RH	Serviceable	69.20 FL	*- FL
19	1		*BRACE PANEL	Serviceable	75.20 FL	*- FL
20	1		*BRACKET,HEADLAMP MOUNTING,RH	Serviceable	25.50 FL	*- FL
21	1		*BRACKET,HEADLAMP MOUNTING,LH	Serviceable	25.50 FL	*- FL
22	1		*RADIATOR ASSY	Serviceable	1,841.80 FL	*- FL
23	1		*STAY,RADIATOR SUPPORT,RH	Serviceable	65.70 FL	*- FL
24	1		*STAY,RADIATOR SUPPORT,LH	Serviceable	65.70 FL	*- FL
25	1		*DEFLECTOR,RADIATOR SIDE,RH	Serviceable	83.50 FL	*- FL
26	1		*DEFLECTOR,RADIATOR SIDE,LH	Serviceable	77.00 FL	*- FL
27	1		*CONDENSER ASSY,W/RECEIVER	Serviceable	1,304.00 FL	*- FL
28	1		*REAR TRUNK LID COVER	Bent	922.50 FL	*922.50 FL
29	1		*REAR TRUNK LID LOCK	Jammed	447.70 FL	*447.70 FL
30	1		*REAR TRUNK LID COVER TRIM BOARD	Serviceable	216.50 FL	*- FL
31	1		*REAR TRUNK LID RUBBER	Distorted	357.00 FL	*357.00 FL
32	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Serviceable	721.30 FL	*- FL
33	1		*GARNISH SUB-ASSY BACK DOOR,OUTSIDE	Distorted	889.70 FL	*889.70 FL
34	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	60.80 FL	*60.80 FL
35	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.40 FL	*52.40 FL
36	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	52.90 FL	*52.90 FL
37	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
38	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
39	1		*REAR BUMPER UNDER COVER	Deformed	552.60 FL	*552.60 FL
40	1		*REAR BUMPER SIDE RETAINER	Distorted	112.70 FL	*112.70 FL
41	1		*REAR BUMPER SPONGE	Torn	143.40 FL	*143.40 FL
42	1		*REAR BUMPER UNDER SIDE COVER (RH)	Serviceable	167.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR BUMPER UNDER SIDE CENTRE COVER	Repeated	552.60 FL	*- FL
44	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
45	1		*ARM SUB-ASSY,REAR BUMPER RH	Not Necessary	139.60 FL	*- FL
46	1		*ARM SUB-ASSY,REAR BUMPER LH	Not Necessary	139.60 FL	*- FL
47	1		*RETAINER REAR BUMPER SIDE RH	Distorted	94.80 FL	*94.80 FL
48	1		*SEAL,REAR BUMPER SIDE RH	Serviceable	148.40 FL	*- FL
49	1		*TAIL LAMP ASSY (UPPER)(LH/RH)	O/s Cracked/N/s Serviceable	1,115.80 FL	*557.90 FL
50	2		*TAIL LAMP ASSY (LOWER)(LH/RH)	Cracked	1,096.80 FL	*1,096.80 FL
51	1		*REAR END PANEL	Bent	602.10 FL	*602.10 FL
52	1		*REAR END PANEL GARNISH	Distorted	121.60 FL	*121.60 FL
53	1		*REAR SPARE TYRE CHUSHION (FLR BOARD CENTRE)	Serviceable	101.40 FL	*- FL
54	1		*REAR EXHAUST PIPE	Repair	1,163.40 FL	*- FL
55	1		*REAR EXHAUST PIPE HANGER	Serviceable	40.70 FL	*- FL
56	1		*REAR EXHAUST PIPE INSULATOR	Serviceable	314.60 FL	*- FL
57	1		*REAR WINDSCREEN GLASS	Necessary	1,555.80 FL	*1,555.80 FL
58	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	208.60 FL	*208.60 FL
59	1		*FRONT NO PLATE TRIM COVER }	Missing	30.00 FS	*40.00 FS
60	1		*FRONT NO PLATE }	Bent	25.00 FS	*- FS
61	1		*FRONT NO PLATE GARNISH	Serviceable	99.00 FS	*- FS
62	1		*REAR TRUNK LID APPS STICKER	Not Necessary	40.00 FS	*- FS
63	1		*REAR TRUNK LID COMFORT & TEL NO STICKER	Necessary	60.00 FS	*60.00 FS
64	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
65	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
66	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 27,352.80 17,759.70  
 - List Item Discount on L Items 20.00/25.00% (\$\$) 5,373.42 4,357.00

Total Parts (\$\$) 21,979.38 13,402.70

Report was unsubmitted during this print-out.
---

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,200.00	1,200.00
2	SPRAY PAINTING CHARGE	New	800.00	800.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	50.00	50.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	-
6	TUFF KOTE	New	50.00	50.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	100.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	60.00
9	REMOVE/REFIX EXHAUST PIPE	New	150.00	80.00
Gross Labour Cost (\$\$)			<b>3,740.00</b>	<b>2,400.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;