

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: 6 SNM18D01178
Assessment Number: CTI10133
Version: LKKAUTOC/2
Date Calculated: 02/05/2018 10:34

Full Report - V1
Registration: SGJ9566P
Printed: 02/05/2018 17:34

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	05/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	6 SNM18D01178	Estimated Repair Time:	
Policy Number:	DMPCSN7042621710	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Odyssey (Reference
Sub Model:	BASE MODEL
Model Sheet Number:	HAB 01
Registration:	SGJ9566P
Registration Month:	July
Registration Year:	2006
VIN Number:	
Manufacture Year:	2006
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

2.3 LTR 110KW	TWO COAT PEARL/MICA
---------------	---------------------

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	05/03/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Primary Impact
Secondary Impact

Addresses

Cost Summary

Total Labour	\$705.60
Total Paint/Material	\$150.37
Total Parts	\$6,088.86
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$6,986.83
7 % GST:	\$489.08
Grand Total Inc GST:	\$7,475.91

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
04711-SX0)	R + R FRONT BUMPER	3.0	12.60
04711-SX0)	RENEW FRONT BUMPER (REMOVED)	3.0	12.60
NO NUMBER	RENEW FRONT NUMBER PLATE (REMOVED)	2.0	8.40
33151-SX0)	R + R HEADLAMPS (BUMPER REMOVED)	7.0	29.40
	INCLUDES: ADJUST HEADLAMPS		
75100-SX0	R + R RADIATOR BLIND	2.0	8.40
60100-SX0)	R + R BONNET	2.0	8.40
60100-SX0)	RENEW BONNET (REMOVED)	9.0	37.80
71850-SX0)	R + R LEFT LOWER BEAM EXTENSION	6.0	25.20
71800-SX0)	R + R RIGHT LOWER BEAM EXTENSION	6.0	25.20
76841-SX0)	R + R WASHER TANK	3.0	12.60
NO NUMBER	R + R LEFT FRONT WING	5.0	21.00
	INCLUDES: R + R LEFT FRONT INNER WING COVER		
NO NUMBER	R + R RIGHT FRONT WING	5.0	21.00
	INCLUDES: R + R RIGHT FRONT INNER WING COVER		
NO NUMBER	RENEW FRONT PANEL CPL	25.0	105.00
80341-SX0)	R + R LINE CONDENSER/DRYER	9.0	37.80
80342-SX0)	R + R EXCHANGER INTAKE HOSE	13.0	54.60
80100-SX0)	R + R AIR CONDITIONING CONDENSER	8.0	33.60
9973	CARRY OUT TEST DRIVE	5.0*	21.00

LABOUR COST

Total Work Units

113.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	11.3HRS	\$474.60
Paint Labour	5.5HRS	\$231.00
Total Labour	16.8HRS	\$705.60

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT PEARL/MICA		
340	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	19.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
283	FRONT BUMPER NEW PART PAINT K1R	10.0	
LABOUR COST - PAINT		39.0	
TIME(PAINT)		11.0	
Preparation Main Work Metal		5.0	
Preparation Comp. Work Plastic		0.0	
Preparation Work Multi Layer Paint		55.0	
Total Work Units (10WU/HR)		5.5HRS	\$231.00
Total Paintwork Labour			Cost Price
MATERIAL COST - PAINT			\$59.34
New Part Painting			\$46.74
New Part Painting - Plastic K1R			\$17.19
Surface-/Blend Paint			\$18.10
Material-Const Main Work Metal			\$9.00
Material-Const Comp. Work Plastic			\$150.37
Total Excluding Pearlescent Uplift			\$0.00
Pearlescent Uplift @ 0.0%			\$150.37
Total Paint Material Cost			

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		25.00*
258	1	FRT NO PLATE REINF	71145SX0A02		25.00*
283	1	FRONT BUMPER	04711SX0020ZZ		653.00*
340	1	FRT BUMPER SUPPORT	71130SX0A00		218.00*
410	1	FRONT GRILLE	75100SX0J12ZB		179.66M
471	1	BONNET	60100SX0000ZZ		639.00*
481	1	BONNET INSULATION	74141SX0010		68.00*
493	1	BONNET LOCK	74120SX0A01		74.80*
525	1	L/F BONNET GASKET	74198SX0000		35.00*
526	1	R/F BONNET GASKET	74148SX0000		35.00*
527	1	FRONT BONNET SEAL	74142SX0000		58.00*
561	1	L/F HEADLAMP	33151SX0Q01		518.00*
562	1	R/F HEADLAMP	33101SX0Q01		518.00*
1009	1	FRONT PANEL CPL	60400S1K300ZZ		750.00*
1436	1	WASHER RESERVOIR	76841SX0C01		55.00*
4465	1	AIR CON CONDENSER	80110SX0003		245.00*
4479	1	CONDENSER TUBE	80341SX0003		157.00*
4480	1	EVAPORATOR TUBE	80342SX0963		157.00*
4485	1	AIR CON BLOWER FAN	38611PT2J02		58.00*
4489	1	AIR CON FAN SHROUD	38615P1EQ00		102.00*

7761	1	RADIATOR	19010PEA901	0%	272.00*
7767	1	FAN SHROUD	19015P1E003	0%	102.00*
7787	1	EXPANSION TANK	19101P1E000	0%	62.00*
1000	1	GRILLE CHROME-UPP	Renew	0%	116.00*
1000	1	GRILLE CHROME-LOWER	Renew	0%	149.00*
1000	1	GRILLE EMBLEM	Renew	0%	26.00*
1000	1	F/BUMPER RETAINER RH	Renew	0%	12.50*
1000	1	F/BUMPER RETAINER LH	Renew	0%	12.50*
1000	1	FRONT BUMPER GRILLE	Renew	0%	54.40*
1000	1	F/BUMPER LWR SPOILER	Renew	0%	612.00*
f: OEM Parts				Sub Total	\$5,988.86
g: Original				Mark Up From Cost	\$0.00
h: Secondhand				Sundry Parts	\$100.00
p: Parallel				Total Parts	\$6,088.86
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	SPECIALIST	Betterment	Price
	AUDATEX FEE		0%	\$42.00
			Total Extras	\$42.00

Final Calculation

Total Parts		\$6,088.86
Labour		
Total Panel/Mechanical	\$474.60	
Total Paintwork	\$231.00	
Total Labour		\$705.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$42.00	
Total of Additional Costs		\$42.00
Total Paint/Material Costs		\$150.37
Grand Total Excludes GST		\$6,986.83
GST @ 7 %		\$489.08
Grand Total Includes GST		\$7,475.91

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018 Sendback Est	07 Mar 2018 15:44 \$513,241.31	07 Mar 2018 16:31 Edit Adj Rpt	\$55,500.00 Edit Estimates	\$55,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ANG BIN KEONG, LAWRENCE , ID: S1401021A									
Vehicle Reg. No.: SGJ9566P		Date of Loss:	05/03/2018 07:00 - :59 [139 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / SNM18D01178C01		Policy/Cover Note No.:	DMPCSN7042621710 (Comprehensive) Coverage: 25/07/2017 - 24/07/2018						
		Excess:	\$0.00						
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/03/2018]									
Driver/Custodian: ANG BIN KEONG, LAWRENCE (/ Male) , NRIC: S1401021A									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA TAIPING (15/03/2018): Alert - Adj Mandate Approved (\$8328.23) - SGJ9566P - Claim Handler: Irene Tay H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGJ9566P (SNM18D01178C01)
OD
Mar 5 2018 7:00AM
[ANG BIN KEONG, LAWRENCE]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser
		1 per page ☒
Assessment Reports		
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)
1	07/03/18 15:44	Repairer Estimates
		☒ Load HTM Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)
1	09/03/18 16:00	Adjuster Immediate Advice
		☒ Load HTM Print
Photos/Images		
		3 per page ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	09/03/18 16:01	General View
2	09/03/18 16:01	General View
3	09/03/18 16:01	General View
4	09/03/18 16:01	General View
5	09/03/18 16:01	General View
6	09/03/18 16:01	General View
7	09/03/18 16:01	General View
8	09/03/18 16:01	General View
9	09/03/18 16:01	General View
10	09/03/18 16:01	General View
11	09/03/18 16:01	General View
12	09/03/18 16:01	General View
13	09/03/18 16:01	General View
14	09/03/18 16:01	General View
15	09/03/18 16:01	General View
16	09/03/18 16:01	General View
17	09/03/18 16:01	General View
18	09/03/18 16:01	General View
19	09/03/18 16:01	General View
20	09/03/18 16:01	General View
21	09/03/18 16:01	General View
22	09/03/18 16:01	General View
23	09/03/18 16:01	General View
24	09/03/18 16:01	General View
25	09/03/18 16:01	General View
26	09/03/18 16:01	General View
27	09/03/18 16:01	General View
28	09/03/18 16:01	General View
29	09/03/18 16:01	General View
30	09/03/18 16:01	General View
31	09/03/18 16:01	General View
32	09/03/18 16:01	General View
33	09/03/18 16:01	General View
34	09/03/18 16:01	General View

Assessment Reports			1 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
				☒
35	09/03/18 16:01	General View	Load JPG	☒
36	09/03/18 16:01	General View	Load JPG	☒
37	09/03/18 16:01	General View	Load JPG	☒
38	09/03/18 16:01	General View	Load JPG	☒
39	09/03/18 16:01	General View	Load JPG	☒
40	09/03/18 16:01	General View	Load JPG	☒
41	09/03/18 16:02	General View	Load JPG	☒
42	09/03/18 16:02	General View	Load JPG	☒
43	09/03/18 16:02	General View	Load JPG	☒
44	09/03/18 16:02	General View	Load JPG	☒
45	09/03/18 16:02	General View	Load JPG	☒
46	16/05/18 11:40	Reinspection Photo	Load JPG	☒
47	16/05/18 11:40	Reinspection Photo	Load JPG	☒
48	16/05/18 11:40	Reinspection Photo	Load JPG	☒
49	16/05/18 11:40	Reinspection Photo	Load JPG	☒
50	16/05/18 11:40	Reinspection Photo	Load JPG	☒
51	16/05/18 11:40	Reinspection Photo	Load JPG	☒
52	16/05/18 11:40	Reinspection Photo	Load JPG	☒
53	16/05/18 11:40	Reinspection Photo	Load JPG	☒
54	16/05/18 11:40	Reinspection Photo	Load JPG	☒
55	16/05/18 11:40	Reinspection Photo	Load JPG	☒
56	16/05/18 11:40	Reinspection Photo	Load JPG	☒
57	16/05/18 11:40	Reinspection Photo	Load JPG	☒
58	16/05/18 11:40	Reinspection Photo	Load JPG	☒
59	16/05/18 11:40	Reinspection Photo	Load JPG	☒
60	16/05/18 11:40	Reinspection Photo	Load JPG	☒
61	16/05/18 11:40	Reinspection Photo	Load JPG	☒
62	16/05/18 11:40	Reinspection Photo	Load JPG	☒
63	16/05/18 11:40	Reinspection Photo	Load JPG	☒
64	16/05/18 11:40	Reinspection Photo	Load JPG	☒
65	16/05/18 11:40	Reinspection Photo	Load JPG	☒
66	16/05/18 11:40	Reinspection Photo	Load JPG	☒
67	16/05/18 11:40	Reinspection Photo	Load JPG	☒
68	16/05/18 11:40	Reinspection Photo	Load JPG	☒
69	16/05/18 11:40	Reinspection Photo	Load JPG	☒
70	16/05/18 11:40	Reinspection Photo	Load JPG	☒
71	16/05/18 11:40	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	07/03/18 15:45	Singapore Accident Statement	Load PDF	
2	07/03/18 15:45	IC & DL	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/18 16:00	REVISED AUDATEX	Load PDF	
2	09/03/18 16:00	ESTIMATE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI18004471/GQD3E2**Date:** 23/05/2018REFERENCEInsured/Claimant: ANG BIN KEONG, LAWRENCE Policy No: DMPCSN7042621710
Date of Loss: 05/03/2018 Nature of Claim: OD Claim No: SNM18D01178C01DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGJ9566P	Engine No:	K24A64000278
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRB18507C200278
Reg. Date:	25/07/2006 (Man. Year: 2006)	Odometer:	177368 km
Colour:	Black		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	S\$35,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,893.04	6,130.86	5,762.18	48.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,348.27	855.97	492.30	36.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,241.31	6,986.83	6,254.48	47.23
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	13,241.31	5,500.00	7,741.31	58.46
+ GST 7.00/7.00% (S\$)	926.89	385.00	541.89	58.46
Nett Amount (S\$)	14,168.20	5,885.00	8,283.20	58.46

INSPECTION

Date of Assignment:	07/03/2018 Present Location:	SMRT Automotive Services Pte Ltd (Woodlands)
Date Inspected:	08/03/2018 Inspected At:	60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2018)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ9566P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR CON BLOWER FAN (WCP)	Cracked	58.00 F	*58.00 F
2	1	NA	*AIR CON BLOWER MOTOR (WCP)	Not Necessary	190.40 F	*- F
3	1	NA	*AIR CON COMPRESSOR (WCP)	Not Necessary	850.00 F	*- F
4	1	NA	*AIR CON CONDENSER (WCP)	Bent	245.00 F	*245.00 F
5	1	NA	*AIR CON FAN SHROUD (WCP)	Cracked	102.00 F	*102.00 F
6	1	NA	*AIR CON PIPE (WCP)	Not Necessary	150.00 F	*- F
7	1	NA	*AIR FILTER ELEMENT (WCP)	Not Necessary	45.00 F	*- F
8	1	NA	*AIR FILTER LWR HSG (WCP)	Not Necessary	125.00 F	*- F
9	1	NA	*AIR FILTER SUPPORT (WCP)	Not Necessary	76.00 F	*- F
10	1	NA	*AIR FILTER UPPER HSG (WCP)	Not Necessary	125.00 F	*- F
11	1	NA	*AIR FLOW METER HOSE (WCP)	Not Necessary	96.00 F	*- F
12	1	NA	*BONNET (WCP)	Buckled	639.00 F	*639.00 F
13	1	NA	*BONNET INSULATION (WCP)	Deformed	68.00 F	*68.00 F
14	1	NA	*BONNET LOCK (WCP)	Bent	74.80 F	*74.80 F
15	1	NA	*BONNET OPENER (WCP)	Not Necessary	98.00 F	*- F
16	1	NA	*BONNET STAY (WCP)	Not Necessary	42.04 F	*- F
17	1	NA	*CONDENSER SUPPORT (WCP)	Not Necessary	125.00 F	*- F
18	1	NA	*CONDENSER TUBE (WCP)	Bent	157.00 F	*157.00 F
19	1	NA	*CONDENSER/COMPR PIPE (WCP)	Not Necessary	157.00 F	*- F
20	1	NA	*CONDENSER/DRYER HOSE (WCP)	Not Necessary	45.00 F	*- F
21	1	NA	*COOLING FAN (WCP)	Not Necessary	55.00 F	*- F
22	1	NA	*DRYER BOTTLE (WCP)	Not Necessary	45.00 F	*- F
23	1	NA	*EVAPORATOR TUBE (WCP)	Bent	157.00 F	*157.00 F
24	1	NA		Deformed	62.00 F	*62.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*EXPANSION TANK (WCP)			
25	1	NA	*F/BUMPER LWR COVER (WCP)	Not Necessary	150.00 F	*- F
26	1	NA	*F/BUMPER LWR SPOILER (WCP)	Deformed	612.00 F	*612.00 F
27	1	NA	*F/BUMPER RETAINER LH (WCP)	Necessary	12.50 F	*12.50 F
28	1	NA	*F/BUMPER RETAINER RH (WCP)	Necessary	12.50 F	*12.50 F
29	1	NA	*FAN MOTOR PROTECTION (WCP)	Not Necessary	85.00 F	*- F
30	1	NA	*FAN SHROUD (WCP)	Cracked	102.00 F	*102.00 F
31	1	NA	*FOG LAMP LH (WCP)	Not Necessary	232.00 F	*- F
32	1	NA	*FOG LAMP RH (WCP)	Not Necessary	232.00 F	*- F
33	1	NA	*FRONT BONNET SEAL (WCP)	Necessary	58.00 F	*58.00 F
34	1	NA	*FRONT BUMPER (WCP)	Deformed	653.00 F	*653.00 F
35	1	NA	*FRONT BUMPER GRILLE (WCP)	Deformed	54.40 F	*54.40 F
36	1	NA	*FRONT GRILLE (WCP)	Cracked	179.66 F	*179.66 F
37	1	NA	*FRONT NUMBER PLATE (WCP)	Bent	25.00 F	*25.00 F
38	1	NA	*FRONT PANEL CPL (WCP)	Bent	750.00 F	*750.00 F
39	1	NA	*FRT BUMPER CLAMP KIT (WCP)	Not Necessary	60.00 F	*- F
40	1	NA	*FRT BUMPER S-ABSORB (WCP)	Not Necessary	150.00 F	*- F
41	1	NA	*FRT BUMPER SUPPORT (WCP)	Bent	218.00 F	*218.00 F
42	1	NA	*FRT NO PLATE REINF (WCP)	Deformed	25.00 F	*25.00 F
43	1	NA	*GRILLE CHROME-LOWER (WCP)	Broken	149.00 F	*149.00 F
44	1	NA	*GRILLE CHROME-UPP (WCP)	Missing	116.00 F	*116.00 F
45	1	NA	*GRILLE EMBLEM (WCP)	Necessary	26.00 F	*26.00 F
46	1	NA	*L/BONNET HINGE (WCP)	Not Necessary	65.00 F	*- F
47	1	NA	*L/F BONNET GASKET (WCP)	Necessary	35.00 F	*35.00 F
48	1	NA	*L/F BUMPER REINF (WCP)	Not Necessary	38.10 F	*- F
49	1	NA	*L/F HEADLAMP (WCP)	Broken	518.00 F	*518.00 F
50	1	NA	*L/F HINGE COVER (WCP)	Not Necessary	88.00 F	*- F
51	1	NA	*L/F WASHER JET (WCP)	Not Necessary	40.80 F	*- F
52	1	NA	*L/F WHEELHOUSE COVER (WCP)	Not Necessary	86.00 F	*- F
53	1	NA	*L/F WING (WCP)	Repair	450.00 F	*- F
54	1	NA	*L/F WING CLAMP KIT (WCP)(NPA)	Not Necessary	0.00 F	*- F
55	1	NA	*LOWER RADIATOR HOSE (WCP)	Not Necessary	55.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1	NA	*R/BONNET HINGE (WCP)	Not Necessary	65.00 F	*- F
57	1	NA	*R/F BONNET GASKET (WCP)	Necessary	35.00 F	*35.00 F
58	1	NA	*R/F BUMPER REINF (WCP)	Not Necessary	38.10 F	*- F
59	1	NA	*R/F HEADLAMP (WCP)	Cracked	518.00 F	*518.00 F
60	1	NA	*R/F HINGE COVER (WCP)	Not Necessary	88.00 F	*- F
61	1	NA	*R/F WASHER JET (WCP)	Not Necessary	40.80 F	*- F
62	1	NA	*R/F WHEELHOUSE COVER (WCP)	Not Necessary	86.00 F	*- F
63	1	NA	*R/F WING (WCP)	Repair	450.00 F	*- F
64	1	NA	*R/F WING CLAMP KIT (WCP)	Not Necessary	35.00 F	*- F
65	1	NA	*RADIATOR (WCP)	Bent	272.00 F	*272.00 F
66	1	NA	*REAR WASH/WIPE PUMP (WCP)	Not Necessary	65.00 F	*- F
67	1	NA	*SCREW (WCP)	Not Necessary	31.60 F	*- F
68	1	NA	*SPECIALIST AUDATEX FEE		42.00 F	*42.00 FS
69	1	NA	*SUNDRY PARTS	Necessary	100.00 F	*100.00 FS
70	1	NA	*UPP EVAPORATOR PIPE (WCP)	Not Necessary	220.00 F	*- F
71	1	NA	*UPP RADIATOR HOSE (WCP)	Not Necessary	55.00 F	*- F
72	1	NA	*WASHER RESERVOIR (WCP)	Deformed	55.00 F	*55.00 F
73	1	NA	*W-SCREEN WASHER PUMP (WCP)	Not Necessary	65.00 F	*- F

F=Franchise part. S=SpcNett

Sub Total (S\$)	11,326.70	6,130.86
+ Margin on L,N Items 5.00/0.00% (S\$)	566.34	0.00
Total Parts (S\$)	11,893.04	6,130.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	372.60	231.00
2	Total Paint Materials	New	193.67	150.37
3	Total Panel/Mechanical Labour	New	782.00	474.60
Gross Labour Cost (\$\$)			1,348.27	855.97

Report was unsubmitted during this print-out.

< END OF ESTIMATES >