

22/03/2002

ASS. REC. BY:

REF: CS/MSG18004500/714d319

Special Instruction:

Survivor:
Menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Fievel Foo

of

MSG

Date/Time:

8/3/18 @ 3:11pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDD 2112D

Insured:

SLV 1229T

at Workshop m/s

Performance

Tel:

63190174

of

303 Alexandra Road

Policy No:

A29067326QMY

Claim No:

551588

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

5/3/18

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

3:42pm @ 8/3/18

Person Contacted:

Caroline

Vehicle IN

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SDD 2112D - CC31AIG18004406/K1ka3

D.O.A = 5/3/18

SLV 1229T-x

14/3/18 @ 4:38pm

revised to travel for vta menmen.

07/3/18 @ 11:21am

Man confirmed with Caroline final Arg to 26284.85, 15 days by email.

(Ref 619776.05, 432)

Signature

Tang

REF: MSU7

ASSIGNMENT

From: Date: 13.03.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDD 2112D
at Workshop m/s Performand
of 303 Alexandra Rd

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Ithiran

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$137K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDD 2112D Yr Regn: 2015 / Per.
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 528I M Sport C.C. 1997.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 62969 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/40R18.

R: 4.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at PML

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction To check limits
SRT 2999 SRT 8035E-mail to Intran Unit @38K
waiting for before print photos.

2/7/2018

RECEIVED 8 JUL 2018

Date/Time: File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time: File Return to?

Days Of Repair: 15

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004500/T1qd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 1229T	Veh. Inspected	SDD 2112D
Policy No.	A29067326QMY	Coverage (\$)	0.00
Claim No.	551588	Excess (\$)	0.00
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	08/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/03/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 2 July 2018 11:29 AM
To: 'PBSP'; Taufikh (LKKAUTO); SUR
Subject: RE: Gentle reminder: FINAL REPORT / SDD2112D

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$26,284.85 before GST and 15 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, 28 June 2018 2:54 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: Gentle reminder: FINAL REPORT / SDD2112D

3rd Reminder

From: PBSP
Sent: Friday, 22 June 2018 7:38:45 PM
To: taufikh@lkkauto.com; SUR
Subject: Gentle reminder: FINAL REPORT / SDD2112D

Gentle reminder

From: PBSP
Sent: Monday, 21 May 2018 4:31 PM
To: Taufikh (LKK Auto)
Subject: Re: FINAL REPORT / SDD2112D

Dear Taufikh

As requested, please see attached

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 14 Mar 2018

Preliminary Advice

Insured Vehicle No	: SLV1229T	Accident Date	: 05/03/2018
TP Vehicle No	: SDD2112D	Assignment Date	: 08/03/2018
Make	: BMW 528i	Est. Duration of Repair	: 18.00
Date of Inspection	: 13/03/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,591.70
Revised Amount	:S\$	21,726.75
Check Items (Estimated)	:S\$	20,263.55
Total	:S\$	41,990.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7360H
Vehicle Details	
Vehicle No.:	SDD2112D
Vehicle to be Exported:	No
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	528I M SPORT D/AB LED NAV
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	A0460666N20B20A
Chassis No.:	WBA5A52030D284923
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$54,459.00
Original Registration Date:	31 Dec 2013
First Registration Date:	31 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$65,027.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2023
PARF Rebate Amount:	\$48,770.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$84,578.00
COE Rebate Amount:	\$48,996.00
Total Rebate Amount:	\$97,766.00

The information contained herein is correct as at 14 Mar 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



BMW 528

Price Range

Depreciation

2013

Vehicle Type

Search

Home » Used Cars » Bavarian Marques Pte Ltd » BMW 5 Series 528i M-Sport

Resources

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Tyres



BMW 5 Series 528i M-Sport

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

PRE



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$125,000**

Depreciation **\$18,530 /yr**
View models with similar depreciation

Reg Date **13-Apr-2013**
(5yrs 29days COE left)

Manufactured **2012**

Mileage **49,000 km (10k /yr)**

Transmission **Auto**

Engine Cap **1,997 cc**

Road Tax **\$1,210 /yr**

Power **180.0 kW (241 bhp)**
View specs of the BMW 528i

Curb Weight **1,695 kg**

Features 2.0L Powerful Inline 4 Cylinder BMW Twin Power Turbo Charger, 8 Speed Auto Steptronic Transmission, ABS, ESP, PDC, Airbags, Comfort/Sports Plus Mode.

Accessories M-Sport Option, 20" Hamman Alloy Wheels & Badging, Sunroof, Keyless Entry & Start, I-Drive, Reverse Camera, Bluetooth, Paddle Shift, PDC With Camera

Description 1 Owner, Flawless Alpine White On Cinnamon Interior. Full M-Sport Bodykit & Expensive 20" Hamman Wheels. Very Low Mileage. Never Driven Outside Of Singapore. Immaculate And Stunning Car, Always Garaged By Fussy Owner. Very Fast And Economical. Rare Colour Combination. Upto 80% Financing, Trade In Welcome. Evaluation Welcomed. Contact Us For A Viewing Appointment Today!

COE **\$66,989**

OMV **\$49,743**

ARF **\$61,641**

Dereg Value **\$80,276 as of today (change)**

No. of Owners **1**

Type of Veh **Luxury Sedan**

Category **PARF Car, Premium Ad Car, Low Mileage Car**



Seller Information

Company **Bavarian Marques Pte**
• dealer's pricelist
• 93 vehs sold | 101 vehs i

Address **8 Ubi Road 2 #08-05**
Search cars nearby this loc

Location **Zervez**

Website **www.bavarianmarques.com**

Office No **68162642**

Contact Person(s) **Shawn** 8
Darren 8

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 15:22
Date Of Accident	05/03/2018 17:00
Exact Location Of Accident	AYE (EXIT @ ALEXANDER)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDD2112D
Insured/Policyholder	
Name Of Registered Owner	TONY TAN KIA MENG
NRIC No	S1827360H
Email Address	TONY.TAN@COMMSSQUARE.COM.SG
Mobile Phone No	(LOCAL) +65-82282112
Alternative Phone No	OFFICE-82282112

Vehicle Particulars

Manufacturer	BMW
Model	528i
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100396502-03
Cover Note Number	

Driver

Name of Driver	TONY TAN KIA MENG
NRIC No	S1827360H
Date Of Birth	21/01/1967
Occupation	INDOOR
Date Of Driving Pass	02/03/1985
Driving Experience	33 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82282112
Fax Number	
Contact Number	OFFICE-82282112
Email Address	TONY.TAN@COMMSSQUARE.COM.SG

Address	42 DAKOTA CRESCENT #14-19
Postcode	399940
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV1229T
Vehicle Make/Model/Colour	NISSAN X-TRAIL BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA7672P
Vehicle Make/Model/Colour	TAXI BLUE

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 6/3/18 1.00pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: Inban M. Thurasamy
NRIC/ID No: Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 5 MAR 18 around 5pm, I was travelling along AYE (Exit @ ALEXANDER), a Taxi (SHA 7672 P) made a sudden brake, I manage to stop in time. Suddenly a car SLV 1229 T has knocked into at rear portion of my car and my car surged forward collided into the taxi.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

6/3/18
1.00pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Inthira M. Thiraseemy
Performance Motors Limited
Reporting Officer's Signature
303 Alexandra Road
Name: Inthira M. Thiraseemy
NRIC/IN No.: Singapore 150041

Car, 7u

BMW Dealer

Performance Motors Limited

A member of the Hine Darby Group

Co. Reg. No. 197401539M GST Reg. No M2-0020081-X

303, Alexandra Road
Hine Darby Performance Centre
Singapore 159941Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747772380, Kampong Arang Road
East Coast Centre
Singapore 438180Tel: 63190888 (AfterSales)
Fax: 63449773315, Alexandra Road
Hine Darby Business Centre
Singapore 159944Tel: 63195528 (AfterSales)
63195533/530 (Motorrad)
Fax: 64786601 (AfterSales)
64786524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

08 MAR 2018

Estimate No. : b1 46163
 Date Estimated : 08/03/2018
 Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -
 Tony Tan Kia Meng
 Apt Blk 42 Dakota Crescent
 #14-19

Singapore 399940

- ACCOUNT - 66
 MSIG Insurance (S) Pte Ltd
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD2112D	D284923	31/12/2013	528iA	0

DESCRIPTIONVALUE

To replace front bumper, air duct (front panel), rear bumper, boot lid, tail panel, trunk floor extension, repair trunk floor and attachments including knock out dent area cause by accident.

8500 / 11,050.00

replace truck floor extension - 10200

Painting front bumper, rear bumper, boot lid, tail panel, and trunk floor.

3015 / 3,350.00

~~To supply front emboss number plate. (Special type).~~

und / 165.00

~~To supply rear emboss number plate. (Special type).~~

crav / 165.00

To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).

852 ? / 1,003.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

?451 / 531.00

To mount accident vehicle on speed bench to facilitate re-alignment of body/chassis accordance with BMW specification.

564 ? / 664.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 / 271.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 / 531.00

To replace bootlid smart opener control unit, top and bottom sensor lines including program and conduct checks for proper function.

561 / 661.00

To replace both left and right headlights including program and conduct tests for proper function.

402 ? / 1,062.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 187401519W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438182
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/830 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46163
Date Estimated : 08/03/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD2112D	D284923	31/12/2013	528ia	0

DESCRIPTION

VALUE

To check electrical wiring systems and lightings at the rear section for proper function.

150. 177.00

To carry out body cavity preservation.
(Per panel).

100. 118.00

To carry out body cavity preservation.
(For cut panel).

451. 531.00

Sundries. *N/A*

NCC 150.00

Total Labour 1: 20,429.00

DESCRIPTION

QTY PRIC

VALUE

CROSS MEMBER TRUNK FLOOR REAR
END PIECE FOR CARGO AREA FLOOR
TAIL END PANEL
BOOTLID
FRT BUMPER CARRIER
FRT SHOCK ABSORBER
FRT BUMPER PANEL PRIMED (M/PDC)
Set of mount
RR BUMPER LH MOUNT
RR BUMPER RH MOUNT
COVER BUMPER REAR (M)
GUIDE CENTRE REAR (M)
GUIDE BOTTOM CENTRE (M)
COVERING TOWING RR PRIMED (M)
REAR BUMPER PANEL PRIMED (M PDC)
ADAPTER (M)
FRT LH GRILLE (BASIS)
FRT RH GRILLE (BASIS)
EMBLEM GROMMET
BMW EMBLEM
MODEL LETTERING 528i
BMW EMBLEM
TRUNK LID LOCK TOP
FRT AIR DUCT(front panel)
FRAME (M)
AIR DUCT FRT BOTTOM (M)
LH HEADLIGHT LED TECHNOLOGY
RH HEADLIGHT LED TECHNOLOGY
REAR LH REFLECTOR (M)
REAR RH REFLECTOR (M)
RR LH LIGHT IN SIDE PANEL
RR RH LIGHT IN SIDE PANEL

1 116.60
1 53.00
1 817.30
1 1,602.40
1 684.75
1 48.00
1 1,533.10
1 62.60
1 142.55
1 142.55
1 174.70
1 75.05
1 46.85
1 55.70
1 1,650.65
1 64.70
1 120.50
1 120.50
2 0.80
1 69.50
1 62.55
1 69.50
1 425.35
1 226.55
1 64.60
1 51.50
1 4,201.60
1 4,201.60
1 35.20
1 35.20
1 572.25
1 572.25

? 116.60
bt 53.00
? 817.30
bt 1,602.40
bt 684.75
de 48.00
de 1,533.10
? 62.60
? 142.55
? 142.55
de 174.70
de 75.05
de 46.85
N/A 55.70
de 1,650.65
de 64.70
ent 120.50
ent 120.50
ent 1.60
ent 69.50
ent 62.55
ent 69.50
bt 425.35
can 226.55
? 64.60
? 51.50
? 4,201.60
? 4,201.60
x 35.20
x 35.20
? 572.25
? 572.25

nr

nr

nr

nr



315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

ESTIMATE

Date:

46010.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46163
Date Estimated : 08/03/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tony Tan Kia Meng
Apt Blk 42 Dakota Crescent
#14-19

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 399940

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SDD2112D	D284923	31/12/2013	528iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	2.00		2.50 <i>ch nec ✓</i>
# BLIND RIVET *	1.25	6.00		7.50 <i>ch nec ✓</i>
# TAILPIPE TIP BLACK CHROME *	157.95	2.00		315.90 <i>ch nec ✓</i>
# PRIMED COATED LH FLAP (M) *	55.70	1.00		55.70 <i>ch de ✓</i>
# EXPANDING NUT *	1.00	4.00		4.00 <i>ch nec ✓</i>
# RR BUMPER CARRIER *	714.25	1.00		714.25 <i>ch nec ✓</i>
# ADHESIVE TAPE *	48.60	1.00		48.60 <i>ch nec ✓</i>
# SUPPORT LH *	18.40	1.00		18.40 <i>ch de ✓</i>
# SUPPORT RH *	18.40	1.00		18.40 <i>ch de ✓</i>
# CONNECTION TOP FRT *	155.35	1.00		155.35 <i>ch de ✓</i>
# M PERFORMANCE FRONT GRILLE RH BLK *	147.15	1.00		147.15 <i>ch nec ✓</i>
# M PERFORMANCE FRONT GRILLE LH BLK *	147.15	1.00		147.15 <i>ch nec ✓</i>
# FRT AIR DUCT *	226.55	1.00		226.55 <i>ch de ✓</i>
# PLUG BLACK D=5MM *	0.90	7.00		6.30 <i>ch nec ✓</i>
# SENSOR WIRE FOR SMART OPENER TOP *	42.10	1.00		42.10 <i>ch nec ✓</i>
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50 <i>ch nec ✓</i>
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85 <i>ch nec ✓</i>

Total Labour :
Total Parts : 2,419.20
Total Labour & Parts : 2,419.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46163
Date Estimated : 08/03/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tony Tan Kia Meng
Apt Blk 42 Dakota Crescent
#14-19

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 399940

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEASE	ORIGINAL PRICE	DISC. %	NETT
SDD2112D	D284923	31/12/2013	528iA	0			
DESCRIPTION					ORIGINAL PRICE	DISC. %	NETT
To replace front/rear bumpers and attachments, front air duct(front panel), tail end panel, boot lid and attachments, front top connection, support LH/RH, rear RH light in trunk lid include making good the trunk floor plate and knocking out dents caused by the accident					8500.00		8,500.00
To spray paint front bumper, rear bumper, boot lid, tail end panel and trunk floor plate					3015.00		3,015.00
To supply front emboss number plate (Special type)					165.00		165.00
To supply rear emboss number plate (Special type)					165.00		165.00
* To replace air con condenser and air con hose include vacuum system, top up freon gas and conducting checks for leak					852.00		852.00
To remove and install boot compartment carpet and garnish to facilitate repairs					230.00		230.00
To transfer lock mechanism from old to new boot lid include conducting checks on new bootlid central locking system for proper function					451.00		451.00
To replace bootlid smart opener control unit, top and bottom sensor lines include programming and conducting checks for proper function					561.00		561.00
To check electrical wiring systems and lightings at the rear section for proper function.					150.00		150.00
To carry out body cavity preservation. (Per panel).					100.00		100.00
To carry out body cavity preservation. (For cut panel).					451.00		451.00
Sundries.					150.00		150.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W. GST Reg. No. M2-0020081-X



FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	2.00		2.50 <i>ch del</i>
# BLIND RIVET *	1.25	6.00		7.50 <i>ch del</i>
# TAILPIPE TIP BLACK CHROME *	157.95	2.00		315.90 <i>ch out</i>
TAIL END PANEL	817.30	1.00		817.30
BOOTLID	1,602.40	1.00		1,602.40
FRT BUMPER CARRIER	684.75	1.00		684.75
FRT SHOCK ABSORBER	48.00	1.00		48.00
# PRIMED COATED LH FLAP (M) *	55.70	1.00		55.70 <i>ch del</i>
FRT BUMPER PANEL PRIMED (M/PDC)	1,533.10	1.00		1,533.10
# EXPANDING NUT *	1.00	4.00		4.00 <i>ch del</i>
# RR BUMPER CARRIER *	714.25	1.00		714.25 <i>ch BT</i>
COVER BUMPER REAR (M)	174.70	1.00		174.70
GUIDE CENTRE REAR (M)	75.05	1.00		75.05
GUIDE BOTTOM CENTRE (M)	46.85	1.00		46.85
REAR BUMPER PANEL PRIMED (M PDC)	1,650.65	1.00		1,650.65
ADAPTER (M)	64.70	1.00		64.70
EMBLEM GROMMET	0.80	2.00		1.60
BMW EMBLEM	69.50	1.00		69.50
MODEL LETTERING 528I	62.55	1.00		62.55
BMW EMBLEM	69.50	1.00		69.50
TRUNK LID LOCK TOP	425.35	1.00		425.35
# ADHESIVE TAPE *	48.60	1.00		48.60 <i>ch del</i>
# SUPPORT LH *	18.40	1.00		18.40 <i>ch del</i>
# SUPPORT RH *	18.40	1.00		18.40 <i>ch del</i>
# CONNECTION TOP FRT *	155.35	1.00		155.35 <i>ch del</i>
# M PERFORMANCE FRONT GRILLE RH BLK *	147.15	1.00		147.15 <i>ch cut</i>
# M PERFORMANCE FRONT GRILLE LH BLK *	147.15	1.00		147.15 <i>ch cut</i>
# FRT AIR DUCT *	226.55	1.00		226.55 <i>ch del</i>
# PLUG BLACK D=5MM *	0.90	7.00		6.30 <i>ch del</i>
# SENSOR WIRE FOR SMART OPENER TOP *	42.10	1.00		42.10 <i>ch cut</i>
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50 <i>ch cut</i>
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85 <i>ch ds</i>
RR RH LIGHT IN TRUNK LID	338.00	1.00		338.00
CONDENSER AIR CONDITIONING	1,028.45	1.00		1,028.45
BLIND RIVET AVIBVLB	0.55	40.00		22.00
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N4	0.55	40.00		22.00
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85
(S/L) SEAM SEAL 300ML	33.80	1.00		33.80

SUPPLEMENTARY ITEMS

Total Labour:	14,790.00
Total Parts:	11,494.85
Total Labour & Parts:	26,284.85
Deduction for Excess:	0.00
Total Repair Costs less Excess:	26,284.85
GST @7%:	1,839.94
Grand Total:	28,124.79

Handwritten signature/initials

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018		08 Mar 2018 15:11 Edit Adj Rpt	S\$26,284.85 Edit Estimates	S\$26,284.85 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN HAN WEI @ CHEN HANWEI , ID: S7921853G, Tel: +6597268629, Email: ALANTAN2306@GMAIL.COM									
Main Claimant: Tony Tan Kia Meng , ID: S1827360H									
Vehicle Reg. No.:	SDD2112D	Date of Loss:	05/03/2018 17:00 - :59 [50 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 551588	Policy/Cover Note No.:	A29067326QMY (Comprehensive) Coverage: 02/01/2018 - 29/01/2019						
Vehicle Reg. No. (Insured):	SLV1229T	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/04/2018]								
Driver/Custodian (Insured):	TAN HAN WEI @ CHEN HANWEI (38 / Male), NRIC: S7921853G, Tel: +6597268629								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDD2112D (551588)

[SLV1229T]

TP

Tony Tan Kia Meng

Mar 5 2018 5:00PM

[TAN HAN WEI @ CHEN HANWEI]

Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

1 per page
 ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/03/18 15:08	Accident Statement From: OD - Reg. No: SLV1229T, Claimant: TAN HAN WEI @ CHEN HANWEI	 Load HTM	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 16:38	Adjuster Immediate Advice	 Load HTM	☒

Photos/Images

3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/07/18 11:26	Odometer Reading	 Load JPG	☒
2	02/07/18 11:26	Chassis Number	 Load JPG	☒
3	02/07/18 11:26	General View	 Load JPG	☒
4	02/07/18 11:26	General View	 Load JPG	☒
5	02/07/18 11:26	General View	 Load JPG	☒
6	02/07/18 11:26	General View	 Load JPG	☒
7	02/07/18 11:26	General View	 Load JPG	☒
8	02/07/18 11:26	General View	 Load JPG	☒
9	02/07/18 11:27	General View	 Load JPG	☒
10	02/07/18 11:27	General View	 Load JPG	☒
11	02/07/18 11:27	General View	 Load JPG	☒
12	02/07/18 11:27	General View	 Load JPG	☒
13	02/07/18 11:27	General View	 Load JPG	☒
14	02/07/18 11:27	General View	 Load JPG	☒
15	02/07/18 11:27	General View	 Load JPG	☒
16	02/07/18 11:27	General View	 Load JPG	☒
17	02/07/18 11:27	General View	 Load JPG	☒
18	02/07/18 11:27	General View	 Load JPG	☒
19	02/07/18 11:27	General View	 Load JPG	☒
20	02/07/18 11:27	General View	 Load JPG	☒
21	02/07/18 11:27	General View	 Load JPG	☒
22	02/07/18 11:27	General View	 Load JPG	☒
23	02/07/18 11:27	General View	 Load JPG	☒
24	02/07/18 11:27	General View	 Load JPG	☒
25	02/07/18 11:27	General View	 Load JPG	☒
26	02/07/18 11:27	General View	 Load JPG	☒
27	02/07/18 11:27	General View	 Load JPG	☒
28	02/07/18 11:27	General View	 Load JPG	☒
29	02/07/18 11:27	General View	 Load JPG	☒
30	02/07/18 11:27	General View	 Load JPG	☒
31	02/07/18 11:27	General View	 Load JPG	☒
32	02/07/18 11:27	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	02/07/18 11:27	General View	 Load JPG	☒
34	02/07/18 11:27	General View	 Load JPG	☒
35	02/07/18 11:27	General View	 Load JPG	☒
36	02/07/18 11:27	General View	 Load JPG	☒
37	02/07/18 11:27	General View	 Load JPG	☒
38	02/07/18 11:27	General View	 Load JPG	☒
39	02/07/18 11:27	General View	 Load JPG	☒
40	02/07/18 11:27	General View	 Load JPG	☒
41	02/07/18 11:27	General View	 Load JPG	☒
42	02/07/18 11:27	General View	 Load JPG	☒
43	02/07/18 11:27	General View	 Load JPG	☒
44	02/07/18 11:27	General View	 Load JPG	☒
45	02/07/18 11:27	General View	 Load JPG	☒
46	02/07/18 11:27	General View	 Load JPG	☒
47	02/07/18 11:27	General View	 Load JPG	☒
48	02/07/18 11:27	General View	 Load JPG	☒
49	02/07/18 11:27	General View	 Load JPG	☒
50	02/07/18 11:27	General View	 Load JPG	☒
51	02/07/18 11:27	General View	 Load JPG	☒
52	02/07/18 11:27	General View	 Load JPG	☒
53	02/07/18 11:27	General View	 Load JPG	☒
54	02/07/18 11:27	General View	 Load JPG	☒
55	02/07/18 11:27	General View	 Load JPG	☒
56	02/07/18 11:27	General View	 Load JPG	☒
57	02/07/18 11:27	General View	 Load JPG	☒
58	02/07/18 11:27	General View	 Load JPG	☒
59	02/07/18 11:27	General View	 Load JPG	☒
60	02/07/18 11:27	General View	 Load JPG	☒
61	02/07/18 11:27	General View	 Load JPG	☒
62	02/07/18 11:27	General View	 Load JPG	☒
63	02/07/18 11:27	General View	 Load JPG	☒
64	02/07/18 11:27	General View	 Load JPG	☒
65	02/07/18 11:27	General View	 Load JPG	☒
66	02/07/18 11:27	General View	 Load JPG	☒
67	02/07/18 11:27	General View	 Load JPG	☒
68	02/07/18 11:27	General View	 Load JPG	☒
69	02/07/18 11:27	General View	 Load JPG	☒
70	02/07/18 11:27	General View	 Load JPG	☒
71	02/07/18 11:27	General View	 Load JPG	☒
72	02/07/18 11:27	General View	 Load JPG	☒
73	02/07/18 11:27	General View	 Load JPG	☒
74	02/07/18 11:27	General View	 Load JPG	☒
75	02/07/18 11:27	General View	 Load JPG	☒
76	02/07/18 11:27	General View	 Load JPG	☒
77	02/07/18 11:27	General View	 Load JPG	☒
78	02/07/18 11:27	General View	 Load JPG	☒
79	02/07/18 11:27	General View	 Load JPG	☒
80	02/07/18 11:27	General View	 Load JPG	☒
81	02/07/18 11:27	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	02/07/18 11:27	General View		☒
83	02/07/18 11:27	General View		☒
84	02/07/18 11:27	General View		☒
85	02/07/18 11:27	General View		☒
86	02/07/18 11:27	General View		☒
87	02/07/18 11:27	Reinspection Photo		☒
88	02/07/18 11:27	Reinspection Photo		☒
89	02/07/18 11:27	Reinspection Photo		☒
90	02/07/18 11:27	Reinspection Photo		☒
91	02/07/18 11:27	Reinspection Photo		☒
92	02/07/18 11:27	Reinspection Photo		☒
93	02/07/18 11:27	Reinspection Photo		☒
94	02/07/18 11:27	Reinspection Photo		☒
95	02/07/18 11:27	Reinspection Photo		☒
96	02/07/18 11:27	Reinspection Photo		☒
97	02/07/18 11:27	Reinspection Photo		☒
98	02/07/18 11:27	Reinspection Photo		☒
99	02/07/18 11:27	Reinspection Photo		☒
100	02/07/18 11:27	Reinspection Photo		☒
101	02/07/18 11:27	Reinspection Photo		☒
102	02/07/18 11:27	Reinspection Photo		☒
103	02/07/18 11:27	Reinspection Photo		☒
104	02/07/18 11:27	Reinspection Photo		☒
105	02/07/18 11:27	Reinspection Photo		☒
106	02/07/18 11:27	Reinspection Photo		☒
107	02/07/18 11:27	Reinspection Photo		☒
108	02/07/18 11:27	Reinspection Photo		☒
109	02/07/18 11:27	Reinspection Photo		☒
110	02/07/18 11:27	Reinspection Photo		☒
111	02/07/18 11:27	Reinspection Photo		☒
112	02/07/18 11:27	Reinspection Photo		☒
113	02/07/18 11:27	Reinspection Photo		☒
114	02/07/18 11:27	Reinspection Photo		☒
115	02/07/18 11:27	Reinspection Photo		☒
116	02/07/18 11:27	Reinspection Photo		☒
117	02/07/18 11:27	Reinspection Photo		☒
118	02/07/18 11:27	Reinspection Photo		☒
119	02/07/18 11:27	Reinspection Photo		☒
120	02/07/18 11:27	Reinspection Photo		☒
121	02/07/18 11:27	Reinspection Photo		☒
122	02/07/18 11:27	Reinspection Photo		☒
123	02/07/18 11:27	Reinspection Photo		☒
124	02/07/18 11:27	Reinspection Photo		☒
125	02/07/18 11:27	Reinspection Photo		☒
126	02/07/18 11:27	Reinspection Photo		☒
127	02/07/18 11:27	Reinspection Photo		☒
128	02/07/18 11:27	Reinspection Photo		☒
129	02/07/18 11:27	Reinspection Photo		☒
130	02/07/18 11:27	Reinspection Photo		☒
131	02/07/18 11:27	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
132	02/07/18 11:27	Reinspection Photo	 Load JPG	☒
133	02/07/18 11:27	Reinspection Photo	 Load JPG	☒
134	02/07/18 11:27	Reinspection Photo	 Load JPG	☒
135	02/07/18 11:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/03/18 15:16	SDD2112D E-FILE REPORT	 Load PDF	
2	08/03/18 15:19	Estimate	 Load PDF	
3	08/03/18 15:19	Survey Agree on SJE - LKK	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/07/18 12:25	SUPPLEMENTART PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004500/QD3Q2

Date: 10/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29067326QMY
 Claimant Vehicle No: SDD2112D Insured Vehicle No: SLV1229T
 Date of Loss: 05/03/2018 Nature of Claim: TP Claim No: 551588

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDD2112D
 Make & Model: BMW 528i, 2.0 L (A) Engine No: A0460666N20B20A
 Reg. Date: 31/12/2013 (Man. Year: 2013) Chassis No: WBA5A52030D284923
 Colour: Black Odometer: 62969 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/40 R18 Rear Tyre Size: 275/40 R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,079.50	11,974.85	14,104.65	54.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,949.00	14,310.00	5,639.00	28.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	46,028.50	26,284.85	19,743.65	42.89
+ GST 7.00/7.00% (S\$)	3,222.00	1,839.94	1,382.06	42.89
Nett Amount (S\$)	49,250.50	28,124.79	21,125.71	42.89

INSPECTION

Date of Assignment: 08/03/2018
 Date Inspected: 13/03/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 15.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2018)
Parts: 143	BMW 528i 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDD2112D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT EMBOSS NUMBER PLATE (SPECIAL TYPE)	Cut	165.00 FS	*165.00 FS
2	1	*REAR EMBOSS NUMBER PLATE (SPECIAL TYPE)	Cracked	165.00 FS	*165.00 FS
3	1	*SUNDRIES	Necessary	150.00 FS	*150.00 FS
4	1	*CROSS MEMBER TRUNK FLOOR REAR	Not Necessary	116.60 FS	*- FS
5	1	*END PIECE FOR CARGO AREA FLOOR	Not Necessary	53.00 FS	*- FS
6	1	*TAIL END PANEL	Bent	817.30 FS	*817.30 FS
7	1	*BOOTLID	Bent	1,602.40 FS	*1,602.40 FS
8	1	*FRT BUMPER CARRIER	Bent	684.75 FS	*684.75 FS
9	1	*FRT SHOCK ABSORBER	Deformed	48.00 FS	*48.00 FS
10	1	*FRT BUMPER PANEL PRIMED (M/PDC)	Deformed	1,533.10 FS	*1,533.10 FS
11	1	*SET OF MOUNT	Not Necessary	62.60 FS	*- FS
12	1	*RR BUMPER LH MOUNT	Not Necessary	142.55 FS	*- FS
13	1	*RR BUMPER RH MOUNT	Not Necessary	142.55 FS	*- FS
14	1	*COVER BUMPER REAR (M)	Deformed	174.70 FS	*174.70 FS
15	1	*GUIDE CENTRE REAR (M)	Deformed	75.05 FS	*75.05 FS
16	1	*GUIDE BOTTOM CENTRE (M)	Deformed	46.85 FS	*46.85 FS
17	1	*COVERING TOWING RR PRIMED (M)	Not Necessary	55.70 FS	*- FS
18	1	*REAR BUMPER PANEL PRIMED (M PDC)	Deformed	1,650.65 FS	*1,650.65 FS
19	1	*ADAPTER (M)	Deformed	64.70 FS	*64.70 FS
20	1	*FRT LH GRILLE (BASIS)	Not Necessary	120.50 FS	*- FS
21	1	*FRT RH GRILLE (BASIS)	Not Necessary	120.50 FS	*- FS
22	2	*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
23	1	*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
24	1	*MODEL LETTERING 528i	Necessary	62.55 FS	*62.55 FS
25	1	*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
26	1	*TRUNK LID LOCK TOP	Bent	425.35 FS	*425.35 FS
27	1	*FRT AIR DUCT (FRONT PANEL)	Not Necessary	226.55 FS	*- FS
28	1	*FRAME (M)	Not Necessary	64.60 FS	*- FS
29	1	*AIR DUCT FRT BOTTOM (M)	Not Necessary	51.50 FS	*- FS
30	1	*LH HEADLIGHT PED TECHNOLOGY	Not Necessary	4,201.60 FS	*- FS
31	1	*RH HEADLIGHT PED TECHNOLOGY	Not Necessary	4,201.60 FS	*- FS
32	1	*REAR LH REFLECTOR (M)	Not Necessary	35.20 FS	*- FS
33	1	*REAR RH REFLECTOR (M)	Not Necessary	35.20 FS	*- FS
34	1	*RR LH LIGHT IN SIDE PANEL	Not Necessary	572.25 FS	*- FS
35	1	*RR RH LIGHT IN SIDE PANEL	Not Necessary	572.25 FS	*- FS
36	1	*RR LH LIGHT IN TRUNK LID	Not Necessary	338.00 FS	*- FS
37	1	*RR RH LIGHT IN TRUNK LID	Cracked	338.00 FS	*338.00 FS
38	1	*CONDENSER AIR CONDITIONING	Bent	1,028.45 FS	*1,028.45 FS
39	8	*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	40.40 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	8		*BUMPER PDC SENSOR (A90 SOPHISTOGRAU)	Not Necessary	2,950.40 FS	*- FS
41	1		*BLIND RIVET AVIBVLB (40 PCS)	Necessary	22.00 FS	*22.00 FS
42	2		*SCREW (SF PLUS M5X15)	Not Necessary	1.10 FS	*- FS
43	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
44	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
45	1		*PUNCH RIVET N4 (40 PCS)	Necessary	22.00 FS	*22.00 FS
46	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
47	2		*BLIND RIVET	Necessary	2.50 FS	*2.50 FS
48	6		*BLIND RIVET	Necessary	7.50 FS	*7.50 FS
49	2		*TAILPIPE TIP BLACK CHROME	Cut	315.90 FS	*315.90 FS
50	1		*PRIMED COATED LH FLAP (M)	Deformed	55.70 FS	*55.70 FS
51	4		*EXPANDING NUT	Necessary	4.00 FS	*4.00 FS
52	1		*RR BUMPER CARRIER	Bent	714.25 FS	*714.25 FS
53	1		*ADHESIVE TAPE	Necessary	48.60 FS	*48.60 FS
54	1		*SUPPORT LH	Deformed	18.40 FS	*18.40 FS
55	1		*SUPPORT RH	Deformed	18.40 FS	*18.40 FS
56	1		*CONNECTION TOP FRT	Deformed	155.35 FS	*155.35 FS
57	1		*M PERFORMANCE FRONT GRILLE RH BLK	Cut	147.15 FS	*147.15 FS
58	1		*M PERFORMANCE FRONT GRILLE LH BLK	Cut	147.15 FS	*147.15 FS
59	1		*FRT AIR DUCT	Deformed	226.55 FS	*226.55 FS
60	7		*PLUG BLACK D=5MM	Necessary	6.30 FS	*6.30 FS
61	1		*SENSOR WIRE FOR SMART OPENER TOP	Cut	42.10 FS	*42.10 FS
62	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Cut	40.50 FS	*40.50 FS
63	1		*CONTROL UNIT SMART OPENER	Distorted	468.85 FS	*468.85 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	26,079.50	11,974.85
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AIR DUCT (FRONT PANEL) ,REAR BUMPER ,BOOT LID ,TAIL PANEL ,TRUNK FLOOR EXTENSION ,REPAIR TRUNK FLOOR AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	11,050.00	8,500.00
2	PAINTING FRONT BUMPER ,REAR BUMPER ,BOOT LID ,TAIL PANEL ,AND TRUNK FLOOR	New	3,350.00	3,015.00
3	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM ,TOP UP FREON GAS AND CHECK FOR LEAK (FOR ALL MODELS EXCEPT FOR 7 SERIES)	New	1,003.00	852.00
4	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECK FOR LEAK	New	531.00	451.00
5	TO MOUNT ACCIDENT VEHICLE ON SPEED BENCH TO FACILITATE RE-ALIGNMENT OF BODY /CHASSIS ACCORDANCE WITH BMW SPECIFICATION	New	664.00	0.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
7	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	0.00
8	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT ,TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	561.00
9	TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	1,062.00	0.00
10	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
11	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
12	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
Gross Labour Cost (S\$)			19,949.00	14,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >