

ASS. REC. BY:

REF:

CS/CTI/8004304/R1rd3

Special Instructions:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Jawyn Tay

of

CTI

Date/Time: 8/3/18 @ 9:02am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KT 9274G

Insured:

SJE 9435A

at Workshop m/s:

Performance Motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

DMPCSN 308 7981701

Claim No:

8NM18D01226C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/3/2018

CA / REV / REP. / REV 24 HRS

lwp

Date/Time:

9:18am 8/3/18

Person Contacted:

Caroline

H.O.D. Endorsement:

Vehicle IN (OUT)

Date/Time	Action/Instruction	Estimate
	8KT 9274G -	
	SJE 9435A -	
	Confirm 3481.20 @ 3 days	
	(Red: \$2633.80, 43%)	

GIA / PR Seen:

Conditions:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lwp

Vehicle: IN / OUT

Date:

Person Contacted:

D.O.A.

65/03/18

D.O.I.

02/04/18

Survey held at:

Performance CG

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 3 AUG 2018

Date/Time: File Pass to?

☐

Preli. Report

Days Of Repair:

3

11 typist

☒

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Transportation

Date/Time: File Return to?

2:

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech Insp \$

☐

Weekend \$

\$ \$ + RC \$

Photo

Others

Report Format:

TP

Lump Sum / I.B.I. \$

3481.20

TOTAL

Janice Lee (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Friday, May 25, 2018 4:55 PM
To: Rasul (LKKAUTO); SUR
Subject: FINAL REPORT / SKT9274G
Attachments: Final Report SKT9274G.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00
Total Parts : 1,467.20
Total Labour & Parts : 3,481.20

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018		08 Mar 2018 09:02 Edit Adj Rpt	S\$3,481.20 Edit Estimates	S\$3,481.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	ONG KHUAN WEE , ID: S7919542A								
Main Claimant:	TAY BOON TECK , ID: S1694452A								
Vehicle Reg. No.:	SKT9274G	Date of Loss:	05/03/2018 07:00 - :59 [32 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01226C02	Policy/Cover Note No.:	DMPCSN3087981701 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJE9435A	Policy No. (Claimant):	VPA/P1633658						
		Excess:	S\$0.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/03/2018]								
Driver/Custodian (Insured):	SHARON SZTO HWEI FUNG (39 / Female), NRIC: S7897197E, Tel: +6596177841								
Adj Asg. Remarks:	EST \$6543.05, CASE WITH SJE								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT9274G (SNM18D01226C02)
[SJE9435A]
TP
TAY BOON TECK
Mar 5 2018 7:00AM
[ONG KHUAN WEE]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	05/03/18 16:12	Accident Statement		Load HTM	
2	06/03/18 09:25	Addendum Sheet		Load TIF	
3	06/03/18 09:25	Accident Statement Addm. #1		Load HTM	

Photos/Images

3 per page

No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	05/03/18 16:10	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
2	05/03/18 16:10	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
3	05/03/18 16:10	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
4	05/03/18 16:10	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
5	05/03/18 16:10	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
2	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
3	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
4	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
5	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
6	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
7	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
8	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
9	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
10	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
11	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
12	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
13	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
14	31/08/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
15	31/08/18 14:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/03/18 09:01	REPAIR EST		Load PDF	
2	08/03/18 09:01	OI GIA REPORT		Load PDF	

No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	05/03/18 16:09	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	05/03/18 16:12	Accident Statement		Load HTM	
2	06/03/18 09:25	Addendum Sheet		Load TIF	
3	06/03/18 09:25	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	05/03/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	05/03/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	05/03/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	05/03/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	05/03/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	05/03/18 16:09	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118004504/R1RD3Q2

Date: 06/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3087981701

Claimant Vehicle
No: SKT9274GInsured Vehicle
No: SJE9435A

Date of Loss: 05/03/2018

Nature of Claim: TP

Claim
No: SNM18D01226C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT9274G

Make & Model: BMW 520i, 2.0 (A)

Reg. Date: 26/06/2015 (Man. Year: 2014)

Colour: Black

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: B7610879N20B20B

Chassis No: WBA5A32050D828424

Odometer: 41181 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,929.00	1,547.20	1,381.80	47.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,186.00	1,934.00	1,252.00	39.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,115.00	3,481.20	2,633.80	43.07
+ GST 7.00/7.00% (S\$)	428.05	243.68	184.37	43.07
Nett Amount (S\$)	6,543.05	3,724.88	2,818.17	43.07

INSPECTION

Date of Assignment: 08/03/2018

Date Inspected: 02/04/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2018)
Parts: 143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9274G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNRIES	Necessary	80.00 FS	*80.00 FS
2	1		*SET OF MOUNT	Serviceable	62.60 FS	*- FS
3	1		*RR BUMPER CARRIER	Serviceable	714.25 FS	*- FS
4	1		*REAR BUMPER CENTRE GUIDE	Serviceable	60.05 FS	*- FS
5	1		*RR LH MOUNT	Serviceable	198.30 FS	*- FS
6	1		*RR RH MOUNT	Serviceable	198.30 FS	*- FS
7	1		*REAR BUMPER PRIMED (PDC)	Torn	1,467.20 FS	*1,467.20 FS
8	1		*REAR BUMPER TOWING EYE COVER PRIMED	Repeated	46.45 FS	*- FS
9	1		*REAR BUMPER TOWING EYE COVER PRIMED	Serviceable	46.45 FS	*- FS
10	1		*REAR RH REFLECTOR	Serviceable	35.20 FS	*- FS
11	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	20.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 2,929.00 1,547.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	1,700.00	850.00
2	TO PAINT REAR BUMPER	New	1,038.00	934.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			3,186.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >