

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7185T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID CRDI PLATE (CONSISTENT)	NECESSARY	41.00	41.00
1	BOOT LID LAMP (LH) (CONSISTENT)	GRAZED	556.80	556.80
1	BOOTLID MOULDING (CONSISTENT)	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM (CONSISTENT)	NECESSARY	41.00	41.00
1	BOOTLID LOWER GARNISH (CONSISTENT)	TO REPAIR SEE LABOUR	398.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$180.00 (CONSISTENT)	SERVICEABLE	360.00	-
1	REAR BUMPER SIDE BRACKET, LH (CONSISTENT)	SERVICEABLE	49.00	-
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE (CONSISTENT)	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER (CONSISTENT)	СИТ	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (LH) (CONSISTENT)	CRACKED	32.00	32.00
1	TAIL LAMP (LH) (CONSISTENT)	CRACKED	565.60	565.60
	LESS 20% DISCOUNT		-725.35	-417.40
			2,901.40	1,669.60
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			185.70	185.70
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID LOWER GARNISH.		500.00	200.00
	SPRAY PAINTING CHARGE.		400.00	360.00
	WIRING CHARGE.		50.00	20.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	20.00
	TOWING.	NOT NECESSARY	50.00	
			1,120.00	600.00
	GRAND TOTAL		4,207.10	2,455.30

Report Ref No. CC4/ASM18004520/K1pa3s2





RECOMMENDED COST OF REPAIRS 2,455.30

Report Ref No. CC4/ASM18004520/K1pa3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

mont

HO LEONG CHUAN

Automotive Assessor