

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7185T

DATE 8/3/2018 10:34

MAKE :

MODEL : HYUNDAI i40

Jumani

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid CRDI Plate — <i>new</i>			\$ 41.00
	Boot Lid Lamp (LH) — <i>new</i>			\$ 556.80
	Bootlid Moulding <i>x 500</i>			\$ 85.00
	Bootlid i40 Emblem — <i>new</i>			\$ 41.00
	Bootlid Lower Garnish <i>x 2</i>			\$ 398.00
	Rear Bumper — <i>new</i>			\$ 603.60
	Rear Bumper Reinforcement <i>new</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>new</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket, LH <i>new</i>			\$ 49.00
	Rear Bumper Clips — <i>new</i>			\$ 22.00
	Rear Bumper Sponge <i>new</i>			\$ 143.40
	Rear Bumper Under Cover — <i>new</i>			\$ 225.00
	Rear Bumper Reflector Lamp (LH) — <i>new</i>			\$ 32.00
	Tail Lamp (LH) — <i>new</i>			\$ 565.60
	SUB TOTAL			\$ 3,626.75
	LESS 20%			\$ 725.35
	DISCOUNTED TOTAL			\$ 2,901.40
	Rear Bumper Reverse Sensor — <i>new</i>			\$ 135.70 Nett
	Rear Bumper Rubber Mat — <i>new</i>			\$ 50.00 Nett
				\$ 185.70
	Labour Charge			200
	Panel Beating			\$ 500.00
	Spray Painting Charge			\$ 400.00 <i>560</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOWING			\$ 50.00 <i>tin</i>
	TOTAL LABOUR			\$ 1,070.00
	ESTIMATE TOTAL			\$ 4,157.10

Kahin 1/10/18

8/3/18 15:00 hrs

2 days

PIP

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier entry must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: 07/03/18 Time Received: 0545 AM		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	
2. ☐ New ☐ SPARK Kakis Name of Customer : Contact No. : 8186 1783 Vehicle No. : SHC7185T Make / Model / Colour : i40 Email :		4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up	
7. Location: 138 Bedok North Street 2		6. Parts Replaced/Remarks:	
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☐ Accident ☐ Engine Stalled ☐ Return Taxi *Accident	
10. Odometer Reading : Fuel Level : F 1/4 1/2 3/4 E		11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested	
Job Attended			
12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☒ GAO ☐ TZ ☐ YISHUN ☐ OTHERS TOWING Name of Driver : Darren Vehicle No. : YM8875A Time Dispatch : 0545 AM Time of Arrival : 0605 AM Time Completed : 0632 AM		 #: Cracked X: Dented /: Spatched O: Missing Signature of Customer	
Cash Invoice Details (if applicable)			
13. Cash Invoice No. :			
Customer Acknowledgement			
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
07/03/18 Date		0605AM Time	
		Signature of Customer	
14. WORKSHOP			
Name of Attending Staff/Guard		Date & Time of Arrival	
		Signature of Attending Staff/Guard	