



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

COMLAW LLC*

Ref : CS/LAW18004551/tb

64 CECIL ST #06-01 IOB BLDG SINGAPORE
049711

Date : 09-03-2018



Code : L050

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	JAH 1469	Veh. Inspected	SJF 8641Y
Policy No.		Coverage (\$)	0.00
Claim No.	CLS.2017.214784.rd	Excess (\$)	0.00
Assign From	CHUA LI SUAN	Assign Date	05/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/10/2016	Inspection Date	13/03/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Chua Li Suan <cls@comlaw.com.sg>
Sent: Monday, 5 March, 2018 5:15 PM
To: assignments@lkkauto.com
Subject: new matter- RE-INSPECTION OF SJF 8641Y (OUR REF CLS.2017.214784.rd)
Attachments: SURVEY REPORT.pdf; COLOUR PHOTOS 1.pdf; COLOUR PHOTOS 2.pdf; REPAIR BILL.pdf; ACCIDENT STATEMENT OF SJF 8641Y.pdf; ACCIDENT REPORT OF JAH 1469.pdf; IMG_4172.jpg; thumbnail_IMG_4173.jpg; IMG_4167.jpg; IMG_4169.jpg; IMG_4178.jpg

Dear Sirs

1. We act for Malaysian Motor Insurance Pool, the insurers of JAH 1469 which was involved in a road accident on 18 October 2016. Our clients are facing a claim by the owner of SJF 8641Y for repair costs and loss of use.

2. We refer to our Ms Rohana's telephone conversation with your Ms Catherine on 5 March 2018 and confirm that an appointment has been fixed for your surveyor to re-inspect the above vehicle on Tuesday 13 March 2018 at 12.00 pm at Hua Meng Spray Painting at 1 Kaki Bukit Avenue 6 #01-61 Singapore 417883 (telephone no. 67465519 (workshop), contact person Ms June).

3. We attach herewith copies of the following documents for your consideration in putting up your report :-
a. Survey report of PAL'S Appraiser Pte Ltd dated 19 December 2016 and 17 pages of colour copied photographs of SJF 8641Y.
b. Repair Bill of Hua Meng Spray Painting Workshop dated 19 December 2016.
c. Accident Statement of driver SJF 8641Y.
d. Police report of driver JAH 1469.
e. Photos of the accident scene.

4. We shall be obliged if you will carry out the re-inspection of SJF 8641Y and let us have your report as soon as possible.

5. We agree to pay your fees on our clients' behalf.

Warm regards
Ms Chua Li Suan
DID: 6506 9132

ComLaw LLC
64 Cecil St #06-01
IOB Building
Singapore 049711

MSME16131281 / SNE Motor Pte Ltd - Kak Bukit
ENTRY DATE & TIME 18/10/2016 17:47

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2016 17:42
Date Of Accident	18/10/2016 13:15
Exact Location Of Accident	KAKI BUKIT RD 2
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF8641Y
Insured/Policyholder	
Name Of Registered Owner	HENG PENG YONG
NRIC No	S7936746Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90476911
Alternative Phone No	Office-90476911
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	Liberty Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SI15V18889VPC/R00
Cover Note Number	
Driver	
Name of Driver	HENG PENG YONG
NRIC No	S7936746Z
Date Of Birth	13/11/1979
Occupation	Indoor
Date Of Driving Pass	20/08/2005
Driving Experience	11 Years And 1 Month
Gender	Male
Mobile Number	(Local) +65-90476911
Fax Number	
Contact Number	Office-90476911
E-Mail Address	NOEMAIL

Address	5 TAMPINES ST 85 #01-20
Postcode	528585
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-
General Information of the Accident	
Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry
Other Information	
Was any foreign vehicle involved in this accident?	Yes
Foreign Vehicle Registration Number	JAH1469 (Commercial Vehicle)
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1
Details of Police Action	
Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Traffic Police Division Hq
Police Station Address	ROAD, 10 Ubi Avenue 3 , POSTCODE: 408665 , COUNTRY Singapore
Police Station Contact	TEL NO: 65470000 - FAX NO.
Was notice of intended Prosecution given?	No
If Yes, against whom?	
Circumstances of Accident	
REFER TO POLICE REPORT: T/20161018/2118.	
Are accident photos available for attachment?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JAH1469
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	WIMAN A/L PAPPOR
NRIC/Passport Number	520624-05-5253
Contact Number	91404106
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	
Details of Witness	
Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBF2773J
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SJZ2569H

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE D

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan #2 Pg.1

Describe Circumstances of the Accident

Please refer to the police report 81K/8101902/L London 2/2016/18/218

Lined area for describing the accident circumstances.

Declaration

We declare the foregoing particulars are true in every respect.

[Signature]

Motorist's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20161018/2118

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20161018/2118

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/10/2016 15:48		Vide Report No.: G/20161018/0192		Station Diary No.:	
Informant's Particulars					
Name of Informant: HENG PENG YONG			Address: APT BLK 5 TAMPINES STREET 85 #01-20 Q BAY RESIDENCES SINGAPORE 528565		
ID Type / ID No.: NRIC NO / S7936746Z			Contact No.: Home/Office: Mobile: 90476911		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 36	Date of Birth: 13/11/1979	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: ARMY			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/10/2016 13:15	Type of Location: Straight Road	
Location: Along Road 1 KAKI BUKIT ROAD 2				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: CHAIN COLLISION			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
GBF2773J	Van					0
JAH1469	Lorry					0
SJF8641Y	Car					0
SJZ2569H	Car					0



**SINGAPORE
POLICE FORCE**



T/20161018/2118

2 of 3

Report No T/20161018/2118

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Brief Details.

As mentioned above date, time and locations.

I came back to my parked vehicle at around 1300 hrs and discovered that my front portion had collided onto SJZ2569H rear due to impact from a lorry JAH1469's front left portion which had collided onto my rear right side. I have the in-car camera footage of the incident scene. That's all.



SINGAPORE
POLICE FORCE



T/20161018/2118

3 of 3

Report No T/20161018/2118

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / LOW CHENG GUI
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Staff Sgt IRMAN BIN MOHAMAD SAID Contact No.: 65476385

Signature Of Informant:
Date/Time: 18/10/2016 15.48
Classification Of Case:

Authentication Stamp
NP168



**SINGAPORE
POLICE FORCE**



T/20161018/2147

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20161018/2147

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/10/2016 18:22	Vide Report No.: G/20161018/0192	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: WIMAN A/L PAPPOR			Address: 32 MAMBAU HEIGHTS 70300 SEREMBAN NEGERI SEMBILAN		
ID Type / ID No.: PASSPORT / A36159302			Contact No.: Home/Office: Mobile: 91404106		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 64	Date of Birth: 24/06/1952	Type of Informant: Rider		
Race:			Language: English	Institution / School Name:	
Occupation: Lorry driver			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/10/2016 13:20	Type of Location: Straight Road
Location: Along Road 1 KAKI BUKIT ROAD 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: CHAIN COLLISION				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
GBF2773J	Van					0
JAH1469	Lorry					0
SJF8641Y	Car					0
SJZ2569H	Car					0

Certified True Copy
pursuant to Sec. 78 of the
Evidence Act. Cap 97A

Yet Hwee Choo
CSO Traffic Police
Date :

18 NOV 2016



SINGAPORE
POLICE FORCE



T/20161018/2147

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20161018/2147

CONTINUATION OF REPORT

Brief Details.

AS MENTIONED ABOVE DATE, TIME AND LOCATIONS.

I WAS ON LEFT SIDE OF ONE LANE, 2 WAY RD ALONG KAKI BT RD 1 TOWARDS KAKI BT AVE 1 (SEPARATED BY BROKEN WHITE LINES). I SAW AN UNKNOWN BIG M/LORRY COMING FROM OPPOSITE DIRECTION AND WAS ENCROACHING INTO MY LANE. I COULD NOT BRAKE ON TIME HENCE I SWERVED TO THE LEFT CAUSING THE CHAIN COLLISION TO THE THIRD VEHICLE GBF2773J, SECOND VEHICLE, SJF8641Y AND FIRST VEHICLE, SJZ2569H. THAT'S ALL.

Certified True Copy
pursuant to Sec. 78 of the
Evidence Act, Cap 97.

.....
Yei Hwee Choo
CSO Traffic Police
Date :

18 NOV 2016



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20161018/2147

3 of 3

Report No. T/20161018/2147

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / LOW CHENG GUI
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Staff Sgt IRMAN BIN MOHAMAD SAID Contact No.: 65476365

Signature Of Informant:
Date/Time: 18/10/2016 18:22
Classification Of Case:

Certified True Copy
pursuant to Sec. 78 of the
Evidence Act, Cap 97.

Authentication Stamp
NP168

.....
Yei Hwee Choo
CSO Traffic Police
Date :

18 OCT 2016



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No : 254678/00M



Your Ref :

19/12/2016

Our Ref :

Date:

VEHICLE NO :SJF 8641 Y
MAKE / MODEL :HONDA VEZEL
NAME : HENG PENG YONG
ADDRESS :BLK 5 TAMPINES ST 86
#01-20
S 528585

FINAL REPAIR BILL FOR VEHICLE NO. SJF 8641 Y

LIST ITEMS	QTY	COST (\$\$)
Front head lamps	2	3841.4
Front outer grille	1	285
Front inner grille	1	250
Front grille chrome moulding (1set)	1	50.2
Front grille logo	1	24.1
Front bumper	1	727.5
Front bumper brackets	2	136
Front bumper fog lamps	2	479.4
Front bumper lower grille	1	90
Front bumper lower spoiler	1	230
Front bumper reinforcement	1	321.3
Front bumper set plates	2	200
Front bumper side retainers	2	47
Front support panel	1	476.2
Rear door	1	930
Rear door glass outer moulding	1	160
Rear door outer handle	1	95
Rear door rubber	1	110
Rear door frame rubber	1	100
Rear windscreen glass	1	1186
Rear windscreen inner side garnishes	2	420
Rear windscreen moulding	1	140
Rear tailgate	1	1300
Rear tailgate dampers	2	420
Rear tailgate hinges	2	110



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg No.: 254678/00M



Your Ref :

20/12/2016

Our Ref :

Date:

VEHICLE NO :SJF 8641 Y
MAKE / MODEL :HONDA VEZEL
NAME : HENG PENG YONG
ADDRESS :BLK 5 TAMPINES ST 86
#01-20
S 528585

FINAL REPAIR BILL FOR VEHICLE NO. SJF 8641 Y

LIST ITEMS	QTY	COST (\$S)
Rear tailgate inner board	1	265
Rear tailgate top spoiler	1	820
Rear tailgate logo	1	32
Rear tailgate outer garnish	1	187
Rear tailgate rubber	1	195
Rear tailgate 'VEZEL' emblem	1	75
Rear wiper motor	1	310
Rear taillamp	1	750
Rear tailgate panel	1	155
Rear end panel	1	660
Rear end panel inner garnish	1	110
Rear side bumper	1	187.4
Rear bumper	1	920
Rear bumper side retainers	2	88
Rear bumper top garnish	1	130
Rear third brake light	1	210
Rear spare tyre board	1	240
Rear spare tyre sponge	1	197.8
Rear spare tyre under cover	1	335
Rear fender	1	995
Rear fender air gate	1	60
Rear fender inner garnish	1	240.9
Rear fender inner panel	1	1100
Rear fender inner shield	1	310



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT
1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No. 254678/00M



Your Ref :

20/12/2016

Our Ref :

Date:

VEHICLE NO :SJF 8641 Y
MAKE / MODEL :HONDA VEZEL
NAME : HENG PENG YONG
ADDRESS :BLK 5 TAMPINES ST 86
#01-20
S 528585

FINAL REPAIR BILL FOR VEHICLE NO. SJF 8641 Y

LIST ITEMS

	QTY	COST (S\$)
Rear fender inner shield clip(1set)	1	30
Rear fender outer arch garnish	1	180
Rear fender inner top garnish	1	105
Rear fender chrome handle	1	150
Rear speaker panel garnish	1	280
Rear shock absorber	1	330
Rear axle	1	1350
		<u>23407.2</u>
	Less 10% Discount	2340.72
	Total	<u>21066.48</u>

SPECIAL NETT ITEMS

Front bumper clip(1set)	1	35
Front bumper sensor (1set)	1	280
Front number plate	1	50
Rear windscreen sealant	1	60
Rear tyre(Depreciation)	1	224
Rear windscreen inner seal	1	85
Rear number plate	1	50
Rear reverse sensor	1	480
	Total	<u>1264</u>



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT
 1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
 Reg. No.: 25467B/00M



Your Ref :

20/12/2016

Our Ref :

Date:

VEHICLE NO :SJF 8641 Y
 MAKE / MODEL :HONDA VEZEL
 NAME : HENG PENG YONG
 ADDRESS :BLK 5 TAMPINES ST 86
 #01-20
 S 528585

FINAL REPAIR BILL FOR VEHICLE NO. SJF 8641 Y

<u>LABOUR COST</u>	PRICE (S\$)
To provide towing service charge.	80
To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	50
To remove and refit damage parts, test for proper functioning and focus of headlamps.	50
To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	180
To remove and refit front bumper sensor.	120
To remove and refit rear bumper sensor.	120
To remove and refit rear undercarriage.	350
To check and re-adjust(Computerized) all wheel alignment.	120
To remove and refit air -con system, refill gas and test for leakages.	120
To remove and refit radiator system.	120
To remove and refit rear windscreen glass.	180



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
 Reg. No.: 254678/00M



Your Ref :

20/12/2016

Our Ref :

Date:

VEHICLE NO :SJF 8641 Y
 MAKE / MODEL :HONDA VEZEL
 NAME : HENG PENG YONG
 ADDRESS :BLK 5 TAMPINES ST 86
 #01-20
 S 528585

FINAL REPAIR BILL FOR VEHICLE NO. SJF 8641 Y

LABOUR COST

PRICE (S\$)

To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.

3500

To spray paint on the replace and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.

3500

To apply undercoating on the repaired and replaced panels for rust protection.

240

Total 8730

Grand Total 31060.48

SGD : THIRTY ONE THOUSAND SIXTY AND CENTS FORTY EIGHT ONLY

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 Kaki Bukit Singapore 417953 Tel: 8181 3802 Fax: 6747 1017
Registration No: 20100268D

Report Reference : TP / 10-16038/DY / 2016
Date of Report : 19 Dec 2016

Heng Peng Yong
Blk 5 Tampines Street 86
#01-20
Singapore 528585

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 18 Oct 2016

As per your instruction dated 19 Oct 2016 with regard to the above matter. We have carried out a physical inspection on the said vehicle SJF 8641 Y. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SJF 8641 Y
Model : Honda Vezel
Year / Capacity : 2015/1496
Chassis No : RU1-1100858
Engine No : L15B4020859
Mileage : 22198
Colour : Maroon

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	215/60 R16	Dunlop	8.00	mm	Sport
REAR	O/S	:	215/60 R16	Dunlop	8.00	mm	Sport
FRONT	N/S	:	215/60 R16	Dunlop	8.00	mm	Sport
REAR	N/S	:	215/60 R16	Dunlop	8.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 3181 8802 Fax: 6747 1017
Registration No. 20100026812

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Hua Meng Spray Painting Workshop
No. 1 Kaki Bukit Avenue 6
#01-61/34 AutoBay @ Kaki Bukit
Singapore 417883

5. Estimated normal period of repair : 25 working days to complete.
6. Enclosed number of photograph : 262 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJF 8641 Y
 Report No: TP/ 10-16038/DY / 2016

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
	<u>List Items</u>			
2	Front headlamps <i>L 12/14</i>	Damage	\$ 3841.40	\$ 3841.40 ^{1420.70} ✓ ✓
1	Front outer grille	Damage	\$ 285.00	\$ 285.00 ✓ ✓
1	Front inner grille	Damage	\$ 250.00	\$ 250.00 ✓ ✓
1	Front grille chrome moulding (1 set)	Necessary	\$ 50.20	\$ 50.20 ✓ ✓
1	Front grille logo	Necessary	\$ 24.10	\$ 24.10 X ✓ ✓
1	Front bumper	Damage	\$ 727.50	\$ 727.50 ✓ ✓
2	Front bumper brackets	Damage	\$ 136.00	\$ 136.00 X ✓ ✓
2	Front bumper fog lamps <i>RH cancelled</i>	Damage	\$ 479.40	\$ 479.40 X ✓ ✓ ^{239.70}
1	Front bumper lower grille	Damage	\$ 90.00	\$ 90.00 X ✓ ✓
1	Front bumper lower spoiler	Damage	\$ 230.00	\$ 230.00 X ✓ ✓
1	Front bumper reinforcement	Damage	\$ 321.30	\$ 321.30 X ✓ ✓
2	Front bumper set plates	Damage	\$ 200.00	\$ 200.00 X ✓ ✓
2	Front bumper side retainers	Necessary	\$ 47.00	\$ 47.00 X ✓ ✓
1	Front support panel	Damage	\$ 476.20	\$ 476.20 X ✓ ✓
1	Rear door <i>Reps</i>	Damage	\$ 930.00	\$ 930.00 X ✓ ✓
1	Rear door glass outer moulding <i>Not Rec</i>	Necessary	\$ 160.00	\$ 160.00 ✓ ✓
1	Rear door outer handle	Damage	\$ 95.00	\$ 95.00 ✓ ✓
1	Rear door rubber <i>3 new</i>	Necessary	\$ 110.00	\$ 110.00 X ✓ ✓
1	Rear door frame rubber	Necessary	\$ 100.00	\$ 100.00 X ✓ ✓
1	Rear windscreen glass	Damage	\$ 1186.00	\$ 1186.00 ✓ ✓
2	Rear windscreen inner side garnishes <i>RH</i>	Damage	\$ 420.00	\$ 420.00 X ✓ ✓ ²¹⁰
1	Rear windscreen moulding	Necessary	\$ 140.00	\$ 140.00 ✓ ✓
1	Rear tailgate	Damage	\$ 1300.00	\$ 1300.00 ✓ ✓
2	Rear tailgate dampers	Damage	\$ 420.00	\$ 420.00 ✓ ✓
2	Rear tailgate hinges	Damage	\$ 110.00	\$ 110.00 ✓ ✓
1	Rear tailgate inner board	Damage	\$ 265.00	\$ 265.00 ✓ ✓
1	Rear tailgate top spoiler	Damage	\$ 820.00	\$ 820.00 ✓ ✓
1	Rear tailgate lamp	Damage	\$ 280.00	\$ 280.00 ✓ ✓
1	Rear tailgate logo	Necessary	\$ 32.00	\$ 32.00 ✓ ✓
1	Rear tailgate outer garnish	Damage	\$ 187.00	\$ 187.00 ✓ ✓
1	Rear tailgate rubber	Necessary	\$ 195.00	\$ 195.00 ✓ ✓
1	Rear tailgate 'VEZEL' emblem	Necessary	\$ 75.00	\$ 75.00 ✓ ✓
1	Rear wiper motor	Damage	\$ 310.00	\$ 310.00 ✓ ✓
1	Rear taillamp	Damage	\$ 750.00	\$ 750.00 ✓ ✓
1	Rear taillamp panel	Damage	\$ 155.00	\$ 155.00 ✓ ✓
1	Rear end panel	Damage	\$ 660.00	\$ 660.00 X ✓ ✓
1	Rear end panel inner garnish	Damage	\$ 110.00	\$ 110.00 X ✓ ✓

List Items Sub Total \$ 15968.10 \$ 15968.10

Vehicle No: SJF 8641 Y
 Report No: TP/ 10-16038/DY / 2016

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

List Items Total c/f \$ 15968.10 \$ 15968.10

<u>List Items</u>				
1	Rear side bumper	Damage	\$ 187.40	\$ 187.40 ✓
1	Rear bumper	Damage	\$ 920.00	\$ 920.00 ✓
2	Rear bumper side retainers	Necessary	\$ 88.00	\$ 88.00 ✓
1	Rear bumper top garnish	Damage	\$ 130.00	\$ 130.00 ✓
1	Rear third brake light	Damage	\$ 210.00	\$ 210.00 ✓
1	Rear spare tyre board	Damage	\$ 240.00	\$ 240.00 ✓
1	Rear spare tyre sponge	Damage	\$ 197.80	\$ 197.80 ✓
1	Rear spare tyre under cover <i>NSP New</i>	Damage	\$ 335.00	\$ 335.00 ✓
1	Rear fender	Damage	\$ 995.00	\$ 995.00 ✓
1	Rear fender air gate	Damage	\$ 60.00	\$ 60.00 ✓
1	Rear fender inner garnish	Damage	\$ 240.90	\$ 240.90 ✓
1	Rear fender inner panel <i>Repair</i>	Damage	\$ 1100.00	\$ 1100.00 ✓
1	Rear fender inner shield	Damage	\$ 310.00	\$ 310.00 ✓
1	Rear fender inner shield clip (1 set)	Necessary	\$ 30.00	\$ 30.00 ✓
1	Rear fender outer arch garnish	Damage	\$ 180.00	\$ 180.00 ✓
1	Rear fender inner top garnish	Damage	\$ 105.00	\$ 105.00 ✓
1	Rear fender chrome handle	Damage	\$ 150.00	\$ 150.00 ✓
1	Rear speaker panel garnish	Damage	\$ 280.00	\$ 280.00 ✓
1	Rear shock absorber <i>Not New</i>	Damage	\$ 330.00	\$ 330.00 ✓
1	Rear axle	Damage	\$ 1350.00	\$ 1350.00 ✓
			\$ 23407.20	\$ 23407.20
	<i>18066.30</i>	Discount 10.0%	\$ 2340.72	\$ 2340.72
	<i>1A453.04</i>		\$ 21066.48	\$ 21066.48

<u>Special Nett Items</u>				
1	Front bumper clip (1 set)	Necessary	\$ 35.00	\$ 35.00 ✓
1	Front bumper sensor (1 set)	Damage	\$ 280.00	\$ 280.00 ✓
1	Front number plate	Damage	\$ 50.00	\$ 50.00 ✓
1	Rear windscreen sealant	Necessary	\$ 60.00	\$ 60.00 ✓
1	Rear tyre (Depreciation)	Damage	\$ 280.00	\$ 224.00 ✓
1	Rear windscreen inner seal	Necessary	\$ 85.00	\$ 85.00 ✓
1	Rear number plate	Damage	\$ 50.00	\$ 50.00 ✓
1	Rear reverse camera	Damage	\$ 480.00	\$ 480.00 ✓
			\$ 1320.00	\$ 1264.00
				<i>63 NA</i>

Spare Parts Total \$ 22386.48 \$ 22330.48

Vehicle No: SJF 8641 Y
 Report No: TP/ 10-16038/DY / 2016

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 22386.48	\$ 22330.48
1	To provide towing service charge.	\$ 80.00	\$ 80.00 ✓ 60
2	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 70.00	\$ 20 50.00 ✓ 30
3	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 70.00	\$ 50.00 ✓ 30
4	To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	\$ 250.00	\$ 180.00 ✓ 150
5	To remove and refit front bumper sensor.	\$ 200.00	\$ 120.00 ✓ 60
6	To remove and refit rear bumper sensor.	\$ 200.00	\$ 120.00 ✓ 60
7	To remove and refit rear undercarriage.	\$ 450.00	\$ 350.00 ✓ 200
8	To check and re-adjust (Computerized) all wheel alignment.	\$ 180.00	\$ 120.00 ✓ 80
9	To remove and refit air-con system, refill gas and test for leakages.	\$ 180.00	\$ 60 120.00 ✓ 60
10	To remove and refit radiator system.	\$ 160.00	\$ 120.00 ✓ 60
11	To remove and refit rear windscreen glass.	\$ 220.00	\$ 100 180.00 ✓ 120
12	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 4800.00	\$ 1500.00 3500.00 ✓ 2000
13	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 4500.00	\$ 1000 3500.00 ✓ 1800
	Sub Total	\$ 33746.48	\$ 30820.48

Vehicle No: SJF 8641 Y
 Report No: TP/ 10-16038/DY / 2016

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Sub Total c/f	\$ 33746.48	\$ 30820.48
14	To apply undercoating on the repaired and replaced panels for rust protection. <i>A790</i>	\$ 350.00	\$ 240.00 <i>80</i>
	Total	\$ 34096.48	\$ 31060.48

Recommended PART BY PART Repair Amount of: \$ 31060.48

SDLS: THIRTY ONE THOUSAND SIXTY AND CENTS FORTY EIGHT ONLY

total 20822.04
1603K.
1A Day.

[Signature]
 Qualified Appraiser

Total Parts (List)	=	10143.70
Trade Discount	=	1014.33
<i>(10/15/20/25/30 %)</i>		
Sub Total Parts (1)	=	9128.97
Less Betterment	=	-
<i>(15/20/25/30/35/40 %)</i>		
Sub Total Parts (2)	=	9128.97
Add Nett Price S/Parts	=	X
Add Paint Material	=	X
Towing Charges	=	80.00
Misc.	=	63.00
Add Panel Work Labor	=	1500.00
Add S/Paint Work	=	1000.00
Grand Total (BMA)	=	11771.97
<i>501 D</i>		

Lim Chin Yap
 EXECUTIVE
 MOTOR CLAIMS TECHNICAL
 LIBERTY INSURANCE PERKAD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 8641Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRONT HEADLAMPS	REPLACED	3,841.40	3,841.40
1	FRONT OUTER GRILLE	REPLACED	285.00	285.00
1	FRONT INNER GRILLE	REPLACED	250.00	250.00
1	SET FRONT GRILLE CHROME MOULDING	REPLACED	50.20	50.20
1	FRONT GRILLE LOGO	REPLACED	24.10	24.10
1	FRONT BUMPER	REPLACED	727.50	727.50
2	FRONT BUMPER BRACKETS	REPLACED	136.00	136.00
2	FRONT BUMPER FOG LAMPS	O/S REPLACED	479.40	239.70
1	FRONT BUMPER LOWER GRILLE	REPLACED	90.00	90.00
1	FRONT BUMPER LOWER SPOILER	REPLACED	230.00	230.00
1	FRONT BUMPER REINFORCEMENT	REPLACED	321.30	321.30
2	FRONT BUMPER SET PLATES	REPLACED	200.00	200.00
2	FRONT BUMPER SIDE RETAINERS	REPLACED	47.00	47.00
1	FRONT SUPPORT PANEL	REPAIRED SEE LABOUR	476.20	-
1	REAR DOOR	REPAIRED SEE LABOUR	930.00	-
1	REAR DOOR GLASS OUTER MOULDING	NOT NECESSARY	160.00	-
1	REAR DOOR OUTER HANDLE	REPLACED	95.00	95.00
1	REAR DOOR RUBBER	NOT NECESSARY	110.00	-
1	REAR DOOR FRAME RUBBER	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN GLASS	REPLACED	1,186.00	1,186.00
2	REAR WINDSCREEN INNER SIDE GARNISHES	O/S DEFORMED	420.00	210.00
1	REAR WINDSCREEN MOULDING	REPLACED	140.00	140.00
1	REAR TAILGATE	REPLACED	1,300.00	1,300.00
2	REAR TAILGATE DAMPERS	REPLACED	420.00	420.00
2	REAR TAILGATE HINGES	REPLACED	110.00	110.00
1	REAR TAILGATE INNER BOARD	REPLACED	265.00	265.00
1	REAR TAILGATE TOP SPOILER	REPLACED	820.00	820.00
1	REAR TAILGATE LAMP	REPLACED	280.00	280.00
1	REAR TAILGATE LOGO	REPLACED	32.00	32.00
1	REAR TAILGATE OUTER GARNISH	REPLACED	187.00	187.00
1	REAR TAILGATE RUBBER	REPLACED	195.00	195.00
1	REAR TAILGATE "VEZEL" EMBLEM	REPLACED	75.00	75.00

Report Ref No. CS/LAW18004551/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WIPER MOTOR	REPLACED	310.00	310.00
1	REAR TAILLAMP	REPLACED	750.00	750.00
1	REAR TAILLAMP PANEL	REPLACED	155.00	155.00
1	REAR END PANEL	REPLACED	660.00	660.00
1	REAR END PANEL INNER GARNISH	REPLACED	110.00	110.00
1	REAR SIDE BUMPER	REPLACED	187.40	187.40
1	REAR BUMPER	REPLACED	920.00	920.00
2	REAR BUMPER SIDE RETAINERS	REPLACED	88.00	88.00
1	REAR BUMPER TOP GARNISH	REPLACED	130.00	130.00
1	REAR THIRD BRAKE LIGHT	REPLACED	210.00	210.00
1	REAR SPARE TYRE BOARD	REPLACED	240.00	240.00
1	REAR SPARE TYRE SPONGE	REPLACED	197.80	197.80
1	REAR SPARE TYRE UNDER COVER	NOT NECESSARY	335.00	-
1	REAR FENDER	REPLACED	995.00	995.00
1	REAR FENDER AIR GATE	REPLACED	60.00	60.00
1	REAR FENDER INNER GARNISH	REPLACED	240.90	240.90
1	REAR FENDER INNER PANEL	REPAIRED SEE LABOUR	1,100.00	-
1	REAR FENDER INNER SHIELD	REPLACED	310.00	310.00
1	SET REAR FENDER INNER SHIELD CLIP	REPLACED	30.00	30.00
1	REAR FENDER OUTER ARCH GARNISH	REPLACED	180.00	180.00
1	REAR FENDER INNER TOP GARNISH	REPLACED	105.00	105.00
1	REAR FENDER CHROME HANDLE	REPLACED	150.00	150.00
1	REAR SPEAKER PANEL GARNISH	REPLACED	280.00	280.00
1	REAR SHOCK ABSORBER	NOT NECESSARY	330.00	-
1	REAR AXLE	NOT NECESSARY	1,350.00	-
	LESS 10% DISCOUNT		-2,340.72	-
	LESS 20% DISCOUNT		-	-3,613.26
			21,066.48	14,453.04
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN)	REPLACED	35.00	35.00
1	SET FRONT BUMPER SENSOR (SN)	REPLACED	280.00	200.00
1	FRONT NUMBER PLATE (SN)	REPLACED	50.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	REPLACED	60.00	60.00
1	REAR TYRE (DEPRECIATION)(SN)	REPLACED	280.00	224.00
1	REAR WINDSCREEN INNER SEAL (SN)	REPLACED	85.00	60.00

Report Ref No. CS/LAW18004551/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	REPLACED	50.00	50.00
1	REAR REVERSE CAMERA (SN)	REPLACED	480.00	480.00
			1,320.00	1,139.00
	LABOUR			
	TO PROVIDE TOWING SERVICE CHARGE.		80.00	60.00
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING,HARNESS WIRES,SOCKETS,REPLACE DAMAGED PARTS.		70.00	30.00
	TO REMOVE AND REFIT DAMAGE PARTS,TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		70.00	30.00
	TO REMOVE AND REFIT REAR CUSHION SEATS,RADIO SPEAKER BOARD,INTERIOR UPHOLSTERY TO FACILITATE THE REPAIRS.		250.00	150.00
	TO REMOVE AND REFIT FRONT BUMPER SENSOR.		200.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		200.00	60.00
	TO REMOVE AND REFIT REAR UNDERCARRIAGE.		450.00	200.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		180.00	80.00
	TO REMOVE AND REFIT AIR-CON SYSTEM,REFILL GAS AND TEST FOR LEAKAGES.		180.00	60.00
	TO REMOVE AND REFIT RADIATOR SYSTEM.		160.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		220.00	120.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL,REAR DOOR AND REAR FENDER INNER PANEL.		4,800.00	2,000.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		4,500.00	1,800.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		350.00	80.00
	-		-	-
	-		-	-
	-		-	-
			11,710.00	4,790.00
	GRAND TOTAL		34,096.48	20,382.04

Report Ref No. CS/LAW18004551/Atbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			16,300.00
---	--	--	-----------

Report Ref No. CS/LAW18004551/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.