

1/5/2010

INS. CASE OWNER:

BODI Sdn | CC3/CTE18004569 | 1klg3st

LKK:

IDAC:

**ASSIGNMENT**

Surveyor:

KALVIN

DOI:

03/03/18

Date / Time :

02/02/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SJ 8494K  
 Name of Insured : WANG MENG YEW  
 Insured Tel No. : \_\_\_\_\_ HP: 9029 9534  
 Excess Sec II :SS \_\_\_\_\_ D.O.A : 07/03/18  
 Is driver the owner?  YES / NO ) Nature of Accident :

Claim No. : SNM1800125202  
 Policy No. : DMPASN3003071901  
 Make / Model : HONDA CIVIC - 2.0L (A)  
 Place of Accident : ALONG CHEN SWEE RD TWDS HAWLOCK RD B/S JLN KULCOH

If NO, Driver Name / Age :

Driver Tel No. :

(V/L)  YES / NO )

OI GIA REPORT:  YES / NO : TP GIA REPORT:  YES / NO

Insured Liability: % Final ? Yes / No

S9C 74M

SJ 8494K

SHC 5256G



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP: Trans-Cab Civic  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI: <u>EMAIL 22/3/18</u>	
	After call ltr to OI:	
	<b>Documentation Check List:</b>	<b>Handler</b> <b>Typist</b>
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 03/03/18 Sent By: Shirley Hoo

FINALIZATION Date/Time: 5/4/18 Confirm with: JPS Confirm by: PAW  
 Repair Cost: 45 \$S 7,150 ( 6 days) Reduction: 83 % Email  Call

FINAL SETTLEMENT Date/Time: 18.7.18 Confirm with: Wai Yin Email  Call   
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 28 If NO or B 28, Ass. Lia : 0%  
 Repair Cost: 0/65 \$S 7,650.50 3 VEH C.C. OIL 2ND  
 Loss of Rental (LOR): \$S 710.22 ( 7 days) x \$101.46  
 Loss of Use (LOU): \$S - ( 5 x days)  
 Loss of Income (LOI): \$S 390.00 ( \$ 90 x 7 days)  
 LOR only  LOU only  LOR + LOU  LOR + LO  (Tick only one)  
 GIALTA Search \$S 7.45  
 Medical: \$S -  
 Disbursement: \$S - (e.g. Tow/ Independent)  
 Legal Cost \$S -  
 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format: TP  
 3) Survey fee: 940

Total: \$S 8,718.17 Global Sum \$S: \_\_\_\_\_ Email  Call

FINAL PAYMENT Date/Time: 18.7.18 Confirm with: Wai Yin Email  Call   
 Payee 1: \$S 8,718.17 Name 1: TRANS CAB AUTO SERVICES PTE LTD  
 Payee 2: (Strike if N.A.) \$S Name 2:  
 Payee 3: (Strike if N.A.) \$S Name 3:

**COPY SENT**  
24/7/18





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18004569/K1es3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 09-03-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLJ 8494K	Veh. Inspected	SHC 5855G
Policy No.	DMPSCN3003071801	Coverage (\$)	0.00
Claim No.	SNM18D01252C02	Excess (\$)	0.00
Assign From		Assign Date	09/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/03/2018	Inspection Date	08/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5855G -

*U/S 7150/6 Pags*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHC5855G - JHOW**  
VF1ABL15AUC280382  
RENAULT  
LATITUDE  
07.03.2018  
*Ching Tai Ping*

		PART		LIST	
1	1	BUMPER COVER REAR	<i>- Behind</i>	\$	1,108.46
2	1	BUMPER LOWER REAR	<i>- Behind</i>	\$	768.84
3	1	BUMPER BRACKET CTR REAR	<i>- one</i>	\$	113.47
4	1	BUMEP R BRACKET SIDE RH REAR	<i>X one</i>	\$	135.97
5	1	BUMEP R RETAINER RH REAR	<i>+ one</i>	\$	44.99
6	1	BUMPER REFLECTOR RH	<i>X one</i>	\$	43.61
7	1	BUMEP R BRACKET SIDE LH REAR	<i>X one</i>	\$	135.97
8	1	BUMEP R RETAINER LH REAR	<i>X one</i>	\$	44.99
9	1	BUMPER REFLECTOR LH	<i>- one</i>	\$	43.61
10	1	BUMPER BEAM REAR	<i>- Behind</i>	\$	777.52
11	1	BUMPER BEAM BRACKET LH REAR	<i>- Behind</i>	\$	225.95
12	1	BUMPER BEAM BRACKET RH REAR	<i>- Behind</i>	\$	225.95
13	1	BOOT REAR	<i>X Repair</i>	\$	2,872.68
14	1	BOOT FINISHER	<i>X one</i>	\$	470.06
15	1	BOOT WHEATERSTRIP	<i>X one</i>	\$	323.05
16	1	BOOT REFLECTOR LAMP LH	<i>X one</i>	\$	493.35
17	1	BOOT REFLECTOR LAMP RH	<i>X one</i>	\$	493.35
18	1	BOOT BADGE 'RENAULT'	<i>X one</i>	\$	225.36
19	1	BOOT BADGE	<i>X one</i>	\$	225.36
20	1	BOOT STRUT LH	<i>X one</i>	\$	276.08
21	1	BOOT STRUT RH	<i>X one</i>	\$	276.08
22	1	BOOT HINGE LH	<i>X one</i>	\$	367.84
23	1	BOOT HINGE RH	<i>X one</i>	\$	367.84
24	1	BOOT INNER TRIM	<i>X one</i>	\$	586.45
25	1	BOOT SWITCH	<i>X one</i>	\$	168.13
26	1	BOOT LOCK	<i>X one</i>	\$	202.67
27	1	BOOT LOCK CATCH	<i>X one</i>	\$	74.40
28	2	LICENCE PLATE LAMP	<i>X one</i>	\$	50.52
29	2	BOOT RUBBER PLUG	<i>X one</i>	\$	221.81
30	1	FENDER PANEL INNER TRIM REAR LH	<i>X one</i>	\$	671.45
31	1	FENDER PANEL REAR LH	<i>X one</i>	\$	3,299.13
32	1	WHEELARCH REAR LH	<i>X one</i>	\$	543.47
33	1	WHEELARCH REAR RH	<i>X one</i>	\$	543.47
34	1	TAILLAMP RH	<i>X one</i>	\$	552.55

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1803-065**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5855G -**

35	1	TAILLAMP PANEL RH	X <i>su</i>	\$	986.70
36	1	TAILLAMP LH	<del>X</del> <i>su</i>	\$	552.55
37	1	TAILLAMP PANEL LH	X <i>su</i>	\$	986.70
38	1	OUTER PANEL REAR (End Panel)	<del>X</del> <i>su</i>	\$	1,471.77
39	1	OUTER PANEL REAR (End Panel)TRIM	<del>X</del> <i>su</i>	\$	404.56
40	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X <i>su</i>	\$	2,189.88
41	1	SPARE WHEEL PANEL TRIM	X <i>su</i>	\$	612.21
42	1	EXHAUST REAR	X <i>su</i>	\$	7,489.05
43	1	EXHAUST CAP REAR	X <i>su</i>	\$	230.49

<b>TOTAL</b>	\$	<b>31,898.36</b>
<b>10%</b>	\$	<b>3,189.84</b>
	\$	<b>28,708.53</b>

*6377-10*

**Special Nett**

1	1SET	PARKING AID	<del>X</del> <i>su</i>	\$	<del>700.00</del> <i>400</i>
2	1SET	REAR BUMPER CLIP	<del>X</del> <i>su</i>	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	<del>X</del> <i>su</i>	\$	33.00
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	<del>X</del> <i>su</i>	\$	10.00
5	1SET	BUMEP R RETAINER RH CLIP RR	X <i>su</i>	\$	20.00
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR	<del>X</del> <i>su</i>	\$	10.00
7	1SET	BUMEP R RETAINER CLIP LH RR	X <i>su</i>	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	<del>X</del> <i>su</i>	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	<del>X</del> <i>su</i>	\$	66.00
10	1	EXHAUST MOUNTING REAR	X <i>su</i>	\$	17.82
11	1SET	BOOT FINISHER CLIP	X <i>su</i>	\$	24.20
12	1	BOOT STICKER "Trans-cab"	<del>X</del> <i>su</i>	\$	30.00
13	1	BOOT STICKER "6555-3333"	<del>X</del> <i>su</i>	\$	30.00
14	1	BOOT INNER TRIM CLIP	X <i>su</i>	\$	45.00
15	1SET	FENDER WHEELARCH REAR LH CLIP	X <i>su</i>	\$	35.00
16	1	FENDER INNER TRIM CLIP LH	X <i>su</i>	\$	28.00
17	1	TAILLAMP CLIP RH	<del>X</del> <i>su</i>	\$	5.00
18	1	TAILLAMP CLIP LH	<del>X</del> <i>su</i>	\$	5.00
19	2	REAR WINDSCREEN SELANT	X <i>su</i>	\$	80.00
20	1	WINDSCREEN MOULDING	X <i>su</i>	\$	100.00
21	1	REAR WINDSCREEN INNER SPONGE SEAL	X <i>su</i>	\$	100.00
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X <i>su</i>	\$	385.00
23	1	SPARE TYRE	X <i>su</i>	\$	330.00

<b>TOTAL</b>	\$	<b>2,162.02</b>
<b>TOTAL PARTS</b>	\$	<b>30,870.55</b>

*6377*

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1803-065**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5855G -**

Putty And Spray Painting Of The Affected Portion.	\$	<del>4,500.00</del> 800
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<del>4,200.00</del> 1000
To Rust-Proofing Of The Affected Areas.	\$	<del>170.00</del> 50
To reinstall rear bumper parking sensor.	\$	<del>170.00</del> 50
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<del>170.00</del> X <sup>11</sup>
To repair and realign rear exhaust pipe.	\$	<del>170.00</del> X <sup>11</sup>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<del>170.00</del> X <sup>11</sup>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<del>170.00</del> 40
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<del>170.00</del> X <sup>11</sup>
To supply and re-do rear luggage floor panel insulation padding.	\$	<del>380.00</del> X <sup>11</sup>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<del>380.00</del> X <sup>11</sup>
Towing Fees	\$	<del>120.00</del> X <sup>11</sup>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<del>170.00</del> X <sup>11</sup>
To check steering geometry and computer wheel alignment	\$	<del>220.00</del> X <sup>11</sup>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without (PARTS BY PARTS) Repair Days"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval of Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**TOTAL \$ 11,160.00**  
**Over All Total \$ 42,030.55<sup>3</sup>**

Kaluzilky 15 Days  
11 8/3/18 13x5h  
5 Lump Sum Repair  
Atta Repair photo  
4/3 7190



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE, 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/QBE18004569/K1es3

Date: 09.03.2018

The Motor Claims Department  
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 5855G**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/03/2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	<u>42,030.55</u>
Revised Estimate Amount	: S\$	<u>8,934.10</u>
"Check" Items Amount	: S\$	<u>120.00</u>
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

**KALVIN ANG**  
**Licensed Appraiser**

## Shirley Hiew (LKK Auto)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Wednesday, 14 March 2018 3:54 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** Chong Boon Sen  
**Subject:** RE: Direct Settlement - Accident Involving SLJ8494K (OI : CTI - SNM18D01252C02) AND SHC5855G (TP : LKK REF - CC3/CTI18004569/K1es3) on 07/03/2018  
**Attachments:** leeSZ\_SNM18D01252C02-SLJ8494K-LKKDirectSettlementAccidentLtr\_CLCR95.345.pdf; MSR118032390-SLJ8494K.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Regards,

**Lucas Lee**

Claims Department (Motor)  
China Taiping Insurance (Singapore) Pte. Ltd.  
3, Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6181  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Wednesday, 14 March, 2018 9:13 AM  
**To:** Claims Dept of CTI; Chong Boon Sen; Asher Sng (LKKAuto)  
**Cc:** Lucas Lee; Admin A; Vic (LKKAuto)  
**Subject:** Direct Settlement - Accident Involving SLJ8494K (OI : QBE - TBA) AND SHC5855G (TP : LKK REF - CC3/CTI18004569/K1es3) on 07/03/2018

### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 5855G at M/s Trans-Cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18004569/K1ea3s2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-07-2018



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 8494K	Veh. Inspected	SHC 5855G
Policy No.	DMPSCN3003071801	Coverage (\$)	0.00
Claim No.	SNM18D01252C02/4	Excess (\$)	0.00
Assign From		Assign Date	08/03/2018

### 2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC280382	Colour	RED
Odometer	432620	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	LING LONG	7 mm
L/H Front Tyre	215/60R16	LING LONG	7 mm
R/H Rear Tyre	215/60R16	LING LONG	7 mm
L/H Rear Tyre	215/60R16	LING LONG	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	07/03/2018	Inspection Date	08/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>6 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5855G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR	DEFORMED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DEFORMED	768.84	768.84
1	BUMPER BRACKET CTR REAR	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	BENT	225.95	225.95
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	TWISTED	323.05	323.05
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	SERVICEABLE	367.84	-
1	BOOT HINGE RH	SERVICEABLE	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	SERVICEABLE	202.67	-
1	BOOT LOCK CATCH	SERVICEABLE	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-

Report Ref No. CC3/CTI18004569/K1ea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL REAR LH	SERVICEABLE	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILAMP RH	CRACKED	552.55	552.55
1	TAILAMP PANEL RH	SERVICEABLE	986.70	-
1	TAILAMP LH	CRACKED	552.55	552.55
1	TAILAMP PANEL LH	SERVICEABLE	986.70	-
1	OUTER PANEL REAR (END PANEL)	DENTED	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	SERVICEABLE	7,489.05	-
1	EXHAUST CAP REAR	SERVICEABLE	230.49	-
	LESS 10% DISCOUNT		-3,189.83	-701.90
			28,708.51	6,317.10
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CT CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NECESSARY	10.00	10.00
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NECESSARY	10.00	10.00
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NECESSARY	22.00	22.00
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-

Report Ref No. CC3/CT118004569/K1ea3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,162.02	677.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	800.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOT REAR AND SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL).		4,200.00	1,000.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	50.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	40.00
	TO TRANSFER OF REAR LUAGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGAGGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CC3/CTI18004569/K1ea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			11,160.00	1,940.00
<b>GRAND TOTAL</b>			<b>42,030.53</b>	<b>8,934.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,150.00</b>

Report Ref No. CC3/CT118004569/K1ea3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.