

ASSIGNMENT

Date 12/3/18

STB 3297 06 12

Estimated Cost
QD TP WS TR RES / QD RES / EVA / INV / MY

To: Inspection No. SJB 3292

at: Worked on: Lim Tan Motor

of: Blk 176 Sin Ming Drive #03-09/10

Insured

Policy No.

Claims No.


Sum Insured Excess

Client's Record

Make of Vehicle

Policy Condition

Remarks: The van had commenced its repair at the time of inspection.



Ball or Market Value

QAC Accident Report Consistent? : Yes or No

QAC PR Seen Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Est. Sum: 20 % B Val: Yes or No

CA / REV / REP / 24 HRS (wp)

Date Person Contacted Vehicle IN / OUT

Date Time Action / Instruction

13/3 File pass to Carhome

Make MS (A) 2496

Model M. Marom

So. Reading 109478

Eng No.

Chassis JN1BBUT3270002900

Gen. Cond. Good Fair Poor Burnt

Steering In Order Jammed Leaked Burnt or

Brake In Order Jammed Leaked Burnt or

Mod. Nil SRM / STC

Tyre Size 215/55ZR17

BS DUN EXNOVA 31 PS LIZA W/O CHTSL PR S.V.

TOYO / YOKO

Front R/Ba 5 --

L/Ba 5 --

D.O.A. 9/13/18

Surveyed at 12/3/18

Assessment of Damages R/Ba R/Ba C/S N/S U/C Roofed

The U/C / Chassis frame Body Structure affected during accident

Date Time File Pass to
Final Report

Days Of Repair
Resurvey No. of Trip

Add Fee
Spare part
Tire
Oil

