

ASS. REC. BY:

REF: CS/FCI18004656/Kqd3n2

Special Instruction:

Surveyor: Kenneth
(WS)

ASSIGNMENT (Office)

From (Person): Eileen Lee

of FCI

Date/Time: 9/3/18 @ 5:15pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 9793B

Insured: 8H 6098L

at Workshop m/s Massive Trading

Tel: 91082728

of Blk 5038 # 01-405 AMK Ind. Prk 2

Policy No: 6-18088936 MFSH

Claim No: D18001959 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/03/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 8:55am @ 12/3/18

Person Contacted:

Anthony

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJV 9793B - NA/INC18004392/h4
	8H 6098L - CS/FCI18015318/Kqd3n2
12/3/18 @ 2:30pm	revised to Eileen Lee by email.
16/4/18 @ 11pm	& 6300 confirmed by email (Ref # 672258, 50%)

FCI

ASSIGNMENT

From: _____ Date: **12/03/2018**

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV _____

To inspect Vehicle No: **SJV 9793B**

at Workshop no: **Massive trading**

of: **Blk 5038 # 01-45, AMK Ind. Prk. 2**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

Clients Record: **Anthony @ 9108 2728**

Make of car: _____

Vehicle: **SJV 9793B** Page: **02 10**

Type: **Car** / **Motorcycle** / **Van** / **Truck** / **Trailer**

Make: **Lotus** **1499**

Colour: **Black**

So Reading: **122156**

Engine No: _____

Chassis No: **JMYSRG.Y2AAU000375**

Gen. Cond: **Good** / **Fair** / **Poor** / **Burnt**

Steering: **Good** / **Jammed** / **Leaked** / **Burnt** / **or**

Brake: **Good** / **Jammed** / **Leaked** / **Burnt** / **or**

Mod: **Nil** / **S Rim** / **STEEL Rim** / **or**

Tyre Size: **R17 205/60R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / S.V.

TOYO / YOKO / **or**


Front	Rear
FRBa 8	RRBa 6
LRBa 8	LLBa 6
DOA 613118	DO 1213118

Survey Report: **✓**

Des. of Damages: **FR** / **Rear** / **OS** / **NIS** / **UO** / **Revised** / **or**

Revised

The UO / Chassis frame / Body Structure affected due to collision



Policy Condition: _____

Remarks: The veh had commenced its repair at the time of inspection.

Sal. or Market Value: _____

DAC Accident Report: _____ Consistent? Yes or No

GIA / PP / Seen: _____ Consistent? Yes or No

Est. Repairs: **06** days Res: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

QA / REV / REP. / 24 HRS (wp)

Date: _____ Person Contacted: _____ Vehicle IN / OUT

Date Time Action Instruction

13/3 File pass to Catherine

RECEIVED 16 APR 2

Date Time File Received: **16/4** **hust**

☐ Preli. Report

☐ Final Report

Days Of Repair: **6**

Resurvey No. of Trip: **2**

Date Time File Returned: _____

Record Format: **TP**

Lum Sum: **6300**

Add Fee: ☐ Site Fee: ☐

☐ ☐

☐ ☐

☐ ☐

2x15 = 30

170 + 30

50

50 + 50

33

383



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004656/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6098L	Veh. Inspected	SJV 9793B
Policy No.		Coverage (\$)	0.00
Claim No.	D18001959MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/03/2018	Inspection Date	12/03/2018
Survey held at	BLK 5038 # 01-405 AMK IND.PARK 2		
Repairer	MASSIVE TRADING & AUTO		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001959MFSH

Date: 13 March 2018

Our Ref: CS/FCI18004656/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJV 9793B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/03/2018 at the premises of M/s MASSIVE TRADING, and have the following to report:-

Workshop Estimate Amount	: S\$ 12,522.58
Revised Estimate Amount	: S\$ 3,819.99
"Check" Items Amount	: S\$ 5,076.70
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear o/s & front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	08-03-2018	Our Ref No. D18001959MFSH
Accident Date	06-03-2018	Claim Type. Third Party
Insured Vehicle	SH6098L	Third Party Vehicle. SJV9793B
Survey Location	Blk 5038 #01-405 Ang mo kio industrial Pk 2	
Contact Person.	ANTHONY	
Contact No.	0/ 91082728	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MASSIVE TRADING & AUTO	Attention. NIL
Cc : TP Solicitor	TEO KENG SIANG LLC	TP Solicitor Fax No. 63335676
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235753)



PRI Documents



Close



PRI Header Details

Claim No	D18001959MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TEO KENC
Workshop Name	MASSIVE TRADING & AUTO (Contact Person : ANTHONY)	Survey Location & Contact Details	Blk 5038 #01-405 Ang mo kio industrial Pk 2 Mobile: 91082728 , Phone: 0 , Fax: 0 EmailId: JANICE.KEE@KSTEOPTR.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6098L	TP Vehicle No	SJV9793B
PRI Recieved Date	08-03-2018 08:14:36 PM	Surveyor Appointed Date	09-03-2018 05:14:42 PM	Surveyor Accept Date	09-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 13 March 2018 2:37 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001959MFSH/1
Attachments: CSFCI18004656Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SJV 9793B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 12 March 2018 9:07 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001959MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 9 March 2018 5:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001959MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

Saroja D/O Applanaidu
Blk 485 Jurong West Ave 1
#05-77
Singapore 640485

Not Not hatched
11 Sep @ 7
Presumably After Rain
6 days

Vehicle No : SJV 9793 B
Make : Mitsubishi Lancer
Year : 2009

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
1 pc	Front bonnet	<i>Am</i> \$655.00	✓
1 pc	Front bonnet lock	<i>D/I</i> \$175.00	✓
1 pc	Front support panel	<i>Am</i> \$687.00	✓
2 pcs	Front headlamp assy	<i>mj.m</i> \$584.00	✓
1 pc	Front bumper	<i>Bu</i> \$695.00	✓
1 pc	Front bumper reinforcement	<i>Am</i> \$255.00	✓
2 pcs	Front bumper side retainer	<i>D/I</i> \$65.00	✓
1 pc	Front bumper lower grille	<i>CM</i> \$135.00	✓
1 pc	Front grille	<i>CM</i> \$275.00	✓
1 pc	Front grille emblem	<i>na</i> \$55.00	✓
1 pc	Front no plate holder	<i>su</i> \$75.00	X
1 pc	Air con condenser	<i>Am</i> \$755.00	✓
1 pc	Rear boot lid	<i>R</i> \$685.00	X
1 pc	Rear n/s boot lid reflector	<i>su</i> \$181.00	X
1 pc	Rear boot lid emblem " Logo "	<i>na</i> \$48.00	X
1 pc	Rear boot lid emblem " Lancer "	<i>na</i> \$50.00	X
1 pc	Rear boot lid emblem " EX "	<i>na</i> \$30.00	X
1 pc	Rear boot lid emblem " Mivec "	<i>na</i> \$35.00	X
1 pc	Rear boot rubber	<i>su</i> \$175.00	X
1 pc	Rear n/s fender inner trim	<i>R</i> \$385.00	X
1 pc	Rear end panel	<i>su</i> \$483.00	X
1 pc	Rear end panel inner garnish	<i>mj.m</i> \$195.00	X
1 pc	Rear n/s tail-lamp assy	<i>Bu</i> \$405.00	✓
1 pc	Rear bumper	<i>R</i> \$781.00	✓
1 pc	Rear bumper top beam	<i>R</i> \$165.00	X
1 pc	Rear bumper reinforcement	<i>su</i> \$228.00	X
1 pc	Rear n/s bumper reflector	<i>su</i> \$65.00	X
2 pcs	Rear bumper side retainer	<i>ol/di</i> \$55.10	✓
1 pc	Rear exhaust silencer	<i>R</i> \$550.00	X
1 pc	Front support top garnish - 105.00	<i>CM</i>	✓
			\$9,631.00
Less 10 %			\$963.10
balance c/f			\$8,667.90

SJV 9793 B

balance b/f \$8,667.90

S Nett

1 pc *151* Rear no plate
1 set Rear reverse sensor
10 pcs Rear bumper clip

nu \$40.00 ✓
su \$200.00 X
\$2.50 *nu* \$25.00 ✓
\$265.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,400.00 *10001*

To putty & spray paint on rear accident affected portion.

\$1,400.00 *9001*

Check/reconnect wiring.

\$45.00 *401*

To spray anti rust on accident affected portion.

\$200.00 *601*

Remove/refit rear boot upholstery to facilitate repair.

nu \$120.00 X

Remove/reew rear exhaust silencer.

\$150.00 *601*

Remove/renew air con condenser and to top up gas

\$180.00 *1001*
Total \$12,427.90 *1252240*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004656/Kqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6098L	Veh. Inspected	SJV 9793B
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001959MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	09/03/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JMYSRCY2AAU000375	Colour	METALLIC BLACK
Odometer	122156	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	FLY	8 mm
L/H Front Tyre	205/60 R16	FLY	8 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/03/2018	Inspection Date	12/03/2018
Survey held at	BLK 5038 # 01-405 AMK IND.PARK 2		
Repairer	MASSIVE TRADING & AUTO		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 9793B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	BENT	655.00	655.00
1	FRONT BONNET LOCK	DISTORTED	175.00	175.00
1	FRONT SUPPORT PANEL	BUCKLED	687.00	687.00
2	FRONT HEADLAMP ASSY @\$584.00	MTG CRACKED	1,168.00	1,168.00
1	FRONT BUMPER	BUCKLED	695.00	695.00
1	FRONT BUMPER REINFORCEMENT	BENT	255.00	255.00
2	FRONT BUMPER SIDE RETAINER @\$65.00	DISTORTED	130.00	130.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	135.00	135.00
1	FRONT GRILLE	CRACKED	275.00	275.00
1	FRONT GRILLE EMBLEM	NECESSARY	55.00	55.00
1	FRONT NO PLATE HOLDER	SERVICEABLE	75.00	-
1	AIR CON CONDENSER	PUNCTURE	755.00	755.00
1	REAR BOOT LID	TO REPAIR SEE LABOUR	685.00	-
1	REAR N/S BOOT LID REFLECTOR	SERVICEABLE	181.00	-
1	REAR BOOT LID EMBLEM "LOGO"	NOT NECESSARY	48.00	-
1	REAR BOOT LID EMBLEM "LANCER"	NOT NECESSARY	50.00	-
1	REAR BOOT LID EMBLEM "EX"	NOT NECESSARY	30.00	-
1	REAR BOOT LID EMBLEM "MIVEC"	NOT NECESSARY	35.00	-
1	REAR BOOT RUBBER	SERVICEABLE	175.00	-
1	REAR N/S FENDER INNER TRIM	SERVICEABLE	385.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	483.00	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	195.00	-
1	REAR N/S TAIL-LAMP ASSY	MTG CRACKED	405.00	405.00
1	REAR BUMPER	BUCKLED	781.00	781.00
1	REAR BUMPER TOP BEAM	TO REPAIR SEE LABOUR	165.00	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	228.00	-
1	REAR N/S BUMPER REFLECTOR	SERVICEABLE	65.00	-
2	REAR BUMPER SIDE RETAINER	O/S DISTORTED	110.00	55.00

Report Ref No. CS/FCI18004656/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	550.00	-
1	FRONT SUPPORT TOP GARNISH	CRACKED	105.00	105.00
	LESS 10% DISCOUNT		-973.60	-633.10
			8,762.40	5,697.90
	SPECIAL NETT ITEMS			
1	FRT NO PLATE (SN)	DENTED	40.00	40.00
1	SET REAR REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
10	REAR BUMPER CLIP @\$2.50 (SN)	NECESSARY	25.00	25.00
			265.00	65.00
	LABOUR			
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING INCLUSIVE OF THE REPAIR OF REAR BOOT LID, REAR END PANEL, REAR BUMPER TOP BEAM, REAR BUMPER REINFORCEMENT AND REAR EXHAUST SILENCER.		1,400.00	1,000.00
	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION.		1,400.00	900.00
	CHECK/RECONNECT WIRING.		45.00	40.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.		200.00	60.00
	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	REMOVE/RENEW REAR EXHAUST SILENCER.		150.00	60.00
	REMOVE/RENEW AIR CON CONDENSER AND TO TOP UP GAS.		180.00	100.00
			3,495.00	2,160.00
	GRAND TOTAL		12,522.40	7,922.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,300.00

Report Ref No. CS/FC118004656/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.