

Lump Sum
limit @ \$32,000
10 days.

ETHOZ

Date : 18/04/2018
To : **FIRST CAPITAL INSURANCE LIMITED**

Attn : **Motor Claim Department** FAX :

Owner : CHIN HOW HSUNG
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTPV01000565 Accident Date : 05/03/2018
Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
-----	-------------	-------------------	-------------------

List Item

1	HEADLAMP LH	3083.00	3083.00 <i>cur</i>
1	INTERCOOLER	1150.00	1150.00 <i>cur</i>
1	FRONT AIRGUIDE	235.00	235.00 <i>de</i>
1	FRONT FENDER LH	872.00	872.00 <i>bt</i>
1	HEADLAMP PANEL LH	273.00	273.00 <i>bt</i>
1	HEADLAMP WASHER JET HOSE	192.00	192.00 <i>du</i>
1	RADIATOR	1340.00	1340.00 <i>bt</i>
1	CHASSIS STABILIZER WEIGHT RH	235.00	235.00 <i>bt</i>
1	FRONT BUMPER	1829.00	1829.00
1	FRONT BUMPER LOWER GRILLE	120.00	120.00
1	DAYRUN LIGHT RH	510.00	510.00
1	DAYRUN LIGHT GARNISH RH	80.00	80.00
1	BUMPER TOWING COVER	45.00	45.00
1	FRONT BUMPER CENTRE	298.00	298.00

PAGE: 1



Date : 18/04/2018

To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : CHIN HOW HSUNG

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01000565 Accident Date : 05/03/2018

Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	REINFORCEMENT		
1	FRONT BUMPER CENTRE SPONGE	160.00	160.00 ✓
1	FRONT BUMPER SPONGE RH	55.00	55.00 ✓
1	FRONT BUMPER SPONGE LH	55.00	0.00 ✓
2	FRONT BUMPER RETAINER	48.00	48.00 ✓
2	FRONT BUMPER BRACKET	558.00	279.00 ✓
20	FRONT BUMPER RIVETS	200.00	200.00 ✓
10	FRONT BUMPER CLIPS	100.00	100.00 ✓
1	FRONT BUMPER WIRE HARNESS	235.00	0.00 ✓
1	FRONT GRILLE	850.00	850.00 ✓
1	FRONT GRILLE UPPER COVER	133.00	0.00 ✓
1	HEADLAMP RH	3083.00	3083.00 ✓
1	HEADLAMP FRAME SEAL RH	53.00	53.00 ✓
1	HEADLAMP HID BALLAST RH	1273.00	1273.00 ✓
1	HEADLAMP WASHER TRIM RH	115.00	115.00 ✓

PAGE : 2



Date : 18/04/2018

To : **FIRST CAPITAL INSURANCE LIMITED**

Attn : **Motor Claim Department**

FAX :

Owner : CHIN HOW HSUNG

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01000565 Accident Date : 05/03/2018

Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	HEADLAMP WASHER JET RH	212.00	212.00 ✓
1	OUTER BUMPER SENSOR RH	277.00	277.00 ✓
1	INNER BUMPER SENSOR RH	277.00	277.00 ✓
1	CENTRE BUMPER SENSOR RH	277.00	0.00
3	BUMPER SENSOR RING RH	36.00	36.00 ✓
2	AIRBAG IMPACT SENSOR	232.00	232.00 ✓
2	TRIGGER UNIT	220.00	0.00
1	BONNET	2826.00	2826.00 ✓
1	BONNET INSULATOR	216.00	216.00 ✓
10	BONNET INSULATOR CLIPS	100.00	100.00 ✓
1	BONNET LOGO	65.00	65.00 ✓
1	BONNET CHROME MOULDING	143.00	143.00 ✓
2	BONNET SPRING ELEMENT	48.00	0.00 ✓
1	BONNET LOWER LOCK RH	68.00	0.00 ✓
1	BONNET UPPER CATCH RH	35.00	35.00 ✓

PAGE: 3

Date : 18/04/2018
To : **FIRST CAPITAL INSURANCE LIMITED**

Attn : **Motor Claim Department** FAX :

Owner : CHIN HOW HSUNG
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTPV01000565 Accident Date : 05/03/2018
Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	RH PEDESTAL PROTECTOR SENSOR	380.00	0.00
1	BONNET CONTACT SWITCH RH	49.00	0.00
1	BONNET HINGE RH	152.00	152.00
1	BONNET HINGE LH	152.00	0.00
1	BONNET STAY RH	57.00	57.00
1	BONNET STAY LH	57.00	0.00
1	BONNET ABSORBER RH	120.00	120.00
2	FRONT FENDER RH	1744.00	1744.00
1	FENDER EMBLEM - BLUE EFFICIENTCY	65.00	65.00
1	FRONT FENDER MOULDING RH	47.00	47.00
1	FRONT FENDER COWLING FRONT RH	162.00	162.00
1	FRONT FENDER COWLING REAR RH	173.00	173.00
10	FRONT FENDER SHIELD CLIPS	100.00	100.00
1	SUPPORT TOP PANEL	188.00	188.00
1	HEADLAMP PANEL RH	273.00	273.00



Date : 18/04/2018

To : FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : CHIN HOW HSUNG

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01000565 Accident Date : 05/03/2018

Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT LOWER ENGINE DUST COVER	227.00	0.00
1	FRONT ENGINE CROSSMEMBER ASSY	2072.00	0.00
1	STEERING RACK AND PINION ASSY	6575.00	0.00
1	FRONT ABSORBER RH	828.00	828.00
1	FRONT ABSORBER TOP MOUNTING RH	245.00	0.00
1	FRONT KNUCKLE ARM RH	775.00	775.00
1	FRONT WHEEL HUB RH	492.00	492.00
1	FRONT WHEEL BEARING RH	156.00	156.00
1	FRONT LOWER ARM RH	518.00	518.00
1	FRONT UPPER ARM RH	450.00	450.00
1	FRONT STABILIZER LINK RH	83.00	0.00
1	FRONT TIE ROD RH	156.00	0.00
1	FRONT TIE ROD END RH	180.00	180.00
1	FRONT SPORTS RIM RH	1245.00	1245.00
1	ROCKER PANEL GARNISH RH	1080.00	1080.00

PAGE : 5



Date : 18/04/2018

To : **FIRST CAPITAL INSURANCE LIMITED**

Attn : **Motor Claim Department**

FAX :

Owner : CHIN HOW HSUNG

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01000565 Accident Date : 05/03/2018

Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT DOOR SIDE AIRBAG RH	775.00	775.00
1	FRONT DOOR SIDE AIRBAG LH	775.00	775.00
1	FRONT DOOR TRIMBOARD RH	3248.00	3248.00
1	FRONT DOOR TRIMBOARD LH	3248.00	3248.00
1	FRONT DOOR AIRBAG CONTROL UNIT	1205.00	1205.00
1	FRONT SEAT BELT RH	1423.00	0.00
1	FRONT SEAT BELT LH	1423.00	1423.00
1	FRONT WHEELHOUSE PANEL RH RESTORE	0.00	0.00
1	FRONT CHASSIS MEMBER RH RESTORE	0.00	0.00
1	FRONT FENDER LH RESTORE	0.00	0.00
1	FRONT DOOR RH RESTORE	0.00	0.00
Sub Total		53110.00	40376.00
Discount % On Parts (0.00)		(5311.00)	(4037.60)

Special Nett Item

PAGE: 6



Date : 18/04/2018

To : **FIRST CAPITAL INSURANCE LIMITED**

Attn : **Motor Claim Department**

FAX :

Owner : CHIN HOW HSUNG

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01000565 Accident Date : 05/03/2018

Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	COOLANT	50.00	30.00
1	FRONT TYRE RH	350.00	280.00
1	POWER STEERING OIL	120.00	0.00
	Sub Total	520.00	310.00

Labour & Misc

LABOUR TO FACILITATE REPAIR	2000.00	1000.00
TO RESPRAY AFFECTED AREAS	2000.00	1200.00
TO REMOVE AND REFIT ENGINE CROSSMEMBER	250.00	150.00
TO REMOVE AND REFIT FRONT UNDERCARRIAGE RH	200.00	120.00
TO CONDUCT FULL WHEEL ALIGNMENT	150.00	80.00
TO REMOVE AND REPLACE SIDE AIRBAG UNIT	300.00	200.00

PAGE : 7



Date : 18/04/2018

To : **FIRST CAPITAL INSURANCE LIMITED**

Attn : **Motor Claim Department**

FAX :

Owner : CHIN HOW HSUNG

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPV01000565 Accident Date : 05/03/2018

Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO REPROGRAM AND RESET AIRBAG SYSTEM	500.00	250.00
	TO PULL AND REPAIR FRONT CHASSIS PANEL	300.00	250.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30.00
	TOWING CHARGES FROM ACCIDENT AREA INTO W/SHOP	100.00	100.00
	TO TOP UP AIRCON GAS	120.00	100.00
	Sub Total	5970.00	3480.00

PAGE: 8



Date : 18/04/2018
To : **FIRST CAPITAL INSURANCE LIMITED**

Attn : **Motor Claim Department** FAX :

Owner : CHIN HOW HSUNG
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTPV01000565 Accident Date : 05/03/2018
Vehicle No : SJZ-1777-E Make & Model : MERCEDES BENZ E250 CGI A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	54,289.00	40,128.40
	GST 7.0 %	3,800.23	2,808.99
	Total	58,089.	42,937.

Surveyor Name : TAUFIK - LKK

Date & Time : 12/03/2018 5:15:00 PM

Selamatshahh

PAGE : 9

CLAIM DEPARTMENT

DID : 66547519

FAX :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004657/T1rd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4886T	Veh. Inspected	SJZ 1777E	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001931MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	09/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2074472F079418	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	PIRELLI	6 mm	
L/H Front Tyre	235/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/40 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2018	Inspection Date	12/03/2018	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 1777E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,829.00	1,829.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	120.00	120.00
1	DAYRUN LIGHT RH	CRACKED	510.00	510.00
1	DAYRUN LIGHT GARNISH RH	DISTORTED	80.00	80.00
1	BUMPER TOWING COVER	MISSING	45.00	45.00
1	FRONT BUMPER CENTRE REINFORCEMENT	BENT	298.00	298.00
1	FRONT BUMPER CENTRE SPONGE	DEFORMED	160.00	160.00
1	FRONT BUMPER SPONGE RH	DEFORMED	55.00	55.00
1	FRONT BUMPER SPONGE LH	NOT NECESSARY	55.00	-
2	FRONT BUMPER RETAINER	NECESSARY	48.00	48.00
2	FRONT BUMPER BRACKET	N/S NOT NECESSARY / O/S DISTORTED	558.00	279.00
20	FRONT BUMPER RIVETS	NECESSARY	200.00	200.00
10	FRONT BUMPER CLIPS	NECESSARY	100.00	100.00
1	FRONT BUMPER WIRE HARNESS	NOT NECESSARY	235.00	-
1	FRONT GRILLE	MISSING	850.00	850.00
1	FRONT GRILLE UPPER COVER	NOT NECESSARY	133.00	-
1	HEADLAMP RH	CRACKED	3,083.00	3,083.00
1	HEADLAMP FRAME SEAL RH	NECESSARY	53.00	53.00
1	HEADLAMP HID BALLAST RH	DISTORTED	1,273.00	1,273.00
1	HEADLAMP WASHER TRIM RH	MISSING	115.00	115.00
1	HEADLAMP WASHER JET RH	DISTORTED	212.00	212.00
1	OUTER BUMPER SENSOR RH	DISTORTED	277.00	277.00
1	INNER BUMPER SENSOR RH	CUT	277.00	277.00
1	CENTRE BUMPER SENSOR RH	NOT NECESSARY	277.00	-
3	BUMPER SENSOR RING RH	NECESSARY	36.00	36.00
2	AIRBAG IMPACT SENSOR	CUT	232.00	232.00
2	TRIGGER UNIT	NOT NECESSARY	220.00	-
1	BONNET	BENT	2,826.00	2,826.00
1	BONNET INSULATOR	DEFORMED	216.00	216.00

Report Ref No. CS/FCI18004657/T1rd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	BONNET INSULATOR CLIPS	NECESSARY	100.00	100.00
1	BONNET LOGO	NECESSARY	65.00	65.00
1	BONNET CHROME MOULDING	CUT	143.00	143.00
2	BONNET SPRING ELEMENT	NOT NECESSARY	48.00	-
1	BONNET LOWER LOCK RH	NOT NECESSARY	68.00	-
1	BONNET UPPER CATCH RH	BENT	35.00	35.00
1	RH PEDESTAL PROTECTOR SENSOR	NOT NECESSARY	380.00	-
1	BONNET CONTACT SWITCH RH	NOT NECESSARY	49.00	-
1	BONNET HINGE RH	BENT	152.00	152.00
1	BONNET HINGE LH	NOT NECESSARY	152.00	-
1	BONNET STAY RH	BENT	57.00	57.00
1	BONNET STAY LH	NOT NECESSARY	57.00	-
1	BONNET ABSORBER RH	BENT	120.00	120.00
1	FRONT FENDER RH	BENT	1,744.00	1,744.00
1	FENDER EMBLEM - BLUE EFFICIENTCY	NECESSARY	65.00	65.00
1	FRONT FENDER MOULDING RH	DEFORMED	47.00	47.00
1	FRONT FENDER COWLING FRONT RH	DEFORMED	162.00	162.00
1	FRONT FENDER COWLING REAR RH	DEFORMED	173.00	173.00
10	FRONT FENDER SHIELD CLIPS	NECESSARY	100.00	100.00
1	SUPPORT TOP PANEL	BENT	188.00	188.00
1	HEADLAMP PANEL RH	BENT	273.00	273.00
1	FRONT LOWER ENGINE DUST COVER	NOT NECESSARY	227.00	-
1	FRONT ENGINE CROSSMEMBER ASSY	NOT NECESSARY	2,072.00	-
1	STEERING RACK AND PINION ASSY	NOT NECESSARY	6,575.00	-
1	FRONT ABSORBER RH	BENT	828.00	828.00
1	FRONT ABSORBER TOP MOUNTING RH	NOT NECESSARY	245.00	-
1	FRONT KNUCKLE ARM RH	BENT	775.00	775.00
1	FRONT WHEEL HUB RH	BENT	492.00	492.00
1	FRONT WHEEL BEARING RH	BENT	156.00	156.00
1	FRONT LOWER ARM RH	BENT	518.00	518.00
1	FRONT UPPER ARM RH	BENT	450.00	450.00
1	FRONT STABILIZER LINK RH	NOT NECESSARY	83.00	-
1	FRONT TIE ROD RH	NOT NECESSARY	156.00	-

Report Ref No. CS/FCI18004657/T1rd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TIE ROD END RH	BENT	180.00	180.00
1	FRONT SPORTS RIM RH	CRACKED	1,245.00	1,245.00
1	ROCKER PANEL GARNISH RH	DEFORMED	1,080.00	1,080.00
1	FRONT DOOR SIDE AIRBAG RH	CUT	775.00	775.00
1	FRONT DOOR SIDE AIRBAG LH	CUT	775.00	775.00
1	FRONT DOOR TRIMBOARD RH	DEFORMED	3,248.00	3,248.00
1	FRONT DOOR TRIMBOARD LH	DEFORMED	3,248.00	3,248.00
1	FRONT DOOR AIRBAG CONTROL UNIT	CUT	1,205.00	1,205.00
1	FRONT SEAT BELT RH	NOT NECESSARY	1,423.00	-
1	FRONT SEAT BELT LH	CUT	1,423.00	1,423.00
1	FRONT WHEELHOUSE PANEL RH (NPA)	NOT NECESSARY	-	-
1	FRONT CHASSIS MEMBER RH (NPA)	NOT NECESSARY	-	-
1	FRONT FENDER LH (NPA)	NOT NECESSARY	-	-
1	FRONT DOOR RH (NPA)	NOT NECESSARY	-	-
1	HEADLAMP LH (ADDITIONAL)	CRACKED	3,083.00	3,083.00
1	INTERCOOLER (ADDITIONAL)	CRACKED	1,150.00	1,150.00
1	FRONT AIRGUIDE (ADDITIONAL)	DEFORMED	235.00	235.00
1	FRONT FENDER LH (ADDITIONAL)	BENT	872.00	872.00
1	HEADLAMP PANEL LH (ADDITIONAL)	BENT	273.00	273.00
1	HEADLAMP WASHER JET HOSE (ADDITIONAL)	DISTORTED	192.00	192.00
1	RADIATOR (ADDITIONAL)	BENT	1,340.00	1,340.00
1	CHASSIS STABILIZER WEIGHT RH (ADDITIONAL)	BENT	235.00	235.00
	LESS 10% DISCOUNT		-5,311.00	-4,037.60
			47,799.00	36,338.40
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN)	NECESSARY	50.00	30.00
1	FRONT TYRE RH (SN) (80%)	CUT	350.00	280.00
1	POWER STEERING OIL (SN)	NOT NECESSARY	120.00	-
			520.00	310.00
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR.		2,000.00	1,000.00
	TO RESPRAY AFFECTED AREAS.		2,000.00	1,200.00

Report Ref No. CS/FCI18004657/T1rd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT ENGINE CROSSMEMBER.		250.00	150.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE RH.		200.00	120.00
	TO CONDUCT FULL WHEEL ALIGNMENT.		150.00	80.00
	TO REMOVE AND REPLACE SIDE AIRBAG UNIT.		300.00	200.00
	TO REPROGRAM AND RESET AIRBAG SYSTEM.		500.00	250.00
	TO PULL AND REPAIR FRONT CHASSIS PANEL.		300.00	250.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		50.00	30.00
	TOWING CHARGES FROM ACCIDENT AREA INTO W/SHOP.		100.00	100.00
	TO TOP UP AIRCON GAS.		120.00	100.00
			5,970.00	3,480.00
GRAND TOTAL			54,289.00	40,128.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				32,000.00

Report Ref No. CS/FCI18004657/T1rd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.