

ASS. REC. BY:

REF:

CS3/GA116021242/

CS4
Vb-11

Special Instruction: Paper Survey

Surveyor:

ASSIGNMENT (Office)From (Person): Angela Tan of GAT Date/Time: 12032018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 6617G Insured: YL 6969Gat Workshop m/s N-51 Automotive Tel: 6847 0051of 2 Kaki Bukit Ave 2 #01-17Policy No: _____ Claim No: CLMDMVC000000272 16/11 @ 4:50pm
SPK116

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06/11/2016

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 08/12/16 10:52am Person Contacted: Hui Xin Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJF 6617G : 14 / 10/11/16 / 15</u>
	<u>YL 6969G : X</u>
	<u>Dismantle: 10/11/16</u>
	<u>After paint: 14/11/16</u>

Survey by Paul

19/3/18 LS \$6800 (Red 3300, 3390), 6 days

RECEIVED 20 MAR 2018


 19/3/2018

No bill

Survey Department Check List (Case Handler)

Reference No.: CS3 / GAS / 6021242 / v6-1
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS3/GAI16021242/vb-1

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 12-03-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 6969G	Veh. Inspected	SJF 6617G
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000000272	Excess (\$)	0.00
Assign From	ANGELA TAN	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/11/2016	Inspection Date	12/03/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Tan, Angela <Angela.Tan@sg.gaig.com>
Sent: Monday, 12 March, 2018 4:42 PM
To: Veron Chen (LKKAuto); Mei Kwan (LKKAuto)
Cc: Admin A; SUR; assignments; Ngian, Kelvyna
Subject: RE: LKK ref: CS3/GAI16021242/Pvbs2 - SJF6617G & YL6969G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS II GAIG ref: CLMOMVC000000272
Attachments: 12032018163505-0001.pdf

Dear Veron,

We refer to your email dated 31 January 2018.

Please find attached copies of Third Party's survey report for your recommend on the repairs cost and the days of repairs ASAP.

Regards

On behalf of Kelvyna

Great American

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, January 31, 2018 4:49 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Tan, Angela <Angela.Tan@sg.gaig.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: LKK ref: CS3/GAI16021242/Pvbs2 - SJF6617G & YL6969G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS II GAIG ref: CLMOMVC000000272

Dear Angela,

The estimated normal period for repairs 05 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 31 January 2018 4:40 PM
To: Tan, Angela <Angela.Tan@sg.gaig.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: LKK ref: CS3/GAI16021242/Pvbs2 - SJF6617G & YL6969G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS II GAIG ref: CLMOMVC000000272

Hi Angela,

Thank you for your email.

By copy to Veron.

FYNA please.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Angela [<mailto:Angela.Tan@sg.gaig.com>]

Sent: Wednesday, 31 January, 2018 4:29 PM

To: Admin A <admin-a@lkkauto.com>

Subject: RE: LKK ref: CS3/GAI16021242/Pvbs2 - SJF6617G & YL6969G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS II GAIG ref: CLMOMVC000000272

Dear Sirs,

We refer to your Pre-repair inspection report dated 17-11-2016.

Please provide us the estimated normal period for repairs XXXX working days.

Regards

On behalf of Kelvyna

Great American

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Tuesday, November 08, 2016 10:54 AM

To: Goh, Stella <Stella.Goh@sg.gaig.com>; sur@lkkauto.com

Cc: 'KKLau' <kklau@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'assignments' <assignments@lkkauto.com>

Subject: RE: SJF6617G & YL6969G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Stella,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh, Stella [<mailto:Stella.Goh@sg.gaig.com>]

Sent: Tuesday, 8 November, 2016 10:43 AM

To: huixin@n51.com.sg

Cc: 'KKLau' <kklau@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'assignments' <assignments@lkkauto.com>

Subject: FW: SJF6617G & YL6969G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

WITHOUT PREJUDICE

Dear Melody,

We refer to your email on even date.

We will appoint LKK to conduct the PRS.

Enclosed a list of surveyors.


By copy to Catherine, please assist.

Thank you.

Stella Goh, Senior Executive | P. 65 6804 6059 | F. 65 6235 3354 | stella.goh@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



Moody's
A1 (Good)
Affirmed June 15, 2015

Standard & Poor's
A+ (Strong)
Affirmed March 2, 2016

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Tuesday, November 08, 2016 9:45 AM

To: Sng, Victor <Victor.Sng@sg.gaig.com>

Subject: SJF6617G & YL6969G - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,


As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0060-17-N51

06 February 2017

ACCIDENT VEHICLE SURVEY REPORT

Tang Chai Seng
Blk 593B Montreal Link #16-48
Singapore 752593

VEHICLE INFORMATION:

Vehicle Reg No.:	SJF6617G	Odometer:	138188km
Make & Model:	Toyota Isis 1.8LX A	Colour:	Black
Chassis number:	ZNM100052052	Date of accident:	06/11/2016
Year of Regn.:	06/06/2008	Date inspected:	08/11/2016
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Michelin	5mm/Michelin	195/65R15
Rear:	5mm/Michelin	5mm/Michelin	195/65R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

reuse - N N

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON CONDENSER	1	bent	1,290.00	1,290.00 XNN
AIRCON CONDENSER LOWER RUBBER BUSH L/R	2	distorted	50.00	50.00 XNN
AIRCON CONDENSER TOP BRACKET L/R	2	bent	50.00	50.00 XNN
AIRCON CONDENSER TOP RUBBER BUSH L/R	2	distorted	50.00	50.00 XNN
AIRCON COOLING PIPE	1	reuse	709.30	0.00
AIRCON DISCHARGE PIPE	1	reuse	370.80	0.00
AIRCON OUTSIDE TEMPERATURE SENSOR	1	reuse	108.50	0.00
AIRCON SUCTION PIPE	1	reuse	929.90	0.00
FRONT AIR DUCT	1	warped	55.00	55.00
FRONT AIR DUCT CLIPS	2	necessary	13.00	13.00
FRONT BONNET	1	buckled	665.00	665.00
FRONT BONNET CABLE	1	reuse	52.90	0.00
FRONT BONNET HINGES L/R	2	repair	120.00	0.00
FRONT BONNET INSULATOR MAT	1	deformed	335.00	335.00 XNN
FRONT BONNET MECHANISM LOCK	1	bent	85.00	85.00
FRONT BONNET RUBBER GUIDE STOPPER L/R	4	deformed	80.00	80.00 XNN
FRONT BONNET STAND HOLDER CLIPS	1	reuse	6.50	0.00
FRONT BONNET WEATHERSTRIP	1	deformed	23.40	23.40 XNN
FRONT BONNET WIPER NOZZLE L/R	2	reuse	82.00	0.00
FRONT BRACE PANEL	1	bent	105.00	105.00
FRONT BUMPER	1	squashed	1,455.00	1,455.00
FRONT BUMPER FOGLAMP COVER L/R	2	fractured	132.80	132.80
FRONT BUMPER LOWER CENTER GRILLE	1	warped	115.00	115.00
FRONT BUMPER LOWER UNDER COVER L/R	2	reuse	301.26	0.00
FRONT BUMPER REINFORCEMENT	1	bent	295.00	295.00
FRONT BUMPER REINFORCEMENT BRACKET L/R	2	bent	200.00	200.00
FRONT BUMPER SIDE RETAINER L/R	2	necessary	110.00	110.00
FRONT GRILLE	1	fractured	480.00	480.00
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	65.70	65.70
FRONT GRILLE CHROME 'LOWER'	1	fractured	125.50	125.50
FRONT GRILLE CHROME 'TOP'	2	fractured	224.60	224.60
FRONT GRILLE CLIPS	4	necessary	26.00	26.00
FRONT HEADLAMP CLIPS L/R	4	necessary	26.00	26.00
FRONT HEADLAMP HOLDER CLIPS L/R	2	necessary	13.00	13.00
FRONT HEADLAMP L/R	2	fractured	2,330.00	2,330.00
FRONT HEADLAMP LOWER PANEL L/R	2	repair	137.20	0.00
FRONT SUPPORT PANEL	1	bent	775.00	775.00 XNR
HORN	2	distortion	280.00	280.00 XNN
RADIATOR (AUTO)	1	bent	1,810.00	1,810.00
RADIATOR FAN BLADE	1	warped	147.00	147.00
RADIATOR FAN COWLING	1	distorted	220.00	220.00
RADIATOR FAN MOTOR	1	shorted	480.00	480.00

RADIATOR LH AIR GUIDE	1	reuse	55.00	0.00
RADIATOR LH AIR GUIDE CLIPS	4	necessary	26.00	26.00
RADIATOR LOWER HOSE	1	deformed	41.00	41.00
RADIATOR LOWER RUBBER BUSH L/R	2	distorted	50.00	50.00
RADIATOR TOP BRACKET L/R	2	bent	40.00	40.00
RADIATOR TOP HOSE	1	deformed	41.00	41.00
RADIATOR TOP RUBBER BUSH L/R	2	distorted	58.00	58.00

Subtotal before discount S\$ 15,241.36 S\$ 12,368.00

Percentage discount 25% and 25% S\$ 3,810.34 S\$ 3,092.00

Sub-total 1 S\$ 11,431.02 S\$ 9,276.00

FRONT BONNET INSULATOR MAT CLIPS - SET	1	necessary	30.00	30.00
FRONT BUMPER CLIPS - SET	1	necessary	30.00	30.00
FRONT BUMPER NUMBER PLATE	1	cracked	25.00	25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	bent	50.00	50.00
RADIATOR COOLANT - BOT	1	necessary	80.00	80.00

Subtotal before discount S\$ 215.00 S\$ 215.00

Sub-total 2 S\$ 215.00 S\$ 215.00

Parts-total S\$ 11,646.02 S\$ 9,491.00

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	150.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	180.00	60.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,250.00	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	1,100.00
To apply anti-rust chemical on repaired and replaced panel.	120.00	60.00

Labour Total S\$ 3,230.00 S\$ 2,370.00

Parts & Labour Total S\$ 14,876.02 S\$ 11,861.00

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 10,100.00
and the recommended number of working days for the repairs is within 7 day(s).

B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS3/GAI16021242/Cvbs2-1

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 20-03-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 6969G	Veh. Inspected	SJF 6617G
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000000272	Excess (\$)	0.00
Assign From	ANGELA TAN	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ISIS 1.8LX A	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ZNM100052052	Colour	BLACK
Odometer	138188	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	MICHELIN	6 mm
L/H Front Tyre	195/65R15	MICHELIN	6 mm
R/H Rear Tyre	195/65R15	MICHELIN	6 mm
L/H Rear Tyre	195/65R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/11/2016	Inspection Date	08/11/2016
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 6617G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	AIRCON CONDENSER	NOT NECESSARY	1,290.00	-
2	AIRCON CONDENSER LOWER RUBBER BUSH L/R	NOT NECESSARY	50.00	-
2	AIRCON CONDENSER TOP BRACKET L/R	NOT NECESSARY	50.00	-
2	AIRCON CONDENSER TOP RUBBER BUSH L/R	NOT NECESSARY	50.00	-
1	AIRCON COOLING PIPE	REUSE	709.30	-
1	AIRCON DISCHARGE PIPE	REUSE	370.80	-
1	AIRCON OUTSIDE TEMPERATURE SENSOR	REUSE	108.50	-
1	AIRCON SUCTION PIPE	REUSE	929.90	-
1	FRONT AIR DUCT	WARPED	55.00	55.00
2	FRONT AIR DUCT CLIPS	NECESSARY	13.00	13.00
1	FRONT BONNET	BUCKLED	665.00	665.00
1	FRONT BONNET CABLE	REUSE	52.90	-
2	FRONT BONNET HINGES L/R	TO REPAIR SEE LABOUR	120.00	-
1	FRONT BONNET INSULATOR MAT	NOT NECESSARY	335.00	-
1	FRONT BONNET MECHANISM LOCK	BENT	85.00	85.00
4	FRONT BONNET RUBBER GUIDE STOPPER L/R	NOT NECESSARY	80.00	-
1	FRONT BONNET STAND HOLDER CLIPS	REUSE	6.50	-
1	FRONT BONNET WEATHERSTRIP	NOT NECESSARY	23.40	-
2	FRONT BONNET WIPER NOZZLE L/R	REUSE	82.00	-
1	FRONT BRACE PANEL	BENT	105.00	105.00
1	FRONT BUMPER	SQUASHED	1,455.00	1,455.00
2	FRONT BUMPER FOGLAMP COVER L/R	FRACTURED	132.80	132.80
1	FRONT BUMPER LOWER CENTER GRILLE	WARPED	115.00	115.00
2	FRONT BUMPER LOWER UNDER COVER L/R	REUSE	301.26	-
1	FRONT BUMPER REINFORCEMENT	BENT	295.00	295.00
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	BENT	200.00	200.00
2	FRONT BUMPER SIDE RETAINER L/R	NECESSARY	110.00	110.00
1	FRONT GRILLE	FRACTURED	480.00	480.00
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	65.70	65.70
1	FRONT GRILLE CHROME 'LOWER'	FRACTURED	125.50	125.50
2	FRONT GRILLE CHROME 'TOP'	FRACTURED	224.60	224.60
4	FRONT GRILLE CLIPS	NECESSARY	26.00	26.00
4	FRONT HEADLAMP CLIPS L/R	NECESSARY	26.00	26.00

Report Ref No. CS3/GAI16021242/Cvbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT HEADLAMP HOLDER CLIPS L/R	NECESSARY	13.00	13.00
2	FRONT HEADLAMP L/R	FRACTURED	2,330.00	2,330.00
2	FRONT HEADLAMP LOWER PANEL L/R	TO REPAIR SEE LABOUR	137.20	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	775.00	-
2	HORN	NOT NECESSARY	280.00	-
1	RADIATOR (AUTO)	BENT	1,810.00	1,810.00
1	RADIATOR FAN BLADE	WARPED	147.00	147.00
1	RADIATOR FAN COWLING	DISTORTED	220.00	220.00
1	RADIATOR FAN MOTOR	SHORTED	480.00	480.00
1	RADIATOR LH AIR GUIDE	REUSE	55.00	-
4	RADIATOR LH AIR GUIDE CLIPS	NOT NECESSARY	26.00	-
1	RADIATOR LOWER HOSE	NOT NECESSARY	41.00	-
2	RADIATOR LOWER RUBBER BUSH L/R	NOT NECESSARY	50.00	-
2	RADIATOR TOP BRACKET L/R	NOT NECESSARY	40.00	-
1	RADIATOR TOP HOSE	NOT NECESSARY	41.00	-
2	RADIATOR TOP RUBBER BUSH L/R	NOT NECESSARY	58.00	-
	LESS 25% DISCOUNT		-3,810.34	-2,294.65
			11,431.02	6,883.95
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN) }	CRACKED	25.00	40.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN) }	BENT	50.00	-
1	BOT RADIATOR COOLANT (SN)	NECESSARY	80.00	50.00
			215.00	150.00
	<u>LABOUR</u>			
	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.		180.00	120.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		180.00	30.00
	TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT BUMPER.		1,250.00	700.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGES L/R, FRONT HEADLAMP LOWER PANEL L/R AND FRONT SUPPORT PANEL.		1,500.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			3,230.00	1,490.00
GRAND TOTAL			14,876.02	8,523.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CS3/GAI16021242/Cvbs2-1

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or fort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.