



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2014 NISSAN TEANA 2.0 CVT (SKW1689E)

Date of Loss

2 March 2018

Time of Loss

12.35

Loss Description

SKW1689E (INSD) C/W GBC3630Y

Comment

Workshop Details

Total Rebate Amount

64253

Nett Loss Amount

\$31,747.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

20/06/2018



Days of work completion *

100



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKW1689E

Registration State

SINGAPORE

Mileage

65833

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2014

ASSESSMENT INFO...

2014

Purchase Date

dd/mm/yyyy



Registration Date *

29/09/2015



Age of Vehicle

2

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LOH SUI SHONG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model

POLICY INFORMAT... TEANA 2.0 CVT

ASSESSMENT INFO... TEANA 2.0 XL CVT

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MNTBBAL33Z0003617

CATEGORY Date of Birth

FNOL INFORMATI... 12 December 1975

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 42

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... MR20038932R

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 25

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... 508C #06-15, WELLINGTON CIRCLE,
753508, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7538130A

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

14/03/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

200

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/55R17

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

215/55R17

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
<input type="checkbox"/>		1	6			CLIP-RH FRONT FENDER PROTECTOR			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		2	3			CANOE RIVET-RH FRONT FENDER PROTECTOR			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		3	1			PROTECTOR-FRONT FENDER, RH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		4	1			MALE ASSY-HOOD LOCK			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		5	1			SUPPORT-RADIATOR CORE, UPPER RH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		6	1			SUPPORT ASSY-RADIATOR CORE			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		7	1			EMBLEM-FRONT (DISC 20%)			Necessary	58.88		5		55.94	Review
<input type="checkbox"/>		8	1			GRILLE-RADIATOR, FRONT (DISC 20%)			Cracked	272.96		5		259.31	Review
<input type="checkbox"/>		9	8			CLIP-UPPER FRONT BUMPER MOULDING			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		10	1			MOULDING-FRONT BUMPER, UPPER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		11	1			LH FRONT BUMPER STAY			Serviceable	0	0	0	0	0	Deny

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
<input type="checkbox"/>		12			RH FRONT BUMPER STAY (DISC 20%)			Deformed	69.28		5		65.82	Review
<input type="checkbox"/>		13			FRONT BUMPER REINFORCEMENT (DISC 20%)			Bent	427.04		5		405.69	Review
<input type="checkbox"/>		14			ABSORBER-FRONT BUMPER, RH (DISC 20%)			Deformed	40.32		5		38.3	Review
<input type="checkbox"/>		15			FRONT BUMPER ENERGY ABSORBER (DISC 20%)			Deformed	212.08		5		201.48	Review
<input type="checkbox"/>		16			RETAINER-FRONT BUMPER, LOWER CENTER (DISC 20%)			Deformed	144		5		136.8	Review
<input type="checkbox"/>		17			RETAINER-FRONT BUMPER, LOWER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		18			RETAINER-FRONT FASCIA, LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		19			RETAINER-FRONT BUMPER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		20			RETAINER-FRONT BUMPER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		21			RETAINER-FRONT FASCIA, RH (DISC 20%)			Necessary	33.6		5		31.92	Review
<input type="checkbox"/>		22			BRACKET-FRONT BUMPER SIDE, RH FRONT (DISC 20%)			Necessary	16.72		5		15.88	Review
<input type="checkbox"/>		23			RH FRONT BUMPER SIDE BRACKET (DISC 20%)			Necessary	16.72		5		15.88	Review

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
<input type="checkbox"/>	<input type="text" value="24"/>	<input type="text" value="1"/>			STIFFENER-FRONT BUMPER SIDE, LH (DISC 20%)			Deformed	48		5		45.6	Review
<input type="checkbox"/>	<input type="text" value="25"/>	<input type="text" value="1"/>			STIFFENER-FRONT BUMPER SIDE, RH (DISC 20%)			Deformed	48		5		45.6	Review
<input type="checkbox"/>	<input type="text" value="26"/>	<input type="text" value="1"/>			BRACKET-LICENCE PLATE			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="27"/>	<input type="text" value="2"/>			FRONT BUMPER CLIP (DISC 20%)			Necessary	0.96		5		1.82	Review
<input type="checkbox"/>	<input type="text" value="28"/>	<input type="text" value="1"/>			COVER-BUMPER BRACKET			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="29"/>	<input type="text" value="1"/>			FRONT BUMPER FASCIA (DISC 20%)			Deformed	612.88		5		582.24	Review
<input type="checkbox"/>	<input type="text" value="30"/>	<input type="text" value="1"/>			RH FOG LAMP FINISHER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="31"/>	<input type="text" value="1"/>			TURN SIGNAL LAMP ASSY-FRONT, RH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="32"/>	<input type="text" value="1"/>			LAMP ASSY-RH (DISC 20%)			Cut	335.36		5		318.59	Review
<input type="checkbox"/>	<input type="text" value="33"/>	<input type="text" value="1"/>			LAMP ASSY-LH			Serviceable	0	0	0	0	0	Deny

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
<input type="checkbox"/>	<input type="text" value="1"/>		VACUUM AIRCOND SYSTEM, TOP UP GAS TO SPECIFICATION & MACHINE LEAKAGE TEST	0	0	0	Deny		1

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		2		FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION (DISC 5%)	45.6	0	0	Reviewing		1
		3		SUPPLY & INSTALL FRONT TURNING SENSOR	0	0	0	Deny		1
		4		REMOVE / INSTALL FRONT BUMPER, RADIATOR SUPPORT PANEL & AFFECTED PORTION, REPAIR BONNET, RH & LHF FENDER (DISC 5%)	712.5	0	0	Reviewing		1
		5		RESPRAY PAINT FRONT BUMPER, RADIATOR SUPPORT PANEL, BONNET, RH FRONT FENDER AND LH FRONT FENDER (DISC 5%)	475	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		1	DAYS OF REPAIR : 5 DAYS	Reviewing		
<input type="checkbox"/>		2	NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT (DISC 5%)	Reviewing	57	CUT 
<input type="checkbox"/>		3	SEAL-CONDENSER, SIDE LH	Reviewing	32	DEFORMED 
<input type="checkbox"/>		4	TANK ASSY-LIQUID	Deny	0	NOT NECESSARY 
<input type="checkbox"/>		5	CONDENSER ASSY	Deny	0	NOT NECESSARY 

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/> 	6	NOZZLE ASSY-HEADLAMP CLEANER, RH	Reviewing	106.3	DISTORTED	
<input type="checkbox"/> 	7	COVER-HEADLAMP CLEANER MOTOR, RH	Deny	0	NOT NECESSARY	
<input type="checkbox"/> 	8	LAMP-FOG, RH	Deny	0	NOT NECESSARY	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$3,449.27

Claim Amount \$3,449.27

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,233.10	\$1,233.10
Miscellaneous	\$195.30	\$195.30
Excess	-\$200.00	-\$200.00
Spare Parts	\$2,220.87	\$2,220.87

Submit for Review