

ASS. REC. BY:

REF: CS3 / SPF 18004730 / WH659

Special Instruction:

Survivor

ASSIGNMENT (Office)From (Person): Abdul Rahman of SPF Date/Time: 13032018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKD 5830TInsured: GBF 1951T

at Workshop m/s

Crain Seng TradingTel: 9856 7164

of

Bik 5034 Amk Ind Park 2 #01-315 / 317

Policy No: _____

Claim No: AEMD / 105 / 009 / 2018 / GBF 1951T

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 05032018

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement: _____

Date/Time: 13032018Person Contacted: AnnieVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 5830T - x
	GBF 1951T - x
	lump sum \$10507 , 2 days
	NO GIA REPORT

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/INV
 To inspect Vehicle No. SKQ 5830T
 at Workshop No. Guan Xian
 of Rik 5034, Amu Ind Pak 2
#01-315 1317
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess _____
 (Client's Record) _____
 Make of Ven _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value _____

JDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24HRS

Date _____ Person Contacted _____

Vehicle: IN / OUT

Veh No: SKQ 5830T Regn: Available
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Honda CC: Available
 Colour: Blue Insured / Std / NI / NA

Sp. Reading: 155516 T. Pass: Insured / Std / NI / NA

Eng No: _____

C No: RN6-1030781

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / LS / Rim / STD A / Rim or

Tyre Size F: 215/60 R16
 R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIR / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front

Rear

R/Bal: 4 mm R/Bal: 4 mm

L/Bal: 4 mm L/Bal: 4 mm

D.O.A. _____ D.O. 13/3/2018

Survey held at: As Above 4.47pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

left rear

The UIC / Chassis frame / Body Structure affected due to collision.

13/3/2018 Accident Report not given

9/4/2018 CA 3-A Report Not Available
 - Total 34 Car Accidents

RECEIVED 11 APR 2018

Date Time File Passed:

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

Transcript

Stamp

Stamp

Stamp

Stamp

Stamp

Stamp

Date Time File Returned:

1

Add Fee: ☐ Site Insp. \$

☐ Interview \$

☐ Tech. Insp. \$

☐ Weekend \$

Report Format: DAR

Lump Sum / I.B.I. \$ 1050

280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18004730/Wtb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 13-03-2018



Code : SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBF 1951T	Veh. Inspected	SKQ 5830T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/GBF1951T	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/03/2018	Inspection Date	13/03/2018
Survey held at	GUAN SIANG TRADING ENTERPRISE 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-317-5 SINGAPORE 569537		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SKQ5830T

Our Ref : AEMD/105/009/2018/GBF1951T

Date : 13 March 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 5 MARCH 2018 INVOLVING POLICE VEHICLE GBF1951T AND OTHER VEHICLE SKQ5830T

We refer to the above matter.

- 2 Please arrange for a Pre-Repair Inspection of vehicle no. **SKQ5830T** at **M/s Guan Siang Tdg Enterprise of Blk 5034 Ang Mo Kio Ind'l Pk 2 #01-315/317, Singapore 569537.**
- 3 For appointment, please contact Annie at **Tel: 98567164.**
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

SKQ 5836T

East Portion

NAC	INC	Item	CON	ACQ
1137	993626	Rear Number Plate		
1138	993627	Rear Number Plate Base		
1139	993630	Rear Number Plate Garnish		
1140	993632	Rear Number Plate Lamps		
1141	993938	Rear Bumper	DD/SCA	✓
1142	993035	Rear Bumper Upper		
1143	993017	Rear Bumper Lower		
1144	993054	Rear Bumper Side		
1145	993103	Rear Bumper Tow Cover		
1146	992341	Rear Bumper Clips	NEC	✓
1147	992976	Rear Bumper Bracket		
1148	993068	Rear Bumper Side Retainer (LH)	NEW	
1149	993045	Rear Bumper Reinforcement		
1150	992970	Rear Bumper Beam		
1151	993077	Rear Bumper Sponge		
1152	992999	Rear Bumper Damper		
1153	993049	Rear Bumper Protector		
1154	993036	Rear Bumper Pad		
1155	993026	Rear Bumper Moulding		
1156	993044	Rear Bumper Reflector		
1157	993023	Rear Bumper Lower Spoiler		
1158	994023	Reverse Sensor		
1159	993327	Rear End Panel		
1160	993339	Rear End Panel Top Garnish		
1161	993333	Rear End Panel Inner Trim		
1162	990333	Boot Compartment Inner Trim		
1163	993851	Rear LH Taillamp		
1164	993853	Rear LH Taillamp Garnish		
1165	993859	Rear LH Taillamp Panel		
1166	995116	Rear RH Taillamp		
1167	993853	Rear RH Taillamp Garnish		
1168	993859	Rear RH Taillamp Panel		
1169	993554	Rear Apron Panel		
1170	992895	Bootlid		
1171	991328	Bootlid Emblem		
1172	990356	Bootlid Handle		
1173	995250	Bootlid Moulding		
1174	990376	Bootlid Reflector		
1175	995222	Bootlid Lamp LH		
1176	992899	Bootlid Lamp RH		
1177	995243	Bootlid Lock		
1178	990377	Bootlid Rubber		
1179	990382	Bootlid Hinge		
1180	993377	Bootlid Spoiler		
1181	994543	Tailgate		
1182	991328	Tailgate Emblem		
1183	994643	Tailgate Outer Handle		
1184	994640	Tailgate Moulding		
1185	994645	Tailgate Garnish		
1186	994648	Tailgate Reflector		
1187	994649	Tailgate Lamps		
1188	994646	Tailgate Protector		
1189	994676	Tailgate Wiper Arm		
1190	994677	Tailgate Wiper Blade		
1191	994679	Tailgate Wiper Nozzle		
1192	994655	Tailgate Wiper Motor		
1193	994602	Tailgate Glass		
1194	994606	Tailgate Glass Rubber		
1195	994604	Tailgate Glass Moulding		
1196	994607	Tailgate Glass Sealant		
1197	994629	Tailgate Lock		
1198	994651	Tailgate Rubber		
1199	994611	Tailgate Hinge		
1200	994694	Tailgate Damper		
1201	994613	Tailgate Inner Board		

700

40

35

12222

NAC	INC	Item	CON/AC/OS
1202	993784	Spare Tyre Board	
1203	994323	Spare Tyre Panel	
1204	993665	Spare Tyre	
1205	994326	Spare Tyre Lock Screws	
1206	993787	Spare Tyre Cover	
1207	995323	Triangle Breakdown Sign	
1208	990507	CD Changer Assy.	
1209	990164	Antenna	
1210	990554	Centre Exhaust Pipe Assy.	
1211	990532	Centre Exhaust Mounting	
1212	993364	Rear Exhaust Pipe	
1213	993357	Rear Exhaust Chrome Pipe	
1214	993361	Rear Exhaust Mounting	
1215	993358	Rear Exhaust Heat Shield	
1216	995223	Rear LH Chassis Member	
1217	993165	Rear RH Chassis Member	
1218	993436	Rear LH Fender	
1219	993449	Rear LH Fender Protector	
1220	993420	Rear LH Fender Inner Panel	
1221	993431	Rear LH Fender Inner Trim	
1222	993415	Rear LH Fender Inner Garnish	
1223	993425	Rear LH Fender Inner Shield	
1224	993621	Rear LH Mudflap	
1225	993933	Rear LH Wheel Rim	
1226	994025	Rear LH Rim Cover	
1227	995065	Rear LH Tyre	
1228	993456	Rear RH Fender	
1229	993450	Rear RH Fender Protector	
1230	993420	Rear RH Fender Inner Panel	
1231	993431	Rear RH Fender Inner Trim	
1232	993415	Rear RH Fender Inner Garnish	
1233	993425	Rear RH Fender Inner Shield	
1234	993622	Rear RH Mudflap	
1235	993934	Rear RH Wheel Rim	
1236	994025	Rear RH Rim Cover	
1237	995065	Rear RH Tyre	
1238	995162	Rear Fender Extension Panel LH	
1239	993401	Rear Fender Extension Panel RH	
1240	993430	Rear Fender Inner Top Garnish	
1241	993673	Rear Fender 1/4 Glass	
1242	993452	Rear Fender 1/4 Glass Rubber	
1243	993453	Rear Fender 1/4 Glass Sealant	
1244	993949	Rear Windscreen Glass	
1245	993976	Rear Windscreen Rubber	
1246	993961	Rear Windscreen Moulding	
1247	993955	Rear Windscreen Sealant	
1248	994729	Third Brake Light	
1249	993385	Rear Fender Air Grille	
1250	992167	Fuel Lid	
1251	992168	Fuel Neck	
1252	992179	Fuel Tank	
1253	992184	Fuel Tank Bracket	
1254	992191	Fuel Tank Floor	
4135	990247	Snoker	
		Tail Lamp (LHS) SCR	

Tail lamp (LHS) SCR ✓ 38

No. of Items:

ASSESSOR:

Labour 200
S.P. #200

2 Days Paper



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS3/SPF18004730/Wtbs2

ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333

Date: 20-04-2018



ATTN: ABDUL RAHMAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBF 1951T	Veh. Inspected	SKQ 5830T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/GBF1951T	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	RN61030781	Colour	BLUE
Odometer	155516 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	MICHELIN	4 mm
L/H Front Tyre	215/60R16	MICHELIN	4 mm
R/H Rear Tyre	215/60R16	MICHELIN	4 mm
L/H Rear Tyre	215/60R16	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/03/2018	Inspect Date / Time	13/03/2018 (04:47 PM)
Survey held at	GUAN SIANG TRADING ENTERPRISE BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-317-5 SINGAPORE 569537		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SKQ 5830T

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / SCRATCHED	700.00
1	REAR BUMPER CLIPS	NECESSARY	40.00
1	REAR BUMPER SIDE RETAINER (LH)	NECESSARY	35.00
1	TAILLAMP (LHS)	SCRATCHED	380.00
	LESS 20% DISCOUNT		-231.00
			924.00
LABOUR			
	LABOUR.		200.00
	SPRAY PAINT.		200.00
			400.00
GRAND TOTAL			1,324.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,050.00

Report Ref No. CS3/SPF18004730/Wtbs2

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)**BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.