4	ASS, REC. BY:  REF: CS FCI 1800 4738 / RIrd3 Special Instruction:
	Surveyor: Rasu ASSIGNMENT (Office) From (Person): 81thura of FCI Date/Time: 12/3/1805-58pm
	Estimated Cost:  OD TP WS/TP RES/OD RES/EVA/INV/MV/CS  To Inspect Vehicle No:  SHA0483P  Insured:  SHA0483P
	at Workshop m/s Auto Inqure Tel: 8833 2626  of GMURSILING FUNE  Policy No: Claim No: D18 0000 41 MFS 14
•	Sum Insured: Excess:
	CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:  Date/Time: 9.56cm@13 3 18 Person Contacted: 80m Vehicle(IN)OUT
	Date/Time Action/Instruction ( ) Estimate  S1F 50445 - ×
	SHA 6483P-NAIMSG17005523/h4 D-04: 18/3/2017
	Confirm with screne \$2515.16 @ 3 days (Red : \$4408.64,647.)

Burrenor Colon	4597K
i l	ASSIGNMENT
From: Date:	Veh No: SLF SOYYS Yr Regn: 2016 / Aug
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLF SoH4S	Make: MAZOA 2 SEDAN ISL c.c. 1496
at Workshop m/s Auto (n Suac	Colour GREY A/C: Insured / Std / NI / NA
of 6, MARSILING LAWE	Sp.Reading 128689 T/Radio: Insured / Std / NI / NA
Insured: FCI TP	Eng/No:
Policy No.	C/No: MM 60L 2SAAGW 213488
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Ingreder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: horder/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SRim / STD A/Rim or
(Policy Condition) Sam \$8332626	Tyre Size: F: (85/65R15
(Policy Condition)	R:
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF TRIANGLE
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. 5 mm
SIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 10/03/18 D.O.I. 13/03/18
.um Sum: % 3 Val.: Yes or No	Survey held at Auto rusus
-	Des. of Damages/ Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS  Vehicle: II	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	•
DECEMBED 2.7.1	400 2018
KEGEIVED 2 1 /	
	The second secon
·	
ate/Time. File Pass to? : Preli. Report	Days Of Repair: 3
. Freii. Report	
Label Time Bares	Resurvey No. of Trip: Survey Fee: 145  Transportation: 50
tuput : Final Report	Transportation: 30
late/Time, File Return to?	
late/Time, File Return to?	Id Fee: : Site Insp (\$)s+RSSI
Ad	Id Fee: : Site Insp (\$
ate/Time, File Return to?	Id Fee: : Site Insp (\$




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		NAME OF TAXABLE PARTY OF TAXABLE PARTY.	rnationale Des Experts En Autom			
FIRS	ST CAPITAL INSUR	ANCE LTD	Ref : CS/FCI1800473	38/R1rd3		
36 R #16-	OBINSON ROAD 01 CITY HOUSES!	NGAPORE 068877	Date: 13-03-2018 Code: FCI2			
1.	Park House Silve	Policy Particu	lars :- THIRD PARTY CLAI	M		
9.78	Insured Veh.	SHA 483P	Veh. Inspected	SLF 5044S		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	D18002041MFSH	Excess (\$)	0.00		
	Assign From	CWS (SITHARA)	Assign Date	13/03/2018		
2.		Vehicle	Particulars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	3	Steering			
	Brakes		Modification			
	General					
3.		Co	onditions of Tyres	and Aller and Burney		
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.	d man consul	Des	cription of Damages			
5.		G	eneral Information			
J.	Accident Date	10/03/2018	Inspection Date	13/03/2018		
	Survey held at	AUTO INSURE PTE LTD				
	Janey Hold at	6 MARSILING LANE S739145				
5a.			Remarks			
	A)THE INSPECTION	ON WAS CONDUCTED ON CE TO YOUR INSTRUCTIO	A"WITHOUT PREJUDICE" BA NS, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.		



MS First Capital Insurance Limited Co. Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068977 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### MOTOR SURVEY ASSIGNMENT

Date

12-03-2018

Our Ref No. D18002041MFSH

**Accident Date** 

10-03-2018

Claim Type. Third Party

Insured Vehicle

SHA483P

Third Party Vehicle. SLF5044S

Survey Location

6 MARSILING LANE

Contact Person.

SAM GOH

Contact No.

315712626/88332626

Fax No. 63680081

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

#### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

#### THIRD PARTY SURVEY REQUEST

Cc: Workshop

AUTO INSURE PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

ob Sheet (/Cl	aimWS/Surveyor/JobSheet/2	235837) 🚣 PRI	Documents 🙆 Close 🗶		
			PRI Header Details		
Claim No	D18002041MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & AUTO INS
Workshop Name	AUTO INSURE PTE LTD (Contact Person : SAM GOH)	Survey Location & Contact Details	6 MARSILING LANE Mobile: 88332626 , Phone EmailId: CLAIMS01@WEB	e: 315712626 -DEZIGNERS.0	, <b>Fax:</b> 636800
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0483P	TP Vehicle No	SLF5044S
PRI Recieved Date	12-03-2018 06:33:22 PM	Surveyor Appointed Date	12-03-2018 05:57:35 PM	Surveyor Accept Date	13-03-2018
70.000.00			Survey Report Upload		
Surveyor Inspection Date *:		Surveyor Report Date	13-03-2018	Upload Survey Report *:	Choose File
			Vehicle Particulars	26	· · · · · · · · · · · · · · · · · · ·
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity		]	
	La compania Uniond	•			
Multiple	ocuments Upload	Upload Multip	le Documents		
File Na	me			Action	
Surveyor	Job Remarks				
	1				



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18002041MFSH

Our Ref: CS/FCI18004738/R1rd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


# INITIAL INSPECTION REPORT OF VEHICLE NO. SLF 50448 .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/03/2018 at the premises of M/s AUTO INSURE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	6,148.60	
Revised Estimate Amount	: S\$	2,515.16	
"Check" Items Amount	: S\$	1,141.52	
Market Value	: <u>S\$</u>	-	
LTA Reimbursement Value	: <u>S\$</u>	-	
Nett Value	: <u>S\$</u>	•	

Description of Damage:

<u>The vehicle sustained damages</u>
at front portion.



Yours faithfully RASUL Automotive Assessor

### Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Thursday, March 15, 2018 11:42 AM

To:

'Claim Workflow System'

Cc:

SITHARA@MSFIRSTCAPITAL.COM.SG; SUR

Subject:

RE: SURVEY ASSESSMENT - D18002041MFSH/1

Attachments:

SLF 5044S.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SLF 5044S.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, March 13, 2018 11:22 AM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18002041MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Monday, 12 March 2018 5:57 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18002041MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.


Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

#### Sketch Plan #3 Pg. 1







### Auto Insure Pte. Ltd.

Bik 3, 391A Woodlands Road Yew Tee Industrial Estate Singapore (677964) E: claims@autoinsure.com.sg W: www.autoinsure.com.sg T: 6368 2788 F: 6368 0081 GST No.: 201437380M

Page No.1

#### **AUTOMOBILE ASSESSMENT REPORT**

Our Ref

SLF5044S

SHA483P

13-Mar-18 Date:

BY EMAIL ONLY (claims@autoinsure.com.sg)

#### ATTENTION: MOTOR CLAIMS DEPT

email:

motor claims@first-insurance.com.sg

First Capital Insurance Limited 6 Raffles Quay #21-00 Singapore 048580

Assessed Vehicle No Car Make and Model : SLF5044S

: MAZDA2 1.5L SDN : 10-Mar-18

Date of Accident Date of Assessment

: 13-Mar-18

We have carried out a physical assessment of SLF SLF5044S sustained damages to the FRONT portion of the vehicle.

#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

P/P

Adjusted Amount

; \$ 5,600.00

Est, Repair Days

4

\*\* Considering that our vehicle is less then 6 months old. We will not agree to any repair of parts, only replacement will be done. \*\*

Pursuant to your instruction, we have NOT AUTHORIZED repair. The assessment was conducted on a "WITHOUT PREJUDICE" basis.


If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

#### isclaime

this report is intended for the exclusive use of the adresses solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE, LTD. For any reliance on this report by any third party.



Our Ref.

SLF5044S SHA483P

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
1 2 3 4 5 6 7 8	1 1 1 1 2 1 1	PARTS REPLACEMENT - LIST ITEMS FRONT BUMPER FRONT BUMPER TOP GARNISH FRONT BUMPER REINFORCEMENT FRONT BUMPER CENTER GRILLE FRONT GRILLE CHROME MOULDING FRONT BUMPER LOWER GRILLE FOG LAMP COVER LH FRONT FOG LAMP COVER RH FRONT FRONT BUMPER GRILLE MAZDA LOGO		\$ 1,325.50 \$ 312.20 \$ 580.60 \$ 488.90 \$ 280.00 \$ 248.20 \$ 144.95 \$ 109.20
10	1	FRONT BUMPER LOWER COVER		\$ 320.0
			SUB TOTAL	\$ 3,954.5
			LESS 20%	\$ 790.9
			TOTAL AMOUNT	\$ 3,163.6

DE/ og/su

X Zna X Xsur

s/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP	. /
1	1 SET	FRONT BUMPER CLIPS		\$ 60.00	35 CRA
2	1	FRONT LICENCE PLATE WITH HOLDER		\$ 1500	35 210
			SUB TOTAL	\$ 135.00	
			TOTAL PARTS COST	\$ 3,298.60	

Our	Ref:	SLF5044S
Our	Ref:	3LF3044

our Ref:	SLF50445			
s/NO	SHA483P DESCRIPTION		EST. BY WORKSHOP	
S/NO	LABOUR & PAINTWORK			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COM BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED T COMPONENTS	MENCE REPAIRS; PANEL HE DAMAGED PARTS AND	\$ 1,200.00	300
2	TOWING CHARGE		5	× 11
3	TO REMOVE/REFIX HEADLAMP FO	CUS	s 15000	X11
4	TO REMOVE/INSTALL REAR WINDS	CREEN	\$ -	x 11
.5	TO DIAGNOSE ERASE FAULT MEMORY AF	TER REPAIR	ş 450.00	×n7
6	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT A	ND CHECK FOR PROPER	\$ 100.00	960,060
7	TO REMOVE / INSTALL REAR REVERSE	SENSOR	\$ -	vv
10	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUR	FY ON PARTS REPLACED	\$ 500.00	300
11	TO PERFORM ANTI-RUST TREATMENT ON A			XXV
12	TO VACUUM; WAXING & CLEA		\$ 100.00	XI
13	TO PERFORM WATER SEEPAGE TEST ON REP		\$ 10000	30
13	101211011111111111111111111111111111111	TOTAL BEFORE GST	\$ 6,148.60	6923.80
		GST 7%	\$ 430.4	6472.00
	TO	OTAL (PARTS & LABOUR):	\$ 6,579.00	)

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$5600.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng Claims Director

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Resy afterwain



### Auto Insure Pte. Ltd.

6 Marsiling Lane
Singapore (739145)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

# **Supplementary Items**

Our Ref:

**SLF5044S** 

Your Ref:

SHA483P

4	EST. BY WORKSHOP		ASSESSED CONDITION	DESCRIPTIONS	QTY	s/NO
report	\$ 969.00			PARTS REPLACEMENT - LIST ITEMS  BONNET	1	1
		_	SUB TOTA			
		_	LESS 20			
0	\$ 775.20	TAL	TOT			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Interna	tionale Des Experts En Auton	nobile
IRST CAPITAL INSU	RANCE LTD	Ref : CS/FCI180047	38/R1rd3n2
6 ROBINSON ROAD 16-01 CITY HOUSES	SINGAPORE 068877	Date: 28-08-2018  Code: FCI2	
	Policy Particula	rs :- THIRD PARTY CLA	lM
Insured Veh.	SHA 483P	Veh. Inspected	SLF 5044S
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18002041MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	12/03/2018
2.	Vehicle Pa	rticulars & Condition	
Make & Model	MAZDA2 SEDAN 1.5L	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MM6DL2SAAGW213488	Colour	GREY
Odometer	128689	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3.	Conditions of Tyres		
	Size	Make	Balance
R/H Front Tyre	185/65 R15	TRIANGLE	5 mm
L/H Front Tyre	185/65 R15	TRIANGLE	5 mm
R/H Rear Tyre	185/65 R15	TRIANGLE	5 mm
L/H Rear Tyre	185/65 R15	TRIANGLE	5 mm
4.		iption of Damages	
THE VEHICLE S	SUSTAINED DAMAGES AT THE	FRONT PORTION.	
DAMAGES SEE	DETAILS.		
5.		neral Information	
Accident Date	10/03/2018	Inspection Date	13/03/2018
Survey held a	t AUTO INSURE PTE LTD		
	6 MARSILING LANE S739145		
5a.		Remarks	
THE WIGHTS	ONSISTENT TO ACCIDENT RE TION WAS CONDUCTED ON A NICE TO YOUR INSTRUCTION	"MITHOUT PREJUDICE" B	ASIS. RISED REPAIRS.
5b.		nate Days of Repair	<b>以中央生态的</b>
	ORMAL PERIOD FOR REPAIR:	3 Working I	Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5044S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,325.50	1,325.50
	FRONT BUMPER TOP GARNISH	DEFORMED	312.20	312.20
	FRONT BUMPER REINFORCEMENT	SERVICEABLE	580.60	1-2
	FRONT BUMPER CENTRE GRILLE	SERVICEABLE	488.90	
	FRONT GRILLE CHROME MOULDING	CRACKED	280.00	280.00
	FRONT BUMPER LOWER GRILLE	SERVICEABLE	248.20	-
	FOG LAMP COVER LH FRONT	NOT NECESSARY	144.95	-
1	FOG LAMP COVER RH FRONT	NOT NECESSARY	144.95	-
1	FRONT BUMPER GRILLE MAZDA LOGO	SERVICEABLE	109.20	-
1	FRONT BUMPER LOWER COVER	CUT	320.00	320.00
1	BONNET (ADDITIONAL)	TO REPAIR SEE LABOUR	969.00	-
	LESS 20% DISCOUNT	00000000000000	-984.70	-447.54
	SPECIAL NETT ITEMS		3,938.80	1,790.16
-	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
	FRONT LICENCE PLATE WITH HOLDER (SN)	CRACKED	75.00	35.00
	FRONT LICENCE PLATE WITH HOLDER (ON)		135.00	95.00
	LABOUR			300.00
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF BONNET.		1,200.0	300.00
	TOWING CHARGE. (NPA)	NOT NECESSARY	2	-
	TO REMOVE/REFIX HEADLAMP FOCUS.	NOT NECESSARY	150.0	0
	TO REMOVE/INSTALL REAR WINDSCREEN. (NPA)	NOT NECESSARY		-
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.	NOT NECESSARY	450.0	
	TO REMOVE/REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.	NOT NECESSARY	100.0	0
	TO REMOVE/INSTALL REAR REVERSE SENSOR. (NPA)	NOT NECESSARY	1	-

Report Ref No. CS/FCI18004738/R1rd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		600.00	300.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	150.00	
	TO VACUUM, WAXING & CLEAN. TO PERFORM WATER SEEPAGE TEST ON REPAIRED		100.00	normal c
	PORTIONS.		2,850.00	
	GRAND TOTAL		6,923.80	2,515.16

RECOMMENDED COST OF REPAIRS	2,515.16
-----------------------------	----------

Report Ref No. CS/FCI18004738/R1rd3n2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

St. S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.