Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040 Tel/Fax: 6886 1106 Mobile: 9007 5234 Email: constant as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Alex Car Express

c/o No 74 Sungei Kadut St.1

Singapore 729374

Date

: 31/05/2017

Reference No : CAS/17-05/060

General Information

Registration No.

SKZ 1106E 10/04/2017

Accident Date

Particulars of Damaged Vehicle

Colour

: White

Make & Model

: Honda Vezel 1.5X A

Engine Capacity

: 1496 cc

Pre-Accident Condition : Good

Mileage (KM)

030739

Engine No.

: L15B4027397

Chassis No.

: RU11107392 Registration Date : 08/01/2016

Steering Brake

: In Order : In Order

Tyre Condition

	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	90%	
L/H Front Tyre	215/60R16	DUNLOP	90%	
R/H Rear Tyre	215/60R16	DUNLOP	90%	
L/H Rear Tyre	215/60R16	DUNLOP	90%	

Inspection

Repairer

: Yeo & Partner

No 74 Sungei Kadut St.1, Singapore 729374

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$6,253.08 Revised Amount

: \$4,000.00

Less Excess

Nett Total

: \$4,000.00

Remarks

- (A) Survey was done on 26/05/2017
- (B) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (C) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Vehicle No: SKZ 1106E

Our ref: CAS/17-05/060

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		PARTS REPLACEMENT – LIST ITEMS			
1	lpc	Front headlamp RH	Grazed/Broken	1,450.50	1,450.50
2	1pc	Front bumper	Broken	1,281.90	1,281.90
3	2pcs	Front bumper side retainer @ \$46.50	Necessary	93.00	93.00
4	1pc	Front bumper top side holder RH	Broken	88.40	88.40
5	1pc	Front bumper top side holder LH	Serviceable	88.40	-
6	1pc	Front bumper lower grille	Deformed/Broken	177.10	177.10
7	1pc	Front bumper lower spoiler	Dented/Deformed	330.60	330.60
8	1pc	Front bumper fog lamp RH	Broken	278.40	278.40
9	1pc	Front bumper fog lamp garnish RH	Broken	98.50	98.50
10	1pc	Front grille	Deformed/Broken	315.20	315.20
11	1pc	Front grille emblem	Necessary	76.50	76.50
12	1pc	Front grille chrome LH	Serviceable	71.40	82
13	1pc	Front grille chrome RH	Serviceable	71.40	-
14	lpc	Front fender RH	Repair	680.60	_
15	lpc	Front fender wheel protector RH	Grazed/Torn	212.60	212.60
16 1 _F	lpc	Front fender inner shield RH	Serviceable	181.60	-
				5,490.10	4,402.70
		Less 20%		(1,098.02)	(880.54)
			Sub total	4,398.08	3,522.16
		PARTS REPLACEMENT - SPECIAL NETT ITEMS			
1	1 set	Front parking sensor	Damaged	280.00	250.00
2	1 set	Front bumper clip	Necessary	45.00	45.00
			Sub total	4,723.08	3,817.16
		LABOUR & MISC. CHARGES			
1		To checkup front electrical system		80.00	40.00
2		To respray undercoating		50.00	30.00
3		To respray painting & etc		700.00	600.00
4		Panel beating, remove & replacing above parts		700.00	500.00
			Grand total	6,253.08	4,987.16
		st of lump sum repair nt condition)			4,000.00

Vehicle No : SKZ 1106E Our ref : CAS/17-05/060

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$4,000.00 on a contractual basis. Under normal circumstances, the repair period would be about 4 (Four) working days.

Yours faithfully,

Constant Appraiser Services

Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA

















































































































